



Chart no. 2293

2293 - Byng Inlet and Approaches / et les approches - New Edition - 30-MAR-2001 - NAD 1983

05-AUG-2022

LNМ/D. 03-SEP-2021

Delete Rep (2021) against obstruction
(See Chart No. 1, K41)

45°43'52.0"N 080°44'10.0"W

This notice affects Electronic Navigational Chart: CA573231

DFO(6604888-01)

05-AUG-2022

LNМ/D. 03-SEP-2021

Delete depth of 10 feet
(See Chart No. 1, I10)

45°45'17.4"N 080°40'16.3"W

This notice affects Electronic Navigational Chart: CA573231

DFO(6604888-02)

05-AUG-2022

LNМ/D. 03-SEP-2021

Add depth of 3 feet
(See Chart No. 1, I10)

45°45'18.0"N 080°40'14.6"W

This notice affects Electronic Navigational Chart: CA573231

DFO(6604888-03)

03-SEP-2021

LNМ/D. 07-JUN-2013

Add obstruction with known depth of 19 feet
(See Chart No. 1, K41)

45°43'52.9"N 080°44'12.9"W

This notice affects Electronic Navigational Chart: CA373052,
CA573231

DFO(6604795-15)

07-JUN-2013

LNМ/D. 05-MAR-2010

Add sounding of 5 feet, Rep (2012)
(See Chart No. 1, I10 & I3.2)

45°46'00.5"N 080°38'54.6"W

This notice affects Electronic Navigational Chart: CA573231

DFO(6603870-01)

05-MAR-2010

LNМ/D. 21-AUG-2009

Add Rescue Station
(See Chart No. 1, T12)

45°44'41.6"N 080°39'33.4"W

DFO(6603571-01)

This notice affects Electronic Navigational Chart: CA573231

21-AUG-2009

LNМ/D. 29-AUG-2008



Chart no. 2293

Amend legend F R 43ft to read F R 42ft against light

45°46'04.3"N 080°36'53.0"W

LL(962) DFO(6603426-01)

This notice affects Electronic Navigational Chart: CA573231

21-AUG-2009

LN/D. 29-AUG-2008

Amend legend F R 27ft to read F R 26ft against light

45°46'03.2"N 080°36'58.8"W

LL(961) DFO(6603426-02)

This notice affects Electronic Navigational Chart: CA573231

29-AUG-2008

LN/D. 02-MAY-2008

Amend legend FR 26ft to read FR 27ft against light

45°46'03.5"N 080°36'58.5"W

DFO(6603237-01)

This notice affects Electronic Navigational Chart: CA573231

29-AUG-2008

LN/D. 02-MAY-2008

Amend legend FR 35ft to read FR 43ft against light

45°46'04.5"N 080°36'53.0"W

DFO(6603237-02)

This notice affects Electronic Navigational Chart: CA573231

02-MAY-2008

LN/D. 01-DEC-2006

Amend legend F R 64ft to read F R 57ft against light

45°45'11.4"N 080°38'20.3"W

(D2008018) LL(958) DFO(6603193-01)

This notice affects Electronic Navigational Chart:
CA373052, CA573231

01-DEC-2006

LN/D. 15-JUL-2005

Add red starboard hand spar buoy, marked H26/2

45°45'46.3"N 080°37'57.4"W

With this notification, Notice 20-Feb-2004 (T) is cancelled. See
reference DFO(6601297-01) appearing in this edition.

(D2006083) DFO(6602835-01)

This notice affects Electronic Navigational Chart: CA573231

15-JUL-2005

LN/D. 03-SEP-2004



Chart no. 2293

Amend legend FG 54ft to read 2 FG (vert) against light 45°45'55.7"N 080°37'43.9"W

LL(960) DFO(6602372-01)

15-JUL-2005

LNM/D. 03-SEP-2004

Amend legend FG 35ft to read FG against light 45°45'52.2"N 080°37'50.2"W

LL(959) DFO(6602372-02)

03-SEP-2004

LNM/D. 20-FEB-2004

Replace red starboard hand pillar light buoy Fl R, marked
HH2, with red starboard hand spar light buoy Fl R,
marked HH2

45°43'58.2"N 080°44'39.9"W

(D2004040) LL(953) DFO(6601939-01)

This notice affects Electronic Navigational Chart:
CA273097

03-SEP-2004

LNM/D. 20-FEB-2004

Replace green port hand pillar light buoy QG, marked
H13, with green port hand spar light buoy QG,
marked H13

45°44'39.1"N 080°40'42.8"W

(D2004041) LL(955.000) DFO(6601939-02)

03-SEP-2004

LNM/D. 20-FEB-2004

Replace red starboard hand pillar light buoy Fl R,
marked H12, with red starboard hand spar
light buoy Fl R, marked H12

45°44'33.8"N 080°40'52.1"W

(D2004042) LL(955.200) DFO(6601939-03)

03-SEP-2004

LNM/D. 20-FEB-2004

Replace green port hand pillar light buoy QG, marked
H19, with green port hand spar light buoy QG,
marked H19

45°45'00.1"N 080°39'27.1"W

(D2004043) LL(956.000) DFO(6601939-04)

03-SEP-2004

LNM/D. 20-FEB-2004



Chart no. 2293

Replace green port hand pillar light buoy Fl G, marked
H21, with green port hand spar light buoy Fl
G, marked H21

45°45'14.0"N 080°38'59.5"W

(D2004044) LL(958.400) DFO(6601939-05)

20-FEB-2004

LN/D. 09-JAN-2004

(T)Add red, starboard hand spar buoy, marked H26/2

45°45'46.3"N 080°37'57.4"W

(D2003169T) DFO(6601297-01)

Notice 20-FEB-2004(T) is cancelled. See reference
DFO(6602835) appearing in this edition.
Cancelled on 01-DEC-06

09-JAN-2004

LN/D. 31-OCT-2003

Reposition red, starboard hand spar buoy, marked H6 from 45°44'20.0"N 080°42'26.0"W
to 45°44'20.5"N 080°42'28.0"W

(D2003138) DFO(6601077-01)

09-JAN-2004

LN/D. 31-OCT-2003

Amend Fl G to read QG against buoy H13

45°44'39.1"N 080°40'43.7"W

(D2003141) LL(955) DFO(6601081-01)

31-OCT-2003

LN/D. 05-JUL-2002

Amend Fl 5sec 52ft 16M to read Oc 10sec 52ft against light

45°44'40.0"N 080°39'32.7"W

(D2003114) LL(954) DFO(6601015-01)

31-OCT-2003

LN/D. 05-JUL-2002

Add rock with known depth of 2 feet 45°45'46.1"N 080°37'56.7"W

DFO(6601038-01)

21-DEC-2001

LN/D. 14-DEC-2001

Replace red, starboard hand conical buoy, marked H6 with red,
starboard hand spar buoy, marked H6

45°44'20.0"N 080°42'26.0"W

(D2001147) DFO(6600010-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 2293

2293 - Continuation A - New Edition - 30-MAR-2001 - NAD 1983

05-JUL-2002 LNM/D. 21-DEC-2001

Delete beacon, Priv 45°46'00.2"N 080°34'27.2"W

DFO(6600195-01)

05-JUL-2002 LNM/D. 21-DEC-2001

Delete beacon, Priv 45°46'00.2"N 080°34'30.0"W

DFO(6600195-02)

14-DEC-2001

Add radio tower R Lts with elevation of 160 feet 45°45'54.4"N 080°33'56.3"W

DFO(6601751-01)