



Chart no. 4023

4023 - Northumberland Strait / Détroit de Northumberland - New Edition - 27-DEC-2002 - World Geodetic System 1984

28-JUL-2023

LN/D. 30-JUN-2023

Delete red and white fairway lighted spar buoy Mo(A),
marked DP

46°54'04.8"N 064°14'07.3"W

(See Chart 1, Qd)

(G2023029) LL(1032.05) DFO(6310696-01)

This notice affects Electronic Navigational

Chart: CA276286, CA376062

28-JUL-2023

LN/D. 30-JUN-2023

Add red and white fairway lighted can buoy Mo(A),
marked DP

46°54'02.2"N 064°14'17.8"W

(See Chart 1, Qd)

(G2023029) LL(1032.05) DFO(6310696-02)

This notice affects Electronic Navigational Chart:

CA276286, CA376062

28-JUL-2023

LN/D. 30-JUN-2023

Delete red and white fairway lighted spar buoy Mo(A)
(See Chart 1, Qd)

46°27'31.6"N 062°44'20.8"W

This notice affects Electronic Navigational Chart: (G2023035) LL(1043.1) DFO(6310702-01)

CA276286

28-JUL-2023

LN/D. 30-JUN-2023

Add red and white fairway lighted pillar buoy Mo(A),
marked JD

46°27'09.2"N 062°44'21.7"W

(See Chart 1, Qd)

(G2023035) LL(1043.1) DFO(6310702-02)

This notice affects Electronic Navigational Chart:

CA276286

30-JUN-2023

LN/D. 14-APR-2023

Delete light FY

46°36'11.5"N 061°03'08.5"W

(See Chart 1, P1)

This notice affects Electronic Navigational Chart: (G2023020) LL(868) DFO(6310673-01)

CA276286

30-JUN-2023

LN/D. 14-APR-2023

Add private yellow ODAS/SADO lighted pillar buoy Fl(5) Y 20s,
marked IML-17

46°57'00.0"N 061°01'06.2"W

(See Chart 1, Q58)

DFO(6310707-01)

This notice affects Electronic Navigational Chart: CA276286,
CA376308



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4023

14-APR-2023

LN/D. 03-MAR-2023

Delete green port hand lighted pillar bell buoy, Fl G,
marked X31

47°07'09.0"N 064°47'06.0"W

(See Chart 1, Qc)

(G2023001) LL(1162) DFO(6310587-01)

This notice affects Electronic Navigational Chart:
CA276286, CA376062, CA476133

14-APR-2023

LN/D. 03-MAR-2023

Add green port hand lighted spar buoy, Fl G, marked X31
(See Chart 1, Qc)

47°07'09.0"N 064°47'06.0"W

This notice affects Electronic Navigational Chart:
CA276286, CA376062, CA476133

(G2023001) LL(1162) DFO(6310587-02)

03-MAR-2023

LN/D. 08-JUL-2022

Delete Note

46°52'30.0"N 064°10'30.0"W

DIAGRAM/DIAGRAMME

See Sailing Directions

DFO(6310561-01)

Voir Instructions nautiques

Miminegash

(See Chart No. 1, A18)

This notice affects Electronic Navigational Chart: CA276286

03-MAR-2023

LN/D. 08-JUL-2022

Delete Note

46°58'15.0"N 064°04'15.0"W

DIAGRAM/DIAGRAMME

See Sailing Directions

DFO(6310561-02)

Voir Instructions nautiques

Skidders Point/Tignish

(See Chart No. 1, A18)

This notice affects Electronic Navigational Chart: CA276286

03-MAR-2023

LN/D. 08-JUL-2022

Delete Note

46°26'30.0"N 062°23'00.0"W

DIAGRAM/DIAGRAMME

See Sailing Directions

DFO(6310561-03)

Voir Instructions nautiques

Naufrage

(See Chart No. 1, A18)

This notice affects Electronic Navigational Chart: CA276286

03-MAR-2023

LN/D. 08-JUL-2022



Chart no. 4023

- Delete Note 46°27'00.0"N 062°11'00.0"W
DIAGRAM/DIAGRAMME
See Sailing Directions *DFO(6310561-04)*
Voir Instructions nautiques
North Lake
(See Chart No. 1, A18)
This notice affects Electronic Navigational Chart: CA276286
- 08-JUL-2022** LNM/D. 05-NOV-2021
Amend Fl 6s 109ft 8M to read LFl 6s109ft12M 46°32'05.0"N 063°30'22.0"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: *(G2022032) LL(1061) DFO(6310104-01)*
CA276286
- 05-NOV-2021** LNM/D. 06-AUG-2021
Delete light FLY(2) 12s47ft10M 46°19'11.8"N 064°30'47.2"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: *(G2021136) LL(1113) DFO(6309643-01)*
CA276286, CA376076, CA476128
- 05-NOV-2021** LNM/D. 06-AUG-2021
Add abandoned lighthouse with legend LtHo (disused) / 46°19'11.8"N 064°30'47.2"W
LtHo (désaffecté)
(See Chart No. 1, P1) *(G2021136) LL(1113) DFO(6309643-02)*
This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476128
- 06-AUG-2021** LNM/D. 09-JUL-2021
Add wreck with known depth of 9 fathoms, 2 feet, PA 46°52'41.2"N 064°47'26.8"W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA276286, *DFO(6309508-01)*
CA376062
- 09-JUL-2021** LNM/D. 26-FEB-2021
Amend "AZMP-ESG" to read "IML-12" against yellow ODAS/SADO 46°48'00.0"N 062°00'00.0"W
lighted pillar buoy Fl(5)Y
(See Chart No. 1, Q58) *DFO(6309414-03)*
This notice affects Electronic Navigational Chart: CA276286
- 09-JUL-2021** LNM/D. 26-FEB-2021



Chart no. 4023

Reposition red and white fairway lighted pillar buoy from 46°27'09.2"N 062°44'21.6"W
Mo(A) to 46°27'31.9"N 062°44'21.1"W
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart: CA276286 (G2021034) LL(1043.1) DFO(6309466-01)

26-FEB-2021

Delete light 2 Lts F Y LNM/D. 06-NOV-2020
(See Chart No. 1, P20.3) 46°26'52.0"N 064°06'19.5"W
This notice affects Electronic Navigational Chart: CA276286 (G2020228) LL(1026) DFO(6309269-02)

26-FEB-2021

Add light Fl R LNM/D. 06-NOV-2020
(See Chart No. 1, P1) 46°13'28.6"N 064°22'58.4"W
This notice affects Electronic Navigational Chart: CA276286, CA376076 (G2020268) LL(1103.5) DFO(6309345-01)

06-NOV-2020

Delete light FRWG LNM/D. 02-OCT-2020
(See Chart No. 1, P1) 46°19'44.0"N 062°20'57.1"W
This notice affects Electronic Navigational Chart: CA276286, CA376248 (G2020227) LL(948.3) DFO(6309268-01)

02-OCT-2020

Reposition red and white fairway lighted spar buoy from 46°39'09.0"N 063°50'50.0"W
Mo(A) to 46°39'28.0"N 063°51'23.0"W
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart: CA276286 (G2020184) LL(1071.35) DFO(6309213-03)

21-AUG-2020

Delete depth of 1 fathom, 4 feet LNM/D. 07-AUG-2020
(See Chart No. 1, I10) 45°45'10.9"N 063°18'18.8"W
This notice affects Electronic Navigational Chart: CA276286 DFO(6308867-01)

21-AUG-2020

Add depth of 1 fathom LNM/D. 07-AUG-2020
(See Chart No. 1, I10) 45°45'22.5"N 063°18'28.4"W
This notice affects Electronic Navigational Chart: CA276286 DFO(6308867-02)



Chart no. 4023

21-AUG-2020

LNМ/D. 07-AUG-2020

Delete depth of 2 fathoms, 2 feet
(See Chart No. 1, I10)

45°46'28.3"N 063°16'48.5"W

This notice affects Electronic Navigational Chart: CA276286

DFO(6308867-03)

21-AUG-2020

LNМ/D. 07-AUG-2020

Add depth of 1 fathom, 4 feet
(See Chart No. 1, I10)

45°46'28.3"N 063°16'48.5"W

This notice affects Electronic Navigational Chart: CA276286

DFO(6308867-04)

21-AUG-2020

LNМ/D. 07-AUG-2020

Delete depth of 2 fathoms, 1 foot
(See Chart No. 1, I10)

45°45'44.6"N 063°18'04.2"W

This notice affects Electronic Navigational Chart: CA276286

DFO(6308867-05)

21-AUG-2020

LNМ/D. 07-AUG-2020

Add depth of 0 fathoms, 4 feet
(See Chart No. 1, I10)

45°45'59.2"N 063°18'04.2"W

This notice affects Electronic Navigational Chart: CA276286

DFO(6308867-06)

21-AUG-2020

LNМ/D. 07-AUG-2020

Delete depth of 2 fathoms, 3 feet
(See Chart No. 1, I10)

45°47'04.7"N 063°15'14.0"W

This notice affects Electronic Navigational Chart: CA276286

DFO(6308867-08)

21-AUG-2020

LNМ/D. 07-AUG-2020

Add depth of 2 fathoms, 1 foot
(See Chart No. 1, I10)

45°46'58.3"N 063°14'55.2"W

This notice affects Electronic Navigational Chart: CA276286

DFO(6308867-09)

21-AUG-2020

LNМ/D. 07-AUG-2020

Affix patch

46°25'00.0"N 065°08'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA276286

DFO(6308867-10)

21-AUG-2020

LNМ/D. 07-AUG-2020



Chart no. 4023

- Delete depth of 2 fathoms, 5 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286
- 45°50'30.0"N 063°09'00.0"W
DFO(6308868-01)
- 21-AUG-2020**
- Add depth of 1 fathom, 3 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286
- LNM/D. 07-AUG-2020
45°50'16.8"N 063°08'31.4"W
DFO(6308868-02)
- 21-AUG-2020**
- Delete depth of 3 fathoms, 1 foot
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286
- LNM/D. 07-AUG-2020
45°46'10.0"N 063°08'00.0"W
DFO(6308869-01)
- 21-AUG-2020**
- Add depth of 2 fathoms, 4 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286
- LNM/D. 07-AUG-2020
45°46'11.5"N 063°07'52.3"W
DFO(6308869-02)
- 07-AUG-2020**
- Delete red starboard hand lighted pillar buoy Fl R
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA276286, CA376076, CA476128
- LNM/D. 05-JUN-2020
46°23'30.0"N 064°33'08.0"W
(G2020048) LL(1115) DFO(6309014-01)
- 07-AUG-2020**
- Add red and white fairway lighted conical buoy Mo(A)
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart: CA276286, CA376076, CA476128
- LNM/D. 05-JUN-2020
46°23'19.7"N 064°32'38.5"W
(G2020049) LL(1115.1) DFO(6309015-01)
- 07-AUG-2020**
- Delete red starboard hand lighted pillar buoy Fl R
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA276286, CA376076, CA476128
- LNM/D. 05-JUN-2020
46°22'24.0"N 064°34'08.0"W
(G2020038) LL(1114.2) DFO(6309129-01)
- 07-AUG-2020**
- LNM/D. 05-JUN-2020



Chart no. 4023

Add red starboard hand lighted conical buoy Fl R 46°22'28.4"N 064°34'00.9"W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: (G2020038) LL(1113.04) DFO(6309129-02)
CA276286, CA376076, CA476128

05-JUN-2020 LNM/D. 29-MAY-2020
Amend Fl(3) 20s 42ft 9M to read Fl(2) 18s42ft9M against 45°45'58.0"N 062°40'45.0"W
light
(See Chart No. 1, P16) (G2020015) LL(918) DFO(6308962-01)
This notice affects Electronic Navigational Chart:
CA276286, CA376691, CA576464

29-MAY-2020 LNM/D. 07-FEB-2020
Replace red starboard hand lighted pillar whistle buoy Q R, 46°02'37.6"N 063°06'49.2"W
with red starboard hand lighted spar buoy Q R,
marked C2 (G2020029) LL(984) DFO(6308984-01)
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart:
CA276286, CA376161, CA476179

07-FEB-2020 LNM/D. 08-NOV-2019
Amend QG to read Fl G against light 46°24'22.4"N 064°08'06.4"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2019146) LL(1025.5) DFO(6308912-01)
CA276286, CA376076

08-NOV-2019 LNM/D. 13-SEP-2019
Replace depth of 1 fathom, 5 feet with depth of 1 fathom, 4 feet 46°10'22.8"N 063°54'18.7"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 DFO(6308734-04)

08-NOV-2019 LNM/D. 13-SEP-2019
Delete sounding of 1 fathom, 1 foot 46°06'15.4"N 063°43'42.3"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286, DFO(6308734-17)
CA376076

08-NOV-2019 LNM/D. 13-SEP-2019



Chart no. 4023

Add depth of 0 fathoms, 5 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286,
CA376076

46°06'05.9"N 063°43'55.0"W
DFO(6308734-18)

08-NOV-2019

Add depth of 1 fathom, 2 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286,
CA376076

LNM/D. 13-SEP-2019
46°03'38.5"N 063°51'23.5"W
DFO(6308734-20)

08-NOV-2019

Delete depth of 2 fathoms, 3 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286,
CA376076

LNM/D. 13-SEP-2019
46°03'21.8"N 063°51'13.6"W
DFO(6308734-21)

08-NOV-2019

Replace depth of 1 fathom, 1 foot with depth of 0 fathoms, 4 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286,
CA376076

LNM/D. 13-SEP-2019
46°05'08.7"N 063°46'34.7"W
DFO(6308734-26)

13-SEP-2019

Delete depth of 5 fathoms, 3 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286

LNM/D. 06-SEP-2019
46°10'46.8"N 062°22'46.3"W
DFO(6308745-04)

13-SEP-2019

Add depth of 4 fathoms, 1 foot
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286,
CA376248, CA476490

LNM/D. 06-SEP-2019
46°10'43.8"N 062°22'36.6"W
DFO(6308745-05)

13-SEP-2019

Replace depth of 2 fathoms, 1 foot with depth of 0 fathoms, 5 feet
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286

LNM/D. 06-SEP-2019
45°58'23.4"N 062°51'46.2"W
DFO(6308774-02)



Chart no. 4023

- 13-SEP-2019** LNM/D. 06-SEP-2019
Replace depth of 1 fathom with depth of 0 fathoms, 5 feet 46°02'42.6"N 062°28'08.4"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 *DFO(6308791-10)*
- 13-SEP-2019** LNM/D. 06-SEP-2019
Add depth of 1 fathom 46°10'01.2"N 062°29'00.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286, *DFO(6308791-19)*
CA476490
- 13-SEP-2019** LNM/D. 06-SEP-2019
Delete depth of 2 fathoms, 5 feet 46°06'00.6"N 062°26'07.4"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 *DFO(6308791-20)*
- 13-SEP-2019** LNM/D. 06-SEP-2019
Replace depth of 1 fathom, 1 foot with depth of 0 fathoms, 5 feet 46°05'46.2"N 062°26'21.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 *DFO(6308791-21)*
- 13-SEP-2019** LNM/D. 06-SEP-2019
Delete depth of 2 fathoms, 2 feet 46°10'08.6"N 062°28'46.0"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286 *DFO(6308791-22)*
- 06-SEP-2019** LNM/D. 28-JUN-2019
Add red and white fairway lighted spar buoy Mo(A), 47°09'19.9"N 064°58'15.1"W
marked ME
(See Chart No. 1, Qh) *(G2019089) LL(1173.91) DFO(6308738-01)*
This notice affects Electronic Navigational Chart:
CA276286, CA476133
- 28-JUN-2019** LNM/D. 21-JUN-2019
Reposition red and white fairway lighted pillar buoy from 46°33'21.0"N 064°07'28.0"W
Mo(A) to 46°33'23.1"N 064°06'38.5"W
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart: CA276286, CA376076 *(G2019039) LL(1027.45) DFO(6308666-01)*



Chart no. 4023

21-JUN-2019

Delete depth of 0 fathoms 4 feet
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA276286,
CA376161

LNМ/D. 10-MAY-2019

46°13'03.6"N 063°07'24.1"W

DFO(6308641-03)

21-JUN-2019

Add depth of 0 fathoms 1 foot
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA276286,
CA376161, CA476179, CA576177

LNМ/D. 10-MAY-2019

46°13'15.6"N 063°07'28.2"W

DFO(6308641-06)

10-MAY-2019

Amend Fl 4s 82ft 17M to read Fl 4s82ft19M 46°08'37.5"N 062°27'57.5"W
(See Chart No. 1, P16)

LNМ/D. 08-FEB-2019

LL(953) DFO(6308636-01)

10-MAY-2019

Replace red and white fairway lighted pillar buoy Mo(A) with red and
white fairway lighted spar buoy Mo(A)
(See Chart No. 1, Qh)

LNМ/D. 08-FEB-2019

46°02'08.8"N 062°27'16.8"W

LL(961) DFO(6308636-02)

08-FEB-2019

Amend Iso R to read Fl R against light
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA276286, CA376076

LNМ/D. 11-JAN-2019

46°10'12.5"N 063°56'01.0"W

(G2019001) LL(1097) DFO(6308551-01)

11-JAN-2019

Delete light FRWG
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA276286, CA376161

LNМ/D. 16-NOV-2018

45°47'40.5"N 063°02'47.3"W

(G2018146) LL(920) DFO(6308524-01)

16-NOV-2018

Delete legend BELL against red and white
fairway lighted pillar bell buoy
Mo(A), (See Chart No. 1, R21)

This notice affects Electronic
Navigational Chart: CA276286

LNМ/D. 17-AUG-2018

46°19'50.6"N 063°51'18.6"W

(G2018104 & G2018124) LL(1018.3) DFO(6308440-01)



Chart no. 4023

17-AUG-2018

LNМ/D. 11-MAY-2018

Delete red and white fairway lighted pillar bell buoy Mo(A)
(See Chart No. 1, Qh)

46°16'57.5"N 064°30'02.7"W

This notice affects Electronic Navigational Chart: (G2018067) LL(1105) DFO(6308310-01)
CA276286, CA376076, CA476128

17-AUG-2018

LNМ/D. 11-MAY-2018

Add red and white fairway lighted pillar bell buoy Mo(A)
(See Chart No. 1, Qh)

46°16'38.0"N 064°29'05.0"W

This notice affects Electronic Navigational Chart: (G2018067) LL(1105) DFO(6308310-02)
CA276286, CA376076, CA476128

11-MAY-2018

LNМ/D. 23-MAR-2018

Delete pilot boarding station
(See Chart No. 1, T1.1)

46°31'30.0"N 064°32'00.0"W

This notice affects Electronic Navigational Chart: CA276286, DFO(6308253-01)
CA376076

11-MAY-2018

LNМ/D. 23-MAR-2018

Delete pilot boarding station
(See Chart No. 1, T1.1)

46°17'10.0"N 064°25'10.0"W

This notice affects Electronic Navigational Chart: CA276286, DFO(6308253-02)
CA376076

23-MAR-2018

LNМ/D. 16-FEB-2018

Add depth of 1 fathom, 3 feet
(See Chart No. 1, I10)

45°47'47.3"N 062°38'19.7"W

This notice affects Electronic Navigational Chart: CA276286, DFO(6308162-01)
CA376691, CA576464

23-MAR-2018

LNМ/D. 16-FEB-2018

Add depth of 1 fathom, 2 feet
(See Chart No. 1, I10)

45°46'12.2"N 062°42'29.9"W

This notice affects Electronic Navigational Chart: CA276286, DFO(6308162-06)
CA376691, CA576464

23-MAR-2018

LNМ/D. 16-FEB-2018



Chart no. 4023

Replace depth of 4 fathoms, 3 feet with depth of 3 fathoms, 5 feet 45°47'30.1"N 062°42'40.8"W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286, DFO(6308162-19)
CA376691

23-MAR-2018

Replace depth of 1 fathom, 5 feet with depth of 1 fathom LNM/D. 16-FEB-2018
(See Chart No. 1, I10) 45°46'09.7"N 062°41'24.6"W
This notice affects Electronic Navigational Chart: CA276286 DFO(6308162-21)

23-MAR-2018

Replace depth of 1 fathom, 3 feet with depth of 0 fathoms, 4 feet LNM/D. 16-FEB-2018
(See Chart No. 1, I10) 45°44'25.5"N 062°44'17.8"W
This notice affects Electronic Navigational Chart: CA276286 DFO(6308162-22)

23-MAR-2018

Replace depth of 3 fathoms, 5 feet with depth of 0 fathoms, 5 feet LNM/D. 16-FEB-2018
(See Chart No. 1, I10) 45°44'23.6"N 062°42'41.5"W
This notice affects Electronic Navigational Chart: CA276286 DFO(6308162-24)

23-MAR-2018

Add depth of 3 fathoms, 4 feet LNM/D. 16-FEB-2018
(See Chart No. 1, I10) 45°44'56.0"N 062°34'25.1"W
This notice affects Electronic Navigational Chart: CA276286, DFO(6308162-48)
CA376691

16-FEB-2018

Delete light 2 Lts F Y LNM/D. 11-AUG-2017
(See Chart No. 1, P20.3, Pe) 46°34'51.9"N 064°43'21.1"W
(G2018001, G2018002) LL(1127.5, 1127.6) DFO(6308199-03)

11-AUG-2017

Replace depth of 0 fathoms, 4 feet with depth of 0 fathoms, 3 feet LNM/D. 28-JUL-2017
(See Chart No. 1, I10) 45°41'09.6"N 062°36'52.3"W
This notice affects Electronic Navigational Chart: CA276286, DFO(6308023-02)
CA376691

28-JUL-2017

LNM/D. 30-JUN-2017



Chart no. 4023

Add yellow ODAS/SADO lighted pillar Fl (5) Y, marked AZMP-ESG 46°48'00.0"N 062°00'00.0"W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA179245, DFO(6308012-03)
CA276286

30-JUN-2017 LNM/D. 16-JUN-2017
Delete light "Fl 3s125ft10M" 45°41'29.8"N 061°29'18.1"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (G2017015) LL(883) DFO(6307918-01)
CA276286, CA376242, CA476678

16-JUN-2017 LNM/D. 28-APR-2017
Add light Fl G 46°52'47.2"N 064°14'01.4"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (G2017014) LL(1033.5) DFO(6307935-03)
CA276286, CA376062

28-APR-2017 LNM/D. 03-FEB-2017
Delete submarine cable area joining 46°08'00.0"N 063°47'12.0"W
(See Chart No. 1, L30.2) 46°08'05.0"N 063°46'10.0"W
This notice affects Electronic Navigational Chart: 46°09'10.0"N 063°43'35.0"W
CA276286 46°12'20.0"N 063°40'40.0"W
46°13'10.0"N 063°40'00.0"W
46°14'15.0"N 063°39'35.0"W
46°14'26.0"N 063°39'50.0"W
and 46°08'00.0"N 063°47'12.0"W
DFO(6307888-03)

28-APR-2017 LNM/D. 03-FEB-2017
Add submarine cable area between 46°08'05.0"N 063°47'25.0"W
(See Chart No. 1, L30.2) and 46°14'45.0"N 063°42'00.0"W
This notice affects Electronic Navigational Chart: DFO(6307888-04)
CA276286

28-APR-2017 LNM/D. 03-FEB-2017
Add submarine cable area between 46°06'10.0"N 063°46'15.0"W
(See Chart No. 1, L30.2) and 46°12'50.0"N 063°37'12.0"W
This notice affects Electronic Navigational Chart: DFO(6307888-05)
CA276286



Chart no. 4023

28-APR-2017

LNМ/D. 03-FEB-2017

Delete front range/leading light 2 Lts F R
(See Chart No. 1, P20.3)

46°52'46.8"N 064°13'57.4"W

This notice affects Electronic Navigational Chart: (G2017010) LL(1033) DFO(6307899-01)
CA276286, CA376062

03-FEB-2017

LNМ/D. 06-JAN-2017

Amend FIG + FIR to read LFl 6s55ft15M against light
(See Chart No. 1, P16)

45°42'19.2"N 062°16'14.5"W

This notice affects Electronic Navigational Chart: CA276286, LL(895) DFO(6307785-01)
CA576695

06-JAN-2017

LNМ/D. 21-OCT-2016

Delete light FIR
(See Chart No. 1, P1)

45°49'20.7"N 062°30'34.2"W

This notice affects Electronic Navigational Chart: (G2016135) LL(900) DFO(6307741-01)
CA276286, CA376691

21-OCT-2016

LNМ/D. 17-JUN-2016

Amend F 13M to read Fl 4s9M against light
(See Chart No. 1, P16)

45°38'50.0"N 061°37'28.0"W

This notice affects Electronic Navigational Chart: (G2016125) LL(887) DFO(6307706-01)
CA276286, CA376242

17-JUN-2016

LNМ/D. 10-JUN-2016

Amend FIG to read 2Lts FIR & FIG against
light

47°01'45.7"N 063°59'19.8"W

(See Chart No. 1, P16) (G2016033) LL(1036.1 & 1084.7) DFO(6307508-01)
This notice affects Electronic
Navigational Chart: CA276286

10-JUN-2016

LNМ/D. 27-MAY-2016

Add light FIG
(See Chart No. 1, P1)

46°34'56.7"N 064°43'10.2"W

This notice affects Electronic Navigational Chart: (G2016028) LL(1127.2) DFO(6307503-01)
CA276286, CA376076

27-MAY-2016

LNМ/D. 26-FEB-2016



Chart no. 4023

Add depth of 4 fathoms (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276286	47°19'47.4"N 061°49'43.3"W <i>DFO(6307529-01)</i>
27-MAY-2016 Delete depth of 5 fathoms, 4 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276286	LN/D. 26-FEB-2016 47°06'49.4"N 063°57'50.2"W <i>DFO(6307529-02)</i>
27-MAY-2016 Add depth of 5 fathoms (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276286	LN/D. 26-FEB-2016 47°07'01.1"N 063°57'25.9"W <i>DFO(6307529-03)</i>
27-MAY-2016 Delete depth of 3 fathoms, 5 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276286	LN/D. 26-FEB-2016 47°15'14.8"N 062°11'06.3"W <i>DFO(6307529-04)</i>
27-MAY-2016 Add depth of 3 fathoms, 4 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276286	LN/D. 26-FEB-2016 47°15'21.1"N 062°11'18.4"W <i>DFO(6307529-05)</i>
27-MAY-2016 Delete depth of 2 fathoms, 4 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276286	LN/D. 26-FEB-2016 47°15'12.5"N 061°43'18.9"W <i>DFO(6307529-06)</i>
27-MAY-2016 Add depth of 1 fathom, 5 feet (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276286	LN/D. 26-FEB-2016 47°15'16.7"N 061°43'08.5"W <i>DFO(6307529-07)</i>
27-MAY-2016 Add depth of 15 fathoms (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA276286	LN/D. 26-FEB-2016 47°18'22.9"N 061°27'09.6"W <i>DFO(6307529-08)</i>



Chart no. 4023

27-MAY-2016

LN/D. 26-FEB-2016

Replace depth of 11 fathoms with depth of 10 fathoms
(See Chart No. 1, I10)

47°05'03.3"N 061°47'49.4"W

This notice affects Electronic Navigational Chart: CA276286

DFO(6307529-09)

26-FEB-2016

LN/D. 27-NOV-2015

Amend 2 Lts FIY to read 2 Lts OcY against light
(See Chart No. 1, P16)

46°32'56.8"N 061°02'32.8"W

This notice affects Electronic Navigational Chart: (G2016002) LL(870.0) *DFO(6307443-02)*
CA276286

27-NOV-2015

LN/D. 19-JUN-2015

Amend 2 Lts FY to read 2 Lts Fl Y against light
(See Chart No. 1, P1)

46°32'58.0"N 061°02'33.5"W

This notice affects Electronic Navigational Chart: CA276286

LL(869) DFO(6307312-01)

19-JUN-2015

LN/D. 07-NOV-2014

Amend FlG to read QG against light
(See Chart No. 1, P16)

46°24'20.5"N 064°08'05.9"W

This notice affects Electronic Navigational Chart: (G2015038) LL(1025.5) *DFO(6307141-01)*
CA276286, CA376076

07-NOV-2014

LN/D. 31-OCT-2014

Add black, yellow and black East cardinal lighted spar
buoy VQ(3) 5s
(See Chart No. 1, Q130.3)

46°27'23.2"N 064°35'41.5"W

This notice affects Electronic Navigational Chart:
CA276286, CA376076, CA476127

(G2014151) LL(1119.2) DFO(6306917-02)

31-OCT-2014

LN/D. 17-OCT-2014

Delete red starboard hand lighted pillar buoy FIR
(See Chart No. 1, Qf)

46°27'03.0"N 064°35'45.0"W

This notice affects Electronic Navigational
Chart: CA276286, CA376076, CA476127

(G2014076) LL(1119.55) DFO(6306899-01)

17-OCT-2014

LN/D. 18-APR-2014



Chart no. 4023

Delete green port hand lighted pillar bell buoy BELL, 46°31'36.0"N 064°32'54.0"W
FIG
(See Chart No. 1, Qg) (G2014075) LL(1125.5) DFO(6306898-01)
This notice affects Electronic Navigational Chart:
CA276286, CA376076

18-APR-2014 LNM/D. 07-FEB-2014
Amend sector light Fl(2)RWG to read FRWG against 46°57'51.4"N 064°49'54.9"W
light
(See Chart No 1 P40.1) (G2014023) LL(1159.6) DFO(6306706-01)
This notice affects Electronic Navigational Chart:
CA276286, CA376062

07-FEB-2014 LNM/D. 03-JAN-2014
Amend Fl 3s 125ft 15M to read Fl 3s 125ft 10M against 46°41'35.3"N 061°29'13.6"W
light
(See Chart No. 1, P1) (G2013008) LL(883) DFO(6306657-01)
This notice affects Electronic Navigational Chart:
CA276286, CA376242

03-JAN-2014 LNM/D. 25-OCT-2013
Delete rear range/leading light 2 Lts FY 46°57'47.8"N 064°49'41.1"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2013163) LL(1161) DFO(6306556-02)
CA276286, CA376062

03-JAN-2014 LNM/D. 25-OCT-2013
Add sector light Fl(2)RWG 46°57'47.2"N 064°49'49.9"W
(See Chart No. 1, P30.3)
This notice affects Electronic Navigational Chart: (G2013164) LL(1159.6) DFO(6306556-03)
CA276286, CA376062

25-OCT-2013 LNM/D. 30-AUG-2013
Add light FIG 46°57'39.5"N 064°49'51.6"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (G2013122) LL(1162.3) DFO(6306492-01)
CA276286, CA376062

25-OCT-2013 LNM/D. 30-AUG-2013



Chart no. 4023

Amend 2 Lts FlR to read 2 Lts Fl & FlR against light 46°57'37.9"N 064°49'47.3"W
(See Chart No 1 P16)
This notice affects Electronic Navigational Chart: (G2013141) LL(1159.5) DFO(6306498-01)
CA276286, CA376062

30-AUG-2013 LNM/D. 26-JUL-2013
Amend Fl(3)20s68ft18M to read Fl 72ft13M against light 47°04'17.5"N 064°47'48.5"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (G2013098) LL(1163.0) DFO(6306470-01)
CA179171, CA276286, CA376062, CA476133

26-JUL-2013 LNM/D. 29-MAR-2013
Add black, yellow and black East cardinal lighted spar 46°00'44.2"N 062°26'17.1"W
buoy Q(3) 10s, marked NN
(See Chart No. 1, Q130.3) (G2013085) LL(970.4) DFO(6306435-02)
This notice affects Electronic Navigational Chart:
CA276286

29-MAR-2013 LNM/D. 22-FEB-2013
Amend WHIS to read BELL against black and yellow North 47°05'00.0"N 064°00'03.0"W
cardinal pillar light buoy Q
(See Chart No 1 Qc) (G2012201) LL(1037) DFO(6306248-01)
This notice affects Electronic Navigational Chart:
CA276286, CA376062

22-FEB-2013 LNM/D. 11-JAN-2013
Add abandoned lighthouse with legend Lt Ho/Phare 45°57'40.3"N 063°51'58.7"W
Aband
This notice affects Electronic Navigational Chart: (G2012208) LL(941.0) DFO(6306323-01)
CA276286

22-FEB-2013 LNM/D. 11-JAN-2013
Amend Chart/Carte 4335 to read Chart/carte 4302 45°40'30.0"N 061°19'30.0"W
(See Chart No. 1, A18)
DFO(6306324-02)

11-JAN-2013 LNM/D. 21-DEC-2012



Chart no. 4023

Delete light Fl 5s 60ft 15M 45°57'41.0"N 063°51'58.0"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (G2012208) LL(941) DFO(6306275-01)
CA276286

21-DEC-2012

Delete light Iso R6s 56ft 15M LNM/D. 19-OCT-2012
45°52'15.8"N 063°40'43.0"W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: (G2012209) LL(926) DFO(6306276-01)
CA276286

21-DEC-2012

Add Abandoned lighthouse with legend Lt Ho/Phare Aband LNM/D. 19-OCT-2012
(See Chart No. 1, B22) 45°52'15.8"N 063°40'43.0"W
This notice affects Electronic Navigational Chart: (G2012209) LL(926) DFO(6306276-13)
CA276286

19-OCT-2012

Delete red and white fairway lighted pillar bell buoy LNM/D. 14-SEP-2012
Mo(A), BELL 45°57'30.2"N 063°38'13.7"W
(See Chart No. 1, Qh) (G2012176) LL(925.12) DFO(6306175-01)

This notice affects Electronic Navigational Chart:
CA276286

14-SEP-2012

Delete light 2 Lts Iso R LNM/D. 20-JUL-2012
(See Chart No. 1, P20.2) 46°24'29.5"N 063°02'22.8"W
(G2012166) LL(1048) DFO(6306160-01)

This notice affects Electronic Navigational Chart:
CA276286

20-JUL-2012

Amend F RWG to read FlG against light LNM/D. 23-MAR-2012
(See Chart No. 1, P1) 46°26'25.9"N 064°06'48.4"W
(G2012108) LL(1027.3) DFO(6306066-01)

This notice affects Electronic Navigational Chart:
CA276286, CA376076



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4023

23-MAR-2012

LNM/D. 02-MAR-2012

Delete red and white fairway lighted pillar buoy Mo(A)
(See Chart No. 1, Qh)

46°11'17.0"N 064°03'23.0"W

(G2012015) LL(1097.8) DFO(6305950-01)

This notice affects Electronic Navigational Chart:
CA276286, CA376076

02-MAR-2012

LNM/D. 10-FEB-2012

Amend FLY 5s 42ft 13M to read Fl 5s 41ft 11M against
light
(See Chart No. 1, P1)

46°14'04.3"N 064°15'49.6"W

(G2012011) LL(1101) DFO(6305930-01)

This notice affects Electronic Navigational Chart:
CA276286, CA376076

10-FEB-2012

LNM/D. 30-DEC-2011

Delete legend Fog Sig against light
(See Chart No. 1, R1, R20)

46°38'58.4"N 061°01'35.2"W

(G2012002) LL(867) DFO(6305909-01)

10-FEB-2012

LNM/D. 30-DEC-2011

Delete rear range/leading light 2 Lts F R
(See Chart No. 1, P20.2)

46°26'23.0"N 064°06'30.0"W

(G2012004) LL(1027.2) DFO(6305911-01)

30-DEC-2011

LNM/D. 09-DEC-2011

Replace light Fl (3) 20s 102ft 22M by abandoned
lighthouse, Lt Ho/Phare Aband. Delete limits of
arcs of visibility.
(See Chart No. 1, P1, P40.1)

47°12'44.8"N 061°58'18.9"W

(Q2011128) LL(1500) DFO(6408458-02)

This notice affects Electronic Navigational Chart:
CA379216

30-DEC-2011

LNM/D. 09-DEC-2011



Chart no. 4023

Replace light Fl 2½s 101ft 20M by abandoned lighthouse,
Lt Ho/Phare Aband
(See Chart No. 1, P1)

47°16'03.5"N 061°42'18.1"W

(Q2011129) LL(1509) DFO(6408459-02)

This notice affects Electronic Navigational Chart:
CA379216, CA479226

09-DEC-2011

LNM/D. 07-OCT-2011

Amend LFl Y 6s 74ft 10M to read LFl Y 6s 55ft 10M against
light
(See Chart No. 1, P16)

46°00'11.1"N 062°27'34.0"W

(G2011309) LL(971) DFO(6305838-03)

This notice affects Electronic Navigational Chart:
CA276286, CA376248

07-OCT-2011

LNM/D. 08-JUL-2011

Delete light Iso
(See Chart No. 1, P1)

46°34'40.8"N 063°43'12.5"W

(G2011250) LL(1067) DFO(6305720-03)

This notice affects Electronic Navigational Chart:
CA276286

08-JUL-2011

LNM/D. 01-JUL-2011

Amend LFl Y 6s 74ft 13M to read LFl Y 6s 74ft 10M against
light
(See Chart 1 P16)

46°00'10.7"N 062°27'36.4"W

(G2011165) LL(971) DFO(6305550-01)

This notice affects Electronic Navigational Chart:
CA376248

01-JUL-2011

LNM/D. 18-MAR-2011

Reposition red starboard hand lighted pillar buoy F1R
(See Chart No. 1, Qf)

from 46°22'24.5"N 064°34'10.0"W
to 46°22'22.9"N 064°34'08.6"W

(G2011163) LL(1114.2) DFO(6305538-01)

18-MAR-2011

LNM/D. 11-MAR-2011



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4023

Delete depth of 0 fathoms, 5 feet 46°07'08.0"N 062°54'09.0"W
(See Chart No. 1, I10)

DFO(6305295-12)

18-MAR-2011

LNM/D. 11-MAR-2011

Add depth of 0 fathoms, 4 feet 46°07'10.5"N 062°54'24.9"W
(See Chart No. 1, I10)

DFO(6305295-13)

11-MAR-2011

LNM/D. 03-DEC-2010

Amend 2 Lts QG & Iso G to read 2 Lts Iso G against light
(See Chart No. 1 P16)

46°28'06.9"N 062°04'05.1"W

(G2011012) LL(1039) DFO(6305230-01)

This notice affects Electronic Navigational Chart:
CA276286

03-DEC-2010

LNM/D. 23-JUL-2010

Amend Fl to read LFl against light
(See Chart No 1 P10.5)

45°39'27.5"N 061°44'50.6"W

(G2010169) LL(888) DFO(6305103-03)

This notice affects Electronic Navigational Chart:
CA276286

23-JUL-2010

LNM/D. 09-JUL-2010

Amend Fl Y 6s 74ft to read LFl Y 6s 74ft 13M against light
(See Chart 1 P16)

46°00'10.7"N 062°27'36.4"W

LL(971) DFO(6304957-01)

This notice affects Electronic Navigational Chart: CA376248

09-JUL-2010

LNM/D. 02-JUL-2010

Reposition red and white fairway lighted spar buoy
Mo(A)
(See Chart 1 Qh)

from 46°39'12.1"N 063°50'28.0"W
to 46°39'08.2"N 063°50'51.3"W

(G2010090) LL(1071.35) DFO(6304908-01)

02-JUL-2010

LNM/D. 11-JUN-2010



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4023

Amend Fl 4s 39ft 5M to read Fl 4s 39ft 10M against light
(See Chart 1 P16)

45°50'05.4"N 063°10'39.7"W

(G2010091) LL(921) DFO(6304909-01)

11-JUN-2010

LNМ/D. 28-MAY-2010

Reposition red and white fairway lighted spar buoy
Mo(A)
(See Chart 1 Qh)

from 46°39'48.2"N 063°51'09.7"W
to 46°39'12.1"N 063°50'28.0"W

(G2010025) LL(1071.35) DFO(6304841-01)

28-MAY-2010

LNМ/D. 21-MAY-2010

Amend LFl to read LFl R against light
(See Chart No 1 P16)

45°51'30.0"N 061°30'05.0"W

(G2010024) LL(882) DFO(6304814-01)

21-MAY-2010

LNМ/D. 30-APR-2010

Amend Iso 10s 48ft 11M to read Iso 10s 46ft 8M against
light
(See Chart No 1 P16)

46°22'39.0"N 063°49'01.1"W

(G2009134) LL(1020) DFO(6304727-01)

30-APR-2010

LNМ/D. 24-APR-2009

Amend FR to read LFl against light
(See Chart 1 P16)

45°51'30.0"N 061°30'05.0"W

(G2010024) LL(882) DFO(6304777-01)

24-APR-2009

LNМ/D. 06-MAR-2009

Amend FG to read F 13M against light
(See Chart No 1 P16)

45°38'49.0"N 061°37'28.0"W

(G2009002) LL(887) DFO(6304303-01)

This notice affects Electronic Navigational Chart:
CA376242

06-MAR-2009

LNМ/D. 28-MAR-2008

Amend Iso R to read 2Lts Iso R QG against light
(See Chart No 1 P1)

46°44'22.0"N 064°22'42.0"W

(G2008102) LL(1031.5) DFO(6304259-02)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4023

06-MAR-2009

LN/D. 28-MAR-2008

Amend Fl to read LFl 6s 14m 12M against light 46°44'23.0"N 064°22'33.0"W
(See Chart No 1 P16)

LL(1032) DFO(6304278-01)

28-MAR-2008

LN/D. 14-MAR-2008

Replace red starboard hand lighted pillar bell buoy FIR,
with red and white fairway lighted spar buoy
Mo(A)
(See Chart No 1 Qf and Qh)

46°54'03.0"N 064°14'20.0"W

(G2007057) LL(1032.05) DFO(6303466-01)

This notice affects Electronic Navigational
Chart: CA376062

14-MAR-2008

LN/D. 22-FEB-2008

Replace green port hand lighted pillar bell buoy FlG with
red and white fairway lighted spar buoy Mo(A)
(See Chart No 1 Qg and Qh)

46°26'03.2"N 063°02'01.6"W

(G2007053) LL(1047.5) DFO(6303462-01)

14-MAR-2008

LN/D. 22-FEB-2008

Replace green port hand lighted pillar bell buoy FlG with
red and white fairway lighted spar buoy Mo(A)
(See Chart No 1 Qg and Qh)

46°26'54.2"N 063°08'18.7"W

(G2007055) LL(1050) DFO(6303464-01)

14-MAR-2008

LN/D. 22-FEB-2008

Replace red starboard hand lighted pillar bell buoy FIR
with red and white fairway lighted spar buoy
Mo(A)
(See Chart No 1 Qf and Qh)

46°26'46.2"N 062°49'55.0"W

(G2007063) LL(1046.8) DFO(6303472-01)

14-MAR-2008

LN/D. 22-FEB-2008

Add red and white fairway lighted spar buoy Mo(A)
(See Chart No 1 Qh)

46°27'09.2"N 062°44'21.6"W

(G2007073) LL(1043.1) DFO(6303516-02)

22-FEB-2008

LN/D. 08-FEB-2008



Chart no. 4023

Delete red starboard hand lighted pillar bell buoy FIR 46°35'00.0"N 063°37'00.0"W
(See Chart No 1 Qf)

(G2007059) LL(1065) DFO(6303468-01)

22-FEB-2008

LNМ/D. 08-FEB-2008

Add red and white fairway lighted spar buoy Mo(A)
(See Chart No 1 Qh)

46°35'00.2"N 063°37'07.7"W

(G2007060) LL(1065.05) DFO(6303468-02)

22-FEB-2008

LNМ/D. 08-FEB-2008

Replace red starboard hand lighted pillar bell buoy FIR
with red and white fairway lighted spar buoy
Mo(A)
(See Chart No 1 Qf and Qh)

46°47'44.3"N 063°59'38.2"W

(G2007061) LL(1075) DFO(6303470-01)

22-FEB-2008

LNМ/D. 08-FEB-2008

Replace green port hand lighted pillar bell buoy FlG
with red and white fairway lighted spar buoy
Mo(A)
(See Chart No 1 Qg and Qh)

46°39'48.2"N 063°51'09.7"W

(G2007065) LL(1071.35) DFO(6303474-01)

08-FEB-2008

LNМ/D. 28-DEC-2007

Replace green port hand lighted pillar bell buoy FlG with
red and white fairway lighted spar buoy Mo(A)
(See Chart No 1 Qg and Qh)

46°28'56.2"N 062°03'27.6"W

(G2007046) LL(1038) DFO(6303457-01)

08-FEB-2008

LNМ/D. 28-DEC-2007

Replace red starboard hand lighted pillar bell buoy FIR
with red and white fairway lighted spar buoy
Mo(A)
(See Chart No 1 Qf and Qh)

46°29'00.2"N 062°24'40.6"W

(G2007048) LL(1040) DFO(6303459-01)

28-DEC-2007

LNМ/D. 10-AUG-2007

Delete light Fl
(See Chart No 1 P16)

46°26'30.0"N 062°45'00.0"W

(G2007172) LL(1044) DFO(6303735-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4023

10-AUG-2007

Replace red starboard hand lighted pillar bell buoy F1R,
BELL with red and white fairway lighted pillar
buoy Mo(A)

LNM/D. 29-JUN-2007

46°05'29.1"N 061°29'28.0"W

(G2007051) LL(874.5) DFO(6303498-01)

This notice affects Electronic Navigational Chart:
CA276271, CA376242

29-JUN-2007

Delete green port hand lighted pillar bell buoy F1G

LNM/D. 25-MAY-2007

46°28'05.2"N 062°44'12.6"W

(G2007050) LL(1043) DFO(6303461-01)

25-MAY-2007

Delete note Chart/Carte 4951 47°17'40.0"N 061°48'00.0"W

LNM/D. 27-OCT-2006

DFO(6303373-01)

25-MAY-2007

Amend "Fl(3) 20s 102ft 20M" to read "Fl(3) 20s 102ft 22M" against
light

LNM/D. 27-OCT-2006

47°12'44.8"N 061°58'18.9"W

LL(1500) DFO(6303403-01)

25-MAY-2007

Amend "Fl 2½s 101ft 19M" to read "Fl 2½s 101ft 20M" against light 47°16'03.5"N 061°42'18.1"W

LNM/D. 27-OCT-2006

LL(1509) DFO(6303403-02)

25-MAY-2007

Delete rock 47°15'45.0"N 062°12'00.0"W

LNM/D. 27-OCT-2006

DFO(6303406-01)

25-MAY-2007

Delete depth of 10 fathoms 47°11'45.0"N 061°46'30.0"W

LNM/D. 27-OCT-2006

DFO(6303407-12)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4023

25-MAY-2007

LNМ/D. 27-OCT-2006

Add depth of 6 fathoms, 4 feet 47°11'02.3"N 061°46'17.7"W

DFO(6303407-13)

25-MAY-2007

LNМ/D. 27-OCT-2006

Delete depth of 14 fathoms 47°11'15.0"N 061°45'30.0"W

DFO(6303407-14)

27-OCT-2006

LNМ/D. 14-JUL-2006

Delete light FRWG 46°50'52.0"N 064°54'34.0"W

(G2006099) LL(1158) DFO(6302994-01)

14-JUL-2006

LNМ/D. 30-JUN-2006

Add ferry route joining 46°20'49.8"N 062°15'25.2"W
46°19'48.0"N 062°15'10.0"W
46°19'00.0"N 062°11'24.0"W
46°20'03.0"N 062°06'42.0"W
46°25'54.0"N 061°55'48.0"W
47°16'45.3"N 061°39'00.0"W
47°18'14.8"N 061°40'00.0"W
and 47°20'01.0"N 061°45'15.0"W

DFO(6302873-04)

30-JUN-2006

LNМ/D. 09-DEC-2005

Add depth of 10 fathoms

45°42'31.3"N 061°46'33.0"W

DFO(6302880-03)

This notice affects Electronic Navigational Chart: CA376242

09-DEC-2005

LNМ/D. 25-NOV-2005



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4023

Add submarine cable

joining 46°05'48.3"N 062°27'07.5"W
46°06'03.7"N 062°26'23.7"W
46°06'14.2"N 062°23'41.3"W
46°06'13.3"N 062°21'08.3"W
46°07'25.8"N 061°56'53.7"W
46°01'24.4"N 061°32'54.0"W
and 46°01'34.5"N 061°32'25.8"W

This notice affects Electronic Navigational Chart:
CA376248

DFO(6302323-01)

09-DEC-2005

LNM/D. 25-NOV-2005

Amend Iso R to read " 2Lts Iso R Iso G " against light

46°57'01.8"N 063°59'33.9"W

(G2005171) LL(1083) DFO(6302623-01)

25-NOV-2005

LNM/D. 16-SEP-2005

Delete light FLR

46°39'22.0"N 063°52'36.0"W

(G2005128) LL(1072) DFO(6302572-01)

16-SEP-2005

LNM/D. 19-AUG-2005

Add red and white fairway lighted pillar buoy Mo (A)

46°27'54.0"N 063°16'30.0"W

(G2005090) LL(1054) DFO(6302454-02)

16-SEP-2005

LNM/D. 19-AUG-2005

Delete red and white fairway light and bell pillar buoy
Mo(A), BELL

46°27'49.2"N 063°16'50.0"W

(G2005090) LL(1054) DFO(6302454-03)

16-SEP-2005

LNM/D. 19-AUG-2005

Add red and white fairway lighted pillar buoy Mo (A)

46°31'41.1"N 063°28'18.0"W

(G2005091) LL(1058) DFO(6302455-02)

16-SEP-2005

LNM/D. 19-AUG-2005

Delete red and white fairway pillar light and bell buoy Mo
(A), BELL

46°31'24.0"N 063°28'30.0"W

(G2005091) LL(1058) DFO(6302455-03)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4023

19-AUG-2005

LNM/D. 29-JUL-2005

Amend "FIR" to read "Iso R" against light

46°57'01.9"N 063°59'28.9"W

(G2005056) LL(1083) DFO(6302397-01)

29-JUL-2005

LNM/D. 22-JUL-2005

Delete depth of 13 fathoms 47°14'48.0"N 061°27'45.0"W

DFO(6302300-01)

29-JUL-2005

LNM/D. 22-JUL-2005

Delete depth of 6 fathoms 47°16'50.0"N 062°13'30.0"W

DFO(6302300-03)

29-JUL-2005

LNM/D. 22-JUL-2005

Delete depth of 6 fathoms 4 feet 47°16'33.0"N 062°12'35.0"W

DFO(6302300-04)

29-JUL-2005

LNM/D. 22-JUL-2005

Add depth of 3 fathoms 5 feet 47°16'36.0"N 062°12'50.0"W

DFO(6302300-05)

29-JUL-2005

LNM/D. 22-JUL-2005

Delete depth of 19 fathoms 47°02'55.0"N 061°46'45.0"W

DFO(6302300-06)

29-JUL-2005

LNM/D. 22-JUL-2005

Add depth of 8 fathoms 3 feet 47°03'08.0"N 061°46'15.0"W

DFO(6302300-07)

29-JUL-2005

LNM/D. 22-JUL-2005



Chart no. 4023

Replace depth of 9 fathoms 3 feet with depth of 8 fathoms 47°11'48.0"N 061°39'30.0"W

DFO(6302300-08)

29-JUL-2005 LNM/D. 22-JUL-2005

Delete depth of 12 fathoms 47°04'30.0"N 061°42'20.0"W

DFO(6302300-09)

29-JUL-2005 LNM/D. 22-JUL-2005

Add depth of 9 fathoms 5 feet 47°04'26.0"N 061°41'38.0"W

DFO(6302300-10)

29-JUL-2005 LNM/D. 22-JUL-2005

Delete depth of 9 fathoms 47°11'15.0"N 061°44'00.0"W

DFO(6302300-11)

29-JUL-2005 LNM/D. 22-JUL-2005

Add depth of 7 fathoms 5 feet 47°11'30.0"N 061°43'54.0"W

DFO(6302300-12)

29-JUL-2005 LNM/D. 22-JUL-2005

Delete depth of 8 fathoms 47°14'29.0"N 061°42'36.0"W

DFO(6302300-13)

29-JUL-2005 LNM/D. 22-JUL-2005

Add depth of 3 fathoms 4 feet 47°14'31.0"N 061°42'32.0"W

DFO(6302300-14)

29-JUL-2005 LNM/D. 22-JUL-2005

Delete depth of 15 fathoms 46°33'15.0"N 064°27'00.0"W

DFO(6302300-17)



Chart no. 4023

29-JUL-2005 LNM/D. 22-JUL-2005
Add depth of 10 fathoms 2 feet 46°33'19.0"N 064°27'12.0"W

DFO(6302300-18)

29-JUL-2005 LNM/D. 22-JUL-2005
Delete depth of 16 fathoms 46°12'54.0"N 063°46'15.0"W

DFO(6302300-19)

29-JUL-2005 LNM/D. 22-JUL-2005
Add depth of 14 fathoms 2 feet 46°12'42.0"N 063°46'19.0"W

DFO(6302300-20)

29-JUL-2005 LNM/D. 22-JUL-2005
Delete depth of 14 fathoms 46°08'54.0"N 063°41'15.0"W

DFO(6302300-21)

29-JUL-2005 LNM/D. 22-JUL-2005
Delete depth of 15 fathoms 46°07'45.0"N 063°40'15.0"W

DFO(6302300-22)

29-JUL-2005 LNM/D. 22-JUL-2005
Add depth of 10 fathoms 5 feet 46°08'21.0"N 063°40'54.0"W

DFO(6302300-23)

22-JUL-2005 LNM/D. 08-JUL-2005
Delete red starboard hand lighted pillar buoy Fl R 46°56'36.2"N 063°57'12.6"W

(G2005043) LL(1084.5) DFO(6302358-01)

08-JUL-2005 LNM/D. 17-JUN-2005



Chart no. 4023

Delete green port hand lighted pillar bell buoy Fl G 47°15'04.7"N 061°42'50.4"W
(L2005031) LL(1507) DFO(6406959-01)

08-JUL-2005 LNM/D. 17-JUN-2005
Add green port hand lighted pillar buoy Fl G, marked YM1 47°15'16.5"N 061°42'55.4"W
(L2005031) LL(1507) DFO(6406959-02)

17-JUN-2005 LNM/D. 05-NOV-2004
Delete legend BELL against buoy 47°19'28.6"N 061°34'25.3"W
(L2005022) LL(1512) DFO(6406932-01)

05-NOV-2004 LNM/D. 15-OCT-2004
Add red starboard hand spar light buoy QR 47°05'51.9"N 064°56'30.0"W
(G2004151) LL(1170) DFO(6301930-03)

15-OCT-2004 LNM/D. 03-SEP-2004
Delete light Iso 60ft 7M 46°47'56.5"N 064°02'09.9"W
(G2004150) LL(1076) DFO(6301901-01)

03-SEP-2004 LNM/D. 09-JUL-2004
Amend FR to read FlR against light 46°57'58.0"N 064°07'33.5"W
(G2004080) LL(1035) DFO(6301639-01)

09-JUL-2004 LNM/D. 11-JUN-2004
Add yellow ODAS/SADO light buoy, Fl (5) Y 46°19'54.0"N 064°22'36.0"W
DFO(6301727-01)

11-JUN-2004 LNM/D. 19-MAR-2004
Delete light Fl G 46°24'30.3"N 064°36'56.4"W
(G2004075) LL(1118.5) DFO(6301450-01)



Chart no. 4023

19-MAR-2004

LNM/D. 26-DEC-2003

Delete light and legend 2 Lts FY

46°37'05.4"N 064°22'19.7"W

(G2003162) LL(1028) DFO(6301195-02)

26-DEC-2003

LNM/D. 31-OCT-2003

Delete red and white fairway pillar light buoy Mo (A),
BELL, marked MH

47°10'46.0"N 065°00'26.0"W

(G2003086) LL(1237) DFO(6301037-01)

31-OCT-2003

LNM/D. 24-OCT-2003

Amend Iso to read Iso R against light 46°10'07.2"N 063°56'01.1"W

LL(1097.000) DFO(6301066-01)

31-OCT-2003

LNM/D. 24-OCT-2003

Amend Oc 5s 97ft 18M to read Oc 5s 84ft 12M against light 46°28'07.2"N 062°25'22.6"W

LL(1042) DFO(6301092-01)

24-OCT-2003

LNM/D. 08-AUG-2003

Amend legend Fl(3) 24s 42 ft 12M to read Fl(3) 20s 42ft 9M

45°45'55.0"N 062°40'48.0"W

(G2002189) LL(918) DFO(6300756-01)

08-AUG-2003

LNM/D. 04-APR-2003

Add yellow ODAS/SADO light buoy, Fl Y 5s, marked 44150 46°51'00.0"N 064°38'48.0"W

DFO(6300963-01)

04-APR-2003

LNM/D. 21-MAR-2003

Amend Fl 5s 100ft 20M to read Fl 5s 100ft 11M

46°27'07.0"N 061°58'20.0"W

(G2000014) LL(943) DFO(6828102-01)

21-MAR-2003



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4023

Delete legend Bell against red and white fairway pillar light
buoy Mo (A)

46°02'05.2"N 062°27'08.2"W

(G2002097) LL(961) DFO(6300438-01)