



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4024

4024 - Baie des Chaleurs/Chaleur Bay aux/to Îles de la Madeleine - New Edition - 06-MAR-2015 - NAD 1983

27-SEP-2024

Reposition yellow SADO/ODAS lighted super-buoy
Fl(5)Y, marked IML-14
(See Chart No. 1, Q58)

LNМ/D. 19-JUL-2024

from 48°08'00.0"N 062°42'00.0"W
to 48°12'30.0"N 062°48'33.0"W

(Q2024159) LL(1512.6) DFO(6411152-01)

19-JUL-2024

Replace Fl 2.5s to read LFl 6s against light
(See Chart 1, P10.5 and P12)

LNМ/D. 29-SEP-2023

47°50'15.0"N 065°00'13.0"W

(G2023156) LL(1324) DFO(6411168-01)

29-SEP-2023

Amend LFl 6s22m9M to read Fl 6s22m9M against light
(See Chart 1, P16)

LNМ/D. 05-MAY-2023

47°49'21.1"N 064°54'14.8"W

This notice affects Electronic Navigational Chart:
CA376187

(G2023039) LL(1322) DFO(6310723-01)

29-SEP-2023

Delete green port hand lighted pillar bell buoy Fl G,
marked X31
(See Chart 1, Qc)

LNМ/D. 05-MAY-2023

47°07'09.0"N 064°47'05.6"W

(G2023001) LL(1162) DFO(6410927-01)

29-SEP-2023

Add green port hand lighted spar buoy Fl G, marked X31
(See Chart 1, Qc)

LNМ/D. 05-MAY-2023

47°07'09.0"N 064°47'05.6"W

(G2023001) LL(1162) DFO(6410927-02)

05-MAY-2023

Add yellow SADO/ODAS lighted super-buoy Fl(5) Y,
marked IML-15 (See Chart 1, Q58)

LNМ/D. 23-DEC-2022

48°05'00.0"N 061°55'54.0"W

(Q2022091) LL(1512.4) DFO(6410777-01)

This notice affects Electronic Navigational Chart:
CA279075

23-DEC-2022

LNМ/D. 17-JUN-2022



Chart no. 4024

Delete yellow SADO/ODAS lighted pillar buoy Fl5 Y 20s, 48°04'48.0"N 061°55'55.2"W
marked IML-15
(See Chart 1, Q58) (Q2022048) LL(1411.2) DFO(6410718-01)
This notice affects Electronic Navigational Chart:
CA279075

17-JUN-2022 LNM/D. 11-FEB-2022
Delete light F R 47°33'24.7"N 061°33'43.0"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (Q2021049) LL(1484) DFO(6410639-01)
CA279075, CA379216, CA579084

17-JUN-2022 LNM/D. 11-FEB-2022
Add yellow SADO/ODAS lighted super-buoy Fl(5) Y 20s, 47°25'55.2"N 062°33'18.6"W
marked IML-16 (See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: (Q2022007) LL(1500.3) DFO(6410639-02)
CA279075

11-FEB-2022 LNM/D. 10-DEC-2021
Amend Fl 22m9M to read LFl 6s22m9M against light 47°49'21.2"N 064°54'16.5"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2021259) LL(1322) DFO(6309998-01)
CA279075, CA376187, CA476275

10-DEC-2021 LNM/D. 03-DEC-2021
Add yellow SADO/ODAS lighted super-buoy Fl(5) Y, marked IML-15 48°04'48.0"N 061°55'55.2"W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA279075 DFO(6410646-01)

03-DEC-2021 LNM/D. 26-NOV-2021
Add wreck, least depth unknown, Rep (2021) 48°09'04.2"N 064°09'50.4"W
(See Chart No. 1, K29, I3.2)
This notice affects Electronic Navigational Chart: CA279075, DFO(6309774-01)
CA376187

26-NOV-2021 LNM/D. 19-NOV-2021
Amend Fl Y 5s16m to read LFl 6s13M against light 47°43'19.7"N 064°39'38.2"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2021134) LL(1254) DFO(6309744-01)
CA279075, CA376187, CA476275, CA576269



Chart no. 4024

19-NOV-2021

LNМ/D. 30-JUL-2021

Amend Oc(2) Y 10s to read LFl 6s12M against light
(See Chart No. 1, P16)

47°53'03.8"N 064°37'25.0"W

This notice affects Electronic Navigational Chart: (G2021148) LL(1275) DFO(6309666-01)
CA279075, CA376187, CA476275

30-JUL-2021

LNМ/D. 21-MAY-2021

Add depth of 1 metre 0 decimetres
(See Chart No. 1, I10)

49°05'08.9"N 061°41'21.0"W

This notice affects Electronic Navigational Chart: CA279043, DFO(6410622-06)
CA379151

30-JUL-2021

LNМ/D. 21-MAY-2021

Delete depth of 7 metres 3 decimetres
(See Chart No. 1, I10)

49°12'48.4"N 061°44'20.9"W

This notice affects Electronic Navigational Chart: CA279043, DFO(6410622-12)
CA379151

30-JUL-2021

LNМ/D. 21-MAY-2021

Add depth of 3 metres 4 decimetres
(See Chart No. 1, I10)

49°13'00.5"N 061°44'38.3"W

This notice affects Electronic Navigational Chart: CA279043, DFO(6410622-13)
CA379151

21-MAY-2021

LNМ/D. 30-APR-2021

Add note ZONE DE PÊCHE 1 / FISHING ZONE 1

48°08'34.0"N 063°14'54.0"W

This notice affects Electronic Navigational Chart: CA279075

DFO(6410604-01)

30-APR-2021

LNМ/D. 23-APR-2021

Delete depth of 7 metres 3 decimetres
(See Chart No. 1, I10)

49°04'00.2"N 061°52'24.5"W

This notice affects Electronic Navigational Chart: CA279043 DFO(6410598-06)

30-APR-2021

LNМ/D. 23-APR-2021

Add depth of 1 metre 1 decimetre
(See Chart No. 1, I10)

49°04'03.8"N 061°51'59.4"W

This notice affects Electronic Navigational Chart: CA279043 DFO(6410598-07)



Chart no. 4024

30-APR-2021

LNМ/D. 23-APR-2021

Delete depth of 7 metres 3 decimetres
(See Chart No. 1, I10)

49°03'17.4"N 061°49'36.9"W

This notice affects Electronic Navigational Chart: CA279043

DFO(6410598-08)

30-APR-2021

LNМ/D. 23-APR-2021

Add depth of 0 metres 6 decimetres
(See Chart No. 1, I10)

49°03'28.9"N 061°49'40.6"W

This notice affects Electronic Navigational Chart: CA279043

DFO(6410598-09)

23-APR-2021

LNМ/D. 08-JAN-2021

Amend Fl R 6s8m6M to read Fl R 6s10m6M against light
(See Chart No. 1, P16)

48°31'15.1"N 064°12'37.7"W

This notice affects Electronic Navigational Chart: (Q2020219) LL(1409) DFO(6410524-01)
CA279075

23-APR-2021

LNМ/D. 08-JAN-2021

Replace subsurface Ocean Data Acquisition system SADO/ODAS of 90 metres with subsurface Ocean Data Acquisition system SADO/ODAS of 85 metres
(See Chart No. 1, L25)

48°16'24.6"N 062°38'22.8"W

This notice affects Electronic Navigational Chart: CA279075

DFO(6410574-07)

23-APR-2021

LNМ/D. 08-JAN-2021

Replace subsurface Ocean Data Acquisition system SADO/ODAS of 20 metres with subsurface Ocean Data Acquisition system SADO/ODAS of 15 metres
(See Chart No. 1, L25)

47°46'26.4"N 064°02'05.0"W

This notice affects Electronic Navigational Chart: CA279075

DFO(6410574-08)

23-APR-2021

LNМ/D. 08-JAN-2021

Add subsurface Ocean Data Acquisition system SADO/ODAS with known depth of 60 metres (See Chart No. 1, L25)

47°45'56.4"N 064°01'55.2"W

This notice affects Electronic Navigational Chart: CA279075

DFO(6410574-09)

08-JAN-2021

LNМ/D. 16-OCT-2020



Chart no. 4024

Add yellow SADO/ODAS lighted super-buoy Fl(5) Y,
marked IML-14

(See Chart No. 1, Q58)

This notice affects Electronic Navigational Chart:
CA179245, CA279075

48°08'00.0"N 062°42'00.0"W

(Q2020122) LL(1411.5) DFO(6410416-01)

08-JAN-2021

Delete depth of 3 metres 9 decimetres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA179245,
CA279075, CA379216

LNМ/D. 16-OCT-2020

47°21'38.3"N 062°06'08.5"W

DFO(6410450-01)

08-JAN-2021

Add depth of 3 metres 2 decimetres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA179245,
CA279075, CA379216

LNМ/D. 16-OCT-2020

47°21'44.3"N 062°05'20.9"W

DFO(6410450-04)

08-JAN-2021

Delete depth of 11 metres 7 decimetres 47°19'28.8"N 061°43'35.6"W
(See Chart No. 1, I10)

LNМ/D. 16-OCT-2020

DFO(6410450-11)

08-JAN-2021

Delete depth of 12 metres 4 decimetres 47°19'33.1"N 061°46'38.0"W
(See Chart No. 1, I10)

LNМ/D. 16-OCT-2020

DFO(6410450-12)

08-JAN-2021

Delete depth of 8 metres 9 decimetres 47°17'47.9"N 061°44'53.6"W
(See Chart No. 1, I10)

LNМ/D. 16-OCT-2020

DFO(6410450-13)

08-JAN-2021

Add 10 metres contour label 47°17'54.2"N 061°44'16.2"W
(See Chart No. 1, I30)

LNМ/D. 16-OCT-2020

DFO(6410450-14)

16-OCT-2020

LNМ/D. 29-MAY-2020



Chart no. 4024

Delete red and white fairway lighted pillar BELL buoy
Mo(A), marked TJ
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart:
CA279075, CA376187, CA476275, CA576269

47°42'37.9"N 064°38'59.3"W
(G2020205) LL(1248) DFO(6309244-01)

16-OCT-2020

Add red and white fairway lighted spar buoy Mo(A),
marked TJ
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart:
CA279075, CA376187, CA476275, CA576269

LNLM/D. 29-MAY-2020
47°42'42.2"N 064°39'16.8"W
(G2020205) LL(1248) DFO(6309244-02)

29-MAY-2020

Add subsurface Ocean Data Acquisition system (SADO/ODAS) with
known depth of 90 metres (See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA179245,
CA279075

LNLM/D. 20-MAR-2020
48°16'40.2"N 062°38'38.4"W
DFO(6410325-01)

20-MAR-2020

Amend 2 Lts F R to read F R against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA279075

LNLM/D. 15-NOV-2019
47°33'22.9"N 061°33'44.4"W
DFO(6410317-02)

15-NOV-2019

Add red and white fairway lighted spar buoy Mo(A),
marked ME
(See Chart No. 1, Qh, Q24)

LNLM/D. 23-AUG-2019
47°09'19.9"N 064°58'15.1"W
(G2019089) LL(1173.91) DFO(6308839-01)

23-AUG-2019

Add environmentally sensitive sea area with legend, ZPM du
Banc-des-Américains / Banc-des-Américains MPA
(See Chart No. 1, N22)
This notice affects Electronic Navigational Chart:
CA179245, CA279075, CA379086

LNLM/D. 19-JUL-2019
joining 48°29'24.0"N 064°08'24.0"W
48°29'24.0"N 063°40'15.0"W
48°45'00.0"N 063°40'15.0"W
48°45'00.0"N 064°08'24.0"W
and 48°29'24.0"N 064°08'24.0"W
DFO(6410193-01)

23-AUG-2019

LNLM/D. 19-JUL-2019



Chart no. 4024

Delete subsurface Ocean Data Acquisition system (SADO/ODAS) with known depth of 20 metres 0 decimetres (See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA279075 48°35'14.0"N 063°54'13.0"W
DFO(6410194-01)

19-JUL-2019

Delete ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart: CA279075 LNLM/D. 12-JUL-2019
joining 47°00'00.0"N 061°42'37.7"W
47°16'38.7"N 061°38'40.5"W
47°17'31.2"N 061°38'46.1"W
47°18'20.0"N 061°39'56.0"W
and 47°21'56.6"N 061°50'39.2"W
DFO(6410160-05)

19-JUL-2019

Add ferry route
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart: CA279075 LNLM/D. 12-JUL-2019
joining 47°00'00.0"N 061°44'35.4"W
47°16'17.9"N 061°39'17.3"W
47°17'33.1"N 061°39'30.1"W
47°18'14.0"N 061°40'17.4"W
and 47°21'45.6"N 061°50'26.2"W
DFO(6410160-06)

12-JUL-2019

Delete yellow SADO/ODAS lighted superbuoy Fl(5) Y,
marked IML-5
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA179245, CA279075 LNLM/D. 01-FEB-2019
47°24'12.0"N 063°23'31.8"W
(Q2019080) LL(1037.5) DFO(6410152-01)

01-FEB-2019

Amend Fl 5s14m20M to read Fl 5s14m4M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA179245, CA279075, CA379086, CA579071 LNLM/D. 02-MAR-2018
48°20'28.1"N 064°39'29.5"W
(Q2018137) LL(1392.7) DFO(6409948-01)

02-MAR-2018

Add depth of 4 metres 9 decimetres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA279075 LNLM/D. 22-DEC-2017
48°07'56.5"N 065°52'36.7"W
DFO(6409758-01)

22-DEC-2017

LNLM/D. 24-NOV-2017



Chart no. 4024

Amend IsoR 2s to read Fl R against light 47°20'28.0"N 064°58'07.0"W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: (G2017106) LL(1238.7) DFO(6409705-01)
CA279075

24-NOV-2017 LNM/D. 17-NOV-2017
Add subsurface Ocean Data Acquisition system (SADO/ODAS) with 48°24'42.0"N 063°41'24.0"W
known depth of 105 metres 0 decimetres
(See Chart No. 1, L25) DFO(6409713-03)

This notice affects Electronic Navigational Chart: CA179245,
CA279075

24-NOV-2017 LNM/D. 17-NOV-2017
Add subsurface Ocean Data Acquisition system (SADO/ODAS) with 48°35'12.0"N 063°53'54.0"W
known depth of 20 metres 0 decimetres
(See Chart No. 1, L25) DFO(6409713-04)

This notice affects Electronic Navigational Chart: CA279075

17-NOV-2017 LNM/D. 03-NOV-2017
Add wreck, least depth unknown, dangerous to surface navigation 47°55'20.7"N 064°22'48.2"W
with legend "Rep (2017)"
(See Chart No. 1, K28, I3.2) DFO(6308134-01)
This notice affects Electronic Navigational Chart: CA279075,
CA376187

03-NOV-2017 LNM/D. 29-SEP-2017
Reposition red and white fairway lighted pillar bell buoy from 47°42'04.0"N 064°39'05.0"W
Mo(A), BELL, marked TJ to 47°42'37.9"N 064°38'59.3"W
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart: CA279075, CA376187, CA476275 (G2017101) LL(1248) DFO(6308087-01)

29-SEP-2017 LNM/D. 04-AUG-2017
Delete light Iso 47°49'10.0"N 064°45'15.5"W
(See Chart No. 1, P1) (G2017082) LL(1306) DFO(6308046-01)

This notice affects Electronic Navigational Chart:
CA279075, CA376187, CA476275



Chart no. 4024

04-AUG-2017

LNМ/D. 21-JUL-2017

Replace red starboard lighted pillar buoy Fl R with bell,
marked TJ2 with red-white fairway lighted pillar
buoy Mo(A) with bell, marked TJ
(See Chart No. 1, Qf, Qh)

47°42'04.0"N 064°39'05.0"W

(G2017008) LL(1248) DFO(6307891-01)

This notice affects Electronic Navigational Chart:
CA279075, CA376187, CA476275

21-JUL-2017

LNМ/D. 05-AUG-2016

Add yellow SADO/ODAS lighted pillar Fl(5) Y, marked
IML-11
(See Chart No. 1, Q58)

48°35'00.0"N 063°53'00.0"W

(Q2017024) LL(1412.5) DFO(6409675-01)

This notice affects Electronic Navigational Chart:
CA179245, CA279075

05-AUG-2016

LNМ/D. 17-JUN-2016

Add subsurface Ocean Data Acquisition system (SADO/ODAS) with
known depth of 20 metres 0 decimetres (See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA279075

47°46'27.0"N 064°02'04.8"W

DFO(6409469-01)

17-JUN-2016

LNМ/D. 05-FEB-2016

Amend FlG 3s7m4M to read 2Lts FlR & FlG
against light
(See Chart No. 1, P16)

47°01'45.7"N 063°59'19.8"W

(G2016033) LL(1036.1 & 1084.7) DFO(6307508-01)

This notice affects Electronic
Navigational Chart: CA276286

05-FEB-2016

Delete obstruction, depth unknown
(See Chart No. 1, K40)

47°43'03.5"N 065°40'53.1"W

This notice affects Electronic Navigational Chart: CA279075,
CA376187

DFO(6307397-01)

05-FEB-2016

Delete TIDAL INFORMATION box

48°31'27.0"N 065°36'05.0"W

The Tidal informations are available on larger scale charts and
in "Canadian Tide and Current Tables"

DFO(6409297-01)

05-FEB-2016



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4024

Delete light Fl R 6s 13m6M
(See Chart No. 1, P1)

48°20'23.7"N 064°40'09.5"W

This notice affects Electronic Navigational Chart: CA279075 LL(1393.0) DFO(6409321-06)

05-FEB-2016

Add light Fl 5s 14m20M
(See Chart No. 1, P1)

48°20'28.1"N 064°39'29.5"W

This notice affects Electronic Navigational Chart: CA279075 LL(1392.7) DFO(6409321-07)