



Chart no. 4241

4241 - Lockeport to / à Cape Sable - New Edition - 08-NOV-2002 - NAD 1983

09-JUN-2023

LNМ/D. 16-JUL-2021

Delete depth of 0.6 metres
(See Chart 1, I10)

43°38'37.8"N 065°18'50.3"W

This notice affects Electronic Navigational Chart: CA376047,
CA576039

DFO(6310664-01)

09-JUN-2023

LNМ/D. 16-JUL-2021

Add rock awash at chart datum
(See Chart 1, K12)

43°38'38.2"N 065°18'53.2"W

This notice affects Electronic Navigational Chart: CA376047,
CA576039

DFO(6310664-02)

09-JUN-2023

LNМ/D. 16-JUL-2021

Add drying height of 0 metres
(See Chart 1, I15)

43°38'24.8"N 065°18'44.6"W

This notice affects Electronic Navigational Chart: CA376047

DFO(6310664-03)

09-JUN-2023

LNМ/D. 16-JUL-2021

Replace depth of 0.4 metres with rock which covers and uncovers
with drying height of 0.1 metres
(See Chart 1, I10, K11)

43°38'16.2"N 065°18'41.2"W

This notice affects Electronic Navigational Chart: CA376047

DFO(6310664-04)

09-JUN-2023

LNМ/D. 16-JUL-2021

Add rock awash at chart datum
(See Chart 1, K12)

43°38'10.4"N 065°18'35.4"W

This notice affects Electronic Navigational Chart: CA376047

DFO(6310664-05)

09-JUN-2023

LNМ/D. 16-JUL-2021

Add drying height of 0.2 metres
(See Chart 1, I15)

43°38'20.6"N 065°19'06.8"W

This notice affects Electronic Navigational Chart: CA376047

DFO(6310664-06)

09-JUN-2023

LNМ/D. 16-JUL-2021

Add rock which covers and uncovers with drying height of 0.1 metres
(See Chart 1, K11)

43°38'28.2"N 065°19'21.6"W

This notice affects Electronic Navigational Chart: CA376047

DFO(6310664-07)



Chart no. 4241

16-JUL-2021	LNM/D. 23-APR-2021
Replace depth of 2.4 metres with depth of 2 metres (See Chart No. 1, I10)	43°43'26.5"N 065°09'09.5"W
This notice affects Electronic Navigational Chart: CA376047	<i>DFO(6309500-01)</i>
16-JUL-2021	LNM/D. 23-APR-2021
Replace depth of 0.9 metres with depth of 0.5 metres (See Chart No. 1, I10)	43°43'21.3"N 065°09'31.8"W
This notice affects Electronic Navigational Chart: CA376047	<i>DFO(6309500-02)</i>
16-JUL-2021	LNM/D. 23-APR-2021
Replace depth of 3.7 metres with depth of 2.9 metres (See Chart No. 1, I10)	43°43'08.0"N 065°09'28.9"W
This notice affects Electronic Navigational Chart: CA376047	<i>DFO(6309500-03)</i>
16-JUL-2021	LNM/D. 23-APR-2021
Delete depth of 3 metres (See Chart No. 1, I10)	43°40'50.4"N 065°13'01.5"W
This notice affects Electronic Navigational Chart: CA376047	<i>DFO(6309500-04)</i>
16-JUL-2021	LNM/D. 23-APR-2021
Add depth of 1.6 metres (See Chart No. 1, I10)	43°40'52.2"N 065°13'02.7"W
This notice affects Electronic Navigational Chart: CA376047	<i>DFO(6309500-05)</i>
16-JUL-2021	LNM/D. 23-APR-2021
Add depth of 1.9 metres (See Chart No. 1, I10)	43°39'06.1"N 065°17'02.9"W
This notice affects Electronic Navigational Chart: CA376047	<i>DFO(6309500-06)</i>
16-JUL-2021	LNM/D. 23-APR-2021
Delete depth of 2.1 metres (See Chart No. 1, I10)	43°32'54.5"N 065°21'50.5"W
This notice affects Electronic Navigational Chart: CA376047	<i>DFO(6309500-07)</i>
16-JUL-2021	LNM/D. 23-APR-2021



Chart no. 4241

Add depth of 1.6 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376047	43°32'56.3"N 065°21'50.7"W <i>DFO(6309500-08)</i>
16-JUL-2021 Replace depth of 5.2 metres with depth of 3.4 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376047	LNM/D. 23-APR-2021 43°31'18.4"N 065°35'14.5"W <i>DFO(6309500-09)</i>
16-JUL-2021 Delete depth of 5.8 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376047	LNM/D. 23-APR-2021 43°29'06.4"N 065°27'07.2"W <i>DFO(6309500-10)</i>
16-JUL-2021 Add depth of 2.8 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376047	LNM/D. 23-APR-2021 43°29'11.5"N 065°27'06.0"W <i>DFO(6309500-11)</i>
16-JUL-2021 Replace depth of 5.5 metres with depth of 0.8 metres (See Chart No. 1, I10) This notice affects Electronic Navigational Chart: CA376047	LNM/D. 23-APR-2021 43°28'05.1"N 065°26'52.1"W <i>DFO(6309500-12)</i>
16-JUL-2021 Add note: WARNING Recent bathymetric surveys show the presence of shallower depths compared to what is presently charted. The shallower depths considered the most hazardous to navigation and within or near main shipping channels will be published in Notices to Mariners (WWW.NOTMAR.CA). Mariners are advised to exercise extreme caution, specifically when they navigate outside of the marked navigation channels. AVERTISSEMENT Des levés bathymétriques récents ont révélé la présence de profondeurs moindres que celles portées sur les cartes marines. Les profondeurs moindres les plus dangereuses pour la navigation et dans ou près des principales voies de navigation seront publiées dans les Avis aux navigateurs (WWW.NOTMAR.CA). Nous demandons aux navigateurs d'exercer la plus grande prudence, particulièrement lors de la navigation en dehors des voies de navigation balisées. This notice affects Electronic Navigational Chart: CA376047	LNM/D. 23-APR-2021 43°46'15.0"N 065°28'45.0"W <i>DFO(6309500-13)</i>



Chart no. 4241

23-APR-2021

Add depth of 1.6 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376047

LNМ/D. 24-MAY-2019

43°27'23.7"N 065°34'41.4"W

DFO(6309392-01)

23-APR-2021

Add wreck, least depth unknown, dangerous to surface navigation
with legend PA

(See Chart No. 1, K28, B7)

This notice affects Electronic Navigational Chart: CA376047

LNМ/D. 24-MAY-2019

43°27'24.6"N 065°34'31.8"W

DFO(6309392-02)

24-MAY-2019

Add breakwater with legend Bkw

(See Chart No. 1, F4.1)

This notice affects Electronic Navigational Chart:
CA376047, CA576039

LNМ/D. 10-MAY-2019

joining 43°40'50.7"N 065°20'21.7"W

43°40'56.6"N 065°20'21.0"W

43°40'57.4"N 065°20'22.4"W

and 43°40'57.4"N 065°20'27.0"W

DFO(6308643-01)

10-MAY-2019

Amend "Hospital Reef" to read "Kelp Shoal"

This notice affects Electronic Navigational Chart: CA376047

LNМ/D. 10-AUG-2018

43°26'41.2"N 065°39'27.5"W

DFO(6308621-01)

10-AUG-2018

Replace depth of 26 metres with depth of 15.7 metres

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA376047

LNМ/D. 29-JUN-2018

43°37'37.3"N 065°07'44.8"W

DFO(6308394-01)

29-JUN-2018

Amend Fl(2)15s28m10M to read LFl 6s28m11M against
light

(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA276800, CA376047

LNМ/D. 18-AUG-2017

43°30'26.2"N 065°20'44.2"W

(F2018019) LL(349) DFO(6308301-01)

18-AUG-2017

LNМ/D. 09-JUN-2017



Chart no. 4241

Replace depth of 2 metres, 4 decimetres with depth of 1 metre, 2
decimetres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376047

43°34'15.4"N 065°26'10.2"W
DFO(6308021-01)

18-AUG-2017 LNM/D. 09-JUN-2017
Replace depth of 1 metre, 8 decimetres with depth of 1 metre, 1
decimetre
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376047

43°34'32.6"N 065°25'42.8"W
DFO(6308021-02)

18-AUG-2017 LNM/D. 09-JUN-2017
Delete depth of 2 metres, 4 decimetres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376047

43°34'28.9"N 065°25'32.9"W
DFO(6308021-03)

18-AUG-2017 LNM/D. 09-JUN-2017
Add depth of 1 metre, 2 decimetres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376047

43°34'25.4"N 065°25'30.9"W
DFO(6308021-04)

09-JUN-2017 LNM/D. 06-MAY-2016
Add marine farm
(See Chart No. 1, K48.1, K48.2)
This notice affects Electronic Navigational Chart: CA376047,
CA476043

43°27'54.5"N 065°38'57.3"W
DFO(6307872-04)

09-JUN-2017 LNM/D. 06-MAY-2016
Add marine farm
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA376047

43°39'16.0"N 065°17'00.9"W
DFO(6307872-06)

09-JUN-2017 LNM/D. 06-MAY-2016
Add marine farm
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA376047

43°40'52.5"N 065°12'16.8"W
DFO(6307872-07)

09-JUN-2017 LNM/D. 06-MAY-2016



Chart no. 4241

- Add marine farm 43°42'10.5"N 065°11'40.3"W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA376047 *DFO(6307872-08)*
- 09-JUN-2017** LNM/D. 06-MAY-2016
Add marine farm 43°43'18.0"N 065°19'18.4"W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA376047, *DFO(6307872-10)*
CA576039
- 09-JUN-2017** LNM/D. 06-MAY-2016
Reposition marine farm from 43°44'40.2"N 065°19'44.8"W
(See Chart No. 1, K48.2) to 43°44'24.2"N 065°19'41.6"W
This notice affects Electronic Navigational Chart: *DFO(6307872-11)*
CA376047, CA576041
- 09-JUN-2017** LNM/D. 06-MAY-2016
Add marine farm 43°43'58.3"N 065°19'47.2"W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA376047 *DFO(6307872-13)*
- 06-MAY-2016** LNM/D. 31-JUL-2015
Add light FLG against beacon with radar reflector 43°26'06.5"N 065°39'13.2"W
(See Chart No. 1, Q81, P16)
This notice affects Electronic Navigational Chart: *(F2016010) LL(323.6) DFO(6307486-01)*
CA376047, CA476043
- 31-JUL-2015** LNM/D. 05-JUN-2015
Amend FogSig 20s (Occas) to read FogSig 20s 43°26'58.7"N 065°28'14.4"W
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart: *(F2015022) LL(336) DFO(6307210-01)*
CA276800, CA376047
- 05-JUN-2015** LNM/D. 06-FEB-2015
Amend FogSig 20s to read FogSig 20s (Occas) 43°26'59.0"N 065°28'15.0"W
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart: *(F2015014) LL(336) DFO(6307115-01)*
CA276800, CA376047



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4241

06-FEB-2015

Amend Fl to read LFl against light
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA376047

LNМ/D. 30-AUG-2013

43°40'52.0"N 065°14'23.0"W

(F2014040) LL(367) DFO(6307008-01)

30-AUG-2013

Delete red starboard hand spar buoy, marked JR52
(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart: CA376047 (F2013017) DFO(6306463-01)

LNМ/D. 12-AUG-2011

43°29'24.2"N 065°33'34.9"W

12-AUG-2011

Amend FR to read LFIR against light
(See Chart No. 1, P16)

(F2011143) LL(352) DFO(6305646-01)

LNМ/D. 15-JUL-2011

43°33'45.7"N 065°21'46.8"W

15-JUL-2011

Delete depth of 0 metres, 9 decimetres
(See Chart No. 1, I10)

DFO(6305367-01)

LNМ/D. 01-JUL-2011

43°28'24.5"N 065°37'56.3"W

15-JUL-2011

Add breakwater between
(See Chart 1 F4.1) and

DFO(6305367-02)

LNМ/D. 01-JUL-2011

43°28'26.4"N 065°37'59.2"W
43°28'19.6"N 065°37'54.0"W

15-JUL-2011

Add light FLG
(See Chart No. 1, P1)

(F2011088) LL(317.1) DFO(6305367-03)

LNМ/D. 01-JUL-2011

43°28'26.4"N 065°37'59.2"W

01-JUL-2011

Amend FLR to read LFIR against light
(See Chart No 1 P16)

(F2011089) LL(318.5) DFO(6305368-01)

LNМ/D. 18-MAR-2011

43°28'24.6"N 065°38'01.7"W

18-MAR-2011

LNМ/D. 23-APR-2010



Chart no. 4241

Amend FR to read LFIR against light
(See Chart No 1 P16)

43°30'19.6"N 065°28'11.1"W

(F2011035) LL(343) DFO(6305294-01)

23-APR-2010

LNМ/D. 05-MAR-2010

Delete obstruction with legend Obstr
(See Chart No 1 K41)

43°44'29.0"N 065°19'08.5"W

DFO(6304735-01)

This notice affects Electronic Navigational Chart: CA576041

23-APR-2010

LNМ/D. 05-MAR-2010

Delete crib in ruins which covers and uncovers with legend Ru
(See Chart No 1 Fb)

43°44'20.6"N 065°19'08.3"W

DFO(6304735-02)

This notice affects Electronic Navigational Chart: CA576041

23-APR-2010

LNМ/D. 05-MAR-2010

Delete light
(See Chart No 1 P1)

43°44'25.8"N 065°19'08.3"W

DFO(6304736-01)

This notice affects Electronic Navigational Chart: CA576041

23-APR-2010

LNМ/D. 05-MAR-2010

Delete light
(See Chart No 1 P1)

43°44'24.6"N 065°19'08.3"W

DFO(6304736-02)

This notice affects Electronic Navigational Chart: CA576041

05-MAR-2010

LNМ/D. 07-AUG-2009

Amend FG to read LFIG against light
(See Chart No 1 P16)

43°29'58.0"N 065°28'14.2"W

(F2009076) LL(344) DFO(6304717-01)

This notice affects Electronic Navigational Chart:
CA376047

07-AUG-2009

LNМ/D. 24-JUL-2009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4241

Amend Fl 10s 33m 16M to read Fl 10s 33m 10M against light
(See Chart No 1 P16)

43°37'21.4"N 065°15'50.0"W

LL(355) DFO(6304444-01)

This notice affects Electronic Navigational Chart: CA276800,
CA376047

24-JUL-2009

LNm/D. 05-JUN-2009

Amend Fl(2) 15s 28m 16M to read Fl(2) 15s 28m 10M against light
(See Chart No 1 P16)

43°30'26.2"N 065°20'44.2"W

LL(349) DFO(6304430-01)

This notice affects Electronic Navigational Chart: CA276800,
CA376047

05-JUN-2009

LNm/D. 27-FEB-2009

Amend LFl R to read LFl G against light
(See Chart No 1 P16)

43°25'56.9"N 065°37'54.9"W

(F2009019) LL(323.5) DFO(6304402-01)

This notice affects Electronic Navigational Chart:
CA376047

27-FEB-2009

LNm/D. 15-FEB-2008

Reposition red starboard hand lighted pillar buoy FlR,
marked JQ52
(See Chart No 1 Qf)

from 43°28'01.0"N 065°33'49.0"W
to 43°27'57.5"N 065°33'40.3"W

(F2008172) LL(331.44) DFO(6304248-01)

This notice affects Electronic Navigational
Chart: CA376047

27-FEB-2009

LNm/D. 15-FEB-2008

Amend VQ(6)+LFl 10s to read Q(6)+LFl 15s against
yellow and black South cardinal lighted spar buoy,
marked KSA
(See Chart No 1 Q130.3)

43°39'00.0"N 065°14'07.8"W

(F2009001) LL(357.8) DFO(6304271-01)

This notice affects Electronic Navigational Chart:
CA376047



Chart no. 4241

15-FEB-2008

LNM/D. 28-DEC-2007

Amend Fl R to read LFl R against light 43°25'56.9"N 065°37'54.0"W
(See Chart No 1 P16)

LL(323.5) DFO(6303799-01)

28-DEC-2007

LNM/D. 21-DEC-2007

Replace yellow, black and yellow West cardinal lighted spar
buoy Q(9) 15s, marked NAC with yellow, black and
yellow West cardinal lighted pillar buoy Q(9) 15s,
marked NAC

43°24'59.3"N 065°39'18.9"W

(F2007083) LL(324) DFO(6303674-01)

21-DEC-2007

LNM/D. 02-NOV-2007

Add light VQ(6)+LFl 10s against yellow and black South
cardinal spar buoy, marked KSA
(See Chart No 1, Q130.3.)

43°39'00.0"N 065°14'07.8"W

(F2007088) LL(357.8) DFO(6303679-01)

02-NOV-2007

LNM/D. 21-SEP-2007

Delete legend 2 Lts F G
(See Chart No 1 Section P 16.)

43°40'51.5"N 065°14'13.0"W

LL(366.5) DFO(6303681-01)

21-SEP-2007

LNM/D. 04-MAY-2007

Delete front leading light and legend 2 Lts F G
(See Chart No 1 Section P 20.2.)

43°40'51.5"N 065°14'13.0"W

(F2007081) LL(366.5) DFO(6303627-01)

21-SEP-2007

LNM/D. 04-MAY-2007

Delete rear leading light with leading line and bearing
303½°
(See Chart No 1 Section P 20.2.)

43°40'53.0"N 065°14'14.0"W

(F2007080) LL(366.6) DFO(6303627-02)

04-MAY-2007

LNM/D. 06-APR-2007

Delete green port hand spar buoy, marked JN51

43°29'55.5"N 065°26'48.5"W

(F2007036) LL(5346.01) DFO(6303382-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4241

04-MAY-2007

Add green port hand lighted spar buoy Q G, marked
JN51

LNLM/D. 06-APR-2007

43°29'55.5"N 065°26'39.4"W

(F2007036) LL(346.01) DFO(6303382-02)

04-MAY-2007

Add light "Q(6)+LF1 15s" against yellow and black South
cardinal spar buoy, marked JJ

LNLM/D. 06-APR-2007

43°26'00.0"N 065°26'35.0"W

(F2007042) LL(340.01) DFO(6303387-01)

04-MAY-2007

Delete red starboard hand lighted pillar whistle buoy FIR,
WHIS, marked KS52

LNLM/D. 06-APR-2007

43°39'59.9"N 065°13'06.0"W

(F2007044) LL(366) DFO(6303389-01)

04-MAY-2007

Add red and white fairway lighted pillar buoy Mo(a),
marked KS

LNLM/D. 06-APR-2007

43°39'44.7"N 065°13'05.0"W

(F2007045) LL(366.1) DFO(6303390-01)

06-APR-2007

Delete red and white fairway lighted pillar buoy Mo(A),
marked KSB

LNLM/D. 23-MAR-2007

43°40'38.5"N 065°13'44.5"W

(F2007026) LL(366.3) DFO(6303376-01)

06-APR-2007

Add green port hand lighted spar buoy QG, marked KS53

LNLM/D. 23-MAR-2007

43°40'37.0"N 065°13'45.5"W

(F2007027) LL(366.35) DFO(6303377-01)

23-MAR-2007

Delete green port hand lighted pillar buoy FIG, marked
JN53

LNLM/D. 12-JAN-2007

43°30'22.0"N 065°27'15.0"W

(F2007006) LL(342) DFO(6303329-01)

23-MAR-2007

LNLM/D. 12-JAN-2007



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4241

Add green port hand lighted spar buoy FlG, marked JN53

43°30'20.8"N 065°27'08.2"W

(F2007006) LL(342) DFO(6303329-02)

23-MAR-2007

LNM/D. 12-JAN-2007

Amend "SSC" to read "SNC" against black and yellow
North cardinal lighted pillar buoy Q

43°32'00.0"N 065°23'30.0"W

(F2007008) LL(350.5) DFO(6303331-01)

12-JAN-2007

LNM/D. 15-DEC-2006

Delete light "Q(2)G 5s"

43°29'19.1"N 065°33'35.1"W

(F2006045) LL(331.5) DFO(6302870-01)

12-JAN-2007

LNM/D. 15-DEC-2006

Add light "Iso G 4s"

43°29'22.5"N 065°33'35.3"W

(F2006075) LL(331.5) DFO(6302870-02)

12-JAN-2007

LNM/D. 15-DEC-2006

Delete depth of 1 metre, 2 decimetres 43°29'21.8"N 065°33'33.0"W

DFO(6302870-03)

12-JAN-2007

LNM/D. 15-DEC-2006

Add breakwater joining 43°29'17.1"N 065°33'32.4"W
43°29'21.8"N 065°33'33.0"W
and 43°29'22.5"N 065°33'35.3"W

DFO(6302870-04)

12-JAN-2007

LNM/D. 15-DEC-2006

Add red starboard hand spar buoy, marked JR52

43°29'24.2"N 065°33'34.9"W

(F2006143) LL(5331.7) DFO(6303124-01)

15-DEC-2006

LNM/D. 24-NOV-2006



Chart no. 4241

Delete legend "BELL" against green port hand lighted pillar
bell buoy FIG, BELL marked KK51

43°37'32.0"N 065°08'11.5"W

(F2006147) LL(369) DFO(6303184-01)

15-DEC-2006

LNМ/D. 24-NOV-2006

Delete red starboard hand conical buoy, marked JK4

43°31'05.0"N 065°25'40.0"W

(F2006148) LL(5344) DFO(6303188-01)

15-DEC-2006

LNМ/D. 24-NOV-2006

Delete red starboard hand conical buoy, marked JK2

43°30'44.0"N 065°25'41.0"W

(F2006150) LL(5343) DFO(6303190-01)

15-DEC-2006

LNМ/D. 24-NOV-2006

Delete red, green and red starboard bifurcation conical
buoy, marked JNK

43°30'15.0"N 065°26'21.0"W

(F2006151) LL(5342) DFO(6303191-01)

15-DEC-2006

LNМ/D. 24-NOV-2006

Delete red starboard hand conical buoy, marked JK6

43°32'12.0"N 065°26'03.0"W

(F2006152) LL(5346) DFO(6303192-01)

15-DEC-2006

LNМ/D. 24-NOV-2006

Delete green port hand can buoy, marked JK5

43°31'57.0"N 065°26'00.0"W

(F2006153) LL(5345) DFO(6303193-01)

15-DEC-2006

LNМ/D. 24-NOV-2006

Reposition green port hand can buoy, marked JN51.5

from 43°30'12.0"N 065°27'06.0"W
to 43°30'11.2"N 065°26'59.0"W

(F2006154) LL(5341) DFO(6303194-01)

15-DEC-2006

LNМ/D. 24-NOV-2006

Amend "KS" to read "KSB" against red and white fairway
lighted pillar buoy Mo(A)

43°40'38.5"N 065°13'44.5"W

(F2006166) LL(366.3) DFO(6303213-01)



Chart no. 4241

24-NOV-2006

Replace red starboard hand spar buoy, marked JQ52 with red starboard hand lighted pillar buoy FIR, marked JQ52

LNМ/D. 10-NOV-2006

43°28'01.0"N 065°33'49.0"W

(F2006109) LL(5331) DFO(6303066-01)

24-NOV-2006

Delete legend "BELL" against red and white fairway lighted pillar bell buoy Mo(A), BELL marked JN

LNМ/D. 10-NOV-2006

43°29'27.0"N 065°26'42.0"W

(F2006120) LL(340) DFO(6303088-01)

24-NOV-2006

Delete legend "WHIS" against red starboard hand lighted pillar whistle buoy FIR, WHIS marked JS56

LNМ/D. 10-NOV-2006

43°25'42.0"N 065°29'16.0"W

(F2006124) LL(337) DFO(6303090-01)

24-NOV-2006

Delete green port hand lighted pillar bell buoy FIG, BELL marked JS53

LNМ/D. 10-NOV-2006

43°23'58.0"N 065°35'18.0"W

(F2006127) LL(328) DFO(6303091-01)

24-NOV-2006

Add green port hand lighted pillar buoy FIG, marked JS53

LNМ/D. 10-NOV-2006

43°23'58.0"N 065°35'20.0"W

(F2006127) LL(328) DFO(6303091-02)

24-NOV-2006

Delete legend "BELL" against green port hand lighted pillar bell buoy FIG, BELL marked JS55

LNМ/D. 10-NOV-2006

43°25'13.0"N 065°34'17.5"W

(F2006129) LL(329) DFO(6303092-01)

24-NOV-2006

Delete legend 'WHIS' against red and white fairway lighted pillar whistle buoy Mo(A), WHIS, marked 'JQ'

LNМ/D. 10-NOV-2006

43°27'24.5"N 065°32'44.5"W

(F2006130) LL(330) DFO(6303093-01)

24-NOV-2006

LNМ/D. 10-NOV-2006



Chart no. 4241

Replace green port hand lighted pillar bell buoy FIG, BELL marked JS59 with green port hand lighted spar buoy FIG, marked JS59

43°27'58.0"N 065°32'48.0"W

(F2006131) LL(331) DFO(6303094-01)

10-NOV-2006

LNМ/D. 01-SEP-2006

Delete legend 'WHIS' against red and white fairway lighted pillar whistle buoy Mo(A), WHIS, marked 'S'

43°37'36.0"N 065°13'51.0"W

(F2006108) LL(357) DFO(6303065-01)

This notice affects Electronic Navigational Chart:
CA276800

10-NOV-2006

LNМ/D. 01-SEP-2006

Delete legend "BELL" against red, green and red starboard bifurcation lighted pillar whistle buoy Fl(2+1) R, BELL marked SAC

43°38'18.0"N 065°13'12.0"W

(F2006116) LL(357.5) DFO(6303078-01)

01-SEP-2006

LNМ/D. 25-AUG-2006

Delete legend "BELL" against red starboard hand lighted pillar bell buoy QR, marked S54

43°41'25.3"N 065°19'39.9"W

(F2006114) LL(362.8) DFO(6303077-01)

25-AUG-2006

LNМ/D. 11-AUG-2006

Amend "FIG 12s 10m" to read "FIG" against light

43°28'06.4"N 065°33'56.1"W

(F2006074) LL(331.2) DFO(6302869-01)

11-AUG-2006

LNМ/D. 23-JUN-2006

(T)Replace yellow, black and yellow West cardinal lighted spar buoy Q(9) 15s, marked NAC with red starboard hand lighted spar buoy FlR, marked NA6

43°24'59.3"N 065°39'18.9"W

(F2006015) LL(324) DFO(6303060-01)

Buoy permanently established. Notice 11-August-2006(T), DFO (6303060-01) is now cancelled. See reference DFO(6303674-01) appearing in this edition.
Cancelled on 28-DEC-07



Chart no. 4241

23-JUN-2006 LNM/D. 16-JUN-2006

Add light FLG 43°25'25.8"N 065°39'25.6"W

(F2006076) LL(323.91) DFO(6302871-01)

23-JUN-2006 LNM/D. 16-JUN-2006

Delete light FLR 43°28'25.1"N 065°38'13.5"W

(F2006080) LL(318) DFO(6302883-01)

16-JUN-2006 LNM/D. 05-MAY-2006

Delete green port hand pillar light and bell buoy FLG,
marked JS61 43°29'21.0"N 065°33'18.0"W

(F2006056) LL(331.6) DFO(6302835-01)

16-JUN-2006 LNM/D. 05-MAY-2006

Add green port hand lighted spar buoy FLG, marked JS61 43°29'21.0"N 065°33'18.0"W

(F2006056) LL(331.6) DFO(6302835-02)

05-MAY-2006 LNM/D. 28-APR-2006

Amend "F" to read "Fl" against light 43°40'52.0"N 065°14'23.0"W

(F2006018) LL(367) DFO(6302782-01)

28-APR-2006 LNM/D. 10-MAR-2006

Delete legend "Buoyed 43°35'57.0"N 065°28'06.0"W
Balisé"

DFO(6302777-01)

28-APR-2006 LNM/D. 10-MAR-2006

Replace red and white fairway lighted pillar buoy Mo(A),
marked NAC with yellow, black and yellow West
cardinal lighted spar buoy Q(9) 15s, marked NAC 43°24'59.3"N 065°39'18.9"W

(F2006015) LL(324) DFO(6302779-01)

28-APR-2006 LNM/D. 10-MAR-2006



Chart no. 4241

Delete red, green and red starboard bifurcation conical buoy,
marked C

43°27'38.5"N 065°39'32.0"W

(F2006017) DFO(6302781-01)

28-APR-2006

LNM/D. 10-MAR-2006

Add red starboard hand conical buoy, marked C6 43°27'37.0"N 065°39'30.9"W

(F2006017) DFO(6302781-02)

10-MAR-2006

LNM/D. 17-FEB-2006

Delete red starboard hand lighted pillar buoy, Fl R, marked
SN54

43°32'17.0"N 065°21'55.5"W

(F2005143) LL(351) DFO(6302727-01)

10-MAR-2006

LNM/D. 17-FEB-2006

Add red starboard hand lighted pillar buoy, Fl R, marked
SP54

43°32'20.6"N 065°21'51.5"W

(F2005143) LL(351) DFO(6302727-02)

10-MAR-2006

LNM/D. 17-FEB-2006

Delete legend 'WHIS' against yellow and black South
cardinal lighted pillar whistle buoy Q (6)+LFl 15s,
WHIS marked 'J'

43°21'00.0"N 065°26'44.0"W

(F2005148) LL(338) DFO(6302731-01)

This notice affects Electronic Navigational Chart:
CA276800

10-MAR-2006

LNM/D. 17-FEB-2006

Delete legend 'BELL' against green port hand pillar light
buoy Fl G, BELL, marked 'JJ51'

43°27'06.0"N 065°27'18.0"W

(F2006005) LL(339) DFO(6302736-01)

10-MAR-2006

LNM/D. 17-FEB-2006

Delete legend 'WHIS' against red and white fairway lighted
pillar whistle buoy Mo(A), WHIS, marked 'JA'

43°26'33.0"N 065°24'09.0"W

(F2006008) LL(347) DFO(6302739-01)

This notice affects Electronic Navigational Chart:
CA276800



Chart no. 4241

- 17-FEB-2006** LNM/D. 10-FEB-2006
Delete red starboard hand spar buoy, marked SP52 43°32'22.5"N 065°21'47.0"W
(F2005111) DFO(6302682-01)
- 17-FEB-2006** LNM/D. 10-FEB-2006
Add red starboard hand lighted spar buoy FIR, marked 43°32'36.4"N 065°21'51.5"W
SP56 (F2005111) LL(351.02) DFO(6302682-02)
- 17-FEB-2006** LNM/D. 10-FEB-2006
Delete red starboard hand spar buoy, marked SN52 43°31'48.9"N 065°20'49.0"W
(F2005112) DFO(6302683-01)
- 17-FEB-2006** LNM/D. 10-FEB-2006
Add red starboard hand lighted spar buoy FIR, marked 43°31'48.9"N 065°20'53.0"W
SN52 (F2005112) LL(350.02) DFO(6302683-02)
- 17-FEB-2006** LNM/D. 10-FEB-2006
Add light 'FIG' against green port hand spar buoy, 43°33'08.0"N 065°22'04.0"W
marked SP59 (F2005113) LL(351.04) DFO(6302684-01)
- 17-FEB-2006** LNM/D. 10-FEB-2006
Delete red starboard hand spar buoy, marked SQ62 43°31'27.0"N 065°20'59.0"W
(F2005123) DFO(6302690-01)
- 17-FEB-2006** LNM/D. 10-FEB-2006
Delete red starboard hand spar buoy, marked SN66 43°34'19.0"N 065°25'42.0"W
(F2005124) DFO(6302691-01)
- 17-FEB-2006** LNM/D. 10-FEB-2006



Chart no. 4241

Delete red starboard hand spar buoy, marked SN70 43°34'53.0"N 065°26'11.0"W
(F2005125) DFO(6302692-01)

17-FEB-2006 LNM/D. 10-FEB-2006
Delete green port hand spar buoy, marked SN73 43°35'24.0"N 065°27'17.0"W
(F2005126) DFO(6302693-01)

17-FEB-2006 LNM/D. 10-FEB-2006
Delete green port hand spar buoy, marked SS59 43°31'52.0"N 065°24'00.0"W
(F2005132) DFO(6302694-01)

17-FEB-2006 LNM/D. 10-FEB-2006
Delete green port hand spar buoy, marked SP57 43°32'57.0"N 065°22'19.0"W
(F2005133) DFO(6302695-01)

10-FEB-2006 LNM/D. 30-SEP-2005
Add red starboard hand lighted spar buoy FIR, marked 43°28'26.9"N 065°38'16.9"W
C10
(F2005103) LL(318.01) DFO(6302675-01)

10-FEB-2006 LNM/D. 30-SEP-2005
Replace green port hand can buoy, marked CA1 with 43°26'42.0"N 065°39'40.0"W
green port hand lighted spar buoy FIG, marked
CA1 (F2005117) LL(322.1) DFO(6302685-01)

10-FEB-2006 LNM/D. 30-SEP-2005
Amend "FIR" to read "QR" against red starboard hand 43°23'46.5"N 065°39'11.0"W
spar light buoy, marked NA4
(F2005137) LL(326.02) DFO(6302698-01)

30-SEP-2005 LNM/D. 22-JUL-2005
Delete legend "BELL" against green port hand pillar light 43°35'58.3"N 065°15'51.4"W
buoy FIG, BELL marked S51
(F2005050) LL(354) DFO(6302471-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4241

22-JUL-2005

Add light 'FIR' against red starboard hand spar buoy,
marked NA4

LNМ/D. 27-MAY-2005

43°23'46.5"N 065°39'11.0"W

(F2005035) LL(326.02) DFO(6302362-01)

27-MAY-2005

Delete fog signal "Fog Sig (Occas)"

LNМ/D. 20-MAY-2005

43°26'39.4"N 065°35'05.9"W

(F2005017) LL(329.4) DFO(6302274-01)

20-MAY-2005

(T)Add green port hand pillar light buoy FIG, marked
NA5

LNМ/D. 25-FEB-2005

43°25'27.6"N 065°39'17.3"W

This buoy is temporarily established.

(F2005013T) LL(323.9) DFO(6302270-01)

This buoy is permanently discontinued. Notice
20-May-2005(T), DFO(6302270) is now cancelled.
Cancelled on 18-NOV-05

25-FEB-2005

Replace red and white fairway pillar, light buoy Mo (A),
BELL, marked NA with red starboard hand pillar
light buoy FIR, marked NA2

LNМ/D. 28-JAN-2005

43°23'30.0"N 065°38'44.0"W

(F2004213) LL(326) DFO(6302181-01)

25-FEB-2005

Delete legend "BELL" against red starboard hand pillar light
and bell buoy FIR, BELL marked C2

LNМ/D. 28-JAN-2005

43°26'46.3"N 065°40'18.0"W

(F2004203) LL(321) DFO(6302197-01)

25-FEB-2005

Amend "FIR" to read "QR" against red starboard pillar light
buoy marked CA2

LNМ/D. 28-JAN-2005

43°26'36.0"N 065°39'45.9"W

(F2004204) LL(322) DFO(6302198-01)

25-FEB-2005

Replace red starboard hand pillar light and whistle buoy
FIR, WHIS, marked N2 with red and white fairway
pillar, light buoy Mo (A), marked N

LNМ/D. 28-JAN-2005

43°20'12.3"N 065°40'45.9"W

(F2004205) LL(325) DFO(6302200-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4241

25-FEB-2005

Replace red starboard hand conical buoy, marked NA2, with red
starboard hand spar buoy, marked NA4

LNМ/D. 28-JAN-2005

43°23'46.0"N 065°39'11.0"W

(F2004102) DFO(6302204-01)

28-JAN-2005

Add light Q(2)G 5s

LNМ/D. 14-JAN-2005

43°29'19.1"N 065°33'35.1"W

(F2004217) LL(331.5) DFO(6302183-01)

14-JAN-2005

Delete red starboard hand spar buoy, marked JJ56

LNМ/D. 05-NOV-2004

43°28'11.0"N 065°27'03.0"W

(F2004180) DFO(6302141-01)

14-JAN-2005

Add red starboard hand spar light buoy FIR, marked JJ56

LNМ/D. 05-NOV-2004

43°27'51.7"N 065°26'59.2"W

(F2004180) LL(340.03) DFO(6302141-02)

14-JAN-2005

Add light 'FIG' against green port hand spar buoy,
marked JJ57

LNМ/D. 05-NOV-2004

43°28'33.0"N 065°27'08.5"W

(F2004181) LL(340.04) DFO(6302143-01)

14-JAN-2005

Delete light "Fl"

LNМ/D. 05-NOV-2004

43°28'44.2"N 065°27'12.1"W

(F2004183) LL(339.5) DFO(6302144-01)

05-NOV-2004

Delete legend, Fog Sig (Occas)

LNМ/D. 16-JUL-2004

43°29'18.5"N 065°33'36.4"W

(F2004125) LL(331.4) DFO(6301938-01)

16-JUL-2004

LNМ/D. 25-JUN-2004



Chart no. 4241

Replace tower symbol "Lt Ho/ Phare Aband" with FR (Priv)
light

43°41'29.3"N 065°19'32.9"W

(F2004062) LL(363) DFO(6301465-01)

25-JUN-2004

LNM/D. 07-MAY-2004

Amend "Fl (3) 10s 16m 16M" to read "Mo (D) 10s 15m 12M" against
light

43°26'59.0"N 065°28'15.0"W

LL(336) DFO(6301236-01)

07-MAY-2004

LNM/D. 12-MAR-2004

Amend "LFl 12s 17m 16M" to read "LFl 12s 17m 8M"
against light

43°28'07.7"N 065°22'43.4"W

(F2004022) LL(348) DFO(6301317-01)

12-MAR-2004

LNM/D. 21-NOV-2003

Delete red, starboard hand spar buoy, marked CM2

43°29'14.0"N 065°37'20.0"W

(F2003124) DFO(6301183-01)

12-MAR-2004

LNM/D. 21-NOV-2003

Delete red, starboard hand spar buoy, marked CM4

43°28'43.0"N 065°36'48.0"W

(F2003125) DFO(6301184-01)

21-NOV-2003

LNM/D. 25-JUL-2003

Add non-dangerous wreck, depth unknown

43°38'06.0"N 065°09'06.0"W

DFO(6301062-01)

25-JUL-2003

LNM/D. 14-FEB-2003

Delete light FIR

43°44'20.6"N 065°19'08.4"W

DFO(6300961-01)

25-JUL-2003

LNM/D. 14-FEB-2003

Amend crib to crib in ruins, Ru, covers and uncovers

43°44'20.6"N 065°19'08.4"W

DFO(6300961-02)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4241

14-FEB-2003

Amend Iso G to read FlG against light

43°26'33.5"N 065°38'08.7"W

(F2002031) LL(323) DFO(6300473-01)