



**Chart no. 4391**

**4391 - LaHave River: Conquerall Bank to / à Bridgewater - New Edition - 20-DEC-2002 - NAD 1983**

**15-APR-2016**

LNM/D. 02-MAY-2008

Replace depth of 22 feet with depth of 16 feet 44°22'06.3"N 064°28'22.4"W  
(See Chart No. 1, I10)

*DFO(6307498-01)*

**15-APR-2016**

LNM/D. 02-MAY-2008

Replace depth of 22 feet with depth of 16 feet 44°22'05.3"N 064°28'24.9"W  
(See Chart No. 1, I10)

*DFO(6307498-02)*

**02-MAY-2008**

LNM/D. 21-DEC-2007

ERRATUM green port hand spar buoy, marked T77 44°22'01.4"N 064°27'53.3"W  
(See Chart No 1 Qg)

*LL(5427.085) DFO(6303853-01)*

**21-DEC-2007**

Add green port hand spar buoy, marked T77  
(See Chart No 1 Qg)

47°22'01.4"N 064°27'53.3"W

*(F2007104) LL(5427.085) DFO(6303680-01)*

**21-DEC-2007**

Reposition red starboard hand spar buoy, marked T90 from 44°22'10.8"N 064°29'51.9"W  
(See Chart No 1 Qf) to 44°22'10.1"N 064°29'51.8"W

*(F2007100) DFO(6303714-01)*

**21-DEC-2007**

Reposition red starboard hand spar buoy, marked T92 from 44°22'10.8"N 064°30'02.6"W  
(See Chart No 1 Qf) to 44°22'10.3"N 064°30'02.5"W

*(F2007103) DFO(6303715-01)*