



Chart no. 4587

4587 - Cow Head Wharves / Quais - New Edition - 25-JAN-2008 - NAD 1983

25-FEB-2022

LNМ/D. 03-SEP-2021

Reposition red, green and red starboard hand bifurcation
lighted pillar buoy Fl(2+1)R, marked PY
(See Chart No. 1, Qi)

from 47°11'33.2"N 055°06'13.2"W
to 47°11'30.8"N 055°06'13.4"W

This notice affects Electronic Navigational
Chart: CA576225

(N2021222) LL(63.7) DFO(6309922-01)

4587 - Marystown Wharves / Quais - New Edition - 25-JAN-2008 - NAD 1983

03-SEP-2021

LNМ/D. 31-AUG-2018

Add light Fl Y, Marystown Wharf Light
(See Chart No. 1, P1)

47°09'56.1"N 055°08'51.6"W

This notice affects Electronic Navigational Chart:
CA576225

(N2021075) LL(63.55) DFO(6309579-01)

31-MAR-2017

LNМ/D. 16-DEC-2016

Delete private light FR, (Priv)
(See Chart No. 1, P1)

47°09'52.2"N 055°08'50.1"W

This notice affects Electronic Navigational Chart:
CA376176, CA576227

(N2016085) LL(63.5) DFO(6307832-01)

4587 - Mortier Bay - New Edition - 25-JAN-2008 - NAD 1983

25-FEB-2022

LNМ/D. 03-SEP-2021

Reposition red, green and red starboard hand bifurcation
lighted pillar buoy Fl(2+1)R, marked PY
(See Chart No. 1, Qi)

from 47°11'33.2"N 055°06'13.2"W
to 47°11'30.8"N 055°06'13.4"W

This notice affects Electronic Navigational
Chart: CA576225

(N2021222) LL(63.7) DFO(6309922-01)

03-SEP-2021

LNМ/D. 31-AUG-2018

Add light Fl Y, Marystown Wharf Light
(See Chart No. 1, P1)

47°09'56.1"N 055°08'51.6"W

This notice affects Electronic Navigational Chart:
CA576225

(N2021075) LL(63.55) DFO(6309579-01)

31-AUG-2018

LNМ/D. 31-MAR-2017



Chart no. 4587

Add floating wharf with legend Flo
(See Chart No. 1, F14, F16)

This notice affects Electronic Navigational Chart:
CA576225

between 47°09'48.8"N 055°06'42.9"W
and 47°09'47.5"N 055°06'45.6"W

DFO(6308390-01)

31-AUG-2018

Delete depth of 5.4 metres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576225

LNМ/D. 31-MAR-2017
47°09'48.0"N 055°06'45.0"W

DFO(6308390-02)

31-AUG-2018

Add depth of 0.8 metres
(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576225

LNМ/D. 31-MAR-2017
47°09'47.2"N 055°06'44.2"W

DFO(6308390-03)

31-MAR-2017

Delete private light FR, (Priv)
(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA376176, CA576227

LNМ/D. 16-DEC-2016
47°09'52.2"N 055°08'50.1"W

(N2016085) LL(63.5) DFO(6307832-01)

16-DEC-2016

Replace green port hand lighted spar buoy QG, marked
PML1 with yellow cautionary lighted spar buoy
Fl Y, marked PML
(See Chart No. 1 Qg and Qm)

This notice affects Electronic Navigational
Chart: CA576225

LNМ/D. 27-NOV-2015
47°09'40.2"N 055°06'38.0"W
(N2016051) LL(63.535) DFO(6307697-01)

27-NOV-2015

Delete anchoring prohibited area
(See Chart No. 1, N20)

This notice affects Electronic Navigational Chart: CA576225

LNМ/D. 06-AUG-2010
47°11'07.7"N 055°06'28.8"W

DFO(6307334-01)

06-AUG-2010

LNМ/D. 22-JAN-2010



Chart no. 4587

Amend Fl 6s 33m 17M to read Fl 6s 33m 16M against light
(See Chart No. 1 P16)

47°06'21.8"N 055°04'19.8"W

LL(65) DFO(6304966-01)

This notice affects Electronic Navigational Chart: CA276091,
CA576225

22-JAN-2010

LN/D. 23-JAN-2009

Add green port hand lighted spar buoy QG, marked
PML1
(See Chart No 1 Qg]

47°09'40.2"N 055°06'38.0"W

(N2009031) LL(63.539) DFO(6304573-01)

This notice affects Electronic Navigational Chart:
CA576225

23-JAN-2009

Add submarine cable
(See Chart No 1 L30.1)

joining 47°11'51.4"N 055°04'40.7"W
47°11'43.0"N 055°04'49.8"W
47°11'22.2"N 055°04'30.0"W
47°10'39.2"N 055°05'01.6"W
47°10'20.7"N 055°04'57.8"W
47°09'55.5"N 055°04'58.8"W
47°08'52.8"N 055°05'09.7"W
47°08'24.3"N 055°05'00.9"W
47°08'14.2"N 055°05'02.3"W
47°07'41.6"N 055°04'20.8"W
47°07'33.7"N 055°04'01.2"W
and 47°07'27.2"N 055°02'27.3"W

This notice affects Electronic Navigational Chart:
CA576225

DFO(6304177-01)