



## Chart no. 4619

### 4619 - Presque Harbour to / à Bar Haven Island and / et Paradise Sound - New Edition - 20-NOV-1998 - NAD 1983

**23-DEC-2022**

LNLM/D. 21-OCT-2022

Add red and white fairway lighted pillar whistle buoy  
Mo(A), marked PH  
(See Chart 1, Qd)  
This notice affects Electronic Navigational Chart:  
CA376173, CA476805

47°23'25.8"N 054°22'15.5"W

*(N2022291) LL(49.5) DFO(6310525-01)*

**21-OCT-2022**

LNLM/D. 24-JUN-2022

Add light Fl Y 5s4M  
(See Chart 1, P1)  
This notice affects Electronic Navigational Chart:  
CA476079

47°38'09.1"N 054°20'24.5"W

*(N2022138) LL(44.09) DFO(6310232-01)*

**21-OCT-2022**

LNLM/D. 24-JUN-2022

Add pier  
(See Chart 1, F14)  
This notice affects Electronic Navigational Chart:  
CA476079

joining 47°38'10.2"N 054°20'26.3"W

47°38'09.3"N 054°20'25.1"W

and 47°38'09.1"N 054°20'24.5"W

*DFO(6310232-03)*

**24-JUN-2022**

LNLM/D. 08-OCT-2021

Add marine farm limits  
(See Chart No. 1, K48.1)  
This notice affects Electronic Navigational Chart:  
CA276274, CA476805

joining 47°32'08.4"N 054°23'31.5"W

47°31'01.7"N 054°24'37.8"W

47°30'52.7"N 054°23'40.5"W

47°31'07.4"N 054°22'52.3"W

47°31'47.4"N 054°22'08.4"W

and 47°32'08.4"N 054°23'31.5"W

*DFO(6310082-03)*

**24-JUN-2022**

LNLM/D. 08-OCT-2021

Add marine farm limits  
(See Chart No. 1, K48.1)  
This notice affects Electronic Navigational Chart:  
CA276274, CA476806

joining 47°35'00.3"N 054°22'04.2"W

47°33'54.2"N 054°20'46.9"W

47°34'22.3"N 054°19'48.8"W

47°35'22.6"N 054°21'20.0"W

and 47°35'00.3"N 054°22'04.2"W

*DFO(6310082-04)*



## Chart no. 4619

### 24-JUN-2022

Add marine farm limits

(See Chart No. 1, K48.1)

This notice affects Electronic Navigational Chart:

CA276274, CA476079

LNM/D. 08-OCT-2021

joining 47°39'03.2"N 054°18'01.0"W

47°38'17.0"N 054°16'43.5"W

47°38'58.6"N 054°15'37.3"W

47°39'38.5"N 054°16'58.3"W

and 47°39'03.2"N 054°18'01.0"W

*DFO(6310082-05)*

### 24-JUN-2022

Add marine farm limits

(See Chart No. 1, K48.1)

This notice affects Electronic Navigational Chart:

CA276274, CA476300

LNM/D. 08-OCT-2021

joining 47°29'29.4"N 054°10'26.2"W

47°29'00.6"N 054°09'56.5"W

47°28'51.8"N 054°09'56.5"W

47°27'59.6"N 054°11'25.5"W

47°28'30.5"N 054°11'51.8"W

47°28'53.3"N 054°11'46.9"W

and 47°29'29.4"N 054°10'26.2"W

*DFO(6310082-06)*

### 24-JUN-2022

Affix patch

[PDF](#)

This notice affects Electronic Navigational Chart: CA476806

LNM/D. 08-OCT-2021

47°35'00.0"N 054°24'00.0"W

*DFO(6310082-11)*

### 08-OCT-2021

Delete red and white fairway lighted pillar whistle buoy

Mo(A), marked PH

(See Chart No. 1, Qh)

This notice affects Electronic Navigational Chart:

CA376173, CA476805

LNM/D. 30-APR-2021

47°23'24.7"N 054°22'15.2"W

*(N2021110) LL(49.5) DFO(6309559-01)*

### 30-APR-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 16 fathoms

(See Chart No. 1, L25)

This notice affects Electronic Navigational Chart: CA476079

LNM/D. 19-JUL-2019

47°39'16.0"N 054°10'11.1"W

*DFO(6309409-01)*

### 19-JUL-2019

LNM/D. 31-AUG-2018



### Chart no. 4619

Amend FLR to read FLY against light  
(See Chart No. 1, P1)

47°34'44.3"N 054°25'45.2"W

This notice affects Electronic Navigational Chart: (N2019024) LL(51.68) DFO(6308678-01)  
CA476806

### 31-AUG-2018

LNМ/D. 10-AUG-2018

Add marine farm  
(See Chart No. 1, K48.2)

47°34'32.0"N 054°10'07.0"W

This notice affects Electronic Navigational Chart: CA476806

DFO(6308408-01)

### 10-AUG-2018

LNМ/D. 22-DEC-2017

Reposition subsurface Ocean Data Acquisition system  
ODAS/SADO with known depth of 2 fathoms, 4 feet  
(See Chart No. 1, L25)

from 47°34'44.4"N 054°21'43.8"W  
to 47°34'49.2"N 054°21'37.8"W

This notice affects Electronic Navigational Chart:  
CA476806

DFO(6308364-02)

### 22-DEC-2017

LNМ/D. 29-JUN-2012

Add subsurface Ocean Data Acquisition system ODAS/SADO with  
known depth of 2 fathoms, 4 feet  
(See Chart No. 1, L25)

47°34'44.4"N 054°21'43.8"W

This notice affects Electronic Navigational Chart: CA476806

DFO(6308166-03)

### 29-JUN-2012

LNМ/D. 12-AUG-2011

Add light Fl R  
(See Chart No. 1, P1)

47°34'44.3"N 054°25'45.2"W

(N2012012) LL(51.68) DFO(6306060-01)

### 29-JUN-2012

LNМ/D. 12-AUG-2011

Add wharf  
(See Chart No 1 F14)

between 47°34'43.0"N 054°25'42.9"W  
and 47°34'44.3"N 054°25'45.2"W

DFO(6306060-02)

### 12-AUG-2011

LNМ/D. 28-JAN-2011



**Chart no. 4619**

Reposition red starboard hand lighted spar buoy F1R,  
marked PH4  
(See Chart No. 1, Qf)

from 47°24'28.7"N 054°21'16.9"W  
to 47°24'28.3"N 054°21'21.2"W

*(N2011047) LL(49.44) DFO(6305654-01)*

This notice affects Electronic Navigational  
Chart: CA476805

**28-JAN-2011**

LNМ/D. 17-OCT-2008

Add anchorage area joining 47°42'45.0"N 054°10'23.1"W  
(See Chart No. 1, N12.1) 47°42'37.0"N 054°10'24.5"W  
47°42'40.2"N 054°11'21.5"W  
and 47°42'45.0"N 054°11'20.7"W

*DFO(6305208-01)*

**02-NOV-2007**

LNМ/D. 15-DEC-2006

(T)Add private yellow cautionary spar buoy  
The mooring is temporary and will be removed by July 2008.  
This buoy is permanently discontinued. Notice 2-NOV-2007(T),  
DFO(6303667) is now cancelled.  
Cancelled on 31-OCT-08

47°31'48.2"N 054°29'33.8"W

*DFO(6303667-03)*

**02-NOV-2007**

LNМ/D. 15-DEC-2006

(T)Add private yellow cautionary spar buoy  
The mooring is temporary and will be removed by July 2008.  
This buoy is permanently discontinued. Notice 2-NOV-2007(T),  
DFO(6303668-R1) is now cancelled.  
Cancelled on 31-OCT-08

47°24'42.0"N 054°29'37.2"W

*DFO(6303668-01)*

**15-DEC-2006**

LNМ/D. 30-SEP-2005

(T)Add private yellow cautionary spar buoy  
The mooring is temporary and will be removed by April 2007.  
The mooring has been removed. Notice 15-December-2006(T),  
DFO (6303199) is now cancelled.  
Cancelled on 02-NOV-07

47°31'49.1"N 054°29'33.0"W

*DFO(6303199-02)*

**15-DEC-2006**

LNМ/D. 30-SEP-2005



### Chart no. 4619

(T)Add private yellow cautionary spar buoy 47°24'40.4"N 054°29'55.1"W  
The mooring is temporary and will be removed by April 2007.  
The mooring has been removed. Notice 15-December-2006(T), *DFO(6303199-04)*  
DFO (6303199) is now cancelled.  
Cancelled on 02-NOV-07

#### 15-DEC-2006

LNLM/D. 30-SEP-2005

(T)Add private yellow cautionary spar buoy 47°32'09.5"N 054°14'45.6"W  
The mooring is temporary and will be removed by April 2007.  
The mooring has been removed. Notice 15-December-2006(T), *DFO(6303199-08)*  
DFO (6303199) is now cancelled.  
Cancelled on 02-NOV-07

#### 15-DEC-2006

LNLM/D. 30-SEP-2005

(T)Add private yellow cautionary spar buoy 47°33'44.6"N 054°13'18.1"W  
The mooring is temporary and will be removed by April 2007.  
The mooring has been removed. Notice 15-December-2006(T), *DFO(6303199-09)*  
DFO (6303199) is now cancelled.  
Cancelled on 02-NOV-07

#### 20-MAY-2005

LNLM/D. 04-OCT-2002

Delete green, port hand spar buoy, marked PV1 47°28'18.0"N 054°23'33.0"W  
*(N2001031) LL(49.41) DFO(6829514-01)*

#### 20-MAY-2005

LNLM/D. 04-OCT-2002

Add green port hand spar light buoy FlG, marked PV1 47°28'21.0"N 054°23'33.6"W  
*(N2001031) LL(49.41) DFO(6829514-02)*

#### 20-MAY-2005

LNLM/D. 04-OCT-2002

Replace red starboard hand spar buoy, marked PV2 with 47°28'18.9"N 054°23'28.8"W  
red starboard hand spar light buoy FlR, marked  
PV2 *(N2001032) LL(49.42) DFO(6829525-01)*

#### 19-OCT-2001

LNLM/D. 06-OCT-2000



Fisheries and Oceans  
Canada

Pêches et Océans  
Canada

Canadian  
Coast Guard

Garde côtière  
canadienne

### Chart no. 4619

Replace red starboard hand spar buoy, marked PH2, with  
red starboard hand spar light buoy FLR, marked  
PH2

47°24'22.2"N 054°21'23.0"W

(N2001033) LL(49.4) DFO(6829526-02)

#### 19-OCT-2001

LN/D. 06-OCT-2000

Replace red starboard hand spar buoy, marked PH4, with  
red starboard hand spar light buoy Fl R, marked  
PH4

47°24'28.6"N 054°21'16.9"W

(N2001034) LL(49.44) DFO(6829527-02)

#### 06-OCT-2000

Delete green, port hand, spar buoy, marked PQ3

47°34'52.0"N 054°25'56.0"W

(N1999-081) LL(5051.660) DFO(6829037-01)

#### 06-OCT-2000

Add green light, port hand spar bouy Fl G, marked PQ3

47°34'51.0"N 054°25'57.0"W

(N1999-081) LL(51.660) DFO(6829037-02)

### 4619 - Continuation A - New Edition - 20-NOV-1998 - NAD 1983

#### 17-OCT-2008

LN/D. 02-NOV-2007

Add light QR  
(See Chart No 1 P1)

47°23'43.0"N 054°35'15.0"W

(N2007060) LL(51.69) DFO(6303991-01)

#### 02-NOV-2007

LN/D. 15-DEC-2006

(T)Add private yellow cautionary spar buoy

47°28'09.2"N 054°32'19.4"W

The mooring is temporary and will be removed by July 2008.

This buoy is permanently discontinued. Notice 2-NOV-2007(T),

DFO(6303667) is now cancelled.

DFO(6303667-01)

Cancelled on 31-OCT-08

#### 15-DEC-2006

LN/D. 30-SEP-2005



**Chart no. 4619**

(T)Add private yellow cautionary spar buoy 47°28'10.3"N 054°32'18.9"W  
The mooring is temporary and will be removed by April 2007.  
The mooring has been removed. Notice 15-December-2006(T), DFO(6303199-03)  
DFO (6303199) is now cancelled.  
Cancelled on 02-NOV-07

**30-SEP-2005** LNM/D. 20-MAY-2005  
Delete depth of 8 fathoms, 4 feet 47°25'00.0"N 054°35'30.0"W  
*DFO(6302502-01)*

**30-SEP-2005** LNM/D. 20-MAY-2005  
Add depth of 1 fathom, 2 feet 47°24'58.6"N 054°35'30.1"W  
*DFO(6302502-02)*

**04-OCT-2002** LNM/D. 04-JAN-2002  
Add green port hand spar light buoy FlG, marked PE5 47°22'57.5"N 054°38'58.3"W  
*(N2001014) LL(53.29) DFO(6829427-01)*

**04-JAN-2002** LNM/D. 19-OCT-2001  
Replace red light, starboard hand spar buoy QR, marked 47°23'44.4"N 054°34'38.0"W  
PE10, with red light, starboard hand spar buoy  
FlR, marked PS2 *(N2000077) LL(51.65) DFO(6828840-01)*