



Chart no. 4619

4619 - Presque Harbour to / à Bar Haven Island and / et Paradise Sound - New Edition - 20-NOV-1998 - NAD 1983

23-DEC-2022

LNLM/D. 21-OCT-2022

Add red and white fairway lighted pillar buoy Mo(A),
marked PH

47°23'25.8"N 054°22'15.5"W

(See Chart 1, Qd)

(N2022291) LL(49.5) DFO(6310525-01)

This notice affects Electronic Navigational Chart:
CA376173, CA476805

21-OCT-2022

LNLM/D. 24-JUN-2022

Add light Fl Y 5s4M

47°38'09.1"N 054°20'24.5"W

(See Chart 1, P1)

(N2022138) LL(44.09) DFO(6310232-01)

This notice affects Electronic Navigational Chart:
CA476079

21-OCT-2022

LNLM/D. 24-JUN-2022

Add pier

joining 47°38'10.2"N 054°20'26.3"W

(See Chart 1, F14)

47°38'09.3"N 054°20'25.1"W

This notice affects Electronic Navigational Chart:
CA476079

and 47°38'09.1"N 054°20'24.5"W

DFO(6310232-03)

24-JUN-2022

LNLM/D. 08-OCT-2021

Add marine farm limits

joining 47°32'08.4"N 054°23'31.5"W

(See Chart No. 1, K48.1)

47°31'01.7"N 054°24'37.8"W

This notice affects Electronic Navigational Chart:
CA276274, CA476805

47°30'52.7"N 054°23'40.5"W

47°31'07.4"N 054°22'52.3"W

47°31'47.4"N 054°22'08.4"W

and 47°32'08.4"N 054°23'31.5"W

DFO(6310082-03)

24-JUN-2022

LNLM/D. 08-OCT-2021

Add marine farm limits

joining 47°35'00.3"N 054°22'04.2"W

(See Chart No. 1, K48.1)

47°33'54.2"N 054°20'46.9"W

This notice affects Electronic Navigational Chart:
CA276274, CA476806

47°34'22.3"N 054°19'48.8"W

47°35'22.6"N 054°21'20.0"W

and 47°35'00.3"N 054°22'04.2"W

DFO(6310082-04)



Chart no. 4619

24-JUN-2022

Add marine farm limits

(See Chart No. 1, K48.1)

This notice affects Electronic Navigational Chart:

CA276274, CA476079

LNM/D. 08-OCT-2021

joining 47°39'03.2"N 054°18'01.0"W

47°38'17.0"N 054°16'43.5"W

47°38'58.6"N 054°15'37.3"W

47°39'38.5"N 054°16'58.3"W

and 47°39'03.2"N 054°18'01.0"W

DFO(6310082-05)

24-JUN-2022

Add marine farm limits

(See Chart No. 1, K48.1)

This notice affects Electronic Navigational Chart:

CA276274, CA476300

LNM/D. 08-OCT-2021

joining 47°29'29.4"N 054°10'26.2"W

47°29'00.6"N 054°09'56.5"W

47°28'51.8"N 054°09'56.5"W

47°27'59.6"N 054°11'25.5"W

47°28'30.5"N 054°11'51.8"W

47°28'53.3"N 054°11'46.9"W

and 47°29'29.4"N 054°10'26.2"W

DFO(6310082-06)

24-JUN-2022

Affix patch

[PDF](#)

This notice affects Electronic Navigational Chart: CA476806

LNM/D. 08-OCT-2021

47°35'00.0"N 054°24'00.0"W

DFO(6310082-11)

08-OCT-2021

Delete red and white fairway lighted pillar whistle buoy

Mo(A), marked PH

(See Chart No. 1, Qh)

This notice affects Electronic Navigational Chart:

CA376173, CA476805

LNM/D. 30-APR-2021

47°23'24.7"N 054°22'15.2"W

(N2021110) LL(49.5) DFO(6309559-01)

30-APR-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 16 fathoms

(See Chart No. 1, L25)

This notice affects Electronic Navigational Chart: CA476079

LNM/D. 19-JUL-2019

47°39'16.0"N 054°10'11.1"W

DFO(6309409-01)

19-JUL-2019

LNM/D. 31-AUG-2018



Chart no. 4619

Amend FLR to read FLY against light
(See Chart No. 1, P1)

47°34'44.3"N 054°25'45.2"W

This notice affects Electronic Navigational Chart: (N2019024) LL(51.68) DFO(6308678-01)
CA476806

31-AUG-2018

LNМ/D. 10-AUG-2018

Add marine farm
(See Chart No. 1, K48.2)

47°34'32.0"N 054°10'07.0"W

This notice affects Electronic Navigational Chart: CA476806

DFO(6308408-01)

10-AUG-2018

LNМ/D. 22-DEC-2017

Reposition subsurface Ocean Data Acquisition system
ODAS/SADO with known depth of 2 fathoms, 4 feet
(See Chart No. 1, L25)

from 47°34'44.4"N 054°21'43.8"W
to 47°34'49.2"N 054°21'37.8"W

This notice affects Electronic Navigational Chart:
CA476806

DFO(6308364-02)

22-DEC-2017

LNМ/D. 29-JUN-2012

Add subsurface Ocean Data Acquisition system ODAS/SADO with
known depth of 2 fathoms, 4 feet
(See Chart No. 1, L25)

47°34'44.4"N 054°21'43.8"W

This notice affects Electronic Navigational Chart: CA476806

DFO(6308166-03)

29-JUN-2012

LNМ/D. 12-AUG-2011

Add light Fl R
(See Chart No. 1, P1)

47°34'44.3"N 054°25'45.2"W

(N2012012) LL(51.68) DFO(6306060-01)

29-JUN-2012

LNМ/D. 12-AUG-2011

Add wharf
(See Chart No 1 F14)

between 47°34'43.0"N 054°25'42.9"W
and 47°34'44.3"N 054°25'45.2"W

DFO(6306060-02)

12-AUG-2011

LNМ/D. 28-JAN-2011



Chart no. 4619

Reposition red starboard hand lighted spar buoy F1R,
marked PH4
(See Chart No. 1, Qf)

from 47°24'28.7"N 054°21'16.9"W
to 47°24'28.3"N 054°21'21.2"W

(N2011047) LL(49.44) DFO(6305654-01)

This notice affects Electronic Navigational
Chart: CA476805

28-JAN-2011

LNМ/D. 17-OCT-2008

Add anchorage area joining 47°42'45.0"N 054°10'23.1"W
(See Chart No. 1, N12.1) 47°42'37.0"N 054°10'24.5"W
47°42'40.2"N 054°11'21.5"W
and 47°42'45.0"N 054°11'20.7"W

DFO(6305208-01)

02-NOV-2007

LNМ/D. 15-DEC-2006

(T)Add private yellow cautionary spar buoy
The mooring is temporary and will be removed by July 2008.
This buoy is permanently discontinued. Notice 2-NOV-2007(T),
DFO(6303667) is now cancelled.
Cancelled on 31-OCT-08

47°31'48.2"N 054°29'33.8"W

DFO(6303667-03)

02-NOV-2007

LNМ/D. 15-DEC-2006

(T)Add private yellow cautionary spar buoy
The mooring is temporary and will be removed by July 2008.
This buoy is permanently discontinued. Notice 2-NOV-2007(T),
DFO(6303668-R1) is now cancelled.
Cancelled on 31-OCT-08

47°24'42.0"N 054°29'37.2"W

DFO(6303668-01)

15-DEC-2006

LNМ/D. 30-SEP-2005

(T)Add private yellow cautionary spar buoy
The mooring is temporary and will be removed by April 2007.
The mooring has been removed. Notice 15-December-2006(T),
DFO (6303199) is now cancelled.
Cancelled on 02-NOV-07

47°31'49.1"N 054°29'33.0"W

DFO(6303199-02)

15-DEC-2006

LNМ/D. 30-SEP-2005



Chart no. 4619

(T)Add private yellow cautionary spar buoy 47°24'40.4"N 054°29'55.1"W
The mooring is temporary and will be removed by April 2007.
The mooring has been removed. Notice 15-December-2006(T), *DFO(6303199-04)*
DFO (6303199) is now cancelled.
Cancelled on 02-NOV-07

15-DEC-2006

LNLM/D. 30-SEP-2005

(T)Add private yellow cautionary spar buoy 47°32'09.5"N 054°14'45.6"W
The mooring is temporary and will be removed by April 2007.
The mooring has been removed. Notice 15-December-2006(T), *DFO(6303199-08)*
DFO (6303199) is now cancelled.
Cancelled on 02-NOV-07

15-DEC-2006

LNLM/D. 30-SEP-2005

(T)Add private yellow cautionary spar buoy 47°33'44.6"N 054°13'18.1"W
The mooring is temporary and will be removed by April 2007.
The mooring has been removed. Notice 15-December-2006(T), *DFO(6303199-09)*
DFO (6303199) is now cancelled.
Cancelled on 02-NOV-07

20-MAY-2005

LNLM/D. 04-OCT-2002

Delete green, port hand spar buoy, marked PV1 47°28'18.0"N 054°23'33.0"W
(N2001031) LL(49.41) DFO(6829514-01)

20-MAY-2005

LNLM/D. 04-OCT-2002

Add green port hand spar light buoy FlG, marked PV1 47°28'21.0"N 054°23'33.6"W
(N2001031) LL(49.41) DFO(6829514-02)

20-MAY-2005

LNLM/D. 04-OCT-2002

Replace red starboard hand spar buoy, marked PV2 with 47°28'18.9"N 054°23'28.8"W
red starboard hand spar light buoy FlR, marked
PV2 *(N2001032) LL(49.42) DFO(6829525-01)*

19-OCT-2001

LNLM/D. 06-OCT-2000



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4619

Replace red starboard hand spar buoy, marked PH2, with
red starboard hand spar light buoy FLR, marked
PH2

47°24'22.2"N 054°21'23.0"W

(N2001033) LL(49.4) DFO(6829526-02)

19-OCT-2001

LN/D. 06-OCT-2000

Replace red starboard hand spar buoy, marked PH4, with
red starboard hand spar light buoy Fl R, marked
PH4

47°24'28.6"N 054°21'16.9"W

(N2001034) LL(49.44) DFO(6829527-02)

06-OCT-2000

Delete green, port hand, spar buoy, marked PQ3

47°34'52.0"N 054°25'56.0"W

(N1999-081) LL(5051.660) DFO(6829037-01)

06-OCT-2000

Add green light, port hand spar bouy Fl G, marked PQ3

47°34'51.0"N 054°25'57.0"W

(N1999-081) LL(51.660) DFO(6829037-02)

4619 - Continuation A - New Edition - 20-NOV-1998 - NAD 1983

17-OCT-2008

LN/D. 02-NOV-2007

Add light QR
(See Chart No 1 P1)

47°23'43.0"N 054°35'15.0"W

(N2007060) LL(51.69) DFO(6303991-01)

02-NOV-2007

LN/D. 15-DEC-2006

(T)Add private yellow cautionary spar buoy

47°28'09.2"N 054°32'19.4"W

The mooring is temporary and will be removed by July 2008.

This buoy is permanently discontinued. Notice 2-NOV-2007(T),

DFO(6303667) is now cancelled.

DFO(6303667-01)

Cancelled on 31-OCT-08

15-DEC-2006

LN/D. 30-SEP-2005



Chart no. 4619

(T)Add private yellow cautionary spar buoy 47°28'10.3"N 054°32'18.9"W
The mooring is temporary and will be removed by April 2007.
The mooring has been removed. Notice 15-December-2006(T), *DFO(6303199-03)*
DFO (6303199) is now cancelled.
Cancelled on 02-NOV-07

30-SEP-2005 LNM/D. 20-MAY-2005
Delete depth of 8 fathoms, 4 feet 47°25'00.0"N 054°35'30.0"W
DFO(6302502-01)

30-SEP-2005 LNM/D. 20-MAY-2005
Add depth of 1 fathom, 2 feet 47°24'58.6"N 054°35'30.1"W
DFO(6302502-02)

04-OCT-2002 LNM/D. 04-JAN-2002
Add green port hand spar light buoy FlG, marked PE5 47°22'57.5"N 054°38'58.3"W
(N2001014) LL(53.29) DFO(6829427-01)

04-JAN-2002 LNM/D. 19-OCT-2001
Replace red light, starboard hand spar buoy QR, marked 47°23'44.4"N 054°34'38.0"W
PE10, with red light, starboard hand spar buoy
FlR, marked PS2 *(N2000077) LL(51.65) DFO(6828840-01)*