



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4703

4703 - White Point to / à Corbet Island - New Edition - 04-APR-2003 - NAD 1983

29-DEC-2023

LNМ/D. 02-DEC-2022

Add black, red and black isolated danger lighted pillar
buoy Fl(2)5s, marked NLL
(See Chart 1, Q130.4)

53°20'17.8"N 055°38'50.6"W

(N2023152) LL(280.17) DFO(6310915-01)

02-DEC-2022

LNМ/D. 19-AUG-2022

Amend Fl 4s 107ft to read Fl 5s107ft against light
(See Chart 1, P16)

53°25'59.9"N 055°44'39.7"W

This notice affects Electronic Navigational Chart: (N2022244) LL(280.9) DFO(6310418-01)
CA376596

02-DEC-2022

LNМ/D. 19-AUG-2022

Amend Fl 6s 72ft to read Fl 5s69ft against light
(See Chart 1, P16)

53°34'38.0"N 056°01'29.0"W

This notice affects Electronic Navigational Chart: (N2022246) LL(282) DFO(6310433-01)
CA376596

19-AUG-2022

LNМ/D. 15-JAN-2016

Amend Fl 6s127ft to read Fl 4s127ft against light
(See Chart No. 1, P16)

53°27'42.6"N 055°44'32.6"W

This notice affects Electronic Navigational Chart: (N2022116) LL(281) DFO(6310177-01)
CA276113, CA376596

15-JAN-2016

LNМ/D. 30-JUL-2010

Add depth of 5 fathoms, 5 feet
(See Chart No. 1, I10)

53°34'09.8"N 056°00'20.7"W

This notice affects Electronic Navigational Chart: CA376596 DFO(6307408-01)

15-JAN-2016

LNМ/D. 30-JUL-2010

Add depth of 4 fathoms, 4 feet
(See Chart No. 1, I10)

53°32'59.0"N 055°57'33.4"W

This notice affects Electronic Navigational Chart: CA376596 DFO(6307408-02)

15-JAN-2016

LNМ/D. 30-JUL-2010

Add depth of 7 fathoms, 5 feet
(See Chart No. 1, I10)

53°31'56.5"N 055°43'30.1"W

This notice affects Electronic Navigational Chart: CA376596 DFO(6307408-03)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4703

30-JUL-2010

Reposition black, yellow and black East cardinal lighted
pillar buoy Q(3) 10s, marked NLG
(See Chart No 1 Q130.3)

LNМ/D. 23-JUL-2010

from 53°21'00.4"N 055°43'36.5"W
to 53°20'56.6"N 055°43'42.4"W

(N2010016) LL(280.15) DFO(6304967-01)

23-JUL-2010

Reposition red starboard hand lighted spar buoy F1R,
marked N14
(See Chart No 1 Qf)

LNМ/D. 02-JUL-2010

from 53°33'33.4"N 055°59'21.0"W
to 53°33'35.3"N 055°59'23.5"W

(N2010016) LL(281.8) DFO(6304961-01)

This notice affects Electronic Navigational
Chart: CA376596

23-JUL-2010

Reposition yellow and black South cardinal lighted pillar
buoy Q(6)+LFl 15s, marked NL
(See Chart No 1 Q130.3)

LNМ/D. 02-JUL-2010

from 53°15'31.3"N 055°41'17.3"W
to 53°15'27.8"N 055°41'22.1"W

(N2010016) LL(280.1) DFO(6304965-01)

02-JUL-2010

Reposition yellow, black, yellow West cardinal pillar
light buoy VQ(9) 10s, marked NLW
(See Chart No 1 Q130.3)

LNМ/D. 03-APR-2009

from 53°18'45.1"N 055°45'03.5"W
to 53°18'50.2"N 055°45'06.7"W

(N2010016) LL(280.13) DFO(6304915-01)

03-APR-2009

Add ferry route joining 53°41'07.5"N 056°11'55.9"W
(See Chart No 1 M50) 53°38'51.0"N 056°03'48.0"W
53°36'48.0"N 055°52'31.2"W
53°33'06.0"N 055°44'30.0"W
53°26'00.0"N 055°34'00.0"W
and 53°13'00.4"N 055°30'06.7"W

LNМ/D. 15-SEP-2006

DFO(6303322-01)

03-APR-2009

LNМ/D. 15-SEP-2006



Chart no. 4703

Add ferry route joining 53°33'06.0"N 055°44'30.0"W
(See Chart No 1 M50) 53°25'42.0"N 055°37'18.0"W
and 53°13'00.4"N 055°32'59.6"W

DFO(6303322-02)

15-SEP-2006

LNМ/D. 08-SEP-2006

Delete red starboard hand lighted spar buoy FIR, marked
NTK2

53°33'02.2"N 055°58'40.0"W

(N2006050) LL(281.7) DFO(6302938-02)

15-SEP-2006

LNМ/D. 08-SEP-2006

Add red starboard hand lighted spar buoy FIR, marked
N12

53°33'02.2"N 055°58'35.6"W

(N2006050) LL(281.7) DFO(6302938-03)

15-SEP-2006

LNМ/D. 08-SEP-2006

Amend "NTK5" to read "N15" against green port hand
spar light buoy FIG

53°33'32.3"N 055°59'42.6"W

(N2006053) LL(281.9) DFO(6302941-01)

15-SEP-2006

LNМ/D. 08-SEP-2006

Amend "NTK6" to read "N14" against red starboard hand
lighted spar buoy FIR

53°33'33.4"N 055°59'21.0"W

(N2006054) LL(281.8) DFO(6302942-01)

08-SEP-2006

LNМ/D. 24-SEP-2004

Delete green port hand lighted pillar buoy FIG, marked
NBT5

53°27'06.0"N 055°45'47.5"W

(N2006051) LL(280.91) DFO(6302939-01)

24-SEP-2004

LNМ/D. 13-FEB-2004

Reposition green port hand spar light buoy FIG, marked
NTK5

from 53°33'33.4"N 055°59'55.6"W
to 53°33'32.3"N 055°59'42.6"W

(N2004150) LL(281.9) DFO(6301836-01)

13-FEB-2004



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4703

Delete red and white fairway, pillar light buoy Mo (A)
marked NL, BELL

53°15'30.0"N 055°41'54.0"W

(N2002094) LL(280.1) DFO(6300509-01)

13-FEB-2004

Add yellow and black , South cardinal pillar light buoy Q
(6) + LFl 15s, marked NL

53°15'31.3"N 055°41'17.3"W

(N2002094) LL(280.1) DFO(6300509-02)

13-FEB-2004

Delete red starboard spar light buoy Fl R, marked NL14

53°18'48.0"N 055°45'03.5"W

(N2002148) LL(280.13) DFO(6300622-01)

13-FEB-2004

Add yellow, black, yellow West cardinal pillar light buoy
VQ(9) 10s, marked NLW

53°18'45.1"N 055°45'03.5"W

(N2002096) LL(280.13) DFO(6300622-02)