



Chart no. 4817

4817 - Bay Bulls to / à St. Mary's Bay - New Edition - 23-AUG-2002 - NAD 1983

24-OCT-2003

Amend Fl to read 2 Lts Oc G Fl R against light 46°52'42.0"N 053°57'01.0"W

(N1998126) LL(10) DFO(6300725-01)

09-JUL-2004

LNM/D. 24-OCT-2003

Amend "Fl 10s 31m 17M" to read "Fl 10s 31m 22M" against light 46°41'25.3"N 053°24'09.2"W

LL(5) DFO(6301607-01)

24-DEC-2004

LNM/D. 09-JUL-2004

Delete legend "WHIS" against red and white fairway pillar
light buoy Mo(A), WHIS marked ML

46°47'00.0"N 054°03'16.0"W

(N2004186) LL(13) DFO(6302059-01)

24-DEC-2004

LNM/D. 09-JUL-2004

Delete legend "BELL" against red and white fairway pillar
light and bell buoy Mo (A), BELL, marked MC

46°37'40.0"N 053°36'47.0"W

(N2004189) LL(7.2) DFO(6302098-01)

24-DEC-2004

LNM/D. 09-JUL-2004

Delete legend "BELL" against red starboard hand pillar light
and bell buoy FIR, BELL marked M14

46°36'18.0"N 053°32'30.0"W

(N2004190) LL(6.5) DFO(6302099-01)

31-DEC-2004

LNM/D. 24-DEC-2004

Delete legend "WHIS" against red, green and red starboard
bifurcation pillar light and whistle buoy Fl(2+1) R,
WHIS marked MS

46°56'11.0"N 053°43'12.0"W

(N2004192) LL(8.7) DFO(6302103-01)

31-DEC-2004

LNM/D. 24-DEC-2004

Delete legend 'BELL' against black and yellow North
cardinal pillar light and bell buoy Q, BELL marked
MLR

46°28'20.9"N 054°01'49.3"W

(N2004193) LL(7.4) DFO(6302104-01)



Chart no. 4817

07-JAN-2005

Delete white and orange information pillar light and whistle buoy FLY, WHIS, marked MMP

LNLM/D. 31-DEC-2004

46°37'04.9"N 053°09'35.5"W

(N2004201) LL(1.5) DFO(6302133-01)

23-SEP-2005

Delete legend "BELL" against red and white fairway pillar light and bell buoy LFI, BELL, marked MPS

LNLM/D. 07-JAN-2005

46°41'25.2"N 053°17'25.0"W

(N2005056) LL(1.55) DFO(6302461-03)

31-OCT-2008

Add black, yellow and black East cardinal lighted pillar buoy Q(3) 10s, marked MCB
(See Chart No 1 Q130.3)

LNLM/D. 23-SEP-2005

47°04'20.3"N 052°50'17.5"W

(N2008034) LL(508.211) DFO(6304033-01)

This notice affects Electronic Navigational Chart:
CA376070

09-APR-2010

Amend Fl 5s 33m 16M to read Fl 5s 33m 15M against light
(See Chart No 1 P16)

LNLM/D. 31-OCT-2008

46°56'26.1"N 052°53'37.9"W

LL(512) DFO(6304778-01)

This notice affects Electronic Navigational Chart: CA276091

09-JUL-2010

Reposition black and yellow North cardinal pillar light buoy Q, marked MLR
(See Chart No 1 Q130.3)

LNLM/D. 09-APR-2010

from 46°28'21.0"N 054°01'48.0"W

to 46°27'57.6"N 054°01'43.8"W

(N2010016) LL(7.4) DFO(6304953-01)

This notice affects Electronic Navigational Chart:
CA376075

31-DEC-2010

Delete legend Loran against tower
(See Chart No. 1, E20)

LNLM/D. 09-JUL-2010

46°46'32.0"N 053°10'28.0"W

(N2010062) DFO(6305143-01)

This notice affects Electronic Navigational Chart: CA176030,
CA276091, CA376106



Chart no. 4817

18-APR-2014

Delete legend Fog Sig against light
(See Chart No. 1, R1, R20)

This notice affects Electronic Navigational Chart:
CA276091, CA376106, CA576107

LNLM/D. 31-DEC-2010

46°41'25.1"N 053°24'05.7"W

(N2014019) LL(5) DFO(6306714-02)

04-DEC-2015

Add submarine cable

(See Chart No. 1, L30.1)

This notice affects Electronic Navigational Chart:
CA376075

LNLM/D. 18-APR-2014

joining 46°43'19.3"N 051°59'57.1"W

46°30'46.1"N 052°42'35.9"W

46°27'27.2"N 052°53'29.2"W

46°18'01.8"N 053°56'14.0"W

and 46°17'00.7"N 054°02'56.4"W

DFO(6307359-01)

31-MAR-2017

Add submarine cable

(See Chart No. 1, L30.1)

This notice affects Electronic Navigational Chart:
CA276091, CA276101, CA376015, CA376070, CA376075

LNLM/D. 04-DEC-2015

joining 47°05'13.0"N 052°53'48.0"W

47°05'13.0"N 052°51'42.0"W

47°06'00.0"N 052°50'16.0"W

47°05'56.0"N 052°48'26.3"W

47°04'27.0"N 052°41'32.0"W

47°04'10.0"N 052°28'44.8"W

46°59'24.0"N 052°15'20.0"W

and 46°56'43.0"N 051°59'57.1"W

DFO(6307887-01)

06-APR-2018

Delete yellow ODAS/SADO lighted super-buoy Fl (5) Y, marked 44251
(See Chart No. 1, Q58)

This notice affects Electronic Navigational Chart: CA176030,
CA276091, CA376075

LNLM/D. 31-MAR-2017

46°26'30.0"N 053°23'18.0"W

DFO(6308224-02)

29-MAR-2019

Amend "WHIS" to read "BELL" against red and white fairway
pillar light buoy Mo(A), marked ME
(See Chart No. 1, R15, R14)

This notice affects Electronic Navigational Chart:
CA376106, CA576107

LNLM/D. 06-APR-2018

46°41'15.0"N 053°24'45.0"W

(N2019005) LL(5.5) DFO(6308597-01)

10-APR-2020

LNLM/D. 29-MAR-2019



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4817

Amend "WHIS" to read "Bell" against red starboard hand
pillar light buoy Fl R, marked M16
(See Chart No. 1, Qc, Qd)

46°41'51.3"N 054°13'08.9"W

(N2020011) LL(12) DFO(6308955-01)

This notice affects Electronic Navigational Chart:
CA276091, CA376135