



Chart no. 4849

4849 - Bonavista Harbour - New Chart - 30-DEC-1988 - NAD 1983

11-JAN-2019

LNM/D. 29-JUN-2018

Affix patch

48°38'56.0"N 053°06'48.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576310

DFO(6308542-01)

29-JUN-2018

LNM/D. 12-MAY-2017

Affix patch

48°39'00.0"N 053°07'00.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576310

DFO(6308316-01)

24-MAR-2017

LNM/D. 28-OCT-2016

Delete light Fl

48°39'06.1"N 053°07'42.6"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (N2016083P) LL(446) DFO(6307807-01)
CA376340, CA576310

24-JUL-2015

LNM/D. 27-MAR-2015

Affix patch

48°39'00.0"N 053°06'50.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576310

DFO(6307176-01)

10-FEB-2012

LNM/D. 04-JUN-2010

Delete green port hand lighted spar buoy FlG, marked JB7 48°39'00.1"N 053°07'54.8"W
(See Chart No. 1, Qg)

LL(445.4) DFO(6305912-01)

10-FEB-2012

LNM/D. 04-JUN-2010

Add green port hand lighted spar buoy FlG, marked JB7 48°39'00.1"N 053°07'11.6"W
(See Chart No. 1, Qg)

LL(445.4) DFO(6305912-02)

03-OCT-2008

LNM/D. 28-DEC-2007

Delete green port hand lighted spar buoy FlG, marked
JB3

48°39'02.5"N 053°07'54.8"W

(See Chart No 1 Qg)

(N2008008) LL(445.2) DFO(6303961-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4849

03-OCT-2008

LNM/D. 28-DEC-2007

Add green port hand lighted pillar buoy FlG, marked JB5

48°39'02.5"N 053°07'54.8"W

(N2008007) LL(446.1) DFO(6303961-02)

19-OCT-2007

LNM/D. 01-JUN-2007

Add breakwater extension and legend Breakwater/Brise-lames joining
(See Chart No 1 Section F 4.3.)

48°38'57.5"N 053°07'06.0"W

48°38'58.2"N 053°07'06.3"W

48°38'58.3"N 053°07'05.8"W

and 48°38'57.7"N 053°07'05.6"W

DFO(6303605-01)

19-OCT-2007

LNM/D. 01-JUN-2007

Delete light QR

48°38'57.5"N 053°07'06.0"W

(See Chart No 1 Section P 16.)

(N2005105) LL(447) DFO(6303605-02)

19-OCT-2007

LNM/D. 01-JUN-2007

Add light QR

48°38'58.1"N 053°07'06.2"W

(See Chart No 1 Section P 16.)

(N2005105) LL(447) DFO(6303605-03)

19-OCT-2007

LNM/D. 01-JUN-2007

Delete depth of 4 metres, 6 decimetres

(See Chart No 1 Section I 10.)

DFO(6303605-04)

01-JUN-2007

LNM/D. 01-SEP-2006

Delete light QR

48°38'57.2"N 053°07'04.5"W

(N2005105) LL(447) DFO(6302708-01)

01-JUN-2007

LNM/D. 01-SEP-2006

Add light QR

48°38'57.5"N 053°07'06.0"W

(N2005105) LL(447) DFO(6302708-02)

01-SEP-2006

LNM/D. 11-AUG-2006



Chart no. 4849

Delete red starboard hand lighted spar buoy FLR, marked JB8 48°38'55.5"N 053°06'56.7"W
(N2006093) LL(447.2) DFO(6303002-01)

01-SEP-2006 LNM/D. 11-AUG-2006
Add green port hand lighted spar buoy FIG, marked JB7 48°39'00.1"N 053°07'54.8"W
(N2006102) LL(445.4) DFO(6303013-01)

01-SEP-2006 LNM/D. 11-AUG-2006
Add green port hand lighted spar buoy FIG, marked JB3 48°39'02.5"N 053°07'54.8"W
(N2006103) LL(445.2) DFO(6303014-01)

01-SEP-2006 LNM/D. 11-AUG-2006
Reposition red starboard hand lighted spar buoy FLR, marked JB6 from 48°38'56.0"N 053°06'59.5"W
to 48°38'55.9"N 053°06'58.2"W
(N2006105) LL(447.1) DFO(6303017-01)

03-JUN-2005 LNM/D. 28-JAN-2005
Add floating dock between 48°39'01.0"N 053°06'53.8"W
and 48°38'59.7"N 053°06'53.2"W
(N2000371) LL(448.1) DFO(6829260-01)

03-JUN-2005 LNM/D. 28-JAN-2005
Add light FIG 48°38'59.7"N 053°06'53.2"W
(N2000371) LL(448.1) DFO(6829260-02)

10-OCT-2003 LNM/D. 20-JUN-2003
Delete red and white fairway pillar, light and whistle buoy Mo (A), WHIS, marked JB 48°38'49.8"N 053°08'33.5"W
(N2002060) LL(445) DFO(6300418-01)

25-JAN-2002 LNM/D. 30-MAR-2001



Chart no. 4849

Amend FG to read FIG 48°39'00.8"N 053°06'50.5"W

(N2000062) LL(448) DFO(6828822-01)

25-JAN-2002

LNМ/D. 30-MAR-2001

Replace red starboard hand spar buoy, marked JB6, with
red light, starboard hand spar buoy FIR, marked
JB6

48°38'56.0"N 053°06'59.5"W

(N2000271) LL(447.1) DFO(6829131-01)

25-JAN-2002

LNМ/D. 30-MAR-2001

Replace red starboard hand spar buoy, marked JB8, with
red light, starboard hand spar buoy FIR, marked
JB8

48°38'55.5"N 053°06'56.7"W

(N2000272) LL(447.2) DFO(6829132-01)

4849 - Catalina and / et Port Union - New Chart - 30-DEC-1988 - NAD 1983

24-DEC-2021

LNМ/D. 26-APR-2019

Delete light FIR

48°30'40.3"N 053°04'03.5"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA576394

(N2021229) LL(458) DFO(6309876-01)

04-JUN-2010

LNМ/D. 08-MAY-2009

Reposition red starboard hand lighted pillar buoy FIR,
marked TC2
(See Chart No 1 Qf)

from 48°30'13.7"N 053°01'26.6"W
to 48°30'12.9"N 053°01'26.5"W

(N2010016) LL(452) DFO(6304837-01)

19-DEC-2003

LNМ/D. 10-OCT-2003

Amend Fl (3) 12s 28m 18M to read Fl 4s 28m 16M against
light

48°30'14.8"N 053°02'37.4"W

(N2003039) LL(453) DFO(6301008-01)

20-JUN-2003

LNМ/D. 13-JUN-2003



Chart no. 4849

Replace red starboard hand pillar light buoy FIR, WHIS,
marked TC2 with red starboard hand pillar light
buoy FIR, marked TC2

48°30'14.0"N 053°01'26.3"W

(N2002049) LL(452) DFO(6300408-01)

25-JAN-2002

LNМ/D. 30-MAR-2001

Replace red starboard hand spar buoy, marked TC6 with
red light, starboard hand spar buoy FIR, marked
TC6

48°30'41.0"N 053°04'16.4"W

(N2000273) LL(458.81) DFO(6829133-01)

4849 - Catalina Harbour - New Chart - 30-DEC-1988 - NAD 1983

24-DEC-2021

LNМ/D. 26-APR-2019

Delete light Fl R

48°30'40.2"N 053°04'03.1"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart:
CA576394

(N2021229) LL(458) DFO(6309876-01)

26-APR-2019

LNМ/D. 11-JAN-2019

Affix patch

48°31'00.0"N 053°04'30.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576394

DFO(6308617-01)

27-MAR-2015

LNМ/D. 10-FEB-2012

Amend FlG to read QG against green port hand pillar light
buoy, marked TC11
(See Chart No. 1, Qg)

48°30'51.1"N 053°04'18.1"W

(N2015011) LL(460) DFO(6307070-01)

This notice affects Electronic Navigational Chart:
CA576395

11-AUG-2006

LNМ/D. 26-MAY-2006

Amend "FR" to read "FIR" against light

48°30'55.3"N 053°04'30.1"W

(N2006020) LL(461) DFO(6302910-01)

28-JAN-2005

LNМ/D. 19-DEC-2003



Chart no. 4849

Delete light FR 48°30'54.8"N 053°04'32.5"W

(N2004200) LL(461) DFO(6302129-01)

28-JAN-2005

LNM/D. 19-DEC-2003

Delete depth of 4 metres, 9 decimetres 48°30'54.8"N 053°04'32.1"W

DFO(6302129-02)

28-JAN-2005

LNM/D. 19-DEC-2003

Add wharf extension joining 48°30'54.7"N 053°04'32.5"W
(See Chart No 1 F14) 48°30'55.2"N 053°04'30.0"W
48°30'55.4"N 053°04'30.1"W
and 48°30'55.0"N 053°04'32.6"W

DFO(6302129-03)

28-JAN-2005

LNM/D. 19-DEC-2003

Add light FR 48°30'55.3"N 053°04'30.1"W

(N2004200) LL(461) DFO(6302129-04)

28-JAN-2005

LNM/D. 19-DEC-2003

Add depth of 3 metres, 7 decimetres 48°30'55.2"N 053°04'32.3"W

DFO(6302129-05)

28-JAN-2005

LNM/D. 19-DEC-2003

Add depth of 3 metres, 9 decimetres 48°30'55.3"N 053°04'30.0"W

DFO(6302129-06)

28-JAN-2005

LNM/D. 19-DEC-2003

Add depth of 4 metres, 2 decimetres 48°30'54.8"N 053°04'31.1"W

DFO(6302129-07)

07-JUN-2002

LNM/D. 25-JAN-2002



Chart no. 4849

Replace red, starboard hand spar buoy, marked TC10
with red starboard hand spar light buoy FIR,
marked TC10

48°30'51.0"N 053°04'14.8"W

(N2001012) LL(459.1) DFO(6300280-01)

25-JAN-2002

LNM/D. 30-MAR-2001

Replace red starboard hand spar buoy, marked TC6 with
red light, starboard hand spar buoy FIR, marked
TC6

48°30'41.0"N 053°04'16.4"W

(N2000273) LL(458.81) DFO(6829133-01)

4849 - Fish Plant / Conserverie de poisson - New Chart - 30-DEC-1988 - NAD 1983

09-SEP-2022

LNM/D. 24-DEC-2021

Add depth of 1 metre

47°41'21.9"N 053°13'16.7"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-01)

09-SEP-2022

LNM/D. 24-DEC-2021

Add depth of 1.6 metres

47°41'27.1"N 053°13'03.7"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-02)

09-SEP-2022

LNM/D. 24-DEC-2021

Add depth of 0.6 metres

47°41'27.1"N 053°13'01.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-03)

09-SEP-2022

LNM/D. 24-DEC-2021

Delete depth of 1.4 metres

47°41'26.8"N 053°13'00.6"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-04)

09-SEP-2022

LNM/D. 24-DEC-2021

Add depth of 1 metre

47°41'26.9"N 053°13'00.4"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-05)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4849

09-SEP-2022

LNМ/D. 24-DEC-2021

Add depth of 5.5 metres

47°41'21.8"N 053°13'16.1"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-06)

09-SEP-2022

LNМ/D. 24-DEC-2021

Delete depth of 5.8 metres

47°41'21.7"N 053°13'16.0"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-07)

09-SEP-2022

LNМ/D. 24-DEC-2021

Add depth of 5.9 metres

47°41'22.3"N 053°13'12.6"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-08)

09-SEP-2022

LNМ/D. 24-DEC-2021

Add depth of 3.6 metres

47°41'26.0"N 053°13'04.2"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-09)

09-SEP-2022

LNМ/D. 24-DEC-2021

Delete depth of 4.2 metres

47°41'25.8"N 053°13'03.9"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-10)

09-SEP-2022

LNМ/D. 24-DEC-2021

Add depth of 1.2 metres

47°41'27.6"N 053°13'01.6"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-11)

09-SEP-2022

LNМ/D. 24-DEC-2021

Delete depth of 1.2 metres

47°41'27.3"N 053°13'01.3"W

(See Chart No. 1, I10)

This notice affects Electronic Navigational Chart: CA576398

DFO(6310229-12)

13-JUN-2003

LNМ/D. 23-MAY-2003



Chart no. 4849

Affix patch 47°42'30.0"N 053°18'30.0"W

DFO(6500109-01)

[PDF](#)

30-MAR-2001

LNМ/D. 01-OCT-1999

(T)Delete light

47°41'24.6"N 053°12'52.8"W

The original light has been temporarily dismantled to facilitate new construction. (N2001-009(T)) LL(481.000) DFO(6829425-01)
A temporary light has been installed.
Temporay light discontinued. Original light reconstructed. See reference DFO 6500109 appearing in Edition 6, 13-JUN-2003. With this notification, Notice dated 30-MAR-2001(T), DFO 6829425 is cancelled.
Cancelled on 22-AUG-03

30-MAR-2001

LNМ/D. 01-OCT-1999

(T)Add light, Fl R

47°41'24.4"N 053°12'52.8"W

The original light has been temporarily dismantled to facilitate new construction. A temporary light has been installed. (N2001-009(T)) DFO(6829425-02)
Temporay light discontinued. Original light reconstructed. See reference DFO 6500109 appearing in Edition 6, 13-JUN-2003. With this notification, Notice dated 30-MAR-2001(T), DFO 6829425 is cancelled.
Cancelled on 18-JUL-03

4849 - Harbour Grace and / et Carbonear - New Chart - 30-DEC-1988 - NAD 1983

12-MAY-2017

LNМ/D. 24-MAR-2017

Add breakwater with legend Bkw

joining 47°44'17.7"N 053°13'22.1"W

(See Chart No. 1, F4.1)

47°44'14.5"N 053°13'22.2"W

This notice affects Electronic Navigational Chart:

and 47°44'13.0"N 053°13'23.6"W

CA376120, CA476405

DFO(6307708-01)

12-MAY-2017

LNМ/D. 24-MAR-2017

Add light FlR

47°44'13.0"N 053°13'23.6"W

(See Chart No. 1, P1)

This notice affects Electronic Navigational Chart: (N2016054) LL(477.5) DFO(6307708-02)

CA376120, CA476405



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4849

28-OCT-2016

Amend Fl R to read Fl Y against light
(See Chart No. 1, P16)

This notice affects Electronic Navigational Chart:
CA376120, CA476405, CA576416

LNМ/D. 24-JUL-2015

47°44'14.5"N 053°13'26.4"W

(N2016053) LL(478) DFO(6307707-01)

26-MAY-2006

Delete depth of 7 metres 47°40'40.5"N 053°14'40.0"W

LNМ/D. 03-JUN-2005

DFO(6302811-01)

26-MAY-2006

Add depth of 0 metres, 2 decimetres, with a bottom quality of Bo 47°40'41.4"N 053°14'40.1"W

LNМ/D. 03-JUN-2005

DFO(6302811-02)

13-JUN-2003

Affix patch 47°41'18.0"N 063°13'00.0"W

LNМ/D. 23-MAY-2003

DFO(6500109-02)

[PDF](#)

23-MAY-2003

Delete red and white fairway pillar light buoy Mo(A), WHIS,
marked CC

LNМ/D. 26-JUL-2002

47°45'00.0"N 053°09'25.5"W

(N2002048) LL(476) DFO(6300407-01)

26-JUL-2002

Delete light FR

LNМ/D. 07-JUN-2002

47°40'52.3"N 053°14'22.2"W

(N2002004) LL(482.000) DFO(6300091-01)

30-MAR-2001

LNМ/D. 01-OCT-1999



Chart no. 4849

(T)Delete light

47°41'24.6"N 053°12'52.8"W

The original light has been temporarily dismantled to facilitate new construction. (N2001-009(T)) LL(481.000) DFO(6829425-01)
A temporary light has been installed.
Temporay light discontinued. Original light reconstructed. See reference DFO 6500109 appearing in Edition 6, 13-JUN-2003. With this notification, Notice dated 30-MAR-2001(T), DFO 6829425 is cancelled.
Cancelled on 22-AUG-03

30-MAR-2001

LNLM/D. 01-OCT-1999

(T)Add light, Fl R

47°41'24.4"N 053°12'52.8"W

The original light has been temporarily dismantled to facilitate new construction. A temporary light has been installed. (N2001-009(T)) DFO(6829425-02)
Temporay light discontinued. Original light reconstructed. See reference DFO 6500109 appearing in Edition 6, 13-JUN-2003. With this notification, Notice dated 30-MAR-2001(T), DFO 6829425 is cancelled.
Cancelled on 18-JUL-03

4849 - Port Union - New Chart - 30-DEC-1988 - NAD 1983

28-JAN-2005

LNLM/D. 19-DEC-2003

Delete yellow cautionary can buoy, marked Priv 48°30'10.0"N 053°04'36.8"W

DFO(6302206-01)

28-JAN-2005

LNLM/D. 19-DEC-2003

Delete yellow cautionary can buoy, marked Priv 48°30'11.3"N 053°04'44.0"W

DFO(6302206-02)

4849 - Public Wharf / Quai - New Chart - 30-DEC-1988 - NAD 1983

26-MAY-2023

LNLM/D. 09-SEP-2022

Delete depth of 1.2 metres

47°44'17.2"N 053°13'26.2"W

(See Chart 1, I10)

This notice affects Electronic Navigational Chart: CA576416

DFO(6310662-01)



Chart no. 4849

26-MAY-2023

LNМ/D. 09-SEP-2022

Add depth of 0.5 metres
(See Chart 1, I10)

47°44'17.3"N 053°13'26.0"W

This notice affects Electronic Navigational Chart: CA576416

DFO(6310662-02)

26-MAY-2023

LNМ/D. 09-SEP-2022

Add depth of 1.7 metres
(See Chart 1, I10)

47°44'17.0"N 053°13'26.4"W

This notice affects Electronic Navigational Chart: CA576416

DFO(6310662-03)

12-MAY-2017

LNМ/D. 24-MAR-2017

Affix patch

47°44'16.0"N 053°13'25.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576416

DFO(6307708-03)

28-OCT-2016

LNМ/D. 24-JUL-2015

Amend Fl R to read Fl Y against light
(See Chart No. 1, P16)

47°44'14.5"N 053°13'26.4"W

This notice affects Electronic Navigational Chart: (N2016053) LL(478) DFO(6307707-01)
CA376120, CA476405, CA576416

4849 - The Admiral's Marina - New Chart - 30-DEC-1988 - NAD 1983

29-JUN-2018

LNМ/D. 12-MAY-2017

Affix patch

47°40'24.0"N 053°14'24.0"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576731

DFO(6308316-02)

08-MAY-2009

LNМ/D. 03-OCT-2008

Delete light FlR
(See Chart No 1 P1)

47°40'23.2"N 053°14'22.8"W

(N2009004) LL(482.71) DFO(6304340-01)

08-MAY-2009

LNМ/D. 03-OCT-2008

Add light FlR
(See Chart No 1 P1)

47°40'23.3"N 053°14'23.0"W

(N2009004) LL(482.71) DFO(6304340-02)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4849

08-MAY-2009

LNМ/D. 03-OCT-2008

Delete coastline between 47°40'22.3"N 053°14'25.2"W
(See Chart No. 1, C1) and 47°40'23.3"N 053°14'22.5"W

DFO(6304340-03)

08-MAY-2009

LNМ/D. 03-OCT-2008

Add wharf extension joining 47°40'22.3"N 053°14'25.2"W
(See Chart No 1 F13) 47°40'23.3"N 053°14'22.9"W
and 47°40'23.2"N 053°14'22.8"W

DFO(6304340-04)

08-MAY-2009

LNМ/D. 03-OCT-2008

Add coastline between 47°40'23.2"N 053°14'22.8"W
(See Chart No. 1 C1) and 47°40'23.3"N 053°14'22.5"W

DFO(6304340-05)

08-MAY-2009

LNМ/D. 03-OCT-2008

Delete depth of 0 metres, 8 decimetres 47°40'22.5"N 053°14'23.9"W
(See Chart No 1 I10)

DFO(6304340-06)

28-DEC-2007

LNМ/D. 19-OCT-2007

Affix patch 47°40'24.0"N 053°14'27.0"W

(N2006117) LL(482.789) DFO(6303760-01)

[PDF](#)