



Chart no. 4854

4854 - Catalina Harbour to / à Inner Gooseberry Islands - New Chart - 25-APR-1997 - NAD 1983

01-JUL-2022

LNM/D. 10-DEC-2021

Amend Fl 3s91m5M to read LFl 6s91m7M against light
(See Chart No. 1, P16)

48°41'09.0"N 053°35'23.1"W

This notice affects Electronic Navigational Chart:
CA276092, CA376340

(N2022063) LL(441) DFO(6310094-01)

01-JUL-2022

LNM/D. 10-DEC-2021

Delete green port hand lighted pillar buoy QG, marked J7
(See Chart No. 1, Qg)

48°37'11.9"N 053°24'58.7"W

This notice affects Electronic Navigational Chart:
CA376340

(N2022073) LL(442.9) DFO(6310106-01)

01-JUL-2022

LNM/D. 10-DEC-2021

Add red starboard hand lighted pillar buoy Q R, marked
JK4

48°37'14.7"N 053°24'56.1"W

(See Chart No. 1, Qf)

This notice affects Electronic Navigational Chart:
CA376340

(N2022073) LL(442.9) DFO(6310106-02)

10-DEC-2021

LNM/D. 15-OCT-2021

Delete underwater rock of unknown depth, dangerous to surface
navigation with legend Rep (2020)

48°32'13.4"N 053°37'57.8"W

(See Chart No. 1, K13)

This notice affects Electronic Navigational Chart: CA376340

DFO(6309804-01)

10-DEC-2021

LNM/D. 15-OCT-2021

Add dangerous underwater rock with depth of 5.2 metres
(See Chart No. 1, K14/K14.2)

48°32'14.4"N 053°37'58.0"W

This notice affects Electronic Navigational Chart: CA376340

DFO(6309804-02)

15-OCT-2021

LNM/D. 21-FEB-2020

Add light Fl Y
(See Chart No. 1, P1)

48°36'27.7"N 053°24'27.1"W

This notice affects Electronic Navigational Chart:
CA376340

(N2021135) LL(442.95) DFO(6309603-01)



Chart no. 4854

21-FEB-2020

Add underwater rock of unknown depth, dangerous to surface navigation with legend "Rep (2020)"
(See Chart No. 1, K13, I3.2)

LNМ/D. 28-JUL-2017

48°32'13.2"N 053°37'57.7"W

DFO(6308931-01)

This notice affects Electronic Navigational Chart: CA376340

28-JUL-2017

Add private yellow ODAS/SADO lighted pillar Fl (5) Y
(See Chart No. 1, Q58)

LNМ/D. 24-MAR-2017

48°41'36.0"N 053°01'00.0"W

DFO(6308013-01)

This notice affects Electronic Navigational Chart: CA376340

24-MAR-2017

Delete light Fl 6s15m5M
(See Chart No. 1, P1)

LNМ/D. 09-JUL-2010

48°39'06.1"N 053°07'42.6"W

This notice affects Electronic Navigational Chart: (N2016083P) LL(446) *DFO(6307807-01)*
CA376340, CA576310

09-JUL-2010

Delete green port hand lighted spar buoy FlG, marked JB3
(See Chart No 1 Qg)

LNМ/D. 04-JUN-2010

48°40'12.2"N 053°07'27.0"W

(N2010016) LL(446.1) DFO(6304949-01)

This notice affects Electronic Navigational Chart:
CA376340

09-JUL-2010

Add green port hand lighted pillar buoy FlG, marked JB3
(See Chart No 1 Qg)

LNМ/D. 04-JUN-2010

48°40'14.0"N 053°07'30.1"W

(N2010016) LL(446.1) DFO(6304949-02)

This notice affects Electronic Navigational Chart:
CA376340

04-JUN-2010

LNМ/D. 06-MAR-2009



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4854

Reposition green port hand lighted pillar buoy FlG,
marked J9
(See Chart No 1 Qg)

from 48°38'12.6"N 053°26'19.2"W
to 48°38'17.7"N 053°26'17.5"W

(N2010016) LL(442.7) DFO(6304836-01)

This notice affects Electronic Navigational
Chart: CA376340

06-MAR-2009

LNLM/D. 03-OCT-2008

Add submarine cable between 48°31'29.1"N 052°45'00.0"W
(See Chart No 1 L30.1) and 48°29'48.0"N 052°48'21.0"W

DFO(6304220-01)

03-OCT-2008

LNLM/D. 01-SEP-2006

Delete green port hand lighted pillar buoy FlG, marked
JB5
(See Chart No 1 Qg)

48°40'13.2"N 053°07'27.0"W

(N2008007) LL(446.1) DFO(6303960-01)

03-OCT-2008

LNLM/D. 01-SEP-2006

Add green port hand lighted spar buoy FlG, marked JB3
(See Chart No 1 Qg)

48°40'12.2"N 053°07'27.0"W

(N2008008) LL(445.2) DFO(6303960-02)

03-OCT-2008

LNLM/D. 01-SEP-2006

Delete green port hand lighted spar buoy FlG, marked
JB3
(See Chart No 1 Qg)

48°39'02.5"N 053°07'54.8"W

(N2008008) LL(445.2) DFO(6303961-01)

03-OCT-2008

LNLM/D. 01-SEP-2006

Add green port hand lighted pillar buoy FlG, marked JB5

48°39'02.5"N 053°07'54.8"W

(N2008007) LL(446.1) DFO(6303961-02)

01-SEP-2006

LNLM/D. 25-AUG-2006

Delete red starboard hand lighted spar buoy FlR, marked
JB4

48°38'34.8"N 053°08'00.0"W

(N2006101) LL(445.3) DFO(6303012-01)



Chart no. 4854

01-SEP-2006

LNM/D. 25-AUG-2006

Add green port hand lighted spar buoy FlG, marked JB3

48°39'02.5"N 053°07'54.8"W

(N2006103) LL(445.2) DFO(6303014-01)

25-AUG-2006

LNM/D. 06-JAN-2006

Delete green port hand lighted spar buoy Fl G, marked J13'

48°34'42.0"N 053°30'00.5"W

(N2006009) LL(442.61) DFO(6302831-01)

06-JAN-2006

LNM/D. 17-SEP-2004

Add depth of 0 metres, 6 decimetres 48°48'08.2"N 053°37'51.3"W

DFO(6302658-01)

06-JAN-2006

LNM/D. 17-SEP-2004

Add depth of 0 metres, 6 decimetres 48°48'01.7"N 053°37'18.4"W

DFO(6302658-02)

06-JAN-2006

LNM/D. 17-SEP-2004

Add rock which covers and uncovers with drying height of 1 metre, 2 decimetres 48°52'32.8"N 053°37'57.1"W

DFO(6302658-03)

17-SEP-2004

LNM/D. 13-AUG-2004

Delete light FLR

48°38'01.0"N 053°02'07.2"W

(N2004125) LL(463.1) DFO(6301793-01)

13-AUG-2004

LNM/D. 30-JUL-2004

Add red, green and red starboard bifurcation pillar light buoy Fl(2+1)R, marked JSB

48°33'21.0"N 053°36'21.0"W

(N2004099) LL(442.17) DFO(6301592-01)

30-JUL-2004

LNM/D. 19-DEC-2003



Chart no. 4854

- Add red starboard hand spar light buoy FIR, marked JB4 48°38'34.8"N 053°08'00.0"W
(N2004069) LL(445.3) DFO(6301559-01)
- 19-DEC-2003** LNM/D. 21-NOV-2003
Amend Fl (3) 12s 28m 18M to read Fl 4s 28m 16M against 48°30'14.8"N 053°02'36.4"W
light (N2003039) LL(453) DFO(6301008-01)
- 21-NOV-2003** LNM/D. 17-OCT-2003
Replace green port hand spar light buoy, Fl G, marked JK3 with 48°37'42.0"N 053°24'03.0"W
green port hand pillar light buoy, Fl G, marked JK3 LL(442.75) DFO(6500161-01)
- 17-OCT-2003** LNM/D. 10-OCT-2003
Delete legend BELL against green port hand pillar light 48°38'12.0"N 053°26'18.0"W
buoy FIG, BELL, marked J9 (N2002069) LL(442.7) DFO(6300421-01)
- 17-OCT-2003** LNM/D. 10-OCT-2003
Reposition green port hand spar light buoy FIG, marked from 48°37'42.1"N 053°23'53.2"W
JK3 to 48°37'42.0"N 053°24'03.0"W
(N2002152) LL(442.75) DFO(6300626-01)
- 17-OCT-2003** LNM/D. 10-OCT-2003
Amend Fl G to read Fl R against light 48°34'03.9"N 053°19'57.4"W
(N2003001) LL(443.1) DFO(6300818-01)
- 10-OCT-2003** LNM/D. 20-JUN-2003
Delete red and white fairway pillar, light and whistle buoy 48°38'49.8"N 053°08'33.5"W
Mo (A), WHIS, marked JB (N2002060) LL(445) DFO(6300418-01)
- 10-OCT-2003** LNM/D. 20-JUN-2003
Delete black and yellow, North cardinal pillar light buoy 48°42'16.8"N 053°03'20.4"W
VQ, marked JBR (N2002061) LL(449.5) DFO(6300419-01)



Chart no. 4854

10-OCT-2003

Add yellow, black and yellow West cardinal pillar light
buoy Q (9) 15s, marked JBR

LNМ/D. 20-JUN-2003

48°42'04.8"N 053°03'36.0"W

(N2002061) LL(449.5) DFO(6300419-02)

10-OCT-2003

Delete legend BELL against red starboard hand pillar
light buoy FIR, marked JB2

LNМ/D. 20-JUN-2003

48°41'48.0"N 053°07'48.0"W

(N2002070) LL(448.4) DFO(6300422-01)

20-JUN-2003

Replace red starboard hand pillar light buoy FIR, WHIS,
marked TC2 with red starboard hand pillar light
buoy FIR, marked TC2

LNМ/D. 11-APR-2003

48°30'14.8"N 053°01'26.0"W

(N2002049) LL(452) DFO(6300408-01)

11-APR-2003

Delete green port hand spar light buoy FIG, marked JR1

LNМ/D. 21-JUN-2002

48°37'07.0"N 053°28'43.0"W

(N2002151) LL(439.31) DFO(6300625-01)

11-APR-2003

Add green port hand pillar light buoy FIG, marked JR1

LNМ/D. 21-JUN-2002

48°37'06.0"N 053°28'57.0"W

(N2002151) LL(439.31) DFO(6300625-02)

11-APR-2003

Add light FIR

LNМ/D. 21-JUN-2002

48°35'58.5"N 053°22'16.5"W

(N2000415) LL(442.8) DFO(6829335-01)

21-JUN-2002

Add light FIG

LNМ/D. 22-FEB-2002

48°32'47.5"N 053°29'08.0"W

(N2000410) LL(442.12) DFO(6829328-01)

21-JUN-2002

LNМ/D. 22-FEB-2002



Chart no. 4854

Add light FIR 48°29'59.4"N 053°30'17.8"W

(N2000413) LL(442.3) DFO(6829330-01)

21-JUN-2002 LNM/D. 22-FEB-2002

Add light FIG 48°35'01.8"N 053°28'59.7"W

(N2000411) LL(442.13) DFO(6829333-01)

21-JUN-2002 LNM/D. 22-FEB-2002

Delete green, port hand spar buoy, marked JR1 48°37'06.7"N 053°28'44.7"W

(N2001115) DFO(6829716-01)

21-JUN-2002 LNM/D. 22-FEB-2002

Add green port hand spar light buoy FIG, marked JR1 48°37'07.0"N 053°28'43.0"W

(N2001115) LL(439.31) DFO(6829716-02)

21-JUN-2002 LNM/D. 22-FEB-2002

Replace green, port hand spar buoy, marked JK3 with 48°37'42.1"N 053°23'53.2"W
green port hand spar light buoy FIG, marked

JK3 *(N2001116) LL(442.75) DFO(6829717-01)*

22-FEB-2002 LNM/D. 20-APR-2001

Add light FIR 48°38'01.0"N 053°02'07.2"W

(N2000372) LL(463.1) DFO(6300025-01)

22-FEB-2002 LNM/D. 20-APR-2001

Add light FIG 48°34'03.9"N 053°19'57.4"W

(N2000376) LL(443.1) DFO(6829263-01)

20-APR-2001 LNM/D. 12-JAN-2001

Delete black, red, black, isolated danger spar buoy, 48°37'42.1"N 053°23'53.2"W
marked JK

(N1999-049) LL(5227.300) DFO(6829383-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 4854

20-APR-2001

Add green, port hand spar buoy, marked JK3

LNМ/D. 12-JAN-2001

48°37'42.1"N 053°23'53.2"W

(N1999-049) LL(5227.300) DFO(6829383-02)

12-JAN-2001

Delete anchorage area 48°30'48.0"N 053°29'36.0"W

LNМ/D. 01-SEP-2000

DFO(6829273-01)

01-SEP-2000

Delete black, red, black, isolated danger pillar light
buoy Fl (2) 10s, marked JBR

LNМ/D. 31-DEC-1999

48°41'58.0"N 053°03'34.0"W

(N1999-052) LL(449.500) DFO(6828982-01)

01-SEP-2000

Add black and yellow, north cardinal pillar light buoy VQ,
marked JBR

LNМ/D. 31-DEC-1999

48°42'16.8"N 053°03'20.4"W

(N1999-052) LL(449.5) DFO(6828982-02)