



Chart no. 5031

5031 - St Lewis Sound and / et Inlet - New Edition - 31-DEC-1999 - NAD 1983

21-JUL-2006

LNМ/D. 14-NOV-2003

Delete red starboard hand conical buoy, marked NR8

52°13'13.2"N 055°36'17.4"W

(N2006024) LL(277.6) DFO(6302915-01)

21-JUL-2006

LNМ/D. 14-NOV-2003

Add red starboard hand lighted pillar buoy FIR, marked
NUC2

52°13'13.2"N 055°36'17.4"W

(N2006024) LL(277.6) DFO(6302915-02)

11-AUG-2006

LNМ/D. 21-JUL-2006

Amend "NS3" to read "NMS1" against green port hand
lighted pillar buoy FlG

52°19'47.4"N 055°46'48.6"W

(N2006026) LL(276.7) DFO(6302917-01)

11-AUG-2006

LNМ/D. 21-JUL-2006

Delete red starboard hand lighted pillar buoy FIR,
marked NS8

52°18'10.2"N 055°46'42.0"W

(N2006027) LL(276.75) DFO(6302918-01)

11-AUG-2006

LNМ/D. 21-JUL-2006

Add red starboard hand lighted spar buoy FIR, marked
NS2

52°18'10.2"N 055°46'42.0"W

(N2006027) LL(276.75) DFO(6302918-02)

11-AUG-2006

LNМ/D. 21-JUL-2006

Delete green port hand lighted pillar buoy FlG, marked
NS9

52°17'40.0"N 055°45'41.0"W

(N2006028) LL(276.8) DFO(6302919-01)

11-AUG-2006

LNМ/D. 21-JUL-2006

Add green port hand lighted pillar buoy FlG, marked NS1

52°17'43.8"N 055°45'44.4"W

(N2006028) LL(276.8) DFO(6302919-02)

06-OCT-2006

LNМ/D. 11-AUG-2006



Chart no. 5031

Reposition light Fl from 52°26'38.0"N 055°37'42.0"W
to 52°26'41.5"N 055°37'48.3"W

(N2006104) LL(276.2) DFO(6303016-01)

25-DEC-2009 LNM/D. 06-OCT-2006

Delete light FLR 52°20'29.5"N 055°44'46.0"W
(See Chart No 1 P1)

(N2009052) LL(276.6) DFO(6304660-01)

31-DEC-2010 LNM/D. 25-DEC-2009

Delete legend Loran against tower 52°22'35.0"N 055°42'28.0"W
(See Chart No. 1, E20)

(N2010064) DFO(6305145-01)

19-SEP-2014 LNM/D. 31-DEC-2010

Delete tower with elevation of 240 metres, WLts 52°22'35.2"N 055°42'27.7"W
(See chart No. 1, E20)

This notice affects Electronic Navigational Chart: CA176030, *DFO(6306799-01)*
CA476380

17-NOV-2017 LNM/D. 30-DEC-2016

Amend Fl 19m to read Fl 14m against light 52°17'36.0"N 055°41'02.7"W
(See Chart No. 1, P16)

LL(276.87) DFO(6308128-01)

08-DEC-2017 LNM/D. 17-NOV-2017

Add pier extension between 52°18'41.4"N 055°49'48.0"W
(See Chart No. 1, F14) and 52°18'42.6"N 055°49'48.4"W

This notice affects Electronic Navigational Chart: *DFO(6308154-02)*
CA476380

08-DEC-2017 LNM/D. 17-NOV-2017

Add pier between 52°18'28.0"N 055°49'59.4"W
(See Chart No. 1, F14) and 52°18'27.6"N 055°49'57.4"W

This notice affects Electronic Navigational Chart: *DFO(6308154-03)*
CA476380

11-MAY-2018 LNM/D. 08-DEC-2017



Chart no. 5031

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 22 metres
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA476380

52°27'00.0"N 055°37'36.0"W

DFO(6308207-01)

11-MAY-2018

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 19 metres
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA476380

LNМ/D. 08-DEC-2017

52°27'08.0"N 055°36'56.0"W

DFO(6308207-02)

11-MAY-2018

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 42 metres
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA476380

LNМ/D. 08-DEC-2017

52°27'17.0"N 055°36'16.0"W

DFO(6308207-03)

11-MAY-2018

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 82 metres
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA476380

LNМ/D. 08-DEC-2017

52°27'25.0"N 055°35'35.0"W

DFO(6308207-04)

19-OCT-2001

Replace red starboard hand spar buoy, marked NU6,
with red starboard hand spar light buoy Fl R,
marked NU6

LNМ/D. 29-JUN-2001

52°15'55.2"N 055°39'49.2"W

(N2001098) LL(277.56) DFO(6829698-01)

5031 - Mary's Harbour - New Edition - 31-DEC-1999 - NAD 1983

08-DEC-2017

Affix patch

[PDF](#)

This notice affects Electronic Navigational Chart: CA576503

LNМ/D. 17-NOV-2017

52°18'30.0"N 055°50'00.0"W

DFO(6308154-01)

19-OCT-2001

LNМ/D. 29-JUN-2001



Chart no. 5031

Replace green port hand spar buoy, marked NMH3, with
green port hand spar light buoy FIG, marked
NMH3

52°18'35.1"N 055°50'01.3"W

(N2001099) LL(276.78) DFO(6829699-01)

19-OCT-2001

LNМ/D. 29-JUN-2001

Replace red starboard hand spar buoy, marked NMH4,
with red starboard hand spar light buoy, FIR,
marked NMH4

52°18'37.0"N 055°50'02.9"W

(N2001100) LL(276.771) DFO(6829700-01)

19-OCT-2001

LNМ/D. 29-JUN-2001

Replace green port hand spar buoy, marked NMH5,
with green port hand spar light buoy FIG,
marked NMH5

52°18'35.5"N 055°50'11.4"W

(N2001101) LL(276.772) DFO(6829701-01)

5031 - Fox Harbour - New Edition - 31-DEC-1999 - NAD 1983

14-NOV-2003

LNМ/D. 19-OCT-2001

Reposition red starboard hand pillar light buoy FIR,
marked NF2

from 52°21'36.5"N 055°41'44.0"W
to 52°21'35.7"N 055°41'41.4"W

(N2002161) LL(276.4) DFO(6300636-01)

19-OCT-2001

LNМ/D. 29-JUN-2001

Delete green port hand pillar light buoy FIG, marked NF1

52°21'37.2"N 055°41'46.8"W

(N2000007) LL(276.3) DFO(6600265-01)

23-FEB-2001

Add depth of 4 metres 52°21'37.6"N 055°41'50.8"W

DFO(6829228-01)

29-JUN-2001

LNМ/D. 23-FEB-2001

Add depth of 5.9 metres 52°21'36.2"N 055°41'48.0"W

DFO(6829521-01)



Chart no. 5031

29-JUN-2001

LNM/D. 23-FEB-2001

Delete depth of 6.4 metres 52°21'36.2"N 055°41'48.6"W

DFO(6829521-02)

5031 - Caribou Run - New Edition - 31-DEC-1999 - NAD 1983

19-OCT-2001

LNM/D. 29-JUN-2001

Replace red starboard hand spar buoy, marked NU6,
with red starboard hand spar light buoy Fl R,
marked NU6

52°15'55.2"N 055°39'49.2"W

(N2001098) LL(277.56) DFO(6829698-01)

5031 - Battle Harbour - New Edition - 31-DEC-1999 - NAD 1983

30-DEC-2016

LNM/D. 19-SEP-2014

Replace wharf with wharf in ruins with legend Ru
(See Chart No. 1 F33.1)
This notice affects Electronic Navigational Chart:
CA576382

joining 52°16'26.2"N 055°35'09.7"W
52°16'26.2"N 055°35'10.8"W
52°16'26.5"N 055°35'11.5"W
52°16'26.4"N 055°35'11.7"W
52°16'26.1"N 055°35'10.9"W
and 52°16'26.0"N 055°35'09.9"W

DFO(6307804-01)

27-MAR-2020

LNM/D. 11-MAY-2018

Affix patch

52°16'25.8"N 055°35'12.6"W

[PDF](#)

This notice affects Electronic Navigational Chart: CA576382

DFO(6308917-01)