



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5138

5138 - Cartwright Harbour - New Edition - 17-APR-1998 - NAD 1983

30-SEP-2022

LN/D. 19-AUG-2022

Add depth of 1 fathom, 1 foot
(See Chart No. 1, I10)

53°42'13.0"N 057°01'17.9"W

This notice affects Electronic Navigational Chart: CA576498

DFO(6310313-02)

30-SEP-2022

LN/D. 19-AUG-2022

Add depth of 1 fathom, 5 feet
(See Chart No. 1, I10)

53°42'11.7"N 057°01'19.4"W

This notice affects Electronic Navigational Chart: CA576498

DFO(6310313-03)

30-SEP-2022

LN/D. 19-AUG-2022

Delete wharf
(See Chart No. 1, F13)
This notice affects Electronic Navigational Chart:
CA576498

joining 53°42'10.8"N 057°01'18.5"W
53°42'11.3"N 057°01'18.5"W
53°42'11.6"N 057°01'17.6"W
53°42'12.0"N 057°01'17.0"W
53°42'12.1"N 057°01'17.3"W
and 53°42'12.9"N 057°01'17.1"W

DFO(6310313-04)

30-SEP-2022

LN/D. 19-AUG-2022

Add wharf
(See Chart No. 1, F13)
This notice affects Electronic Navigational Chart:
CA576498

joining 53°42'10.8"N 057°01'18.5"W
53°42'11.3"N 057°01'18.8"W
and 53°42'12.9"N 057°01'17.1"W

DFO(6310313-05)

19-AUG-2022

LN/D. 18-MAR-2022

Add light Fl G
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart:
CA576498

53°42'07.4"N 057°01'40.7"W

(N2022095) LL(284.51) DFO(6310159-01)

19-AUG-2022

LN/D. 18-MAR-2022

Amend Fl R to read Fl Y against light
(See Chart No. 1, P16)

53°42'11.0"N 057°01'16.5"W

This notice affects Electronic Navigational Chart: *(N2022098) LL(284.72) DFO(6310162-01)*
CA576498



Chart no. 5138

18-MAR-2022

LNМ/D. 25-DEC-2020

Add green port hand lighted spar buoy Fl G, marked
NCH1

53°40'44.7"N 057°04'38.0"W

(See Chart No. 1, Qg)

(N2022023) LL(284.73) DFO(6310024-01)

This notice affects Electronic Navigational Chart:
CA476494, CA576498

18-MAR-2022

LNМ/D. 25-DEC-2020

Add green port hand lighted spar buoy Q G, marked
NCH3

53°40'42.3"N 057°04'38.3"W

(See Chart No. 1, Qg)

(N2022024) LL(284.74) DFO(6310025-01)

This notice affects Electronic Navigational Chart:
CA476494, CA576498

25-DEC-2020

LNМ/D. 30-OCT-2020

Amend Fl G to read Q G against green port hand lighted
pillar buoy, marked NC5

53°42'10.2"N 057°02'06.8"W

(See Chart No. 1, Qg)

(N2020049) LL(284.5) DFO(6309297-01)

This notice affects Electronic Navigational Chart:
CA576498

02-JUL-2010

LNМ/D. 27-MAR-2009

Delete red starboard hand lighted pillar buoy FIR,
marked NC6

53°41'59.3"N 057°01'10.9"W

(See Chart No 1 Qf)

(N2010016) LL(284.71) DFO(6304917-01)

02-JUL-2010

LNМ/D. 27-MAR-2009

Add red starboard hand lighted spar buoy FIR, marked
NC6

53°42'00.1"N 057°01'11.6"W

(See Chart No 1 Qf)

(N2010016) LL(284.71) DFO(6304917-02)

27-MAR-2009

LNМ/D. 11-AUG-2006



Chart no. 5138

Add ferry route joining 53°43'10.8"N 057°01'10.9"W
(See Chart No 1 M50) 53°43'03.9"N 057°01'26.4"W
53°42'10.0"N 057°02'16.3"W
53°42'04.2"N 057°02'13.3"W
53°41'58.6"N 057°02'04.9"W
53°41'56.5"N 057°01'52.0"W
53°42'00.0"N 057°01'36.2"W
and 53°42'09.2"N 057°01'21.9"W

DFO(6303315-03)

26-NOV-2004 LNM/D. 17-SEP-2004

Affix patch 54°42'00.0"N 057°01'30.0"W

DFO(6302051-02)

[PDF](#)

26-NOV-2004

LNM/D. 17-SEP-2004

Amend "NC3" to read "NC5" against green port hand pillar light buoy 53°42'10.0"N 057°02'07.0"W
FIG

LL(284.5) DFO(6302051-03)

26-NOV-2004

LNM/D. 17-SEP-2004

Delete green port hand pillar light buoy FIG, marked NC5 53°42'04.9"N 057°01'37.0"W

LL(284.7) DFO(6302051-04)

03-SEP-2004

LNM/D. 18-OCT-2002

Delete green port hand pillar light buoy FIG, marked NC5 53°42'04.9"N 057°01'39.0"W

(N2004121) LL(284.7) DFO(6301778-01)

03-SEP-2004

LNM/D. 18-OCT-2002

Amend "NC3" to read "NC5" against green port hand 53°42'10.0"N 057°02'07.0"W
pillar light buoy FIG

(N2004122) LL(284.5) DFO(6301790-01)

03-SEP-2004

LNM/D. 18-OCT-2002



Chart no. 5138

Delete red starboard hand pillar light buoy FIR, marked
NC2

53°43'02.0"N 057°01'40.0"W

(N2004124) LL(284.6) DFO(6301792-01)

03-SEP-2004

LN/D. 18-OCT-2002

Add red starboard hand pillar light buoy FIR, marked NC4

53°43'00.4"N 057°01'35.8"W

(N2004124) LL(284.6) DFO(6301792-02)

5138 - Paradise River - New Edition - 17-APR-1998 - NAD 1983

24-SEP-2010

LN/D. 30-JUL-2010

Replace wharf with wharf in ruins with legend Ru
(See Chart No. 1 F33.1)

joining 53°26'18.2"N 057°16'39.8"W

53°26'17.8"N 057°16'41.2"W

53°26'17.6"N 057°16'41.1"W

53°26'17.5"N 057°16'41.5"W

53°26'18.1"N 057°16'41.9"W

53°26'18.2"N 057°16'41.5"W

53°26'17.9"N 057°16'41.3"W

and 53°26'18.3"N 057°16'40.0"W

This notice affects Electronic Navigational Chart:
CA576497

DFO(6305016-01)

11-AUG-2006

LN/D. 30-DEC-2005

Delete red starboard hand lighted spar buoy FIR, marked
NV2

53°26'47.6"N 057°17'32.0"W

(N2006059) LL(284.9) DFO(6302947-01)

11-AUG-2006

LN/D. 30-DEC-2005

Delete red starboard hand lighted spar buoy FIR,
marked NV4

53°26'36.6"N 057°17'24.0"W

(N2006060) LL(284.95) DFO(6302948-01)

11-AUG-2006

LN/D. 30-DEC-2005

Delete red starboard hand lighted spar buoy FIR,
marked NV6

53°26'17.0"N 057°16'58.3"W

(N2006061) LL(284.951) DFO(6302949-01)

30-DEC-2005

LN/D. 26-NOV-2004



Chart no. 5138

Replace black buoy with a red buoy for lighted spar buoy Fl R,
marked NV6

53°26'17.0"N 057°16'58.3"W

LL(284.951) DFO(6302655-01)

18-OCT-2002

LNМ/D. 28-JAN-2000

Add red starboard hand spar light buoy FIR, marked
NV6

53°26'17.0"N 057°16'58.3"W

(N2001106) LL(284.951) DFO(6829706-01)

5138 - Sandwich Bay - New Edition - 17-APR-1998 - NAD 1983

13-JAN-2023

LNМ/D. 30-SEP-2022

Delete red starboard hand lighted spar buoy FIR,
marked NCD2

53°42'35.4"N 057°06'16.9"W

(See Chart 1, Qb)

(N2022298) LL(284.45) DFO(6310540-01)

This notice affects Electronic Navigational Chart:
CA476494

18-MAR-2022

LNМ/D. 25-DEC-2020

Add green port hand lighted spar buoy Fl G, marked
NCH1

53°40'44.7"N 057°04'38.0"W

(See Chart No. 1, Qg)

(N2022023) LL(284.73) DFO(6310024-01)

This notice affects Electronic Navigational Chart:
CA476494, CA576498

18-MAR-2022

LNМ/D. 25-DEC-2020

Add green port hand lighted spar buoy Q G, marked
NCH3

53°40'42.3"N 057°04'38.3"W

(See Chart No. 1, Qg)

(N2022024) LL(284.74) DFO(6310025-01)

This notice affects Electronic Navigational Chart:
CA476494, CA576498

30-OCT-2020

LNМ/D. 15-JAN-2016

Add green port hand lighted spar buoy Fl G, marked
NC3

53°44'37.0"N 056°55'07.1"W

(See Chart No. 1, Qg)

(N2020093) LL(284.41) DFO(6309260-01)

This notice affects Electronic Navigational Chart:
CA376355, CA476494

30-OCT-2020

LNМ/D. 15-JAN-2016



Chart no. 5138

Add red starboard hand lighted spar buoy Fl R, marked NC2/2 53°44'26.8"N 056°56'21.6"W
 (See Chart No. 1, Qf) (N2020094) LL(284.42) DFO(6309261-01)
 This notice affects Electronic Navigational Chart:
 CA376355, CA476494

15-JAN-2016 LNM/D. 25-NOV-2011
 Replace depth of 20 fathoms with depth of 3 fathoms, 5 feet 53°47'02.6"N 057°04'21.4"W
 (See Chart No. 1, I10)
 This notice affects Electronic Navigational Chart: CA376355 DFO(6307408-04)

25-NOV-2011 LNM/D. 24-SEP-2010
 Add rock with known depth of 0 fathoms, 2 feet, dangerous to surface navigation 53°47'06.8"N 057°02'49.2"W
 (See Chart No. 1, K14.2) DFO(6305822-01)

This notice affects Electronic Navigational Chart: CA376355,
 CA476494

30-JUL-2010 LNM/D. 02-JUL-2010
 Reposition green port hand lighted pillar buoy FlG, from 53°46'08.5"N 056°48'40.4"W
 marked NC1 to 53°46'10.0"N 056°48'42.9"W
 (See Chart No 1 Qg) (N2010016) LL(284.3) DFO(6304963-01)

27-MAR-2009 LNM/D. 11-AUG-2006
 Add ferry route joining 53°46'35.0"N 056°47'26.0"W
 (See Chart No 1 M50) 53°46'19.2"N 056°49'15.0"W
53°44'52.8"N 056°53'06.0"W
53°44'09.0"N 056°59'00.0"W
 This notice affects Electronic Navigational Chart: 53°43'03.9"N 057°01'26.4"W
 CA476494 53°42'10.0"N 057°02'16.3"W
53°41'58.6"N 057°02'04.9"W
53°41'56.5"N 057°01'52.0"W
53°42'00.0"N 057°01'36.2"W
 and 53°42'09.2"N 057°01'21.9"W
DFO(6303315-01)

27-MAR-2009 LNM/D. 11-AUG-2006



Chart no. 5138

Add ferry route
(See Chart No 1 M50)

joining 53°44'52.8"N 056°53'06.0"W
53°47'30.0"N 056°47'46.8"W
and 53°48'00.6"N 056°47'51.4"W

This notice affects Electronic Navigational Chart:
CA476494

DFO(6303315-02)

11-AUG-2006

LNM/D. 30-DEC-2005

Amend "NS4" to read "NCH2" against red starboard hand
lighted pillar buoy FLR

53°39'28.0"N 057°04'24.0"W

(N2006047) LL(284.8) DFO(6302935-01)

11-AUG-2006

LNM/D. 30-DEC-2005

Amend "NC8" to read "NCD2" against red starboard
hand lighted spar buoy FLR

53°42'35.4"N 057°06'17.4"W

(N2006048) LL(284.45) DFO(6302936-01)

30-DEC-2005

LNM/D. 26-NOV-2004

Delete front range light "FR 43ft"

53°46'20.7"N 056°51'21.0"W

(N2005098) LL(284.31) DFO(6302653-01)

This notice affects Electronic Navigational Chart:
CA476494

30-DEC-2005

LNM/D. 26-NOV-2004

Delete rear range light "FR 89ft"

53°46'19.5"N 056°51'41.0"W

(N2005097) LL(284.32) DFO(6302653-02)

This notice affects Electronic Navigational Chart:
CA476494

30-DEC-2005

LNM/D. 26-NOV-2004

Delete leading line and legend "084½° 264½°"

between 53°46'19.5"N 056°51'41.0"W
and 53°46'34.0"N 056°47'26.0"W

This notice affects Electronic Navigational Chart:
CA476494

LL(284.31) DFO(6302653-03)

26-NOV-2004

LNM/D. 17-SEP-2004



Chart no. 5138

Affix patch 53°42'12.0"N 057°01'30.0"W

DFO(6302051-02)

[PDF](#)

17-SEP-2004

Amend "NC1.2" to read "NC2" against red starboard hand
spar light buoy FIR

LNM/D. 03-SEP-2004

53°44'47.4"N 056°55'00.0"W

(N2004076) LL(284.4) DFO(6301566-01)

03-SEP-2004

Delete red starboard hand pillar light buoy FIR, marked
NC2

LNM/D. 18-OCT-2002

53°43'02.0"N 057°01'40.0"W

(N2004124) LL(284.6) DFO(6301792-01)

03-SEP-2004

Add red starboard hand pillar light buoy FIR, marked NC4

LNM/D. 18-OCT-2002

53°43'00.4"N 057°01'35.8"W

(N2004124) LL(284.6) DFO(6301792-02)

28-JAN-2000

Amend 264 1/2° to read 8 1/2° 53°46'27.0"N 056°49'42.0"W

LNM/D. 09-APR-1999

DFO(6500040-01)

28-JAN-2000

Amend 84 1/2° to read 264 1/2° 53°46'31.0"N 056°48'06.0"W

LNM/D. 09-APR-1999

DFO(6500040-02)

5138 - Continuation A - New Edition - 17-APR-1998 - NAD 1983

11-AUG-2006

Delete red starboard hand lighted spar buoy FIR, marked
NV2

LNM/D. 30-DEC-2005

53°26'47.6"N 057°17'32.0"W

(N2006059) LL(284.9) DFO(6302947-01)



Fisheries and Oceans
Canada

Pêches et Océans
Canada

Canadian
Coast Guard

Garde côtière
canadienne

Chart no. 5138