Chart no. 2000

2000 - Lake Ontario/Lac Ontario - New Edition - 10-APR-1998 - NAD 1983

11-OCT-2019 LNM/D. 05-APR-2019

Amend Iso Y 6s 14m to read Iso G 4s 14m against light (See Chart No. 1, P16) 43°18′03.6″N 079°47′25.8″W

(B2019004) LL(535) DFO(6604564-01)

This notice affects Electronic Navigational Chart: CA273096, CA473519, CA573362

05-APR-2019 LNM/D. 08-FEB-2019

Delete red and white fairway lighted pillar buoy, marked Mo (A) 44°01′45.0″N 076°27′00.0″W

(See Chart No. 1, Qh) *(B2018016) LL(391.91) DFO(6604515-01)*

This notice affects Electronic Navigational Chart: CA273096, CA373063, CA473036

08-FEB-2019 LNM/D. 13-NOV-2015

Add submarine cable joining 43°19′41.0″N 078°46′07.7″W
(See Chart No. 1, L30.1) 43°20′03.1″N 078°46′09.6″W
This notice affects Electronic Navigational Chart: 43°20′18.1″N 078°46′20.8″W
CA273096, CA373091, CA573008 43°38′23.5″N 079°16′48.0″W
43°38′40.6″N 079°17′14.6″W
43°38′56.2″N 079°17′24.9″W
43°39′12.8″N 079°17′36.3″W
and 43°39′49.1″N 079°18′17.6″W

DFO(6604493-01)

13-NOV-2015 LNM/D. 31-AUG-2012

Amend ″AlWR 10s 17m 10M Fog SIG″ to read ″Fl R 10s 17m 9M Fog Sig″ against light 43°28′23.7″N 076°31′01.4″W

This notice affects Electronic Navigational Chart: CA273096 *(USCG:LNM 38/15) DFO(6604139-03)*

31-AUG-2012 LNM/D. 04-DEC-2009

Amend LFlR 10s, 16 m to read IsoR 4s, 15m 9M against light 43°14′41.2″N 079°13′02.9″W

(See Chart 1, P10.3) *(B2012020) LL(551.06) DFO(6603790-01)*

04-DEC-2009 LNM/D. 03-JUL-2009

Chart no. 2000

Delete yellow ODAS/SADO lighted buoy Fl (5) Y 43°25′25.0″N 079°22′35.8″W
(See Chart No. 1, Q58)
(B2009106) LL(528.5) DFO(6603506-01)

04-DEC-2009 LNM/D. 03-JUL-2009

Add yellow ODAS/SADO lighted buoy Fl (5) Y 43°15′32.3″N 079°32′19.3″W
(See Chart No. 1, Q58)
(B2009106) LL(528.5) DFO(6603506-02)

03-JUL-2009 LNM/D. 19-DEC-2008

Add yellow ODAS/SADO lighted buoy Fl (5) Y 20s, marked 45159 43°46′00.0″N 078°59′06.0″W
(See Chart No. 1, Q58) *(B2009065) LL(505.5) DFO(6603419-01)*

This notice affects Electronic Navigational Chart:
CA273096, CA373091

19-DEC-2008 LNM/D. 07-NOV-2008

Amend legend Fl 10s 21m 13M to read LFl 10s 21m 11M against light 43°50′22.1″N 077°09′10.1″W
(See Chart No.1, P10.5) *(B2008165) LL(490) DFO(6603339-01)*

This notice affects Electronic Navigational Chart:
CA273096, CA373071

07-NOV-2008 LNM/D. 26-SEP-2008

Replace red starboard hand lighted pillar buoy Fl R with red starboard hand lighted spar buoy Fl R 43°55′19.0″N 076°43′09.0″W
(B2008137) LL(426) DFO(6603294-01)

This notice affects Electronic Navigational Chart:
CA273096, CA373063

26-SEP-2008 LNM/D. 02-MAY-2008

Chart no. 2000

Amend legend Fl 10s 16m 17M to read LFl 10s 16m against light — 44°09′10.0″N 076°33′25.0″W
(See Chart No.1, P10.5 and P16) *(B2008092) LL(419) DFO(6603244-01)*

This notice affects Electronic Navigational Chart:
CA273096, CA373063, CA473276, CA573118

26-SEP-2008 LNM/D. 02-MAY-2008

Amend legend Fl R 10s 15m 13M to read LFl R 10s 15m against light — 43°14′45.0″N 079°13′10.0″W
(See Chart No.1, P10.5 and P16) *(B2008094) LL(551.06) DFO(6603245-01)*

This notice affects Electronic Navigational Chart:
CA273096, CA373091, CA573010

02-MAY-2008 LNM/D. 09-MAR-2007

Amend legend F R 9m 6M to read Iso R 2s 12m against light — 43°26′22.0″N 079°39′55.6″W

(B2008073) LL(528) DFO(6603196-01)

This notice affects Electronic Navigational Chart:
CA273096, CA373091

09-MAR-2007 LNM/D. 11-AUG-2006

Amend Fl 6s 24m 17M to read Fl 6s 24m against light — 43°55′53.0″N 076°38′11.5″W

(B2007003) LL(424) DFO(6602882-01)

This notice affects Electronic Navigational Chart:
CA273096, CA373063

11-AUG-2006 LNM/D. 06-DEC-2002

Delete chimney with elevation of 154m, RLts and legend 4 Chys — 43°34′19.0″N 079°33′07.0″W

DFO(6602765-01)

This notice affects Electronic Navigational Chart: CA273096

06-DEC-2002 LNM/D. 21-JUN-2002

Chart no. 2000

Delete firing danger area joining 43°15′42.0″N 079°05′42.0″W
43°16′03.0″N 079°05′42.0″W
43°16′54.0″N 079°06′33.0″W
43°16′12.0″N 079°07′36.0″W
and 43°15′33.0″N 079°06′33.0″W

(B2002009) DFO(6600496-01)

21-JUN-2002 LNM/D. 12-APR-2002

Add yellow ODAS/SADO light buoy, Fl (4) Y, marked 45012 — 43°37′15.0″N 077°24′03.0″W

(NGA:19/02) LL(2655) DFO(6600194-01)

12-APR-2002 LNM/D. 13-JUL-2001

Add firing danger area joining 43°37′00.0″N 076°45′00.0″W
43°24′00.0″N 076°45′00.0″W
43°24′00.0″N 078°00′00.0″W
and 43°37′00.0″N 078°00′00.0″W

DFO(6600146-01)

12-APR-2002 LNM/D. 13-JUL-2001

Add legend ″See FIRING PRACTICE AND EXERCISE AREAS / voir ZONES DE PRATIQUES DE TIR ET D′EXERCICES″ — 43°33′45.0″N 077°22′30.0″W

DFO(6600146-02)

12-APR-2002 LNM/D. 13-JUL-2001

Add note — 43°22′00.0″N 076°00′00.0″W

FIRING PRACTICE AND EXERCISE AREA — *DFO(6600146-03)*

Limits of Firing Practice and Exercise Areas. See Notice to Mariners No. 35 of each year. In United States waters consult Chapter 2 of US Coast Pilot, Vol. 6.

ZONES DE PRATIQUES DE TIR ET D′EXERCICES

Limites des zones de pratiques de tir et d′exercices. Consulter l′Avis aux navigateurs n° 35 de chaque année. Dans les eaux des États Unis d′Amérique, consulter Chapter 2, US Coast Pilot, Vol. 6.

Chart no. 2000

13-JUL-2001 LNM/D. 20-OCT-2000

Amend ″Fl W 10s 22m 24M″ to read ″Oc 4s 18m, Priv″ against light 43°22′24.0″N 078°29′18.0″W

(NGA:33/98) DFO(6601532-01)

20-OCT-2000 LNM/D. 21-AUG-1998

Amend Fl 4s 14m 5M to read Iso 2s 14m 5M 43°56′13.0″N 076°51′35.0″W

DFO(6601313-01)