Chart no. 4047

4047 - St. Pierre Bank / Banc de Saint-Pierre to / au Whale Bank / Banc de la Baleine - New Edition - 09-OCT-1998 - NAD 1983

12-AUG-2022 LNM/D. 29-JUL-2022

Add depth of 20.4 metres 46°53′30.4″N 056°04′17.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276091, CA376164 *DFO(6310186-01)*

12-AUG-2022 LNM/D. 29-JUL-2022

Delete depth of 37 metres 46°53′14.0″N 056°03′52.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276091, CA376164 *DFO(6310186-02)*

12-AUG-2022 LNM/D. 29-JUL-2022

Add depth of 27.4 metres 46°53′06.0″N 056°03′19.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276091, CA376164 *DFO(6310186-03)*

12-AUG-2022 LNM/D. 29-JUL-2022

Add depth of 12.2 metres 46°51′57.2″N 056°03′04.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276091, CA376164 *DFO(6310186-05)*

29-JUL-2022 LNM/D. 17-JUN-2022

Delete ferry route between 46°34′33.1″N 056°29′58.9″W
(See Chart No. 1, M50) and 46°42′36.7″N 054°41′48.3″W
This notice affects Electronic Navigational Chart: CA276091, CA276271, CA276284, CA376093, CA376164, CA376166, CA376173 *DFO(6310118-01)*

29-JUL-2022 LNM/D. 17-JUN-2022

Delete ferry route joining 46°35′14.0″N 056°29′55.7″W
(See Chart No. 1, M50) 46°49′50.0″N 055°19′21.4″W
This notice affects Electronic Navigational Chart: and 47°07′13.5″N 054°27′04.4″W
CA276091, CA276284, CA376164, CA376166, CA376176, CA576095 *DFO(6310118-02)*

Chart no. 4047

29-JUL-2022 LNM/D. 17-JUN-2022

Add ferry route joining 46°41′52.4″N 056°29′57.1″W
(See Chart No. 1, M50) 46°39′08.9″N 056°11′14.3″W
This notice affects Electronic Navigational Chart: 46°43′26.9″N 055°47′57.6″W
CA276091, CA276271, CA276284, CA376093, CA376166, 46°46′41.8″N 055°15′52.2″W
CA376176, CA576095 and 47°06′08.9″N 054°27′27.3″W

DFO(6310118-03)

29-JUL-2022 LNM/D. 17-JUN-2022

Add ferry route joining 46°39′08.9″N 056°11′14.3″W
(See Chart No. 1, M50) 46°43′34.6″N 055°15′49.8″W
This notice affects Electronic Navigational Chart: and 46°52′15.8″N 054°51′57.7″W
CA276091, CA376164, CA376166, CA376176

DFO(6310118-04)

29-JUL-2022 LNM/D. 17-JUN-2022

Delete ferry route between 46°41′34.9″N 054°56′09.4″W
(See Chart No. 1, M50) and 46°46′38.6″N 054°49′32.4″W
This notice affects Electronic Navigational Chart:
CA276091 *DFO(6310118-05)*

17-JUN-2022 LNM/D. 24-SEP-2021

Add environmentally sensitive sea area with legend, joining 45°26′53.0″N 056°30′00.0″W
Laurentian Channel MPA / ZPM du chenal Laurentien 45°20′20.0″N 056°24′07.0″W
(See Chart No. 1, N22) 44°59′49.0″N 056°24′05.0″W
and 44°59′31.0″N 056°30′00.0″W

This notice affects Electronic Navigational Chart:
CA276090, CA276091, CA276271, CA276284 *DFO(6310080-01)*

24-SEP-2021 LNM/D. 02-OCT-2020

Delete light Fl R 46°57′15.0″N 055°14′00.0″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: *(N2021115) LL(72) DFO(6309604-01)*
CA276091, CA376176

02-OCT-2020 LNM/D. 17-JUL-2020

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 9 metres (See Chart No. 1, L25) 44°11′33.8″N 053°16′29.2″W
This notice affects Electronic Navigational Chart: CA276091 *DFO(6309223-05)*

Chart no. 4047

17-JUL-2020 LNM/D. 10-APR-2020

Replace wreck showing a portion of superstructure with wreck, least depth unknown, dangerous to surface navigation with legend ″PD″ 47°06′09.0″N 056°20′05.0″W
(See Chart No. 1, K24, K28, B8)
This notice affects Electronic Navigational Chart: CA276091, CA376627 *DFO(6308979-02)*

17-JUL-2020 LNM/D. 10-APR-2020

Delete legend WHIS against black, yellow and black East cardinal lighted pillar buoy 47°03′22.0″N 056°11′17.0″W
(See Chart No. 1, Qd)
This notice affects Electronic Navigational Chart: CA276091, CA376627 *DFO(6308979-05)*

17-JUL-2020 LNM/D. 10-APR-2020

Amend WHIS to read Bell against red and white fairway lighted pillar buoy 46°48′21.0″N 056°07′33.0″W
(See Chart No. 1, Qc, Qd)
This notice affects Electronic Navigational Chart: CA276091, CA376164 *DFO(6308979-06)*

17-JUL-2020 LNM/D. 10-APR-2020

Delete legend WHIS against black, yellow and black East cardinal lighted pillar buoy 46°47′17.0″N 056°06′04.0″W
(See Chart No. 1, Qd)
This notice affects Electronic Navigational Chart: CA276091, CA376164 *DFO(6308979-07)*

17-JUL-2020 LNM/D. 10-APR-2020

Delete legend WHIS against yellow and black South cardinal lighted pillar buoy 46°43′52.0″N 056°12′54.0″W
(See Chart No. 1, Qd)
This notice affects Electronic Navigational Chart: CA276091, CA376164 *DFO(6308979-08)*

17-JUL-2020 LNM/D. 10-APR-2020

Delete legend WHIS against yellow, black and yellow West cardinal lighted pillar buoy 46°45′29.0″N 056°15′12.0″W
(See Chart No. 1, Qd)
This notice affects Electronic Navigational Chart: CA276091, CA376164 *DFO(6308979-09)*

Chart no. 4047

17-JUL-2020 LNM/D. 10-APR-2020

Replace depth of 44 metres with depth of 40 metres 46°43′00.0″N 056°15′30.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276091 *DFO(6308997-07)*

10-APR-2020 LNM/D. 22-NOV-2019

Amend ″WHIS″ to read ″Bell″ against red starboard hand pillar light buoy FlR 46°41′46.8″N 054°13′15.2″W
(See Chart No. 1, Qc, Qd) *(N2020011) LL(12) DFO(6308955-01)*

This notice affects Electronic Navigational Chart: CA276091, CA376135

22-NOV-2019 LNM/D. 15-MAR-2019

Add private yellow ODAS/SADO lighted pillar buoy Fl(5) Y 20s, Priv 46°58′30.0″N 054°41′50.0″W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA276091, CA376173 *DFO(6308838-01)*

15-MAR-2019 LNM/D. 11-JAN-2019

Amend Q(6)+LFl(1)15s to read Q(6)+LFl 15s against yellow and black South cardinal lighted pillar whistle buoy 46°43′52.0″N 056°12′54.0″W
(See Chart No. 1, Q130.3) *LL(89) DFO(6308579-01)*

11-JAN-2019 LNM/D. 26-OCT-2018

Affix patch 47°00′00.0″N 056°00′00.0″W
PDF
This notice affects Electronic Navigational Chart: CA276091 *DFO(6308543-03)*

26-OCT-2018 LNM/D. 06-APR-2018

Replace depth of 22 metres with depth of 15.7 metres 46°49′26.5″N 056°02′06.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276091 *DFO(6308428-13)*

26-OCT-2018 LNM/D. 06-APR-2018

Replace depth of 15.2 metres with depth of 8.2 metres 47°05′13.0″N 056°17′17.5″W
(See Chart No. 1, I10)
DFO(6308428-14)

This notice affects Electronic Navigational Chart: CA276091

Chart no. 4047

26-OCT-2018 LNM/D. 06-APR-2018

Add depth of 9.9 metres 46°59′23.8″N 056°12′14.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276091 *DFO(6308428-24)*

26-OCT-2018 LNM/D. 06-APR-2018

Add depth of 61 metres 47°06′43.9″N 056°09′45.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276091, CA376627 *DFO(6308428-35)*

06-APR-2018 LNM/D. 31-MAR-2017

Delete yellow ODAS/SADO lighted super-buoy Fl (5) Y, marked 44251 46°26′30.0″N 053°23′30.0″W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA176030, CA276091, CA376075 *DFO(6308224-02)*

06-APR-2018 LNM/D. 31-MAR-2017

Delete yellow ODAS/SADO lighted super-buoy Fl (5) Y, marked 44138 44°13′00.0″N 053°36′00.0″W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA176030, CA276091 *DFO(6308224-03)*

31-MAR-2017 LNM/D. 02-DEC-2016

Add submarine cable joining 47°05′13.0″N 052°53′48.0″W
(See Chart No. 1, L30.1) 47°05′13.0″N 052°51′42.0″W
This notice affects Electronic Navigational Chart: 47°06′00.0″N 052°50′16.0″W
CA276091, CA276101, CA376015, CA376070, CA376075 47°05′56.0″N 052°48′26.3″W
47°04′27.0″N 052°41′32.0″W
and 47°04′10.0″N 052°28′44.8″W

DFO(6307887-01)

02-DEC-2016 LNM/D. 02-SEP-2016

Add subsurface Ocean Data Acquisition system (ODAS/SADO) with known depth of 9 metres 44°11′33.8″N 053°16′29.2″W
(See Chart No. 1, L25) *DFO(6307699-05)*
This notice affects Electronic Navigational Chart: CA176030, CA276091

Chart no. 4047

02-SEP-2016 LNM/D. 06-MAY-2016

Delete legend Fog Sig against light — 46°45′52.2″N 056°09′26.9″W
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart: CA276091, CA376164 — *DFO(6307665-01)*

06-MAY-2016 LNM/D. 11-MAR-2016

Replace depth of 16 metres, 8 decimetres with depth of 14 metres, 5 decimetres — 47°05′04.4″N 056°09′07.9″W
(See Chart No. 1, I10) — *DFO(6307517-02)*
This notice affects Electronic Navigational Chart: CA276091

11-MAR-2016 LNM/D. 04-DEC-2015

Reposition yellow ODAS/SADO lighted super-buoy Fl (5) Y, marked 44138 — from 44°15′29.9″N 053°37′24.5″W to 44°13′00.0″N 053°36′00.0″W
(See Chart No. 1, Q58)

(G2016008) LL(664.8) DFO(6307461-01)

This notice affects Electronic Navigational Chart: CA276091

04-DEC-2015 LNM/D. 05-DEC-2014

Add submarine cable — joining 46°34′48.0″N 052°28′44.8″W 46°27′27.2″N 052°53′29.2″W 46°18′01.8″N 053°56′14.0″W 46°07′19.2″N 055°02′58.4″W and 45°52′14.4″N 056°29′56.8″W
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart: CA276091

DFO(6307363-01)

05-DEC-2014 LNM/D. 25-JUL-2014

Add legend Fog Sig against light — 46°50′48.0″N 055°47′51.5″W
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart: CA276091, CA376164 — *(N2014079) LL(76) DFO(6307007-02)*

25-JUL-2014 LNM/D. 25-APR-2014

Add wreck, least depth unknown — 46°49′38.4″N 056°05′09.0″W
(See Chart No. 1, K29)
This notice affects Electronic Navigational Chart: CA276091, CA376164 — *DFO(6306742-01)*

Chart no. 4047

25-JUL-2014 LNM/D. 25-APR-2014

Add wreck, least depth unknown 46°49′19.4″N 056°06′49.3″W
(See Chart No. 1, K29)
This notice affects Electronic Navigational Chart: CA276091, CA376164 *DFO(6306742-02)*

25-APR-2014 LNM/D. 18-APR-2014

Delete legend Fog Sig against light 46°50′48.0″N 055°47′51.5″W
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart: CA276091, CA376164 *(N2014020) LL(76) DFO(6306716-01)*

18-APR-2014 LNM/D. 03-FEB-2012

Delete legend Fog Sig against light 46°41′25.1″N 053°24′05.7″W
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart: CA276091, CA376106, CA576107 *(N2014019) LL(5) DFO(6306714-02)*

03-FEB-2012 LNM/D. 26-AUG-2011

Add yellow ODAS/SADO lighted super-buoy Fl (5) Y 46°42′06.0″N 056°11′18.0″W
(See Chart No. 1, Q58)
DFO(6305904-01)

This notice affects Electronic Navigational Chart: CA276091, CA376164

26-AUG-2011 LNM/D. 18-MAR-2011

Delete obstruction with known depth of 100 metres with legend ODAS/SADO 44°33′21.4″N 056°03′56.1″W
(See Chart No. 1, K41) *DFO(6305672-01)*
The mooring is temporary. The proposed date of removal is July 2012.

This notice affects Electronic Navigational Chart: CA276091

26-AUG-2011 LNM/D. 18-MAR-2011

Chart no. 4047

Delete obstruction with known depth of 100 metres with legend ODAS/SADO 44°44′47.5″N 056°05′08.7″W
(See Chart No. 1, K41)
The mooring is temporary. The proposed date of removal is July 2012.
DFO(6305672-02)

This notice affects Electronic Navigational Chart: CA276091

18-MAR-2011 LNM/D. 31-DEC-2010

Delete radar transponder beacon with legend Racon 46°55′44.0″N 055°22′45.0″W
(See Chart No 1 S3.3)
DFO(6305286-01)

31-DEC-2010 LNM/D. 06-AUG-2010

Delete legend Loran against tower 46°46′30.0″N 053°10′30.0″W
(See Chart No. 1, E20)
(N2010062) DFO(6305143-01)

This notice affects Electronic Navigational Chart: CA176030, CA276091, CA376106

06-AUG-2010 LNM/D. 02-JUL-2010

Amend Fl to read Fl 10s 31m 22M against light 46°41′25.1″N 053°24′05.7″W
(See Chart No. 1 P16)
LL(5) DFO(6304964-01)

This notice affects Electronic Navigational Chart: CA276091

06-AUG-2010 LNM/D. 02-JUL-2010

Amend Fl 6s 34m 6M to read Fl 6s 33m 16M against light 47°06′21.8″N 055°04′19.8″W
(See Chart No. 1 P16)
LL(65) DFO(6304966-01)

This notice affects Electronic Navigational Chart: CA276091, CA576225

02-JUL-2010 LNM/D. 09-APR-2010

Add obstruction with depth of 100 metres and legend ODAS/SADO 44°33′21.4″N 056°03′56.1″W
The mooring is temporary. The proposed date of removal is June 2011.
DFO(6304914-01)

This notice affects Electronic Navigational Chart: CA276091

Chart no. 4047

02-JUL-2010 LNM/D. 09-APR-2010

Add obstruction with depth of 100 metres and legend ODAS/SADO 44°44′47.5″N 056°05′08.7″W
The mooring is temporary. The proposed date of removal is June 2011. *DFO(6304914-02)*

This notice affects Electronic Navigational Chart: CA276091

09-APR-2010 LNM/D. 26-FEB-2010

Amend Fl 5s 33m 16M to read Fl 5s 33m 15M against light 46°56′25.9″N 052°53′34.4″W
(See Chart No 1 P16)

LL(512) DFO(6304778-01)

This notice affects Electronic Navigational Chart: CA276091

26-FEB-2010 LNM/D. 12-JUN-2009

Amend Fl 5s 33m 8M to read Fl 5s 33m 16M against light 46°56′25.9″N 052°53′34.4″W
(See Chart No 1 P16)

LL(512) DFO(6304695-01)

This notice affects Electronic Navigational Chart: CA276091, CA376070

26-FEB-2010 LNM/D. 12-JUN-2009

Amend Fl 15s 27m 11M to read Fl 15s 27m 17M against light 46°53′52.8″N 055°20′51.2″W
(See Chart No 1 P16)

LL(73) DFO(6304696-01)

This notice affects Electronic Navigational Chart: CA276091

12-JUN-2009 LNM/D. 23-JAN-2009

(T)Add subsurface mooring at a depth of 100 metres 44°32′58.3″N 056°03′21.0″W

The mooring has been removed. Notice 12-June-2009(T), DFO (6304405) is cancelled.
Cancelled on 18-JUN-10 *DFO(6304405-01)*

12-JUN-2009 LNM/D. 23-JAN-2009

(T)Add subsurface mooring at a depth of 1050 metres 44°45′01.1″N 056°05′32.7″W

The mooring has been removed. Notice 12-June-2009(T), DFO (6304405) is cancelled.
Cancelled on 18-JUN-10 *DFO(6304405-02)*

Chart no. 4047

23-JAN-2009 LNM/D. 31-DEC-2004

Add submarine cable joining 47°07′26.7″N 055°02′19.9″W
(See Chart No 1 L30.1) 47°08′46.5″N 054°50′28.3″W
and 47°10′00.0″N 054°46′18.3″W

This notice affects Electronic Navigational Chart: CA276091 *DFO(6304176-01)*

31-DEC-2004 LNM/D. 24-DEC-2004

Delete legend ″WHIS″ against red, green and red starboard bifurcation pillar light and whistle buoy Fl(2+1) R, WHIS 46°56′12.0″N 053°43′09.0″W

(N2004192) LL(8.7) DFO(6302103-01)

31-DEC-2004 LNM/D. 24-DEC-2004

Delete legend ′BELL′ against black and yellow North cardinal pillar light and bell buoy Q, BELL marked MLR 46°28′20.9″N 054°01′49.3″W

(N2004193) LL(7.4) DFO(6302104-01)

24-DEC-2004 LNM/D. 18-JUN-2004

Delete legend ″WHIS″ against red and white fairway pillar light buoy Mo(A), WHIS 46°47′00.0″N 054°03′16.0″W

(N2004186) LL(13) DFO(6302059-01)

18-JUN-2004 LNM/D. 14-MAR-2003

Add limit of restricted area joining 44°02′00.0″N 055°00′00.0″W
44°02′00.0″N 055°25′00.0″W
43°45′00.0″N 055°25′00.0″W
43°45′00.0″N 055°00′00.0″W
and 44°02′00.0″N 055°00′00.0″W

DFO(6301284-01)

18-JUN-2004 LNM/D. 14-MAR-2003

Add legend ″CAUTION″, ″Explosives and Chemicals″, ″Explosifs et produits chimiques″ 43°51′00.0″N 055°12′00.0″W

DFO(6301284-02)

14-MAR-2003 LNM/D. 01-FEB-2002

Chart no. 4047

Add non-dangerous wreck 46°48′13.8″N 054°54′41.4″W

(N2002075) DFO(6300433-01)

01-FEB-2002 LNM/D. 18-JAN-2002

Add wreck 46°48′42.0″N 055°44′42.0″W

(N2001151) DFO(6300011-01)

18-JAN-2002 LNM/D. 14-DEC-2001

Delete black, red, black, isolated danger pillar light buoy Fl (2) 5s, BELL, marked MLR 46°28′01.8″N 054°01′33.0″W

(N2000128) LL(7.4) DFO(6828930-01)

18-JAN-2002 LNM/D. 14-DEC-2001

Add black and yellow, North cardinal pillar light buoy Q, BELL, marked MLR 46°28′20.9″N 054°01′49.3″W

(N2000-128) LL(7.4) DFO(6828930-02)

14-DEC-2001 LNM/D. 05-OCT-2001

Add depth of 18 metres 5 decimetres 46°42′03.5″N 055°42′03.1″W

DFO(6829838-01)

14-DEC-2001 LNM/D. 05-OCT-2001

Delete depth of 49 metres 46°41′50.0″N 055°42′30.0″W

DFO(6829838-02)

05-OCT-2001 LNM/D. 10-AUG-2001

Amend Fl to read Fl R 46°57′15.0″N 055°14′06.0″W

(N2000036) LL(72.000) DFO(6828797-01)

10-AUG-2001 LNM/D. 22-JUN-2001

Amend LFl to read Fl 10s 26m 17M 46°58′50.0″N 055°11′30.0″W

(N2001079) LL(71.000) DFO(6829580-01)

Chart no. 4047

10-AUG-2001 LNM/D. 22-JUN-2001
Add Fog Sig 46°58′50.0″N 055°11′30.0″W

LL(71.2) DFO(6829580-02)

22-JUN-2001 LNM/D. 20-AUG-1999
Delete radiobeacon and legend RC 46°45′56.0″N 056°09′30.0″W

DFO(6828978-01)

22-JUN-2001 LNM/D. 20-AUG-1999
Add aeronautical radiobeacon with legend Aero RC 46°45′50.0″N 056°10′30.0″W

DFO(6828978-02)