Chart no. 4230

4230 - Little Hope Island to / à Cape St Marys - New Chart - 15-JUN-1990 - NAD 1983

29-MAR-2024 LNM/D. 17-FEB-2023

Replace depth of 11.3 metres with depth of 10.5 metres 43°42′07.2″N 064°59′13.7″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6311060-06)*

17-FEB-2023 LNM/D. 26-AUG-2022

Add wreck, least depth unknown, with legend PA Rep (2022) 43°21′00.0″N 065°45′00.0″W
(See Chart 1, K29, B7, I3)
This notice affects Electronic Navigational Chart: CA276206, CA376014, CA476043 *DFO(6310555-01)*

26-AUG-2022 LNM/D. 06-MAY-2022

Add rock which covers and uncovers with legend Rep (2022) 43°31′12.9″N 065°45′16.8″W
(See Chart No. 1, K11, I3)
This notice affects Electronic Navigational Chart: CA376014, CA476043 *DFO(6310227-01)*

06-MAY-2022 LNM/D. 07-JAN-2022

Amend Fl 5s 25m 19M to read Oc 3s25m19M against light 43°41′22.3″N 066°08′36.8″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276206, CA376018 *(F2022001) LL(272) DFO(6310079-01)*

07-JAN-2022 LNM/D. 19-JUN-2020

Replace depth of 7 metres with depth of 4.2 metres 43°55′00.2″N 064°44′30.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6309965-01)*

07-JAN-2022 LNM/D. 19-JUN-2020

Delete depth of 4 metres 43°53′11.0″N 064°44′29.0″W
(See Chart No. 1, I10)
DFO(6309965-02)

07-JAN-2022 LNM/D. 19-JUN-2020

Add depth of 2.5 metres 43°53′17.9″N 064°44′29.2″W
(See Chart No. 1, I10)
DFO(6309965-03)

Chart no. 4230

07-JAN-2022 LNM/D. 19-JUN-2020

Replace depth of 7.3 metres with depth of 6.1 metres 43°48′59.5″N 064°47′44.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6309965-04)*

07-JAN-2022 LNM/D. 19-JUN-2020

Add depth of 0.6 metres 43°49′37.6″N 064°52′20.9″W
(See Chart No. 1, I10)
DFO(6309965-05)

07-JAN-2022 LNM/D. 19-JUN-2020

Replace depth of 0.2 metres with drying height of 0 metres 43°38′15.6″N 065°18′40.0″W
(See Chart No. 1, I10, I15)
DFO(6309965-06)

07-JAN-2022 LNM/D. 19-JUN-2020

Replace depth of 0.4 metres with drying height of 0.1 metres (See 43°38′28.2″N 065°19′21.6″W
Chart No. 1, I10, I15)
DFO(6309965-07)

07-JAN-2022 LNM/D. 19-JUN-2020

Add depth of 0.1 metres 43°28′25.7″N 065°41′08.1″W
(See Chart No. 1, I10)
DFO(6309965-08)

07-JAN-2022 LNM/D. 19-JUN-2020

Replace depth of 3 metres with depth of 0.5 metres 43°38′35.3″N 065°58′29.7″W
(See Chart No. 1, I10)
DFO(6309965-09)

07-JAN-2022 LNM/D. 19-JUN-2020

Chart no. 4230

Add WARNING Recent bathymetric surveys show the presence of shallower depths compared to what is presently charted. The shallower depths considered the most hazardous to navigation and within or near main shipping channels will be published in Notices to Mariners (WWW.NOTMAR.CA). Mariners are advised to exercise extreme caution, specifically when they navigate outside of the marked navigation channels. AVERTISSEMENT Des levés bathymétriques récents ont révélé la présence de profondeurs moindres que celles portées sur les cartes marines. Les profondeurs moindres les plus dangereuses pour la navigation et dans ou près des principales voies de navigation seront publiées dans les Avis aux navigateurs (WWW.NOTMAR.CA). Nous demandons aux navigateurs d'exercer la plus grande prudence, particulièrement lors de la navigation en dehors des voies de navigation balisées.
44°03′30.0″N 065°05′50.0″W
DFO(6309965-10)

19-JUN-2020 LNM/D. 15-MAY-2020

Amend FI6s 16m 9M to read LFI 6s16m9M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276206, CA376018, CA476048
43°37′44.0″N 066°01′35.0″W
(F2020023) LL(283) DFO(6308988-01)

15-MAY-2020 LNM/D. 14-FEB-2020

Delete light FG
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376018, CA576020
43°48′56.3″N 066°09′09.0″W
(F2020010) LL(257) DFO(6308960-01)

14-FEB-2020 LNM/D. 11-OCT-2019

Amend FI 15s 30m 14M to read FI G 15s30m10M against light
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA376044, CA476048
43°39′45.8″N 065°52′01.0″W
(F2019042) LL(295) DFO(6308905-01)

11-OCT-2019 LNM/D. 29-JUN-2018

Add wreck Wk with known depth of 16.5 metres
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA376018
44°03′41.3″N 066°16′05.4″W
DFO(6308803-01)

29-JUN-2018 LNM/D. 05-JAN-2018

Chart no. 4230

Amend Fl(2)15s28m10M to read LFl 6s28m11M against light — 43°30′26.2″N 065°20′44.2″W
(See Chart No. 1, P16) — *(F2018019) LL(349) DFO(6308301-01)*

This notice affects Electronic Navigational Chart: CA276800, CA376047

05-JAN-2018 — LNM/D. 05-FEB-2016

Delete fog signal against light — 43°31′10.5″N 065°44′43.1″W
(See Chart No. 1, R1)
This notice affects Electronic Navigational Chart: CA376014, CA476043 — *(F2017020) LL(312) DFO(6307973-01)*

05-FEB-2016 — LNM/D. 31-JUL-2015

Add wreck WK with known depth of 19 metres, 7 decimetres — 43°45′06.5″N 066°10′11.6″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA376018, CA576020 — *DFO(6307394-02)*

31-JUL-2015 — LNM/D. 05-JUN-2015

Amend FogSig 20s (Occas) to read FogSig 20s — 43°27′00.0″N 065°28′15.4″W
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart: CA276800, CA376047 — *(F2015022) LL(336) DFO(6307210-01)*

05-JUN-2015 — LNM/D. 27-MAR-2015

Amend FogSig 20s to read FogSig 20s (Occas) — 43°26′59.0″N 065°28′15.0″W
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart: CA276800, CA376047 — *(F2015014) LL(336) DFO(6307115-01)*

27-MAR-2015 — LNM/D. 10-OCT-2014

Add light FlR — 43°59′09.6″N 066°09′39.6″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376018 — *(F2015005) LL(250.1) DFO(6307066-01)*

10-OCT-2014 — LNM/D. 24-JAN-2014

Chart no. 4230

Delete fog signal Fog Sig 20s against light 43°41′23.1″N 066°08′38.3″W
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart: CA276206, CA376018 *(F2014029) LL(272) DFO(6306854-01)*

24-JAN-2014 LNM/D. 18-OCT-2013

Delete red starboard hand lighted pillar buoy FlR, marked KC52 43°42′08.2″N 064°59′58.3″W
(See Chart No. 1, Qf) *(F2013037) LL(386) DFO(6306576-01)*
This notice affects Electronic Navigational Chart: CA376044, CA376045

24-JAN-2014 LNM/D. 18-OCT-2013

Add black, yellow and black East cardinal lighted pillar buoy Q(3)10s, marked KC 43°42′29.4″N 064°59′42.0″W
(See Chart No. 1, Q130.3) *(F2013037) LL(386.0) DFO(6306576-02)*
This notice affects Electronic Navigational Chart: CA376044, CA376045

18-OCT-2013 LNM/D. 11-NOV-2011

Add wreck with legend ″PA Rep(2011)″, least depth unknown 43°18′15.6″N 066°00′45.0″W
(See Chart No. 1, K28)
This notice affects Electronic Navigational Chart: CA376014 *DFO(6306427-01)*

11-NOV-2011 LNM/D. 05-AUG-2011

Amend FlG to read LFlG against light 43°59′09.5″N 066°09′32.9″W
(See Chart No. 1, P1)
(F2011178) LL(247) DFO(6305794-01)

This notice affects Electronic Navigational Chart: CA376018

05-AUG-2011 LNM/D. 23-APR-2010

Amend FL 12s 35m 13M to read LFl 12s 35m 13M (Priv) against light 43°47′38.8″N 066°09′19.3″W
(See Chart No. 1, P16) *(F2011102) LL(260) DFO(6305611-01)*

This notice affects Electronic Navigational Chart: CA576020

Chart no. 4230

23-APR-2010 LNM/D. 21-AUG-2009

Delete crib 43°44′19.0″N 065°19′09.4″W
(See Chart No 1 Fb)

DFO(6304735-02)

This notice affects Electronic Navigational Chart: CA576041

21-AUG-2009 LNM/D. 07-AUG-2009

Delete private yellow ODAS/SADO lighted super-buoy Fl (5) Y 43°37′39.6″N 066°33′13.2″W
(See Chart No 1 Q58)

DFO(6304496-01)

This notice affects Electronic Navigational Chart: CA276206, CA376044

07-AUG-2009 LNM/D. 24-JUL-2009

Amend Fl 10s 33m 16M to read Fl 10s 33m 10M against light 43°37′22.5″N 065°15′52.5″W
(See Chart No 1 P16)

LL(355) DFO(6304444-01)

This notice affects Electronic Navigational Chart: CA276800, CA376047

07-AUG-2009 LNM/D. 24-JUL-2009

Replace green port hand can buoy, marked EA1 with 43°43′09.3″N 066°07′34.5″W
green port hand can light buoy FlG, marked EA1
(See Chart No 1 Qg) *(F2004223) LL(272.23) DFO(6304452-01)*

24-JUL-2009 LNM/D. 22-MAY-2009

Amend Fl(2) 15s 28m 16M to read Fl(2) 15s 28m 10M against light 43°30′26.2″N 065°20′44.2″W
(See Chart No 1 P16)

LL(349) DFO(6304430-01)

This notice affects Electronic Navigational Chart: CA276800, CA376047

22-MAY-2009 LNM/D. 27-MAR-2009

Chart no. 4230

Add non-dangerous wreck 43°12′11.6″N 066°49′04.1″W
(See Chart No 1 K29)
DFO(6304363-01)

27-MAR-2009 LNM/D. 27-FEB-2009

Amend legend Fl 15s 30m 8M to read Fl 15s 30m 14M against light 43°39′45.8″N 065°52′02.6″W
(See Chart No 1 P16)
DFO(6304285-01)

27-FEB-2009 LNM/D. 07-NOV-2008

Amend VQ(6)+LFl 10s to read Q(6)+LFl 15s against yellow and black South cardinal lighted spar buoy, marked KSA 43°39′00.0″N 065°14′07.8″W
(See Chart No 1 Q130.3)
(F2009001) LL(357.8) DFO(6304271-01)

This notice affects Electronic Navigational Chart: CA376047

07-NOV-2008 LNM/D. 07-MAR-2008

Delete circular radiobeacon against light Fl 10s 31m 43°23′40.0″N 066°00′51.0″W
(See Chart No 1 S10)
DFO(6304021-01)

This notice affects Electronic Navigational Chart: CA276206, CA376014

07-MAR-2008 LNM/D. 18-JAN-2008

Amend Roseway Basin Right Whale Conservation Area / Zone de préservation des baleines noires du Bassin Roseway to read 43°09′00.0″N 065°06′30.0″W
See CAUTION NO. 2/Voir ATTENTION nº2
DFO(6303814-01)

07-MAR-2008 LNM/D. 18-JAN-2008

Chart no. 4230

Add note: 43°55′45.0″N 065°53′15.0″W

CAUTION NO. 2
Roseway Basin Seasonal Area to be Avoided. In order to significantly reduce the risk of ship strikes of the highly endangered North Atlantic right whale, it is recommended that ships of 300 gross tonnage and upwards solely in transit during the period of June 1st through December 31st should avoid this area.

DFO(6303814-02)

ATTENTION nº2
Zone du bassin Roseway à éviter sur une base saisonnière. On recommande aux navires de 300 tonnes brut et plus et transitant dans cette zone de conservation, d'éviter cette dernière durant la période allant du 1er juin au 31 décembre afin de réduire considérablement le risque de collision entre les navires et les baleines noires de l'Atlantique Nord, dont l'espèce est en voie de disparition.

(See Chart No 1 Section A 14.)

18-JAN-2008 LNM/D. 28-DEC-2007

Add limit of restricted area joining 43°04′00.0″N 065°30′00.0″W
(See Chart No 1 N2.1) 43°16′00.0″N 064°55′00.0″W
and 43°04′00.0″N 064°56′30.0″W

DFO(6303774-01)

18-JAN-2008 LNM/D. 28-DEC-2007

Add legend Roseway Basin Right Whale Conservation Area / Zone de préservation des baleines noires du Bassin Roseway 43°09′00.0″N 065°06′30.0″W

DFO(6303774-02)

28-DEC-2007 LNM/D. 21-DEC-2007

Replace yellow, black and yellow West cardinal lighted spar buoy Q(9) 15s, marked NAC with yellow, black and yellow West cardinal lighted pillar buoy Q(9) 15s, marked NAC 43°24′59.3″N 065°39′18.9″W

(F2007083) LL(324) DFO(6303674-01)

21-DEC-2007 LNM/D. 04-MAY-2007

Chart no. 4230

Replace green port hand spar buoy, marked KA51 with green port hand lighted pillar buoy FlG, marked KA51 — 43°43′12.0″N 064°58′00.0″W

(F2007087) LL(386.01) DFO(6303678-01)

21-DEC-2007 — LNM/D. 04-MAY-2007

Add light VQ(6)+LFl 10s against yellow and black South cardinal spar buoy, marked KSA
(See Chart No 1, Q130.3.) — 43°39′00.0″N 065°14′07.8″W

(F2007088) LL(357.8) DFO(6303679-01)

04-MAY-2007 — LNM/D. 23-MAR-2007

Add light ″Q(6)+LFl 15s″ against yellow and black South cardinal spar buoy, marked JJ — 43°26′00.0″N 065°26′35.0″W

(F2007042) LL(340.01) DFO(6303387-01)

23-MAR-2007 — LNM/D. 09-FEB-2007

Replace red starboard hand lighted pillar bell buoy FlR, BELL, marked KE56 with red and white fairway lighted pillar buoy Mo(A), marked KE — 43°39′31.3″N 065°04′18.9″W

(F2007024) LL(383.1) DFO(6303346-01)

09-FEB-2007 — LNM/D. 15-DEC-2006

Reposition green port hand lighted spar buoy FlG, marked P1 — from 43°35′12.0″N 065°48′10.5″W
to 43°35′10.3″N 065°48′13.9″W

(F2006181) LL(302.5) DFO(6303271-01)

15-DEC-2006 — LNM/D. 24-NOV-2006

Delete legend ″BELL″ against green port hand lighted pillar bell buoy FlG, BELL marked KK51 — 43°37′32.0″N 065°08′11.5″W

(F2006147) LL(369) DFO(6303184-01)

15-DEC-2006 — LNM/D. 24-NOV-2006

Delete legend ″BELL″ against red starboard hand lighted pillar bell buoy FlR, marked UV52 — 43°47′15.0″N 064°49′53.0″W

(F2006162) LL(391) DFO(6303209-01)

15-DEC-2006 — LNM/D. 24-NOV-2006

Chart no. 4230

Delete green port hand lighted pillar whistle buoy FlG, WHIS marked KC51 — 43°42′27.0″N 064°59′34.0″W

(F2006164) LL(385) DFO(6303210-01)

15-DEC-2006 — LNM/D. 24-NOV-2006

Add red starboard hand lighted pillar buoy FlR, marked KC52 — 43°42′07.5″N 065°00′00.0″W

(F2006165) LL(386) DFO(6303211-01)

24-NOV-2006 — LNM/D. 17-NOV-2006

Delete legend ″WHIS″ against red starboard hand lighted pillar whistle buoy FlR, WHIS marked JS56 — 43°25′42.0″N 065°29′16.0″W

(F2006124) LL(337) DFO(6303090-01)

24-NOV-2006 — LNM/D. 17-NOV-2006

Delete green port hand lighted pillar bell buoy FlG, BELL marked JS53 — 43°23′58.0″N 065°35′20.0″W

(F2006127) LL(328) DFO(6303091-01)

24-NOV-2006 — LNM/D. 17-NOV-2006

Add green port hand lighted pillar buoy FlG, marked JS53 — 43°23′58.0″N 065°35′20.0″W

(F2006127) LL(328) DFO(6303091-02)

24-NOV-2006 — LNM/D. 17-NOV-2006

Delete legend ″BELL″ against green port hand lighted pillar bell buoy FlG, BELL marked JS55 — 43°25′13.0″N 065°34′20.0″W

(F2006129) LL(329) DFO(6303092-01)

24-NOV-2006 — LNM/D. 17-NOV-2006

Delete legend ′WHIS′ against red and white fairway lighted pillar whistle buoy Mo(A), WHIS, marked ′JQ′ — 43°27′24.5″N 065°32′44.5″W

(F2006130) LL(330) DFO(6303093-01)

17-NOV-2006 — LNM/D. 10-NOV-2006

Chart no. 4230

Reposition yellow ODAS/SADO light buoy Fl (5) Y, marked PRIV — from 43°37′31.2″N 066°37′16.2″W to 43°37′39.6″N 066°33′13.2″W

This notice affects Electronic Navigational Chart: CA276206, CA276800 — *DFO(6303157-01)*

10-NOV-2006 — LNM/D. 25-AUG-2006

Delete legend ′WHIS′ against red and white fairway lighted pillar whistle buoy Mo(A), WHIS, marked ′S′ — 43°37′34.0″N 065°13′51.0″W

(F2006108) LL(357) DFO(6303065-01)

This notice affects Electronic Navigational Chart: CA276800

10-NOV-2006 — LNM/D. 25-AUG-2006

Delete legend ″BELL″ against red, green and red starboard bifurcation lighted pillar whistle buoy Fl(2+1) R, BELL marked SAC — 43°38′18.0″N 065°13′12.0″W

(F2006116) LL(357.5) DFO(6303078-01)

25-AUG-2006 — LNM/D. 11-AUG-2006

Amend ″FlG 12s 10m″ to read ″FlG″ against light — 43°28′06.4″N 065°33′56.1″W

(F2006074) LL(331.2) DFO(6302869-01)

11-AUG-2006 — LNM/D. 14-JUL-2006

(T)Replace yellow, black and yellow West cardinal lighted spar buoy Q(9) 15s, marked NAC with red starboard hand lighted spar buoy FlR, marked NA6 — 43°24′59.3″N 065°39′18.9″W

(F2006015) LL(324) DFO(6303060-01)

Buoy permanently established. Notice 11-August-2006(T), DFO (6303060-01) is now cancelled. See reference DFO(6303674-01) appearing in this edition.
Cancelled on 28-DEC-07

14-JUL-2006 — LNM/D. 30-JUN-2006

Chart no. 4230

Delete legend ″BELL″ against red starboard hand lighted pillar bell buoy FlR, marked N6 — 43°36′40.0″N 066°12′42.0″W

(F2006087) LL(273) DFO(6302894-01)

This notice affects Electronic Navigational Chart: CA276206, CA276800, CA376018

30-JUN-2006 — LNM/D. 23-JUN-2006

Delete light ″LFl 12s 30m 9M″ — 43°48′34.0″N 064°47′21.0″W

(F2006083) LL(393) DFO(6302886-01)

This notice affects Electronic Navigational Chart: CA276800

23-JUN-2006 — LNM/D. 28-APR-2006

Add light FlG — 43°25′25.8″N 065°39′25.6″W

(F2006076) LL(323.91) DFO(6302871-01)

28-APR-2006 — LNM/D. 10-MAR-2006

Replace red and white fairway lighted pillar buoy Mo(A), marked NAC with yellow, black and yellow West cardinal lighted spar buoy Q(9) 15s, marked NAC — 43°24′59.3″N 065°39′18.9″W

(F2006015) LL(324) DFO(6302779-01)

28-APR-2006 — LNM/D. 10-MAR-2006

Delete legend ″BELL″ against green, red and green port bifurcation lighted pillar bell buoy Fl(2+1) G, marked TA — 43°39′27.3″N 065°58′20.9″W

(F2006016) LL(293.55) DFO(6302780-01)

10-MAR-2006 — LNM/D. 03-MAR-2006

Delete legend ′WHIS′ against yellow and black South cardinal lighted pillar whistle buoy Q (6)+LFl 15s, WHIS marked ′J′ — 43°21′00.0″N 065°26′44.0″W

(F2005148) LL(338) DFO(6302731-01)

This notice affects Electronic Navigational Chart: CA276800

10-MAR-2006 — LNM/D. 03-MAR-2006

Chart no. 4230

Delete red starboard hand lighted pillar whistle buoy FlR, marked U36 — 43°47′21.5″N 064°46′50.0″W

(F2006006) LL(392) DFO(6302737-01)

10-MAR-2006 — LNM/D. 03-MAR-2006

Delete legend ′WHIS′ against red and white fairway lighted pillar whistle buoy Mo(A), WHIS, marked ′JA′ — 43°26′33.0″N 065°24′09.0″W

(F2006008) LL(347) DFO(6302739-01)

This notice affects Electronic Navigational Chart: CA276800

10-MAR-2006 — LNM/D. 03-MAR-2006

Add green port hand lighted pillar buoy FlG, marked US51 — 43°51′45.0″N 064°46′16.8″W

(F2006010) LL(394.5) DFO(6302741-01)

10-MAR-2006 — LNM/D. 03-MAR-2006

Add black, yellow and black East cardinal lighted pillar buoy Q(3) 10s, marked UEF — 43°48′12.6″N 064°46′27.2″W

(F2006014) LL(394.01) DFO(6302747-01)

03-MAR-2006 — LNM/D. 24-FEB-2006

Delete legend ″BELL″ against red and white fairway pillar light and bell buoy Mo (A), BELL, marked NSC — 43°35′59.6″N 066°03′47.6″W

(F2005138) LL(288) DFO(6302723-01)

03-MAR-2006 — LNM/D. 24-FEB-2006

Delete legend ″BELL″ against red starboard hand pillar light and bell buoy FlR, BELL marked NE2 — 43°37′08.6″N 065°54′51.4″W

(F2005139) LL(285.2) DFO(6302724-01)

24-FEB-2006 — LNM/D. 10-FEB-2006

Delete legend ″BELL″ against red starboard hand pillar light and bell buoy FlR, BELL marked ND4 — 43°30′30.3″N 065°49′10.4″W

(F2005141) LL(303) DFO(6302725-01)

24-FEB-2006 — LNM/D. 10-FEB-2006

Chart no. 4230

Delete legend ″WHIS″ against green port hand pillar light and whistle buoy FlG, WHIS, marked Y3 — 43°46′57.3″N 066°09′29.5″W

(F2005142) LL(259) DFO(6302726-01)

24-FEB-2006 — LNM/D. 10-FEB-2006

Delete red starboard hand conical buoy, marked KE52 — 43°39′05.3″N 065°02′02.9″W

(F2006009) DFO(6302740-01)

This notice affects Electronic Navigational Chart: CA276800, CA576040

24-FEB-2006 — LNM/D. 10-FEB-2006

Add red starboard hand lighted pillar buoy FlR, marked KE52 — 43°38′27.0″N 065°02′30.0″W

(F2006009) LL(382.01) DFO(6302740-02)

This notice affects Electronic Navigational Chart: CA276800, CA576040

10-FEB-2006 — LNM/D. 25-NOV-2005

Add black and yellow North cardinal spar buoy, marked EA — 43°43′24.4″N 066°08′01.1″W

(F2005106) DFO(6302678-01)

This notice affects Electronic Navigational Chart: CA376018

10-FEB-2006 — LNM/D. 25-NOV-2005

Amend ″FlR″ to read ″QR″ against red starboard hand spar light buoy, marked NA4 — 43°23′46.5″N 065°39′13.0″W

(F2005137) LL(326.02) DFO(6302698-01)

25-NOV-2005 — LNM/D. 18-NOV-2005

Delete legend ″BELL″ against red starboard hand pillar light and bell buoy FlR, BELL marked Y2 — 43°45′10.3″N 066°09′41.0″W

(F2005088) LL(268) DFO(6302598-01)

This notice affects Electronic Navigational Chart: CA376018

18-NOV-2005 — LNM/D. 04-NOV-2005

Chart no. 4230

Delete legend ″Fog Sig 20s″ against light 43°27′23.2″N 065°44′36.2″W

(F2005085) LL(307) DFO(6302558-01)

04-NOV-2005 LNM/D. 30-SEP-2005

Delete legend ″BELL″ against red and white fairway pillar light and bell buoy Mo (A), BELL, marked NSH 43°40′04.2″N 066°03′39.0″W

(F2005077) LL(275) DFO(6302547-01)

This notice affects Electronic Navigational Chart: CA376018

30-SEP-2005 LNM/D. 23-SEP-2005

Delete legend ″BELL″ against green port hand pillar light buoy FlG, BELL marked S51 43°35′58.3″N 065°15′51.4″W

(F2005050) LL(354) DFO(6302471-01)

23-SEP-2005 LNM/D. 22-JUL-2005

Delete red starboard hand pillar light and whistle buoy FlR, WHIS, marked K38 43°36′57.0″N 065°01′55.0″W

(F2005051) LL(382) DFO(6302472-01)

This notice affects Electronic Navigational Chart: CA276800

22-JUL-2005 LNM/D. 08-JUL-2005

Add light ′FlR′ against red starboard hand spar buoy, marked NA4 43°23′46.5″N 065°39′13.0″W

(F2005035) LL(326.02) DFO(6302362-01)

08-JUL-2005 LNM/D. 27-MAY-2005

Delete legend ″WHIS″ against red and white fairway pillar light buoy Mo(A), WHIS marked UX 43°46′19.0″N 064°54′47.0″W

(F2005036) LL(387) DFO(6302363-01)

27-MAY-2005 LNM/D. 20-MAY-2005

Delete fog signal ″Fog Sig Occas″ 43°26′39.4″N 065°35′05.9″W

(F2005017) LL(329.4) DFO(6302274-01)

Chart no. 4230

20-MAY-2005 LNM/D. 06-MAY-2005

Add light FlR 43°35′53.4″N 065°46′55.6″W

(F2005019) LL(299) DFO(6302276-01)

06-MAY-2005 LNM/D. 08-APR-2005

Delete red starboard hand conical buoy, marked NK2 43°20′08.3″N 065°58′45.9″W

(F2004211) DFO(6302220-01)

06-MAY-2005 LNM/D. 08-APR-2005

Add black, yellow and black East cardinal pillar light buoy Q(3) 10s, marked NK 43°20′26.9″N 065°58′43.4″W

(F2004211) LL(290.2) DFO(6302220-02)

08-APR-2005 LNM/D. 04-MAR-2005

Delete rock awash 43°20′27.8″N 065°59′09.0″W

DFO(6302248-01)

08-APR-2005 LNM/D. 04-MAR-2005

Add rock which covers and uncovers with drying height of 0.4 metres 43°20′27.2″N 065°59′11.0″W

DFO(6302248-02)

04-MAR-2005 LNM/D. 25-FEB-2005

Delete green port hand can buoy, marked NJ1 43°32′53.3″N 066°02′08.9″W

(F2004193) DFO(6302187-01)

This notice affects Electronic Navigational Chart: CA376018

04-MAR-2005 LNM/D. 25-FEB-2005

Delete red and white fairway pillar light and bell buoy Mo(A), BELL, marked NS 43°31′36.0″N 066°05′06.0″W

(F2004196) LL(274) DFO(6302190-01)

04-MAR-2005 LNM/D. 25-FEB-2005

Chart no. 4230

Add yellow and black South cardinal pillar light buoy ′Q(6)+LFl 15s′, marked NSA — 43°30′45.3″N 066°02′31.0″W

(F2004207) LL(274.2) DFO(6302202-01)

04-MAR-2005 — LNM/D. 25-FEB-2005

Add black and yellow North cardinal pillar light buoy Q, marked NSB — 43°33′23.5″N 066°03′00.0″W

(F2004210) LL(274.4) DFO(6302205-01)

This notice affects Electronic Navigational Chart: CA376018

25-FEB-2005 — LNM/D. 11-FEB-2005

Replace red starboard hand conical buoy, marked NC2 with red starboard hand pillar light buoy FlR, marked N2 — 43°22′51.0″N 065°41′49.5″W

(F2004212) LL(307.02) DFO(6302175-01)

25-FEB-2005 — LNM/D. 11-FEB-2005

Replace red and white fairway pillar, light buoy Mo (A), BELL, marked NA with red starboard hand pillar light buoy FlR, marked NA2 — 43°23′30.3″N 065°38′42.9″W

(F2004213) LL(326) DFO(6302181-01)

25-FEB-2005 — LNM/D. 11-FEB-2005

Add green port hand spar light buoy FlG, marked P1 — 43°35′12.0″N 065°48′10.5″W

(F2004214) LL(302.5) DFO(6302182-01)

25-FEB-2005 — LNM/D. 11-FEB-2005

Delete red and white fairway pillar light and whistle buoy Mo(A), WHIS, marked P — 43°34′51.0″N 065°48′12.0″W

(F2004194) LL(302) DFO(6302188-01)

25-FEB-2005 — LNM/D. 11-FEB-2005

Delete legend ″BELL″ against red and white fairway pillar light and bell buoy Mo (A), BELL, marked D — 43°29′09.3″N 065°46′28.9″W

(F2004197) LL(304) DFO(6302191-01)

Chart no. 4230

25-FEB-2005 LNM/D. 11-FEB-2005

Replace red starboard hand pillar light and bell buoy FlR, BELL, marked ND2 with red and white fairway pillar, light buoy Mo (A), marked C — 43°26′23.3″N 065°44′43.9″W

(F2004202) LL(306) DFO(6302195-01)

25-FEB-2005 LNM/D. 11-FEB-2005

Delete legend ″BELL″ against red starboard hand pillar light and bell buoy FlR, BELL marked C2 — 43°26′46.3″N 065°40′19.9″W

(F2004203) LL(321) DFO(6302197-01)

25-FEB-2005 LNM/D. 11-FEB-2005

Replace red starboard hand pillar light and whistle buoy FlR, WHIS, marked N2 with red and white fairway pillar, light buoy Mo (A), marked N — 43°20′12.3″N 065°40′45.9″W

(F2004205) LL(325) DFO(6302200-01)

25-FEB-2005 LNM/D. 11-FEB-2005

Replace red starboard hand conical buoy, marked NA2, with red starboard hand spar buoy, marked NA4 — 43°23′46.5″N 065°39′13.0″W

(F2004102) DFO(6302204-01)

11-FEB-2005 LNM/D. 14-JAN-2005

Replace green port hand pillar light and bell buoy FlG, BELL with green port hand spar light buoy FlG, marked TA3 — 43°40′12.4″N 065°57′36.0″W

(F2004191) LL(293.6) DFO(6302185-01)

11-FEB-2005 LNM/D. 14-JAN-2005

Delete legend ″WHIS″ against red, green and red starboard bifurcation pillar light and whistle buoy Fl(2+1) R, WHIS marked NP — 43°58′47.3″N 066°18′24.0″W

(F2004198) LL(245) DFO(6302192-01)

This notice affects Electronic Navigational Chart: CA376018

11-FEB-2005 LNM/D. 14-JAN-2005

Chart no. 4230

Delete legend ″BELL″ against red and white fairway pillar light and bell buoy Mo (A), BELL, marked NU — 43°59′36.3″N 066°10′18.0″W

(F2004199) LL(246) DFO(6302193-01)

This notice affects Electronic Navigational Chart: CA376018

11-FEB-2005 — LNM/D. 14-JAN-2005

Delete legend ″WHIS″ against red, green and red starboard bifurcation pillar light and whistle buoy Fl(2+1) R, WHIS, marked NM — 43°49′00.3″N 066°29′58.0″W

(F2004200) LL(251) DFO(6302194-01)

This notice affects Electronic Navigational Chart: CA376018

11-FEB-2005 — LNM/D. 14-JAN-2005

Delete legend ″WHIS″ against green port hand pillar light and whistle buoy FlG, WHIS, marked N9 — 43°53′00.3″N 066°26′10.0″W

(F2004201) LL(251.5) DFO(6302196-01)

This notice affects Electronic Navigational Chart: CA376018

11-FEB-2005 — LNM/D. 14-JAN-2005

Delete red and white fairway pillar light and bell buoy Mo(A), BELL, marked E — 43°43′46.3″N 066°07′24.0″W

(F2004208) LL(271) DFO(6302203-01)

This notice affects Electronic Navigational Chart: CA376018

11-FEB-2005 — LNM/D. 14-JAN-2005

Add yellow and black South cardinal pillar light buoy ′Q(6)+LFl 15s′, marked E — 43°43′46.6″N 066°07′06.8″W

(F2004201) LL(271) DFO(6302203-02)

14-JAN-2005 — LNM/D. 07-JAN-2005

Delete light ″Fl″ — 43°28′44.2″N 065°27′12.1″W

(F2004183) LL(339.5) DFO(6302144-01)

Chart no. 4230

14-JAN-2005 LNM/D. 07-JAN-2005

Delete red starboard hand pillar light and bell buoy FlR, BELL marked N4 — 43°18′36.0″N 066°00′02.0″W

(F2004185) LL(290) DFO(6302146-01)

07-JAN-2005 LNM/D. 05-NOV-2004

Amend legend ′Fl 5s 25m 12M′ to read ′Fl 5s 25m 19M′ against light 43°41′23.1″N 066°08′38.3″W

LL(272) DFO(6302112-01)

This notice affects Electronic Navigational Chart: CA376018

05-NOV-2004 LNM/D. 29-OCT-2004

Delete legend ″BELL″ against red and white fairway pillar light buoy Mo (A), marked NV, BELL — 44°04′10.3″N 066°12′35.0″W

(F2004114) LL(242) DFO(6301918-01)

This notice affects Electronic Navigational Chart: CA376018

05-NOV-2004 LNM/D. 29-OCT-2004

Delete legend ″BELL″ against red starboard pillar light buoy Fl R, BELL, marked NT2 — 43°55′50.8″N 066°10′53.0″W

(F2004115) LL(252) DFO(6301919-01)

05-NOV-2004 LNM/D. 29-OCT-2004

Delete fog signal — 43°59′03.3″N 066°09′28.3″W

(F2004130) LL(248) DFO(6301961-01)

This notice affects Electronic Navigational Chart: CA376018

29-OCT-2004 LNM/D. 09-JUL-2004

Replace red starboard pillar light and bell buoy FlR, BELL, marked NQ2 with green port hand pillar light buoy FlG, marked NQ1 — 43°50′35.2″N 066°10′38.5″W

(F2004113) LL(256) DFO(6301917-01)

This notice affects Electronic Navigational Chart: CA376018

Chart no. 4230

09-JUL-2004 LNM/D. 02-JUL-2004

(T)Delete light 43°48′34.0″N 064°47′21.0″W
Light has been temporarily discontinued.
Notice 2004-07-09(T) is cancelled. Light is discontinued. *LL(393) DFO(6301436-01)*
See DFO reference (6302886) appearing in this edition.
Cancelled on 30-JUN-06

02-JUL-2004 LNM/D. 25-JUN-2004

Amend ″Fl 10s 14m 16M″ to read ″Fl 10s 14m 10M″ against light 43°27′23.2″N 065°44′36.2″W

(F2004059) LL(307) DFO(6301606-01)

02-JUL-2004 LNM/D. 25-JUN-2004

Amend ″Fl 6s 16m 16M″ to read ″Fl 6s 16m 9M″ against light 43°37′42.6″N 066°01′34.9″W

LL(283) DFO(6301613-01)

25-JUN-2004 LNM/D. 07-MAY-2004

Amend ″Fl 15s 17m 16M″ to read ″LFl 15s 17m 12M″ against light 43°39′18.3″N 065°05′55.9″W

LL(370) DFO(6301232-01)

25-JUN-2004 LNM/D. 07-MAY-2004

Amend ″Fl (3) 10s 16m 16M″ to read ″Mo (D) 10s 15m 12M″ against light 43°26′59.0″N 065°28′15.0″W

LL(336) DFO(6301236-01)

25-JUN-2004 LNM/D. 07-MAY-2004

Amend ″Fl 10s 30m 13M″ to read ″LFl 12s 30m 9M″ against light 43°48′34.0″N 064°47′21.0″W

LL(393) DFO(6301237-01)

07-MAY-2004 LNM/D. 26-MAR-2004

Amend ″LFl 12s 17m 16M″ to read ″LFl 12s 17m 8M″ against light 43°28′07.7″N 065°22′43.4″W

(F2004022) LL(348) DFO(6301317-01)

07-MAY-2004 LNM/D. 26-MAR-2004

Chart no. 4230

Amend ″WHIS″ to read ″BELL″ against red starboard hand pillar light buoy FlR, marked N4, WHIS — 43°18′36.0″N 066°00′02.0″W

(F2004006) LL(290) DFO(6301321-01)

07-MAY-2004 — LNM/D. 26-MAR-2004

Amend ″WHIS″ to read ″BELL″ against red and white fairway pillar light buoy Mo(A) marked NS, WHIS — 43°31′36.0″N 066°05′00.0″W

(F2004007) LL(274) DFO(6301322-01)

26-MAR-2004 — LNM/D. 07-NOV-2003

Delete light FlR — 43°28′35.0″N 065°43′08.5″W

(F2003118) LL(308) DFO(6301206-01)

07-NOV-2003 — LNM/D. 08-AUG-2003

Delete yellow ODAS/SADO light buoy, Fl (5) Y 43°37′30.0″N 066°33′12.0″W

DFO(6301094-01)

08-AUG-2003 — LNM/D. 23-AUG-2002

Add yellow ODAS/SADO light buoy, Fl (5) Y, marked PRIV 43°37′31.2″N 066°37′16.2″W

DFO(6300964-01)

23-AUG-2002 — LNM/D. 22-MAR-2002

Add submarine cable joining 43°09′05.4″N 064°43′58.0″W
43°07′26.4″N 064°50′32.4″W
43°04′52.0″N 064°58′32.3″W
and 43°04′00.0″N 065°04′33.3″W

DFO(6300452-01)

22-MAR-2002 — LNM/D. 09-MAR-2001

Add yellow ODAS/SADO light buoy, Fl (5) Y 43°37′30.0″N 066°33′12.0″W

DFO(6829835-01)

09-MAR-2001 — LNM/D. 02-FEB-2001

Chart no. 4230

Delete depth of 1 metre 4 decimetres 43°40′30.0″N 065°11′10.0″W

DFO(6829386-01)

09-MAR-2001 LNM/D. 02-FEB-2001
Add depth of 14 metres 43°40′30.0″N 065°11′10.0″W

DFO(6829386-02)

02-FEB-2001 LNM/D. 05-MAY-2000
Delete light 43°39′37.2″N 065°49′12.1″W

(F2000115) LL(296) DFO(6828725-02)

05-MAY-2000 LNM/D. 14-APR-2000
Amend Fl(2)10s 38m 22M to read ″Fl 12s 35m 13M″ 43°47′38.8″N 066°09′19.2″W

(F1998/066) LL(260.000) DFO(6828380-01)

14-APR-2000 LNM/D. 24-DEC-1999
Delete light and Fog Sig 43°35′53.4″N 065°46′55.5″W

(F1999057) LL(299.000) DFO(6300003-11)

14-APR-2000 LNM/D. 24-DEC-1999
Reposition red and white light and whistle buoy ″P″ from 43°31′14.3″N 065°51′58.0″W
to 43°34′51.0″N 065°48′12.0″W

(F1999052) LL(302.000) DFO(6300003-12)

14-APR-2000 LNM/D. 24-DEC-1999
Delete green light and bell buoy P1 43°34′55.3″N 065°48′10.9″W

(F1999047) LL(298.000) DFO(6300003-14)