Chart no. 4240

4240 - Liverpool Harbour to / à Lockeport Harbour - New Chart - 06-OCT-1989 - NAD 1983

16-JUL-2021 LNM/D. 09-APR-2021

Add depth of 2.6 metres 44°03′24.5″N 064°37′47.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6309504-01)*

16-JUL-2021 LNM/D. 09-APR-2021

Add depth of 1.9 metres 44°02′42.9″N 064°38′48.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6309504-02)*

16-JUL-2021 LNM/D. 09-APR-2021

Add depth of 8.7 metres 44°02′17.9″N 064°40′38.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6309504-03)*

16-JUL-2021 LNM/D. 09-APR-2021

Add depth of 3 metres 43°56′52.9″N 064°46′17.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6309504-04)*

16-JUL-2021 LNM/D. 09-APR-2021

Add depth of 2.5 metres 43°53′18.0″N 064°44′29.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6309504-06)*

16-JUL-2021 LNM/D. 09-APR-2021

Replace depth of 3.4 metres with depth of 0.6 metres 43°49′37.7″N 064°52′21.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6309504-07)*

16-JUL-2021 LNM/D. 09-APR-2021

Replace depth of 4 metres with a drying height of 0.1 metres 43°40′22.3″N 065°02′02.0″W
(See Chart No. 1, I10, I15)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6309504-08)*

16-JUL-2021 LNM/D. 09-APR-2021

Chart no. 4240

Add depth of 5.8 metres 43°41′06.0″N 065°05′23.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6309504-09)*

16-JUL-2021 LNM/D. 09-APR-2021

Add depth of 5.2 metres 43°39′34.3″N 065°05′40.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6309504-10)*

16-JUL-2021 LNM/D. 09-APR-2021

Replace depth of 2.4 metres with depth of 2 metres 43°43′26.5″N 065°09′09.5″W
(See Chart No. 1, I10)
DFO(6309504-11)

16-JUL-2021 LNM/D. 09-APR-2021

Replace depth of 3.7 metres with depth of 2.9 metres 43°43′08.0″N 065°09′28.9″W
(See Chart No. 1, I10)
DFO(6309504-12)

16-JUL-2021 LNM/D. 09-APR-2021

Replace depth of 0.9 metres with depth of 0.5 metres 43°43′21.3″N 065°09′31.8″W
(See Chart No. 1, I10)
DFO(6309504-13)

16-JUL-2021 LNM/D. 09-APR-2021

Add note: WARNING Recent bathymetric surveys show the presence of shallower depths compared to what is presently charted. The shallower depths considered the most hazardous to navigation and within or near main shipping channels will be published in Notices to Mariners (WWW.NOTMAR.CA). Mariners are advised to exercise extreme caution, specifically when they navigate outside of the marked navigation channels. AVERTISSEMENT Des levés bathymétriques récents ont révélé la présence de profondeurs moindres que celles portées sur les cartes marines. Les profondeurs moindres les plus dangereuses pour la navigation et dans ou près des principales voies de navigation seront publiées dans les Avis aux navigateurs (WWW.NOTMAR.CA). Nous demandons aux navigateurs d'exercer la plus grande prudence, particulièrement lors de la navigation en dehors des voies de navigation balisées. 43°59′27.2″N 065°00′19.1″W
DFO(6309504-14)
This notice affects Electronic Navigational Chart: CA376045

Chart no. 4240

16-JUL-2021 LNM/D. 09-APR-2021

Delete depth of 10.4 metres 43°41′09.2″N 065°05′22.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 *DFO(6309504-15)*

09-APR-2021 LNM/D. 26-MAR-2021

Delete depth of 18.9 metres (See Chart No. 1, I10) 43°42′42.8″N 064°58′18.5″W
This notice affects Electronic Navigational Chart: CA376045
DFO(6309280-01)

09-APR-2021 LNM/D. 26-MAR-2021

Add depth of 11.9 metres (See Chart No. 1, I10) 43°42′39.0″N 064°58′19.0″W
This notice affects Electronic Navigational Chart: CA376045
DFO(6309280-02)

26-MAR-2021 LNM/D. 10-AUG-2018

Amend QG to read Iso G against light 44°01′10.1″N 064°39′44.7″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA376045, CA476202 *(F2021004) LL(408.2) DFO(6309357-01)*

10-AUG-2018 LNM/D. 27-JUL-2018

Replace depth of 26 metres with depth of 15.7 metres 43°37′37.3″N 065°07′44.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376047 *DFO(6308394-01)*

27-JUL-2018 LNM/D. 11-AUG-2017

Reposition light Fl 4s 18m 7M from 44°02′01.1″N 064°37′41.8″W
(See Chart No. 1, P1) to 44°02′03.5″N 064°37′42.5″W
This notice affects Electronic Navigational Chart: CA276800, CA376045, CA476202 *(F2018021) LL(407) DFO(6308352-01)*

27-JUL-2018 LNM/D. 11-AUG-2017

Amend Fl 4s 18m 7M to read Fl 4s15m7M against light 44°02′03.5″N 064°37′42.5″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276800, CA376045, CA476202 *(F2018021) LL(407) DFO(6308352-02)*

11-AUG-2017 LNM/D. 09-JUN-2017

Chart no. 4240

Add depth of 1 metre, 6 decimetres — 43°48′16.5″N 064°55′30.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 — *DFO(6308022-01)*

11-AUG-2017 — LNM/D. 09-JUN-2017

Add depth of 0 metres, 5 decimetres — 43°49′19.7″N 064°53′03.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045 — *DFO(6308022-02)*

09-JUN-2017 — LNM/D. 24-JAN-2014

Add marine farm — 43°54′54.2″N 064°48′43.6″W
(See Chart No. 1,K48.2)
This notice affects Electronic Navigational Chart: CA376045 — *DFO(6307872-09)*

24-JAN-2014 — LNM/D. 17-JAN-2014

Delete red starboard hand lighted pillar buoy FlR, marked KC52 — 43°42′07.3″N 064°59′59.8″W
(See Chart No. 1, Qf) — *(F2013037) LL(386) DFO(6306576-01)*
This notice affects Electronic Navigational Chart: CA376044, CA376045

24-JAN-2014 — LNM/D. 17-JAN-2014

Add black, yellow and black East cardinal lighted pillar buoy Q(3)10s, marked KC — 43°42′29.4″N 064°59′42.0″W
(See Chart No. 1, Q130.3) — *(F2013037) LL(386.0) DFO(6306576-02)*
This notice affects Electronic Navigational Chart: CA376044, CA376045

17-JAN-2014 — LNM/D. 21-SEP-2012

Amend Fl to read FlR against light — 43°42′57.5″N 065°01′48.1″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376045, CA576040 — *(F2013039) LL(384) DFO(6306609-01)*

21-SEP-2012 — LNM/D. 17-AUG-2012

Chart no. 4240

Add marine farm 44°02′33.0″N 064°38′24.0″W
(See Chart No. 1, K48.2)

DFO(6306164-03)

This notice affects Electronic Navigational Chart: CA376045, CA476202

17-AUG-2012 LNM/D. 26-FEB-2010

Amend 3,4m (2008) to read 3,0m (2010) 44°02′37.6″N 064°41′55.8″W
(See Chart No. 1, I22)

DFO(6306041-09)

This notice affects Electronic Navigational Chart: CA376045

27-NOV-2009 LNM/D. 01-MAY-2009

Delete BELL against green port hand lighted pillar bell buoy 44°02′46.3″N 064°42′03.9″W
QG, BELL marked UM53
(See Chart No 1 Qg) *(F2006159) LL(410) DFO(6304650-01)*

01-MAY-2009 LNM/D. 24-APR-2009

Add breakwater joining 43°55′16.0″N 064°50′33.0″W
(See Chart 1 F4.1) 43°55′16.3″N 064°50′32.0″W
and 43°55′14.6″N 064°50′30.2″W

This notice affects Electronic Navigational Chart: CA376045 *DFO(6303359-02)*

01-MAY-2009 LNM/D. 24-APR-2009

Add light FlG 43°55′16.0″N 064°50′33.0″W
(See Chart No 1 P1)

(F2007043) LL(401.5) DFO(6303359-03)

This notice affects Electronic Navigational Chart: CA376045

24-APR-2009 LNM/D. 10-OCT-2008

Chart no. 4240

Delete fog signal Fog Sig 20s 44°01′08.0″N 064°39′52.0″W
(See Chart No 1 R20)

(F2009002) LL(408.3) DFO(6304317-01)

This notice affects Electronic Navigational Chart:
CA376045

10-OCT-2008 LNM/D. 16-MAY-2008

Amend legend 4.0m (2004) to read 3.4m (2008) 44°02′39.0″N 064°41′56.0″W
(See Chart No. 1, I22)

DFO(6304053-13)

16-MAY-2008 LNM/D. 21-DEC-2007

Amend FR to read Iso R against light 43°57′05.3″N 064°46′07.4″W
(See Chart No 1 P16)

(F2008013) LL(403) DFO(6303854-01)

This notice affects Electronic Navigational Chart:
CA376045

16-MAY-2008 LNM/D. 21-DEC-2007

Delete red and white fairway lighted pillar buoy Mo(A), 44°01′34.0″N 064°38′50.0″W
marked UMA
(See Chart No 1 Qh) *(F2002066) LL(408) DFO(6303856-01)*

This notice affects Electronic Navigational Chart:
CA376045

21-DEC-2007 LNM/D. 23-MAR-2007

Replace green port hand spar buoy, marked KA51 with 43°43′12.0″N 064°58′00.0″W
green port hand lighted pillar buoy FlG, marked
KA51 *(F2007087) LL(386.01) DFO(6303678-01)*

23-MAR-2007 LNM/D. 09-FEB-2007

Add light ′FlR′ against red starboard hand spar buoy, 43°41′16.3″N 065°05′47.9″W
marked KK64

(F2007007) LL(371.02) DFO(6303330-01)

Chart no. 4240

23-MAR-2007 LNM/D. 09-FEB-2007

Replace red starboard hand conical buoy, marked KD60 with yellow and black South cardinal spar buoy, marked KD 43°40′01.3″N 065°04′03.9″W

(F2007009) LL(5383.03) DFO(6303332-01)

23-MAR-2007 LNM/D. 09-FEB-2007

Add light ′QG′ against green port hand spar buoy, marked KK57 43°40′00.3″N 065°06′13.9″W

(F2007011) LL(369.04) DFO(6303333-01)

23-MAR-2007 LNM/D. 09-FEB-2007

Add light ′FlG′ against green port hand spar buoy, marked UX53 43°48′30.0″N 064°55′24.0″W

(F2007016) LL(387.01) DFO(6303335-01)

23-MAR-2007 LNM/D. 09-FEB-2007

Add red starboard hand lighted conical buoy FlR, marked UX56 43°48′49.0″N 064°55′42.0″W

(F2007005) LL(387.04) DFO(6303337-01)

23-MAR-2007 LNM/D. 09-FEB-2007

Replace red starboard hand lighted pillar bell buoy FlR, BELL, marked KE56 with red and white fairway lighted pillar buoy Mo(A), marked KE 43°39′31.3″N 065°04′18.9″W

(F2007024) LL(383.1) DFO(6303346-01)

09-FEB-2007 LNM/D. 15-DEC-2006

Delete legend ″BELL″ against red starboard hand lighted pillar bell buoy FlR, marked UQ52 43°55′36.5″N 064°43′02.0″W

(F2006175) LL(404) DFO(6303265-01)

15-DEC-2006 LNM/D. 01-DEC-2006

Delete legend ″BELL″ against green port hand lighted pillar bell buoy FlG, BELL marked KK51 43°37′32.0″N 065°08′11.5″W

(F2006147) LL(369) DFO(6303184-01)

15-DEC-2006 LNM/D. 01-DEC-2006

Chart no. 4240

Delete legend ″BELL″ against red starboard hand lighted pillar bell buoy FlR, marked UV52 — 43°47′15.0″N 064°49′53.0″W

(F2006162) LL(391) DFO(6303209-01)

15-DEC-2006 — LNM/D. 01-DEC-2006

Delete green port hand lighted pillar whistle buoy FlG, WHIS marked KC51 — 43°42′27.0″N 064°59′34.0″W

(F2006164) LL(385) DFO(6303210-01)

15-DEC-2006 — LNM/D. 01-DEC-2006

Add red starboard hand lighted pillar buoy FlR, marked KC52 — 43°42′07.5″N 065°00′00.0″W

(F2006165) LL(386) DFO(6303211-01)

01-DEC-2006 — LNM/D. 30-JUN-2006

Amend ″KE″ to read ″KEA″ against yellow, black and yellow West cardinal lighted pillar buoy Q(9) 15s — 43°40′14.3″N 065°04′57.9″W

(F2006145) LL(383.5) DFO(6303182-01)

30-JUN-2006 — LNM/D. 19-MAY-2006

Delete light ″LFl 12s 30m 9M″ — 43°48′34.0″N 064°47′21.0″W

(F2006083) LL(393) DFO(6302886-01)

This notice affects Electronic Navigational Chart: CA276800

19-MAY-2006 — LNM/D. 10-MAR-2006

Amend ″FR″ to read ″FlR″ against light — 43°48′45.7″N 064°55′30.0″W

(F2005109) LL(388) DFO(6302680-01)

10-MAR-2006 — LNM/D. 24-FEB-2006

Delete legend ″BELL″ against green port hand pillar light buoy FlG, BELL marked UN55 — 43°56′09.0″N 064°47′28.5″W

(F2006002) LL(402) DFO(6302734-01)

10-MAR-2006 — LNM/D. 24-FEB-2006

Chart no. 4240

Delete red starboard hand lighted pillar whistle buoy FlR, marked U36 — 43°47′21.5″N 064°46′50.0″W

(F2006006) LL(392) DFO(6302737-01)

10-MAR-2006 — LNM/D. 24-FEB-2006

Add green port hand lighted pillar buoy FlG, marked US51 — 43°51′45.0″N 064°46′16.8″W

(F2006010) LL(394.5) DFO(6302741-01)

10-MAR-2006 — LNM/D. 24-FEB-2006

Delete legend ″WHIS″ against red and white fairway pillar light buoy Mo(A), WHIS marked UN — 43°53′31.0″N 064°42′30.0″W

(F2006012) LL(395) DFO(6302744-01)

This notice affects Electronic Navigational Chart: CA276800

10-MAR-2006 — LNM/D. 24-FEB-2006

Add black, yellow and black East cardinal lighted pillar buoy Q(3) 10s, marked UEF — 43°48′12.6″N 064°46′27.2″W

(F2006014) LL(394.01) DFO(6302747-01)

24-FEB-2006 — LNM/D. 04-NOV-2005

Delete red starboard hand conical buoy, marked KE52 — 43°39′05.3″N 065°02′02.9″W

(F2006009) DFO(6302740-01)

This notice affects Electronic Navigational Chart: CA276800, CA576040

24-FEB-2006 — LNM/D. 04-NOV-2005

Add red starboard hand lighted pillar buoy FlR, marked KE52 — 43°38′27.0″N 065°02′15.0″W

(F2006009) LL(382.01) DFO(6302740-02)

This notice affects Electronic Navigational Chart: CA276800, CA576040

04-NOV-2005 — LNM/D. 14-OCT-2005

Chart no. 4240

Amend ″Fl″ to read ″LFl″ against light 44°02′40.6″N 064°41′30.2″W

(F2005076) LL(409) DFO(6302546-01)

14-OCT-2005 LNM/D. 23-SEP-2005

Amend ″F″ to read ″Fl″ against light 43°42′57.5″N 065°01′48.1″W

(F2005067) LL(384) DFO(6302481-01)

This notice affects Electronic Navigational Chart: CA576040

23-SEP-2005 LNM/D. 08-JUL-2005

Delete red starboard hand pillar light and whistle buoy FlR, WHIS, marked K38 43°36′54.0″N 065°01′53.9″W

(F2005051) LL(382) DFO(6302472-01)

This notice affects Electronic Navigational Chart: CA276800

08-JUL-2005 LNM/D. 24-JUN-2005

Delete legend ″WHIS″ against red and white fairway pillar light buoy Mo(A), WHIS marked UX 43°46′19.0″N 064°54′47.0″W

(F2005036) LL(387) DFO(6302363-01)

24-JUN-2005 LNM/D. 24-DEC-2004

Amend ″FlY″ to read ″QG″ against light 44°01′10.3″N 064°39′45.6″W

(F2004025) LL(408.2) DFO(6301349-01)

24-DEC-2004 LNM/D. 17-DEC-2004

Amend legend ″4.6m (1998)″ to read ″4.0m (2004)″ 44°02′39.0″N 064°41′56.0″W

DFO(6301890-04)

17-DEC-2004 LNM/D. 08-OCT-2004

Add depth of 4 metres 9 decimetres 43°54′31.0″N 064°48′47.0″W

DFO(6302105-01)

Chart no. 4240

17-DEC-2004 LNM/D. 08-OCT-2004

Replace rock which covers and uncovers, with dangerous underwater rock of 2 metres or less. 43°54′29.0″N 064°48′48.0″W

DFO(6302105-02)

08-OCT-2004 LNM/D. 03-SEP-2004

Replace green port hand pillar light buoy FlG, marked KK61, BELL with green port hand spar light buoy FlG, marked KK61 43°41′01.8″N 065°05′45.9″W

(F2004121) LL(371) DFO(6301910-01)

03-SEP-2004 LNM/D. 09-JUL-2004

Delete green port hand pillar light buoy QG, marked KK69, BELL 43°42′08.3″N 065°05′58.9″W

(F2004083) LL(372) DFO(6301723-01)

03-SEP-2004 LNM/D. 09-JUL-2004

Add green port hand spar light buoy QG, marked KK69 43°42′08.3″N 065°05′58.9″W

(F2004083) LL(372) DFO(6301723-02)

09-JUL-2004 LNM/D. 25-JUN-2004

(T)Delete light 43°48′34.0″N 064°47′21.0″W

Light has been temporarily discontinued.
Notice 2004-07-09(T) is cancelled. Light is discontinued. *LL(393) DFO(6301436-01)*
See DFO reference (6302886) appearing in this edition.
Cancelled on 30-JUN-06

25-JUN-2004 LNM/D. 30-APR-2004

Amend ″Fl 15s 17m 16M″ to read ″LFl 15s 17m 12M″ against light 43°39′18.3″N 065°05′55.9″W

LL(370) DFO(6301232-01)

25-JUN-2004 LNM/D. 30-APR-2004

Amend ″Fl 10s 30m 13M″ to read ″LFl 12s 30m 9M″ against light 43°48′34.0″N 064°47′21.0″W

LL(393) DFO(6301237-01)

Chart no. 4240

30-APR-2004 LNM/D. 21-NOV-2003
Amend FG to read FlG against light 43°42′05.6″N 065°06′25.8″W

(F2004010) LL(375) DFO(6301323-01)

21-NOV-2003 LNM/D. 07-FEB-2003
Add non-dangerous wreck, depth unknown 43°38′06.0″N 065°09′06.0″W

DFO(6301062-01)

07-FEB-2003 LNM/D. 04-OCT-2002
Delete red starboard hand pillar light buoy FlR, marked UM48 44°01′30.3″N 064°37′32.8″W

(F2002022) LL(408.4) DFO(6300295-01)

07-FEB-2003 LNM/D. 04-OCT-2002
Add light Fl 4s 18m 7M 44°02′01.1″N 064°37′41.8″W

(F2002024) LL(407) DFO(6300300-01)

04-OCT-2002 LNM/D. 20-JUL-2001
Amend FlG to read FlY against light 44°01′10.3″N 064°39′45.6″W

(F2002020) LL(408.2) DFO(6300220-01)

20-JUL-2001 LNM/D. 02-FEB-2001
Add red and white fairway pillar light buoy Mo (A), BELL, marked KP 43°40′14.6″N 065°09′33.0″W

(F2000211) LL(368) DFO(6829294-01)

20-JUL-2001 LNM/D. 02-FEB-2001
Delete green light, port hand pillar buoy FlG, marked KP51 43°41′59.5″N 065°09′35.0″W

(F2000212) LL(367.5) DFO(6829345-01)

02-FEB-2001 LNM/D. 27-OCT-2000

Chart no. 4240

Add red light, starboard hand pillar buoy FlR, marked UM48 — 44°01′30.3″N 064°37′32.8″W

(F2000-032) LL(408.4) DFO(6828043-02)

02-FEB-2001 — LNM/D. 27-OCT-2000

Delete light — 44°02′00.9″N 064°37′41.9″W

(F2000-133) LL(407) DFO(6828749-02)

27-OCT-2000 — LNM/D. 01-SEP-2000

Add wreck WK with known depth of 4 metres, 5 decimetres 43°54′05.4″N 064°47′18.0″W

DFO(6829152-01)

01-SEP-2000 — LNM/D. 07-JUL-2000

Add non-dangerous wreck, PA 44°01′06.4″N 064°38′09.8″W

DFO(6828860-01)

07-JUL-2000 — LNM/D. 12-MAY-2000

Amend FG to read, Fl G — 44°01′10.3″N 064°39′45.6″W

(F2000-075) LL(408.2) DFO(6828421-01)

12-MAY-2000 — LNM/D. 14-JAN-2000

Affix patch — 44°02′30.0″N 064°42′00.0″W

DFO(6500282-01)

PDF

4240 - Port Mouton - New Chart - 06-OCT-1989 - NAD 1983

16-JUL-2021 — LNM/D. 09-APR-2021

Add depth of 3.5 metres — 43°55′24.7″N 064°50′06.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376045, CA576046 — *DFO(6309504-05)*

Chart no. 4240

26-FEB-2010 LNM/D. 27-NOV-2009

Amend FR to read LFlR against light 43°55′10.0″N 064°50′49.8″W
(See Chart 1 P16)

(F2009074) LL(399.5) DFO(6304699-01)

This notice affects Electronic Navigational Chart:
CA576046

01-MAY-2009 LNM/D. 24-APR-2009

Delete coastline between 43°55′15.2″N 064°50′30.4″W
(See Chart 1 C1) and 43°55′13.0″N 064°50′31.4″W

DFO(6303359-01)

01-MAY-2009 LNM/D. 24-APR-2009

Add breakwater with loose boulders joining 43°55′15.2″N 064°50′30.4″W
(See Chart 1 F4.2) 43°55′15.2″N 064°50′30.7″W
43°55′16.6″N 064°50′31.8″W
43°55′16.1″N 064°50′33.1″W
43°55′15.9″N 064°50′33.0″W
43°55′16.3″N 064°50′32.0″W
43°55′14.9″N 064°50′30.9″W
43°55′13.6″N 064°50′31.6″W
and 43°55′13.0″N 064°50′31.4″W

This notice affects Electronic Navigational Chart:
CA376045

DFO(6303359-02)

01-MAY-2009 LNM/D. 24-APR-2009

Add light FlG 43°55′16.0″N 064°50′33.0″W
(See Chart No 1 P1)

(F2007043) LL(401.5) DFO(6303359-03)

This notice affects Electronic Navigational Chart:
CA376045

01-MAY-2009 LNM/D. 24-APR-2009

Delete lifeboat station 43°55′13.0″N 064°50′32.0″W
(See Chart No 1 T12)

DFO(6304324-01)