Chart no. 4403

4403 - East Point to / à Cape Bear - New Edition - 04-APR-2003 - NAD 1983

26-AUG-2022 LNM/D. 12-NOV-2021

Reposition black, yellow and black East Cardinal spar buoy, marked NJA — from 46°11′08.1″N 062°23′17.0″W to 46°11′09.2″N 062°23′08.2″W
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: CA376248, CA476490 — *(G2022062) DFO(6310202-01)*

12-NOV-2021 LNM/D. 11-JUN-2021

Reposition black, yellow and black East Cardinal spar buoy, marked NJA — from 46°11′09.2″N 062°23′09.3″W to 46°11′08.1″N 062°23′17.0″W
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: CA376248, CA476490 — *(G2021077) DFO(6309592-01)*

11-JUN-2021 LNM/D. 06-NOV-2020

Add depth of 6 fathoms, 4 feet — 46°09′44.2″N 062°30′15.9″W
(See Chart No. 1, I10)
DFO(6309432-09)

11-JUN-2021 LNM/D. 06-NOV-2020

Delete depth of 4 fathoms, 3 feet — 46°09′40.3″N 062°29′44.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6309432-12)*

11-JUN-2021 LNM/D. 06-NOV-2020

Add depth of 3 fathoms, 5 feet — 46°09′42.0″N 062°29′40.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6309432-13)*

06-NOV-2020 LNM/D. 13-SEP-2019

Delete sector light FRWG and limits of arcs of visibility — 46°19′42.8″N 062°20′59.8″W
(See Chart No. 1, P40.1)
This notice affects Electronic Navigational Chart: CA276286, CA376248 — *(G2020227) LL(948.3) DFO(6309268-01)*

13-SEP-2019 LNM/D. 06-SEP-2019

Chart no. 4403

Delete depth of 1 fathom, 4 feet — 46°10′41.0″N 062°29′09.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6308745-01)*

13-SEP-2019 — LNM/D. 06-SEP-2019

Delete depth of 1 fathom, 3 feet — 46°12′09.8″N 062°28′46.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6308745-02)*

13-SEP-2019 — LNM/D. 06-SEP-2019

Add depth of 0 fathoms, 3 feet — 46°12′14.4″N 062°28′44.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248, CA476490 — *DFO(6308745-03)*

13-SEP-2019 — LNM/D. 06-SEP-2019

Add depth of 4 fathoms, 1 foot — 46°10′43.8″N 062°22′36.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276286, CA376248, CA476490 — *DFO(6308745-05)*

13-SEP-2019 — LNM/D. 06-SEP-2019

Add depth of 2 fathoms, 2 feet — 46°14′53.4″N 062°22′35.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248, CA476490 — *DFO(6308745-06)*

13-SEP-2019 — LNM/D. 06-SEP-2019

Delete depth of 1 fathom, 2 feet — 46°10′45.0″N 062°29′01.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6308745-07)*

13-SEP-2019 — LNM/D. 06-SEP-2019

Add depth of 1 fathom — 46°10′45.0″N 062°29′10.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248, CA476490 — *DFO(6308745-08)*

13-SEP-2019 — LNM/D. 06-SEP-2019

Chart no. 4403

Add depth of 2 fathoms, 4 feet — 46°01′33.6″N 062°33′54.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248, CA476490 — *DFO(6308746-03)*

13-SEP-2019 — LNM/D. 06-SEP-2019

Affix patch — 46°10′00.0″N 062°30′00.0″W
PDF
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6308791-01)*

06-SEP-2019 — LNM/D. 02-AUG-2019

Delete depth of 4 fathoms, 4 feet — 46°15′49.1″N 062°21′38.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6308743-02)*

06-SEP-2019 — LNM/D. 02-AUG-2019

Add depth of 3 fathoms, 2 feet — 46°15′47.4″N 062°21′49.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248, CA476490 — *DFO(6308743-03)*

06-SEP-2019 — LNM/D. 02-AUG-2019

Add depth of 5 fathoms, 1 foot — 46°15′46.8″N 062°21′27.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6308743-04)*

06-SEP-2019 — LNM/D. 02-AUG-2019

Replace depth of 6 fathoms with depth of 4 fathoms, 4 feet — 46°18′09.0″N 062°19′25.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6308743-06)*

06-SEP-2019 — LNM/D. 02-AUG-2019

Add depth of 0 fathoms, 5 feet — 46°19′55.2″N 062°16′45.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6308743-08)*

06-SEP-2019 — LNM/D. 02-AUG-2019

Chart no. 4403

Add depth of 1 fathom, 5 feet 46°20′36.6″N 062°14′00.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 *DFO(6308743-09)*

06-SEP-2019 LNM/D. 02-AUG-2019

Delete depth of 2 fathoms, 3 feet 46°20′36.4″N 062°13′40.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 *DFO(6308743-10)*

06-SEP-2019 LNM/D. 02-AUG-2019

Add depth of 0 fathoms, 5 feet 46°20′36.6″N 062°13′39.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 *DFO(6308743-11)*

02-AUG-2019 LNM/D. 10-MAY-2019

Amend note Chart / Carte 4421 to read Chart / Carte 4935 46°14′04.1″N 062°22′17.3″W
(See Chart No. 1, A18)
DFO(6308675-06)

02-AUG-2019 LNM/D. 10-MAY-2019

Amend note Chart / Carte 4422 to read Chart / Carte 4935 46°09′16.3″N 062°25′38.8″W
(See Chart No. 1, A18)
DFO(6308675-07)

02-AUG-2019 LNM/D. 10-MAY-2019

Amend note Chart / Carte 4420 to read Chart / Carte 4935 46°02′53.1″N 062°26′04.1″W
(See Chart No. 1, A18)
DFO(6308675-08)

10-MAY-2019 LNM/D. 30-JUN-2017

Amend Fl 4s 82ft 17M to read Fl 4s82ft19M 46°08′38.6″N 062°28′01.0″W
(See Chart No. 1, P16)
LL(953) DFO(6308636-01)

10-MAY-2019 LNM/D. 30-JUN-2017

Replace red and white fairway lighted pillar buoy Mo(A), marked NM with red and white fairway lighted spar buoy Mo(A), marked NM 46°02′07.2″N 062°27′09.5″W *LL(961) DFO(6308636-02)*
(See Chart No. 1, Qh)

Chart no. 4403

10-MAY-2019 LNM/D. 30-JUN-2017

Replace red and white fairway lighted pillar buoy Mo(A), marked NP with red and white fairway lighted spar buoy Mo(A), marked NP — 46°05′45.3″N 062°25′58.8″W
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart: CA376248 — *LL(958.5) DFO(6308636-03)*

30-JUN-2017 LNM/D. 12-AUG-2016

Delete front range/leading light F — 46°09′50.8″N 062°31′45.3″W
(See Chart No. 1, P20.2)
This notice affects Electronic Navigational Chart: CA376248 — *(G2017052) LL(955) DFO(6307970-01)*

30-JUN-2017 LNM/D. 12-AUG-2016

Delete rear range/leading light F with leading line and bearings 100° - 280° — 46°09′53.6″N 062°32′09.0″W
(See Chart No. 1, P20.2, Pe) — *(G2017053) LL(956) DFO(6307970-02)*
This notice affects Electronic Navigational Chart: CA376248

12-AUG-2016 LNM/D. 10-JUL-2015

Add red starboard hand lighted spar buoy FlR, marked NH4 — 46°09′41.6″N 062°29′53.9″W
(See Chart No. 1, Qf) — *(G2016113) LL(953.4) DFO(6307648-01)*
This notice affects Electronic Navigational Chart: CA376248

10-JUL-2015 LNM/D. 08-MAY-2015

Reposition green port hand lighted spar buoy Fl G, marked NH3 — from 46°09′30.2″N 062°29′41.7″W to 46°09′31.1″N 062°29′34.5″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA376248 — *(G2015041) LL(953.5) DFO(6307152-01)*

08-MAY-2015 LNM/D. 13-FEB-2015

Replace depth of 4 fathoms, 4 feet with depth of 4 fathoms — 46°09′54.1″N 062°27′20.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6307104-01)*

Chart no. 4403

08-MAY-2015 LNM/D. 13-FEB-2015

Add depth of 4 fathoms, 1 foot 46°09′44.4″N 062°28′35.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 *DFO(6307104-02)*

08-MAY-2015 LNM/D. 13-FEB-2015

Delete depth of 6 fathoms 46°08′24.7″N 062°26′32.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 *DFO(6307104-03)*

08-MAY-2015 LNM/D. 13-FEB-2015

Add depth of 4 fathoms, 5 feet 46°08′25.0″N 062°26′27.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 *DFO(6307104-05)*

08-MAY-2015 LNM/D. 13-FEB-2015

Add depth of 6 fathoms, 2 feet 46°07′57.4″N 062°26′36.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 *DFO(6307104-06)*

08-MAY-2015 LNM/D. 13-FEB-2015

Replace depth of 6 fathoms, 2 feet with depth of 5 fathoms, 4 feet 46°08′07.3″N 062°24′33.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 *DFO(6307104-09)*

08-MAY-2015 LNM/D. 13-FEB-2015

Add depth of 5 fathoms, 5 feet 46°06′11.6″N 062°24′57.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 *DFO(6307104-11)*

08-MAY-2015 LNM/D. 13-FEB-2015

Delete depth of 7 fathoms 46°06′08.6″N 062°24′49.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 *DFO(6307104-13)*

08-MAY-2015 LNM/D. 13-FEB-2015

Chart no. 4403

Add depth of 6 fathoms, 3 feet — 46°06′46.1″N 062°24′23.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6307104-15)*

08-MAY-2015 — LNM/D. 13-FEB-2015

Add depth of 5 fathoms, 3 feet — 46°01′16.4″N 062°16′31.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6307104-18)*

08-MAY-2015 — LNM/D. 13-FEB-2015

Delete depth of 6 fathoms — 46°01′20.0″N 062°16′35.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6307104-19)*

08-MAY-2015 — LNM/D. 13-FEB-2015

Delete depth of 6 fathoms, 1 foot — 46°01′11.4″N 062°16′32.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376248 — *DFO(6307104-20)*

13-FEB-2015 — LNM/D. 12-SEP-2014

Delete front range/leading light Iso — 46°15′32.9″N 062°25′17.2″W
(See Chart No. 1, P20.2)
This notice affects Electronic Navigational Chart: CA376248 — *(G2014203) LL(949) DFO(6307011-01)*

13-FEB-2015 — LNM/D. 12-SEP-2014

Delete rear range/leading light Iso with leading line and bearings 124° - 304° — 46°15′58.2″N 062°26′13.2″W
(See Chart No. 1, P20.2, Pe) — *(G2014204) LL(950) DFO(6307011-02)*
This notice affects Electronic Navigational Chart: CA376248

13-FEB-2015 — LNM/D. 12-SEP-2014

Add sector light FRWG — 46°15′32.9″N 062°25′19.7″W
Visible through an arc of 3°, red from 301½° to 302½°, white from 302½° to 303½° and green from 303½° to 304½° — *(G2014208) LL(949.5) DFO(6307011-03)*
(See Chart No. 1, P40.1)
This notice affects Electronic Navigational Chart: CA376248

Chart no. 4403

12-SEP-2014 LNM/D. 26-JUL-2013

Delete pier between 46°20′59.7″N 062°15′01.7″W
(See Chart No. 1, F14) and 46°21′00.9″N 062°15′03.7″W
This notice affects Electronic Navigational Chart:
CA376248 *DFO(6306818-02)*

26-JUL-2013 LNM/D. 22-JUN-2012

Replace red starboard hand lighted spar buoy QR, marked NN2 with black, yellow and black East cardinal lighted spar buoy Q(3) 10s, marked NN 46°00′44.2″N 062°26′17.1″W *(G2013084) LL(970.4) DFO(6306435-01)*

This notice affects Electronic Navigational Chart:
CA376248

22-JUN-2012 LNM/D. 09-DEC-2011

Delete depth of 3 fathoms, 4 feet 46°01′22.0″N 062°28′33.8″W
(See Chart No. 1, I10)
DFO(6306009-02)

22-JUN-2012 LNM/D. 09-DEC-2011

Delete depth of 1 fathom 46°01′22.4″N 062°28′45.2″W
(See Chart No. 1, I10)
DFO(6306009-09)

22-JUN-2012 LNM/D. 09-DEC-2011

Delete depth of 3 fathoms, 3 feet 46°01′10.4″N 062°29′05.0″W
(See Chart No. 1, I10)
DFO(6306009-10)

22-JUN-2012 LNM/D. 09-DEC-2011

Delete depth of 0 fathoms, 4 feet 46°01′03.7″N 062°30′07.5″W
(See Chart No. 1, I10)
DFO(6306009-11)

22-JUN-2012 LNM/D. 09-DEC-2011

Add depth of 0 fathoms, 3 feet 46°01′05.0″N 062°30′06.5″W
(See Chart No. 1, I10)
DFO(6306009-12)

Chart no. 4403

22-JUN-2012 LNM/D. 09-DEC-2011

Add depth of 2 fathoms, 1 foot 46°01′09.6″N 062°29′09.9″W
(See Chart No. 1, I10)

DFO(6306009-16)

22-JUN-2012 LNM/D. 09-DEC-2011

Add depth of 0 fathoms, 1 foot 46°01′20.8″N 062°28′40.3″W
(See Chart No. 1, I10)

DFO(6306009-18)

09-DEC-2011 LNM/D. 08-JUL-2011

Amend LFl Y 6s 74ft 10M to read LFl Y 6s 55ft 10M against light 46°00′11.1″N 062°27′34.0″W
(See Chart No. 1, P16) *(G2011309) LL(971) DFO(6305838-03)*

This notice affects Electronic Navigational Chart:
CA276286, CA376248

08-JUL-2011 LNM/D. 23-JUL-2010

Amend LFl Y 6s 74ft 13M to read LFl Y 6s 74ft 10M against light 46°00′10.7″N 062°27′36.4″W
(See Chart 1 P16) *(G2011165) LL(971) DFO(6305550-01)*

This notice affects Electronic Navigational Chart:
CA376248

23-JUL-2010 LNM/D. 13-MAR-2009

Amend Fl Y 6s 74ft to read LFl Y 6s 74ft 13M against light 46°00′10.7″N 062°27′36.4″W
(See Chart 1 P16)

LL(971) DFO(6304957-01)

This notice affects Electronic Navigational Chart: CA376248

13-MAR-2009 LNM/D. 21-NOV-2008

Replace green port hand lighted spar buoy FlG, marked NJ3 with green port hand lighted pillar buoy FlG, marked NJ3 46°12′02.7″N 062°30′20.6″W
(See Chart No 1 Qg) *LL(951.7) DFO(6304265-01)*

This notice affects Electronic Navigational Chart: CA376248

Chart no. 4403

21-NOV-2008 LNM/D. 14-MAR-2008

Replace green port hand can buoy, marked NJ3 with green port hand lighted spar buoy FlG, marked NJ3 — 46°12′02.7″N 062°30′20.6″W
(See Chart No 1 Qg) *(G2008066) LL(951.7) DFO(6304139-01)*

This notice affects Electronic Navigational Chart: CA376248

21-NOV-2008 LNM/D. 14-MAR-2008

Add red starboard hand lighted pillar buoy FlR, marked NJ2 — 46°12′03.2″N 062°29′51.2″W
(See Chart No 1 Qf) *(G2008068) LL(951.6) DFO(6304141-01)*

This notice affects Electronic Navigational Chart: CA376248

14-MAR-2008 LNM/D. 14-JUL-2006

Delete depth of 1 fathom 3 feet — 46°02′08.0″N 062°31′41.0″W
(See Chart No 1 I10)

DFO(6303804-02)

This notice affects Electronic Navigational Chart: CA376248

14-JUL-2006 LNM/D. 20-JAN-2006

Add ferry route — joining 46°20′49.8″N 062°15′25.2″W
46°19′48.0″N 062°15′19.2″W
46°19′00.0″N 062°11′24.0″W
46°20′03.0″N 062°06′42.0″W
46°25′54.0″N 061°55′48.0″W
and 46°28′40.4″N 061°54′54.0″W

This notice affects Electronic Navigational Chart: CA376248

DFO(6302873-03)

20-JAN-2006 LNM/D. 09-DEC-2005

Add marine park — joining 46°23′51.0″N 062°04′30.0″W
46°22′55.0″N 062°04′02.0″W
46°21′07.0″N 062°07′36.0″W
and 46°22′04.0″N 062°08′04.0″W

This notice affects Electronic Navigational Chart: CA376248

DFO(6302706-01)

Chart no. 4403

20-JAN-2006 LNM/D. 09-DEC-2005

Add legend ″Basin Head Marine Protected Area/Zone de protection marine du Basin Head″ 46°22′18.0″N 062°06′12.0″W

DFO(6302706-02)

This notice affects Electronic Navigational Chart: CA376248

09-DEC-2005 LNM/D. 23-SEP-2005

Add submarine cable joining 46°05′48.5″N 062°27′10.0″W
46°05′53.2″N 062°26′47.1″W
46°06′03.7″N 062°26′23.7″W
46°06′07.0″N 062°26′02.7″W
46°06′14.2″N 062°23′41.4″W
46°06′13.3″N 062°21′08.3″W
46°07′25.9″N 061°56′53.7″W
and 46°03′07.0″N 061°39′27.9″W

This notice affects Electronic Navigational Chart: CA376248

DFO(6302323-01)

23-SEP-2005 LNM/D. 03-JUN-2005

Add light FlY 46°05′47.7″N 062°27′03.5″W

(G2004204) LL(960.1) DFO(6302207-01)

This notice affects Electronic Navigational Chart: CA376248

23-SEP-2005 LNM/D. 03-JUN-2005

Add light FlR 46°05′47.0″N 062°27′01.9″W

(G2004205) LL(960.2) DFO(6302207-02)

This notice affects Electronic Navigational Chart: CA376248

23-SEP-2005 LNM/D. 03-JUN-2005

Add breakwater between 46°05′47.7″N 062°27′03.5″W
and 46°05′47.0″N 062°27′01.9″W

This notice affects Electronic Navigational Chart: CA376248

DFO(6302207-03)

03-JUN-2005

Chart no. 4403

Amend legend ′Q′ to read ′Iso′ against light 46°15′32.0″N 062°25′17.9″W

LL(949) DFO(6302314-01)

This notice affects Electronic Navigational Chart: CA376248