Chart no. 4448

4448 - Havre Boucher Annulé/Cancelled by 6306824 - New Edition - 13-DEC-2002 - NAD 1983

21-NOV-2014 LNM/D. 26-SEP-2014

Amend ″PORT HOOD, MABOU HARBOUR AND/ET HAVRE BOUCHER″ to read ″PORT HOOD AND/ET MABOU HARBOUR″ against Main Title (See chart No. 1, A13) in the title block of the chart

DFO(6306967-02)

21-NOV-2014 LNM/D. 26-SEP-2014

Amend ″PORT HOOD, MABOU HARBOUR AND/ET HAVRE BOUCHER″ to read ″PORT HOOD AND/ET MABOU HARBOUR″ against Sub-title (See chart No. 1, A11) in the southeast margin of the chart.

DFO(6306967-04)

26-SEP-2014 LNM/D. 02-NOV-2012

Delete Havre Boucher ″Compartment″ 45°41′00.0″N 061°31′00.0″W

DFO(6306824-01)

02-NOV-2012 LNM/D. 23-DEC-2011

Reposition red starboard hand lighted spar buoy FlR, marked VQ4 (See Chart No. 1, Qf) from 45°41′34.1″N 061°31′23.9″W to 45°41′37.2″N 061°31′23.4″W

(G2012178) LL(883.5) DFO(6306182-01)

02-NOV-2012 LNM/D. 23-DEC-2011

Reposition green port hand lighted spar buoy FlG, marked VQ5 (See Chart No. 1, Qg) from 45°41′31.7″N 061°31′21.7″W to 45°41′31.4″N 061°31′20.8″W

(G2012179) LL(883.6) DFO(6306183-01)

23-DEC-2011 LNM/D. 12-AUG-2011

Delete front range/leading light FG 31ft (See Chart No. 1, P20.2) 45°40′55.2″N 061°31′37.6″W

(G2011322) LL(884) DFO(6305856-01)

23-DEC-2011 LNM/D. 12-AUG-2011

Add front range/leading light FG 27ft (See Chart No. 1, P20.2) 45°40′54.4″N 061°31′37.7″W

(G2011322) LL(884) DFO(6305856-02)

Chart no. 4448

23-DEC-2011 LNM/D. 12-AUG-2011

Delete rear range/leading light FG 112ft with leading line bearing 194½° and the reciprocal bearing 014½° 45°40′41.7″N 061°31′42.7″W
(See Chart No. 1, P20.2) *(G2011325) LL(885) DFO(6305857-01)*

23-DEC-2011 LNM/D. 12-AUG-2011

Add rear range/leading light FG 106ft with leading line bearing 194½° and the reciprocal bearing 014½° 45°40′40.9″N 061°31′42.7″W
(See Chart No. 1, P20.2) *(G2011325) LL(885) DFO(6305857-02)*

12-AUG-2011 LNM/D. 12-NOV-2010

Delete red starboard hand lighted pillar buoy FlR, marked VQ4 45°41′34.1″N 061°31′24.8″W
(See Chart No. 1, Qf) *(G2011236) LL(883.5) DFO(6305655-01)*

12-AUG-2011 LNM/D. 12-NOV-2010

Add red starboard hand lighted spar buoy FlR, marked VQ4 45°41′34.1″N 061°31′23.9″W
(See Chart No. 1, Qf) *(G2011236) LL(883.5) DFO(6305655-02)*

12-AUG-2011 LNM/D. 12-NOV-2010

Add green port hand lighted spar buoy FlG, marked VQ5 45°41′31.7″N 061°31′21.7″W
(See Chart No. 1, Qg)
(G2011237) LL(883.6) DFO(6305656-01)

04-APR-2003

Amend ″Channel Staked/Chenal jalonné″ to read ″Channel Buoyed/Chenal balisé″ 45°41′21.8″N 061°31′33.8″W
DFO(6300833-01)

4448 - Mabou Harbour - New Edition - 13-DEC-2002 - NAD 1983

20-SEP-2019 LNM/D. 12-OCT-2018

Chart no. 4448

Reposition green port hand lighted can buoy Fl G, marked VJ1 (See Chart No. 1, Qg) — from 46°05′24.9″N 061°28′53.6″W to 46°05′26.3″N 061°28′52.3″W
This notice affects Electronic Navigational Chart: CA576663 — *(G2019092) LL(874.52) DFO(6308763-01)*

20-SEP-2019 — LNM/D. 12-OCT-2018

Reposition red starboard hand conical lighted buoy Fl R, marked VJ2 (See Chart No. 1, Qf) — from 46°05′22.9″N 061°28′55.2″W to 46°05′23.7″N 061°28′52.7″W
This notice affects Electronic Navigational Chart: CA576663 — *(G2019093) LL(874.53) DFO(6308764-01)*

13-MAR-2015 — LNM/D. 21-NOV-2014

Affix patch 46°05′18.0″N 061°28′30.0″W
PDF
DFO(6307057-01)

12-NOV-2010 — LNM/D. 04-SEP-2009

Reposition green port hand lighted pillar buoy Fl G, marked VJ3 (See Chart No. 1 Qg) — from 46°05′19.1″N 061°28′35.0″W to 46°05′18.2″N 061°28′33.7″W
(G2010164) LL(874.55) DFO(6305084-01)

12-NOV-2010 — LNM/D. 04-SEP-2009

Reposition red starboard hand lighted pillar buoy Fl R, marked VJ4 (See Chart No. 1 Qf) — from 46°05′17.6″N 061°28′38.0″W to 46°05′17.2″N 061°28′32.4″W
(G2010165) LL(874.6) DFO(6305085-01)

15-MAY-2009 — LNM/D. 24-APR-2009

Amend FG to read FG (Priv) against light (See Chart No 1 P16 and P65) — 46°05′09.2″N 061°27′55.2″W
(G2009047) LL(876) DFO(6304377-01)

15-MAY-2009 — LNM/D. 24-APR-2009

Delete depth of 11 feet (See Chart No. 1 I10) — 46°05′25.4″N 061°28′54.0″W
DFO(6304382-01)

Chart no. 4448

15-MAY-2009 LNM/D. 24-APR-2009

Delete depth of 11 feet 46°05′22.3″N 061°28′55.8″W
(See Chart No. 1 I10)

DFO(6304382-02)

15-MAY-2009 LNM/D. 24-APR-2009

Delete depth of 7 feet 46°05′20.6″N 061°28′50.8″W
(See Chart No. 1 I10)

DFO(6304382-03)

15-MAY-2009 LNM/D. 24-APR-2009

Delete depth of 9 feet 46°05′23.0″N 061°28′50.3″W
(See Chart No. 1 I10)

DFO(6304382-04)

15-MAY-2009 LNM/D. 24-APR-2009

Delete depth of 1 foot 46°05′22.3″N 061°28′42.6″W
(See Chart No. 1 I10)

DFO(6304382-05)

15-MAY-2009 LNM/D. 24-APR-2009

Delete depth of 3 feet 46°05′21.4″N 061°28′38.2″W
(See Chart No. 1 I10)

DFO(6304382-06)

15-MAY-2009 LNM/D. 24-APR-2009

Add depth of 6 feet 46°05′23.1″N 061°28′54.5″W
(See Chart No. 1 I10)

DFO(6304382-07)

15-MAY-2009 LNM/D. 24-APR-2009

Add depth of 5 feet 46°05′22.0″N 061°28′50.9″W
(See Chart No. 1 I10)

DFO(6304382-08)

15-MAY-2009 LNM/D. 24-APR-2009

Chart no. 4448

Add depth of 2 feet 46°05′17.0″N 061°28′26.7″W
(See Chart No. 1 I10)
DFO(6304382-09)

15-MAY-2009 LNM/D. 24-APR-2009

Add depth of 2 feet 46°05′14.8″N 061°28′15.2″W
(See Chart No. 1 I10)
DFO(6304382-10)

19-DEC-2008 LNM/D. 14-NOV-2008

Add green port hand lighted can buoy FlG, marked VJ1 46°05′25.0″N 061°28′53.7″W
(See Chart No 1 Qg)
(G2008073) LL(874.52) DFO(6304145-01)

19-DEC-2008 LNM/D. 14-NOV-2008

Add red starboard hand lighted conical buoy FlR, marked VJ2 46°05′23.0″N 061°28′55.4″W
(See Chart No 1 Qf) *(G2008074) LL(874.53) DFO(6304146-01)*

10-AUG-2007 LNM/D. 16-MAR-2007

Replace red starboard hand lighted pillar bell buoy FlR, BELL, marked VJ2 with red and white fairway lighted pillar buoy Mo(A), marked VJ 46°05′29.1″N 061°29′28.0″W
(G2007051) LL(874.5) DFO(6303498-01)

This notice affects Electronic Navigational Chart:
CA276271, CA376242

03-DEC-2004 LNM/D. 11-JUN-2004

Replace green port hand spar buoy, marked VJ3, with green port hand pillar light buoy FlG, marked VJ3 46°05′19.1″N 061°28′35.0″W
(G2004177) LL(874.55) DFO(6302025-01)

4448 - Port Hood - New Edition - 13-DEC-2002 - NAD 1983

11-NOV-2022 LNM/D. 25-MAR-2022

Chart no. 4448

Affix patch 45°56′50.0″N 061°25′56.0″W
PDF
DFO(6310338-06)

25-MAR-2022 LNM/D. 03-SEP-2021

Delete light FlG 46°01′01.7″N 061°32′25.2″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376242, CA576661 *(G2022001) LL(878.1) DFO(6310028-01)*

25-MAR-2022 LNM/D. 03-SEP-2021

Amend sector light F R W G red from 077° to 121°, white from 121° to 123°, green from 123° to 161° to read sector light F R W G red from 093° to 121°, white from 121° to 123°, green from 123° to 155° (see Chart No. 1, P40.1) 45°57′28.9″N 061°31′37.2″W
This notice affects Electronic Navigational Chart: CA376242, CA576661 *(G2022010) LL(881.3) DFO(6310048-01)*

03-SEP-2021 LNM/D. 23-JUL-2021

Delete red starboard hand conical buoy, marked VK14 46°00′31.0″N 061°32′30.3″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA576661 *(G2021068) DFO(6309496-01)*

03-SEP-2021 LNM/D. 23-JUL-2021

Delete green port hand lighted pillar buoy Fl G, marked VK7 45°59′06.5″N 061°33′19.7″W
(See Chart No. 1, Qg) *(G2021082) LL(879.5) DFO(6309513-01)*
This notice affects Electronic Navigational Chart: CA376242, CA576661

03-SEP-2021 LNM/D. 23-JUL-2021

Add green port hand lighted spar buoy Q G, marked VK7 45°59′06.2″N 061°33′19.6″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA376242, CA576661 *(G2021082) LL(879.5) DFO(6309513-02)*

03-SEP-2021 LNM/D. 23-JUL-2021

Chart no. 4448

Replace yellow and black South cardinal spar buoy, marked VM with yellow and black South cardinal lighted spar buoy Q(6)+LFl 15s, marked VM (See Chart No. 1, Q130.3) 46°00′23.2″N 061°33′07.6″W
This notice affects Electronic Navigational Chart: CA576661 *(G2021083) LL(882.3) DFO(6309514-01)*

23-JUL-2021 LNM/D. 08-JAN-2021

Add red and white fairway lighted pillar buoy Mo(A), marked VX 46°01′51.7″N 061°33′57.2″W
(See Chart No. 1, Qh) *(G2021037) LL(876.5) DFO(6309468-01)*
This notice affects Electronic Navigational Chart: CA376242, CA576661

23-JUL-2021 LNM/D. 08-JAN-2021

Add green port hand lighted can buoy Fl G, marked VK13 (See Chart No. 1, Qg) 46°00′29.4″N 061°32′46.8″W
This notice affects Electronic Navigational Chart: CA576661 *(G2021040) LL(880.2) DFO(6309470-01)*

23-JUL-2021 LNM/D. 08-JAN-2021

Add green port hand lighted can buoy Fl G, marked VK15 (See Chart No. 1, Qg) 46°01′03.5″N 061°33′02.7″W
This notice affects Electronic Navigational Chart: CA576661 *(G2021041) LL(880.5) DFO(6309471-01)*

23-JUL-2021 LNM/D. 08-JAN-2021

Add red starboard hand lighted conical buoy Fl R, marked VK16 46°01′03.8″N 061°33′01.8″W
(See Chart No. 1, Qf) *(G2021042) LL(880.6) DFO(6309472-01)*
This notice affects Electronic Navigational Chart: CA576661

23-JUL-2021 LNM/D. 08-JAN-2021

Add Add green port hand lighted can buoy Fl G, marked VK17 (See Chart No. 1, Qg) 46°01′04.9″N 061°33′04.0″W
This notice affects Electronic Navigational Chart: CA576661 *(G2021067) LL(880.7) DFO(6309495-01)*

23-JUL-2021 LNM/D. 08-JAN-2021

Chart no. 4448

Add red starboard hand lighted conical buoy Q R, marked VK18 — 46°01′05.1″N 061°33′03.1″W
This notice affects Electronic Navigational Chart: CA576661 — *(G2021069) LL(880.8) DFO(6309497-01)*

08-JAN-2021 — LNM/D. 22-NOV-2019

Delete light FG — 46°01′29.4″N 061°32′20.5″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376242, CA576661 — *(G2020261) LL(879.1) DFO(6309305-01)*

22-NOV-2019 — LNM/D. 20-SEP-2019

Replace depth of 25 feet with depth of 12 feet — 46°00′29.2″N 061°32′41.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576661 — *DFO(6308840-02)*

22-NOV-2019 — LNM/D. 20-SEP-2019

Replace depth of 12 feet with depth of 11 feet — 46°00′49.4″N 061°32′54.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576661 — *DFO(6308840-03)*

22-NOV-2019 — LNM/D. 20-SEP-2019

Replace depth of 14 feet with depth of 13 feet — 46°00′56.0″N 061°32′54.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576661 — *DFO(6308840-04)*

22-NOV-2019 — LNM/D. 20-SEP-2019

Replace depth of 15 feet with depth of 14 feet — 46°00′55.8″N 061°32′59.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576661 — *DFO(6308840-05)*

22-NOV-2019 — LNM/D. 20-SEP-2019

Replace depth of 16 feet with depth of 15 feet — 46°00′58.8″N 061°32′59.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576661 — *DFO(6308840-06)*

12-OCT-2018 — LNM/D. 13-MAR-2015

Chart no. 4448

Amend FG to read Fl G against light 45°57′31.7″N 061°31′42.0″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: *(G2018109) LL(881.1) DFO(6308392-01)*
CA376242, CA576661

04-SEP-2009 LNM/D. 15-MAY-2009
Add yellow cautionary spar buoy 46°01′13.0″N 061°32′33.9″W
(See Chart No 1 Qm)
(G2009088) DFO(6304499-01)

04-SEP-2009 LNM/D. 15-MAY-2009
Add yellow cautionary spar buoy 46°01′10.5″N 061°32′43.6″W
(See Chart No 1 Qm)
(G2009089) DFO(6304500-01)

04-SEP-2009 LNM/D. 15-MAY-2009
Add yellow cautionary spar buoy 46°01′08.5″N 061°32′52.2″W
(See Chart No 1 Qm)
(G2009090) DFO(6304501-01)

04-SEP-2009 LNM/D. 15-MAY-2009
Add yellow cautionary spar buoy 46°01′06.8″N 061°32′59.8″W
(See Chart No 1 Qm)
(G2009091) DFO(6304502-01)

04-SEP-2009 LNM/D. 15-MAY-2009
Add yellow cautionary spar buoy 46°01′04.1″N 061°33′09.0″W
(See Chart No 1 Qm)
(G2009092) DFO(6304503-01)

04-SEP-2009 LNM/D. 15-MAY-2009
Add yellow cautionary spar buoy 46°01′09.0″N 061°32′37.2″W
(See Chart No 1 Qm)
(G2009094) DFO(6304504-01)

04-SEP-2009 LNM/D. 15-MAY-2009
Add yellow cautionary spar buoy 46°01′07.9″N 061°32′43.5″W
(See Chart No 1 Qm)
(G2009095) DFO(6304505-01)

Chart no. 4448

04-SEP-2009 LNM/D. 15-MAY-2009

Add yellow cautionary spar buoy 46°01′05.4″N 061°32′53.0″W
(See Chart No 1 Qm)

(G2009096) DFO(6304506-01)

04-SEP-2009 LNM/D. 15-MAY-2009

Add yellow cautionary spar buoy 46°01′03.6″N 061°32′59.6″W
(See Chart No 1 Qm)

(G2009097) DFO(6304507-01)

04-SEP-2009 LNM/D. 15-MAY-2009

Add yellow cautionary spar buoy 46°01′00.7″N 061°33′10.5″W
(See Chart No 1 Qm)

(G2009098) DFO(6304508-01)

24-APR-2009 LNM/D. 27-FEB-2009

Add light FG 46°01′29.4″N 061°32′20.5″W
(See Chart No 1 P1)

(G2009001) LL(879.1) DFO(6304300-01)

This notice affects Electronic Navigational Chart:
CA376242

27-FEB-2009 LNM/D. 19-DEC-2008

Delete light FlG 46°01′34.0″N 061°32′39.7″W
(See Chart No 1 P1)

(G2008095) LL(876.8) DFO(6304252-01)

27-FEB-2009 LNM/D. 19-DEC-2008

Add light FlG 46°01′33.3″N 061°32′39.7″W
(See Chart No 1 P1)

(G2008095) LL(876.8) DFO(6304252-02)

27-FEB-2009 LNM/D. 19-DEC-2008

Add light FlR 46°01′35.7″N 061°32′38.0″W
(See Chart No 1 P1)

(G2008096) LL(876.9) DFO(6304253-01)

This notice affects Electronic Navigational Chart:
CA376242

Chart no. 4448

27-FEB-2009 LNM/D. 19-DEC-2008

Add light FlG 46°01′01.7″N 061°32′25.2″W
(See Chart No 1 P1)

(G2008099) LL(878.1) DFO(6304256-01)

This notice affects Electronic Navigational Chart:
CA376242

14-NOV-2008 LNM/D. 22-AUG-2008

Delete ruins partly submerged at high water joining 46°01′04.7″N 061°33′04.3″W
(See Chart No 1 F33.2) 46°01′05.3″N 061°33′02.2″W
46°01′04.5″N 061°33′01.8″W
and 46°01′04.0″N 061°33′03.9″W

DFO(6304086-01)

14-NOV-2008 LNM/D. 22-AUG-2008

Add submerged ruins joining 46°01′04.7″N 061°33′04.3″W
(See Chart No 1 F33.1) 46°01′05.3″N 061°33′02.2″W
46°01′04.5″N 061°33′01.8″W
and 46°01′04.0″N 061°33′03.9″W

DFO(6304086-02)

22-AUG-2008 LNM/D. 10-AUG-2007

Add submerged ruins joining 46°01′04.7″N 061°33′04.3″W
(See Chart No 1 F33.1) 46°01′05.3″N 061°33′02.2″W
46°01′04.5″N 061°33′01.8″W
and 46°01′04.0″N 061°33′03.9″W

DFO(6303992-01)

22-AUG-2008 LNM/D. 10-AUG-2007

Add See CAUTION/Voir ATTENTION 46°01′09.0″N 061°33′03.0″W
(See Chart No 1 A14)

DFO(6303992-02)

22-AUG-2008 LNM/D. 10-AUG-2007

Chart no. 4448

Add note: 46°02′18.0″N 061°31′51.0″W

CAUTION
Mariners are advised that the breakwater ruins are unstable. The ruins and nearby depths are subject to change. *DFO(6303992-03)*

ATTENTION
Nous informons les navigateurs que les ruines du brise-lames sont instables. Les ruines et les profondeurs adjacentes peuvent changer.

16-MAR-2007 LNM/D. 08-DEC-2006

Affix patch 46°01′04.0″N 061°33′00.0″W

DFO(6303207-01)

PDF

08-DEC-2006 LNM/D. 11-AUG-2006

Delete front leading light ″FlG 18ft″ 46°01′02.8″N 061°32′25.6″W

(G2006117) LL(878) DFO(6303130-01)

This notice affects Electronic Navigational Chart: CA376242

08-DEC-2006 LNM/D. 11-AUG-2006

Delete rear leading light ″FG 60ft″ with leading line and bearing legend ″007½º 187½º″ 46°01′29.4″N 061°32′20.4″W

(G2006118) LL(879) DFO(6303130-02)

This notice affects Electronic Navigational Chart: CA376242

08-DEC-2006 LNM/D. 11-AUG-2006

Delete green port hand lighted pillar buoy QG, marked VX1 46°01′26.2″N 061°32′37.6″W

(G2006202) LL(876.3) DFO(6303173-01)

This notice affects Electronic Navigational Chart: CA376242

08-DEC-2006 LNM/D. 11-AUG-2006

Chart no. 4448

Add green port hand lighted spar buoy QG, marked VX1 — 46°01′27.7″N 061°32′38.5″W

(G2006202) LL(876.3) DFO(6303173-02)

This notice affects Electronic Navigational Chart: CA376242

11-AUG-2006 — LNM/D. 30-JUN-2006

Amend ″FR″ to read ″FlG″ against light — 46°01′34.0″N 061°32′39.7″W

(G2006103) LL(876.8) DFO(6302997-01)

This notice affects Electronic Navigational Chart: CA376242

30-JUN-2006 — LNM/D. 24-MAR-2006

Delete red starboard hand conical buoy, marked VK4 — 45°59′51.8″N 061°34′57.6″W

(G2006042) DFO(6302899-01)

This notice affects Electronic Navigational Chart: CA376242

30-JUN-2006 — LNM/D. 24-MAR-2006

Add red starboard hand lighted spar buoy FlR, marked VM4 — 45°59′27.5″N 061°35′34.7″W

(G2006043) LL(882.2) DFO(6302900-01)

This notice affects Electronic Navigational Chart: CA376242

30-JUN-2006 — LNM/D. 24-MAR-2006

Replace green port hand can buoy, marked VM3 with green port hand lighted spar buoy FlG, marked VM3 — 45°59′39.7″N 061°35′09.6″W

(G2006045) LL(882.1) DFO(6302902-01)

This notice affects Electronic Navigational Chart: CA376242

30-JUN-2006 — LNM/D. 24-MAR-2006

Replace red starboard hand conical buoy, marked VK12 with red starboard hand lighted spar buoy FlR, marked VK12 — 45°59′58.2″N 061°32′32.6″W

(G2006047) LL(880.1) DFO(6302904-01)

Chart no. 4448

30-JUN-2006 LNM/D. 24-MAR-2006

Replace red starboard hand conical buoy, marked VM6 with yellow and black South cardinal spar buoy, marked VM 46°00′23.2″N 061°33′07.6″W

(G2006049) DFO(6302906-01)

24-MAR-2006 LNM/D. 09-DEC-2005

Delete anchorage symbol 46°00′09.5″N 061°32′52.5″W

DFO(6302769-01)

24-MAR-2006 LNM/D. 09-DEC-2005

Add anchorage symbol 46°00′22.3″N 061°33′20.8″W

DFO(6302769-02)

09-DEC-2005 LNM/D. 03-DEC-2004

Add submarine cable joining 46°02′30.3″N 061°37′01.5″W
46°01′47.3″N 061°34′06.6″W
46°01′39.7″N 061°33′54.0″W
46°01′28.0″N 061°33′20.8″W
46°01′24.4″N 061°32′54.0″W
46°01′26.8″N 061°32′46.0″W
46°01′30.5″N 061°32′39.2″W
and 46°01′34.0″N 061°32′27.0″W

This notice affects Electronic Navigational Chart: CA376248

DFO(6302323-01)

09-DEC-2005 LNM/D. 03-DEC-2004

Add cable sign 46°01′34.5″N 061°32′25.8″W

DFO(6302323-02)

11-JUN-2004 LNM/D. 26-DEC-2003

Amend legend F G 18ft to read Fl G 18ft against light 46°01′02.8″N 061°32′25.6″W

(G2004072) LL(878) DFO(6301448-01)

26-DEC-2003 LNM/D. 04-APR-2003

Chart no. 4448

Delete red, starboard hand spar buoy 46°01′04.2″N 061°32′58.1″W

(G2003099) DFO(6301048-01)

26-DEC-2003 LNM/D. 04-APR-2003

Delete green, port hand spar buoy 46°01′04.2″N 061°33′00.6″W

(G2003100) DFO(6301049-01)