Chart no. 4530

4530 - Carmanville - New Edition - 15-MAR-2002 - NAD 1983

18-MAR-2022 LNM/D. 31-DEC-2021

Replace green port hand lighted pillar buoy Fl G, marked DC7 with green port hand lighted spar buoy Fl G, marked DC7. 49°24′46.9″N 054°16′11.6″W
(See Chart No. 1, Qg) *(N2022014) LL(390) DFO(6310016-01)*

31-DEC-2021 LNM/D. 08-OCT-2021

Delete green port hand lighted spar buoy Fl G, marked DC13 49°23′34.9″N 054°16′54.6″W
(See Chart No. 1, Qg) *(N2021171) LL(390.131) DFO(6309893-01)*
This notice affects Electronic Navigational Chart: CA476813, CA576280

31-DEC-2021 LNM/D. 08-OCT-2021

Add black, red and black isolated danger lighted spar buoy Fl(2)5s, marked DC 49°23′34.9″N 054°16′54.6″W
(See Chart No. 1, Q130.4) *(N2021171) LL(390.131) DFO(6309893-02)*
This notice affects Electronic Navigational Chart: CA476813, CA576280

28-OCT-2011 LNM/D. 10-DEC-2010

Add yellow cautionary lighted spar buoy Fl Y, marked DCK 49°24′12.6″N 054°16′57.5″W
(See Chart No. 1, Qm) *(N2011082) LL(390.15) DFO(6305784-01)*

This notice affects Electronic Navigational Chart: CA576280

10-DEC-2010 LNM/D. 01-OCT-2010

Delete depth of 6 metres, 7 decimetres 49°23′53.3″N 054°16′55.7″W
(See Chart No 1 I10)
DFO(6305132-04)

This notice affects Electronic Navigational Chart: CA476813, CA576280

10-DEC-2010 LNM/D. 01-OCT-2010

Chart no. 4530

Add depth of 5 metres, 5 decimetres 49°23′53.9″N 054°16′55.0″W
(See Chart No 1 I10)

DFO(6305132-05)

This notice affects Electronic Navigational Chart: CA476813, CA576280

10-DEC-2010 LNM/D. 01-OCT-2010

Add depth of 3 metres, 9 decimetres 49°23′50.7″N 054°16′46.9″W
(See Chart No 1 I10)

DFO(6305132-06)

This notice affects Electronic Navigational Chart: CA576280

10-DEC-2010 LNM/D. 01-OCT-2010

Add depth of 7 metres, 3 decimetres 49°24′40.9″N 054°16′13.7″W
(See Chart No 1 I10)

DFO(6305132-08)

This notice affects Electronic Navigational Chart: CA476813, CA576280

10-DEC-2010 LNM/D. 01-OCT-2010

Add depth of 8 metres, 3 decimetres 49°25′20.2″N 054°15′39.9″W
(See Chart No 1 I10)

DFO(6305132-10)

This notice affects Electronic Navigational Chart: CA476813, CA576280

10-DEC-2010 LNM/D. 01-OCT-2010

Delete depth of 3 metres, 7 decimetres 49°24′16.9″N 054°16′17.9″W
(See Chart No 1 I10)

DFO(6305132-11)

This notice affects Electronic Navigational Chart: CA476813, CA576280

10-DEC-2010 LNM/D. 01-OCT-2010

Chart no. 4530

Add depth of 2 metres, 1 decimetre — 49°24′16.0″N 054°16′17.7″W
(See Chart No 1 I10)

DFO(6305132-12)

This notice affects Electronic Navigational Chart: CA476813, CA576280

4530 - Hamilton Sound: Eastern Portion / Partie-est - New Edition - 15-MAR-2002 - NAD 1983

18-MAR-2022 — LNM/D. 31-DEC-2021

Replace green port hand lighted pillar buoy Fl G, marked DC7 with green port hand lighted spar buoy Fl G, marked DC7. — 49°24′46.9″N 054°16′11.6″W
(See Chart No. 1, Qg)

(N2022014) LL(390) DFO(6310016-01)

31-DEC-2021 — LNM/D. 08-OCT-2021

Add black, red and black isolated danger lighted spar buoy Fl(2)5s, marked DC — 49°23′34.9″N 054°16′54.6″W
(See Chart No. 1, Q130.4)
This notice affects Electronic Navigational Chart: CA476813, CA576280

(N2021171) LL(390.131) DFO(6309893-02)

08-OCT-2021 — LNM/D. 10-SEP-2021

Reposition red starboard hand lighted pillar buoy Fl R, marked DX8 — from 49°33′33.8″N 054°17′03.6″W to 49°33′34.1″N 054°17′12.3″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA476813

(N2021058) LL(373) DFO(6309538-01)

08-OCT-2021 — LNM/D. 10-SEP-2021

Add black, yellow and black East cardinal lighted spar buoy Q(3)10s, marked DX — 49°34′07.7″N 054°15′55.5″W
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: CA476813

(N2021096) LL(372.6) DFO(6309570-01)

10-SEP-2021 — LNM/D. 25-SEP-2020

Chart no. 4530

Amend Fl R to read Fl against light — 49°27′36.2″N 053°57′19.7″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376655, CA476279, CA576504 — *(N2021049) LL(396.75) DFO(6309530-01)*

10-SEP-2021 — LNM/D. 25-SEP-2020

Amend Oc G to read Fl G against light — 49°27′23.1″N 053°56′28.5″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376655, CA476279 — *(N2021062) LL(399) DFO(6309541-01)*

25-SEP-2020 — LNM/D. 17-AUG-2018

Amend Fl 6s9m to read Fl 4s10m against light — 49°26′55.9″N 054°13′41.6″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA376655, CA476813 — *(N2020073) LL(389) DFO(6309151-01)*

17-AUG-2018 — LNM/D. 15-SEP-2017

Add light Fl R — 49°27′36.2″N 053°57′19.7″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA376655, CA476279 — *(N2018038) LL(396.75) DFO(6308330-01)*

15-SEP-2017 — LNM/D. 25-AUG-2017

Add ON CERTAIN COPIES ferry route — between 49°34′10.4″N 054°18′15.1″W and 49°34′12.0″N 054°18′26.6″W
(See Chart No. 1, M50)

DFO(6308059-01)

25-AUG-2017 — LNM/D. 26-JUN-2015

Add ferry route — joining 49°34′03.5″N 054°18′26.6″W 49°34′10.4″N 054°18′15.1″W and 49°34′14.5″N 054°18′08.1″W
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart: CA376655, CA476813

DFO(6308011-06)

26-JUN-2015 — LNM/D. 16-JAN-2015

Chart no. 4530

Add breakwater extension between 49°27′32.7″N 053°57′22.6″W
(See Chart No. 1, F4.1) and 49°27′32.2″N 053°57′24.9″W
This notice affects Electronic Navigational Chart:
CA476279 *DFO(6307149-01)*

16-JAN-2015 LNM/D. 29-JUN-2012

Delete legend Fog Sig 30s against light 49°31′49.6″N 053°51′04.8″W
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart: *(N2014067) LL(395) DFO(6306987-01)*
CA276092, CA376655, CA476279

29-JUN-2012 LNM/D. 16-MAR-2012

Affix patch 49°27′19.0″N 053°57′19.0″W

DFO(6306039-01)

PDF
This notice affects Electronic Navigational Chart: CA476279

16-MAR-2012 LNM/D. 28-OCT-2011

Reposition red starboard hand lighted spar buoy FlR, marked DX6 from 49°33′39.5″N 054°16′49.5″W
(See Chart No. 1, Qf) to 49°33′39.8″N 054°16′38.6″W

LL(372.62) DFO(6305947-01)

10-DEC-2010 LNM/D. 01-OCT-2010

Delete depth of 6 metres, 7 decimetres 49°23′53.3″N 054°16′55.7″W
(See Chart No 1 I10)

DFO(6305132-04)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010 LNM/D. 01-OCT-2010

Add depth of 5 metres, 5 decimetres 49°23′53.9″N 054°16′55.0″W
(See Chart No 1 I10)

DFO(6305132-05)

This notice affects Electronic Navigational Chart: CA476813,
CA576280

10-DEC-2010 LNM/D. 01-OCT-2010

Chart no. 4530

Delete depth of 10 metres, 1 decimetre 49°24′41.9″N 054°16′11.5″W
(See Chart No 1 I10)

DFO(6305132-07)

This notice affects Electronic Navigational Chart: CA476813

10-DEC-2010 LNM/D. 01-OCT-2010

Add depth of 7 metres, 3 decimetres 49°24′40.9″N 054°16′13.7″W
(See Chart No 1 I10)

DFO(6305132-08)

This notice affects Electronic Navigational Chart: CA476813, CA576280

10-DEC-2010 LNM/D. 01-OCT-2010

Delete depth of 8 metres, 8 decimetres 49°25′21.2″N 054°15′37.9″W
(See Chart No 1 I10)

DFO(6305132-09)

10-DEC-2010 LNM/D. 01-OCT-2010

Add depth of 8 metres, 3 decimetres 49°25′20.2″N 054°15′39.9″W
(See Chart No 1 I10)

DFO(6305132-10)

This notice affects Electronic Navigational Chart: CA476813, CA576280

10-DEC-2010 LNM/D. 01-OCT-2010

Delete depth of 3 metres, 7 decimetres 49°24′16.9″N 054°16′17.9″W
(See Chart No 1 I10)

DFO(6305132-11)

This notice affects Electronic Navigational Chart: CA476813, CA576280

10-DEC-2010 LNM/D. 01-OCT-2010

Add depth of 2 metres, 1 decimetre 49°24′16.0″N 054°16′17.7″W
(See Chart No 1 I10)

DFO(6305132-12)

This notice affects Electronic Navigational Chart: CA476813, CA576280

Chart no. 4530

01-OCT-2010 LNM/D. 17-SEP-2010

Delete note: 49°27′06.0″N 053°58′15.0″W
DIAGRAM / DIAGRAMME
See Sailing Directions
Voir Instructions nautiques

DFO(6305060-01)

This notice affects Electronic Navigational Chart: CA476279

17-SEP-2010 LNM/D. 23-OCT-2009

Amend Fl 6s 13m 8M to read Fl 6s 13m 16M against light 49°36′03.6″N 054°09′29.3″W
(See Chart No. 1 P16)

LL(378) DFO(6305022-01)

This notice affects Electronic Navigational Chart: CA476279

17-SEP-2010 LNM/D. 23-OCT-2009

Delete green port hand lighted spar buoy FlG, marked JM3/1 49°27′48.0″N 053°57′00.0″W
(See Chart No 1 Qg)

LL(399.125) DFO(6305044-01)

This notice affects Electronic Navigational Chart: CA476279

17-SEP-2010 LNM/D. 23-OCT-2009

Add green port hand lighted spar buoy FlG, marked JM1 49°27′44.6″N 053°56′55.4″W
(See Chart No 1 Qg)

LL(399.41) DFO(6305045-01)

This notice affects Electronic Navigational Chart: CA476279

17-SEP-2010 LNM/D. 23-OCT-2009

Add red starboard hand lighted spar buoy FlR, marked JM2 49°27′46.7″N 053°57′02.7″W
(See Chart No 1 Qf)

LL(400) DFO(6305046-01)

This notice affects Electronic Navigational Chart: CA476279

23-OCT-2009 LNM/D. 26-OCT-2007

Chart no. 4530

Add breakwater with legend Bkw — joining 49°27′36.3″N 053°57′28.8″W 49°27′35.5″N 053°57′23.3″W and 49°27′32.6″N 053°57′22.2″W

This notice affects Electronic Navigational Chart: CA476279

DFO(6304612-01)

23-OCT-2009 — LNM/D. 26-OCT-2007

Delete light FlR — 49°27′32.2″N 053°57′27.0″W
(See Chart No 1 P1)

(N2008041) LL(397) DFO(6304612-02)

This notice affects Electronic Navigational Chart: CA476279

23-OCT-2009 — LNM/D. 26-OCT-2007

Add light FlR — 49°27′32.6″N 053°57′22.2″W
(See Chart No 1 P1)

(N2008041) LL(397) DFO(6304612-03)

This notice affects Electronic Navigational Chart: CA476279

26-OCT-2007 — LNM/D. 09-DEC-2005

Amend note Adjoining Chart/Carte adjacente 4531 to read Adjoining Chart/Carte adjacente 4862 — centre of west border

DFO(6303536-12)

26-OCT-2007 — LNM/D. 09-DEC-2005

Amend note Adjoining Chart/Carte adjacente 4520 to read Adjoining Chart/Carte adjacente 4820 — right side of north border

DFO(6303536-13)

09-DEC-2005 — LNM/D. 18-NOV-2005

Amend Fl to read Fl G against buoy marked JM3/1 — 49°27′47.8″N 053°57′00.0″W

LL(399.125) DFO(6302485-01)

18-NOV-2005 — LNM/D. 22-JUL-2005

Chart no. 4530

Add light FlR 49°28′25.0″N 054°03′27.0″W

(N2004154) LL(393.7) DFO(6301846-01)

18-NOV-2005 LNM/D. 22-JUL-2005

Add wharf between 49°28′25.0″N 054°03′27.0″W
and 49°28′26.6″N 054°03′27.4″W

DFO(6301846-02)

22-JUL-2005 LNM/D. 14-JAN-2005

Add light ′FlG′ against green port hand spar buoy, marked JA1 49°28′34.8″N 054°02′58.0″W

LL(393.5) DFO(6302370-01)

22-JUL-2005 LNM/D. 14-JAN-2005

Add light ′FlR′ against red starboard hand spar buoy, marked JA2 49°28′29.4″N 054°03′09.6″W

LL(393.6) DFO(6302370-02)

14-JAN-2005 LNM/D. 02-MAY-2003

Delete light FlG 49°36′36.6″N 054°10′57.4″W

(N2004191) LL(378.7) DFO(6302102-01)

14-JAN-2005 LNM/D. 02-MAY-2003

Delete depth of 5 metres, 8 decimetres 49°36′37.8″N 054°10′56.3″W

DFO(6302102-02)

14-JAN-2005 LNM/D. 02-MAY-2003

Add breakwater joining 49°36′34.4″N 054°10′54.9″W
49°36′36.3″N 054°10′55.0″W
and 49°36′38.5″N 054°10′56.4″W

DFO(6302102-03)

14-JAN-2005 LNM/D. 02-MAY-2003

Chart no. 4530

Add light FlG 49°36′38.5″N 054°10′56.4″W

(N2004191) LL(378.7) DFO(6302102-04)

02-MAY-2003 LNM/D. 14-MAR-2003

Delete light FR 49°27′15.8″N 053°57′26.7″W

(N2002041) LL(398) DFO(6300283-01)

02-MAY-2003 LNM/D. 14-MAR-2003

Replace red starboard hand pillar light and whistle buoy Fl R, WHIS, marked J4 with red starboard hand pillar light buoy Fl R, marked J4 49°28′44.9″N 053°54′08.6″W

(N2002071) LL(402) DFO(6300423-01)

14-MAR-2003 LNM/D. 21-FEB-2003

Delete light FIR 49°34′17.0″N 054°18′01.0″W

LL(372.7) DFO(6300764-01)

14-MAR-2003 LNM/D. 21-FEB-2003

Add light FIR 49°34′15.8″N 054°18′05.5″W

LL(372.7) DFO(6300764-02)

14-MAR-2003 LNM/D. 21-FEB-2003

Delete dolphin and legend ″Dn″ 49°34′17.0″N 054°18′01.0″W

DFO(6300764-03)

21-FEB-2003 LNM/D. 27-DEC-2002

Delete dangerous underwater rock of 2m or less 49°29′19.0″N 053°48′54.0″W

DFO(6300810-01)

27-DEC-2002

Delete green, port hand can buoy, marked DX5 49°33′45.0″N 054°16′04.0″W

(N2000177) DFO(6828994-01)

Chart no. 4530

27-DEC-2002

Add green port hand spar light buoy FlG, marked DX5 — 49°33′43.4″N 054°16′16.4″W

(N2000177) LL(372.63) DFO(6828994-02)

27-DEC-2002

Delete red, starboard hand conical buoy, marked DX6 — 49°33′40.0″N 054°16′38.5″W

(N2000178) DFO(6828995-01)

27-DEC-2002

Add red starboard hand spar light buoy FlR, marked DX6 — 49°33′39.5″N 054°16′49.5″W

(N2000178) LL(372.62) DFO(6828995-02)

27-DEC-2002

Replace red, starboard hand spar buoy, marked DS2, with red starboard hand spar light buoy FlR, marked DS2 — 49°36′41.3″N 054°11′02.9″W

(N2000179) LL(378.9) DFO(6828996-01)

27-DEC-2002

Replace red, starboard hand spar buoy, marked DG2, with red starboard hand spar light buoy FlR, marked DG2 — 49°34′28.9″N 054°16′29.8″W

(N2000180) LL(372.2) DFO(6828997-01)

27-DEC-2002

Replace green, port hand can buoy, marked DW3, with green port hand spar light buoy FlG, marked DW3 — 49°34′03.4″N 054°13′58.9″W

(N2000397) LL(346.4) DFO(6829312-01)