Chart no. 4592

4592 - Little Bay Island to / à League Rock - New Edition - 10-OCT-2003 - NAD 1983

02-MAY-2025 LNM/D. 28-OCT-2022

Delete ferry route joining 49°35′19.6″N 055°50′02.3″W
(See Chart 1, M50) 49°35′22.8″N 055°49′37.0″W
49°35′31.7″N 055°48′58.7″W
49°32′59.2″N 055°46′48.7″W
49°32′55.9″N 055°46′22.1″W
and 49°32′48.2″N 055°46′14.5″W

DFO(6311938-01)

28-OCT-2022 LNM/D. 12-NOV-2021

Delete yellow, black and yellow West cardinal lighted spar buoy Q(9) 15s, marked DBB 49°37′36.9″N 055°48′20.5″W
(See Chart 1, Q130.3) *DFO(6310330-01)*
This notice affects Electronic Navigational Chart: CA376656

28-OCT-2022 LNM/D. 12-NOV-2021

Add black, yellow and black East cardinal lighted spar buoy Q(3) 10s marked DNC 49°32′44.5″N 055°36′23.6″W
(See Chart 1, Q130.3) *DFO(6310330-02)*
This notice affects Electronic Navigational Chart: CA376656

12-NOV-2021 LNM/D. 10-SEP-2021

Delete light FlR 49°37′57.0″N 055°48′23.3″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376656 *(N2021139) LL(332.5) DFO(6309708-01)*

12-NOV-2021 LNM/D. 10-SEP-2021

Delete light Fl R 49°38′30.6″N 055°47′17.8″W
(See Chart No. 1, P1)
(N2021140) LL(332.3) DFO(6309709-01)

10-SEP-2021 LNM/D. 24-JUL-2020

Delete red starboard hand lighted spar buoy Fl R, marked DLB2 49°38′13.1″N 055°46′01.8″W
(See Chart No. 1, Qf) *(N2021053) LL(331.9) DFO(6309533-01)*

10-SEP-2021 LNM/D. 24-JUL-2020

Chart no. 4592

Add black, yellow and black East cardinal lighted spar buoy Q(3)10s, marked DLB — 49°38′11.5″N 055°45′55.6″W
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: CA376656
(N2021053) LL(331.9) DFO(6309533-02)

24-JUL-2020 LNM/D. 27-NOV-2015

Amend Fl to read Fl 6s6m5M against light. — 49°35′18.0″N 055°43′19.0″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA376656
(N2020033) LL(334) DFO(6309003-01)

27-NOV-2015 LNM/D. 28-AUG-2015

Reposition red starboard hand lighted spar buoy FlR, marked DNC2 — from 49°32′23.0″N 055°36′58.0″W to 49°32′26.6″N 055°36′56.3″W
(See Chart No. 1, Qf)
(N2015052) LL(341.2) DFO(6307276-01)

28-AUG-2015 LNM/D. 05-DEC-2014

Add ferry route — joining 49°37′50.2″N 055°48′33.9″W 49°33′57.6″N 055°45′12.6″W 49°33′52.2″N 055°44′31.2″W and 49°33′41.8″N 055°44′20.1″W
(See Chart No. 1, M50)
This notice affects Electronic Navigational Chart: CA376656
DFO(6307213-01)

05-DEC-2014 LNM/D. 06-JAN-2012

Replace depth of 6 fathoms with islet 49°38′49.5″N 055°40′19.1″W
(See Chart No. 1, K10)
DFO(6306963-03)

06-JAN-2012 LNM/D. 14-JAN-2011

Add yellow, black and yellow West cardinal lighted spar buoy Q(9) 15s, marked DBB — 49°37′37.0″N 055°48′20.0″W
(See Chart No. 1, Q130.3)
True geographic position (49-37-39.6N, 55-48-19.5W) differs from charted position.
(N2011093) LL(335.9) DFO(6305866-01)

14-JAN-2011 LNM/D. 19-NOV-2010

Chart no. 4592

Delete ferry route joining 49°37′57.0″N 055°48′23.0″W
(See Chart No. 1, M50) 49°37′53.0″N 055°48′32.8″W
49°37′40.9″N 055°49′33.5″W
and 49°37′28.5″N 055°50′09.7″W

DFO(6305134-01)

14-JAN-2011 LNM/D. 19-NOV-2010

Add ferry route joining 49°37′57.0″N 055°48′23.6″W
(See Chart No. 1, M50) 49°37′51.5″N 055°48′33.5″W
49°37′37.6″N 055°49′34.6″W
and 49°37′33.5″N 055°50′09.7″W

DFO(6305134-02)

19-NOV-2010 LNM/D. 18-JUN-2010

Add ferry route joining 49°37′57.0″N 055°48′23.0″W
(See Chart No. 1 M50) 49°37′53.0″N 055°48′32.8″W
49°37′40.9″N 055°49′33.5″W
and 49°37′28.5″N 055°50′09.7″W

DFO(6305088-01)

19-NOV-2010 LNM/D. 18-JUN-2010

Amend FlR Priv to read FlR against light 49°37′57.2″N 055°48′23.3″W
(See Chart No 1 P16)

LL(332.5) DFO(6305088-03)

18-JUN-2010 LNM/D. 28-DEC-2007

Add green port hand lighted spar buoy FlG, marked DLR1 49°34′33.7″N 055°30′03.2″W
(See Chart 1 Qg)

(N2010027) LL(340.1) DFO(6304898-01)

18-JUN-2010 LNM/D. 28-DEC-2007

Add green port hand lighted spar buoy FlG, marked DLR3 49°34′18.6″N 055°31′00.9″W
(See Chart 1 Qg)

(N2010028) LL(340.3) DFO(6304899-01)

18-JUN-2010 LNM/D. 28-DEC-2007

Chart no. 4592

Add green port hand lighted spar buoy Fl G, marked DR1 — 49°31′49.6″N 055°45′40.4″W
(See Chart 1 Qg)
(N2010029) LL(332.61) DFO(6304900-01)

28-DEC-2007 LNM/D. 01-DEC-2006
Add light FlR — 49°34′03.0″N 055°44′10.8″W
(See Chart No 1 P16)
(N2007056) LL(332.9) DFO(6303712-01)

01-DEC-2006 LNM/D. 06-JAN-2006
Amend ″Adjoining Chart/Carte adjacente 4594″ to read ″Adjoining Chart/Carte adjacente 4864″ — lower east border
DFO(6303187-09)

01-DEC-2006 LNM/D. 06-JAN-2006
Amend ″Adjoining Chart/Carte adjacente 4520″ to read ″Adjoining Chart/Carte adjacente 4821″ — upper east border
DFO(6303187-10)

01-DEC-2006 LNM/D. 06-JAN-2006
Amend ″Adjoining Chart/Carte adjacente 4520″ to read ″Adjoining Chart/Carte adjacente 4821″ — centre of north border
DFO(6303187-11)

06-JAN-2006 LNM/D. 27-AUG-2004
Add light FlG — 49°32′24.5″N 055°46′48.5″W
(N2005083) LL(332.6) DFO(6302593-01)

27-AUG-2004
Add red starboard hand spar light buoy FlR, marked DLB2 — 49°38′13.3″N 055°46′00.9″W
(N2004141) LL(331.9) DFO(6301814-01)