Chart no. 4832

4832 - Fortune Bay: Southern Portion / Partie Sud - New Chart - 02-OCT-1987 - NAD 1983

22-NOV-2019 LNM/D. 01-NOV-2019

Replace green port hand can light buoy FlG , marked VF1 with green port hand spar light buoy Fl G, marked VF1 — 47°04′39.7″N 055°49′31.5″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA376233, CA576235
(N2019066) LL(103) DFO(6308780-01)

01-NOV-2019 LNM/D. 11-OCT-2019

Add private yellow ODAS/SADO lighted pillar buoy Fl(5) Y 20s, Priv — 47°15′40.0″N 055°30′00.0″W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA276274, CA376233
DFO(6308822-01)

11-OCT-2019 LNM/D. 11-JAN-2019

Amend Fl5s24m5M to read Fl 5s24m15M against light — 47°04′28.0″N 055°51′34.0″W
(See Chart No. 1, P16)
LL(102) DFO(6308728-01)

11-JAN-2019 LNM/D. 31-AUG-2018

Add submarine cable — joining 47°07′59.5″N 055°52′45.0″W
(See Chart No. 1, L30.1) — 47°07′36.0″N 055°52′10.0″W
This notice affects Electronic Navigational Chart: CA276091, CA376233, CA376627 — and 47°04′43.0″N 055°48′47.0″W
DFO(6308456-03)

31-AUG-2018 LNM/D. 11-AUG-2017

Add marine farm — 47°32′12.0″N 055°37′30.0″W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA376233, CA476323
DFO(6308409-01)

31-AUG-2018 LNM/D. 11-AUG-2017

Add marine farm — 47°30′54.0″N 055°36′00.0″W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA376233, CA476323
DFO(6308412-01)

Chart no. 4832

11-AUG-2017 LNM/D. 28-JUL-2017

Delete red and white fairway lighted pillar whistle buoy Mo(A), WHIS, marked VSS 47°21′39.9″N 055°48′34.3″W
(See Chart No. 1, Qh) *(N2017024) LL(120.2) DFO(6308026-01)*

This notice affects Electronic Navigational Chart: CA376233, CA476323

28-JUL-2017 LNM/D. 14-JUL-2017

Delete light Fl G 47°27′28.3″N 055°37′26.1″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376233, CA476323 *(N2017018) LL(121.3) DFO(6307990-01)*

14-JUL-2017 LNM/D. 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°11′40.3″N 055°35′48.9″W
(See Chart No. 1, L25) *DFO(6307974-01)*
This notice affects Electronic Navigational Chart: CA276274, CA376233

14-JUL-2017 LNM/D. 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°19′49.9″N 055°44′07.7″W
(See Chart No. 1, L25) *DFO(6307974-02)*
This notice affects Electronic Navigational Chart: CA276274, CA376233

14-JUL-2017 LNM/D. 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°31′25.7″N 055°20′26.4″W
(See Chart No. 1, L25) *DFO(6307974-03)*
This notice affects Electronic Navigational Chart: CA376233

14-JUL-2017 LNM/D. 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°18′13.0″N 055°21′28.7″W
(See Chart No. 1, L25) *DFO(6307974-05)*
This notice affects Electronic Navigational Chart: CA376233

Chart no. 4832

14-JUL-2017 LNM/D. 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°26′03.4″N 055°29′27.3″W
(See Chart No. 1, L25) *DFO(6307974-06)*
This notice affects Electronic Navigational Chart: CA376233

14-APR-2017 LNM/D. 16-DEC-2016

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres 47°33′29.4″N 055°19′44.4″W
(See Chart No. 1, L25) *DFO(6307848-08)*
This notice affects Electronic Navigational Chart: CA276274, CA376233

14-APR-2017 LNM/D. 16-DEC-2016

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres 47°33′26.0″N 055°19′54.0″W
(See Chart No. 1, L25) *DFO(6307848-09)*
This notice affects Electronic Navigational Chart: CA376233

14-APR-2017 LNM/D. 16-DEC-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°31′25.7″N 055°20′26.4″W
(See Chart No. 1, L25) *DFO(6307848-11)*
This notice affects Electronic Navigational Chart: CA376233

14-APR-2017 LNM/D. 16-DEC-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°26′03.4″N 055°29′27.3″W
(See Chart No. 1, L25) *DFO(6307848-13)*
This notice affects Electronic Navigational Chart: CA376233

14-APR-2017 LNM/D. 16-DEC-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°18′13.0″N 055°21′28.7″W
(See Chart No. 1, L25) *DFO(6307848-14)*
This notice affects Electronic Navigational Chart: CA376233

14-APR-2017 LNM/D. 16-DEC-2016

Chart no. 4832

Replace depth of 10 metres with depth of 8 metres — 47°11′46.8″N 055°35′13.8″W
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276274, CA376233 — *DFO(6307848-17)*

14-APR-2017 — LNM/D. 16-DEC-2016

Reposition subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres — from 47°11′46.8″N 055°35′13.8″W to 47°11′40.3″N 055°35′48.9″W
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276274, CA376233 — *DFO(6307848-18)*

14-APR-2017 — LNM/D. 16-DEC-2016

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres — 47°11′37.8″N 055°35′32.4″W
(See Chart No. 1, L25) — *DFO(6307848-19)*
This notice affects Electronic Navigational Chart: CA376233

14-APR-2017 — LNM/D. 16-DEC-2016

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres — 47°20′33.0″N 055°43′04.2″W
(See Chart No. 1, L25) — *DFO(6307848-20)*
This notice affects Electronic Navigational Chart: CA376233

14-APR-2017 — LNM/D. 16-DEC-2016

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres — 47°20′21.6″N 055°43′04.2″W
(See Chart No. 1, L25) — *DFO(6307848-21)*
This notice affects Electronic Navigational Chart: CA276274, CA376233

14-APR-2017 — LNM/D. 16-DEC-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres — 47°19′49.9″N 055°44′07.7″W
(See Chart No. 1, L25) — *DFO(6307848-22)*
This notice affects Electronic Navigational Chart: CA276274, CA376233

16-DEC-2016 — LNM/D. 05-FEB-2016

Chart no. 4832

Delete red, green and red starboard bifurcation lighted pillar bell buoy Fl(2+1) R, BELL, marked VSN (See Chart No. 1, Qi) — 47°23′03.0″N 055°45′58.0″W
(N2016066) LL(120.4) DFO(6307692-01)
This notice affects Electronic Navigational Chart: CA376233, CA476323

05-FEB-2016 — LNM/D. 07-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres (See Chart No. 1, L25) — 47°11′37.8″N 055°35′32.4″W
This notice affects Electronic Navigational Chart: CA376233 — *DFO(6307401-02)*

05-FEB-2016 — LNM/D. 07-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres (See Chart No. 1, L25) — 47°11′46.8″N 055°35′13.8″W
DFO(6307401-03)
This notice affects Electronic Navigational Chart: CA276274

05-FEB-2016 — LNM/D. 07-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres (See Chart No. 1, L25) — 47°20′33.0″N 055°43′04.2″W
This notice affects Electronic Navigational Chart: CA376233 — *DFO(6307401-04)*

05-FEB-2016 — LNM/D. 07-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres (See Chart No. 1, L25) — 47°20′21.6″N 055°43′04.2″W
DFO(6307401-05)
This notice affects Electronic Navigational Chart: CA276274, CA376233

07-AUG-2015 — LNM/D. 29-MAR-2013

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres. (See Chart No. 1, L25) — 47°33′29.4″N 055°19′44.4″W
DFO(6307179-03)
This notice affects Electronic Navigational Chart: CA276274, CA376233

07-AUG-2015 — LNM/D. 29-MAR-2013

Chart no. 4832

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres. 47°33′26.4″N 055°19′55.8″W
(See Chart No. 1, L25) *DFO(6307179-04)*
This notice affects Electronic Navigational Chart: CA376233

29-MAR-2013 LNM/D. 02-NOV-2012

Add marine farm 47°33′18.0″N 055°23′28.4″W
(See Chart No. 1, K48.2)
DFO(6306337-01)

02-NOV-2012 LNM/D. 22-JUN-2012

Add marine farm 47°29′53.0″N 055°42′16.0″W
(See Chart No. 1, K48.2)
DFO(6306220-01)

22-JUN-2012 LNM/D. 28-OCT-2011

Add marine farm 47°32′19.0″N 055°45′13.0″W
(See Chart No. 1, K48.2)
DFO(6306046-01)

22-JUN-2012 LNM/D. 28-OCT-2011

Add marine farm 47°33′38.0″N 055°44′50.0″W
(See Chart No. 1, K48.2)
DFO(6306046-02)

28-OCT-2011 LNM/D. 29-OCT-2010

Delete red and white fairway lighted pillar bell buoy Mo(A) 6s, BELL, marked VFD 47°15′17.4″N 055°23′17.5″W
(See Chart No. 1, Qh) *(N2011070) LL(111.9) DFO(6305760-01)*

28-OCT-2011 LNM/D. 29-OCT-2010

Add red and white fairway lighted pillar bell buoy Mo(A), BELL, marked VFD 47°15′14.5″N 055°22′20.2″W
(See Chart No. 1, Qh) *(N2011079) LL(111.9) DFO(6305760-02)*

28-OCT-2011 LNM/D. 29-OCT-2010

Chart no. 4832

Add yellow, black and yellow West cardinal lighted pillar buoy Q(9) 15s, marked VC — 47°12′49.8″N 055°28′06.0″W
(See Chart No. 1, Q130.3) *(N2011071) LL(111.095) DFO(6305761-01)*

28-OCT-2011 LNM/D. 29-OCT-2010

Add yellow, black and yellow West cardinal lighted pillar buoy Q(9) 15s, marked VF — 47°18′22.2″N 055°18′55.2″W
(See Chart No. 1, Q130.3) *(N2011072) LL(112.5) DFO(6305762-01)*

28-OCT-2011 LNM/D. 29-OCT-2010

Add yellow and black South cardinal lighted pillar buoy Q(6)+LFl 15s, marked VW — 47°31′01.4″N 055°35′42.6″W
(See Chart No. 1, Q130.3) *(N2011074) LL(122.6) DFO(6305764-01)*

29-OCT-2010 LNM/D. 24-SEP-2010

Add wharf between 47°31′36.5″N 055°24′33.9″W
(See Chart No. 1 F13) and 47°31′34.8″N 055°24′33.6″W

DFO(6305015-01)

29-OCT-2010 LNM/D. 24-SEP-2010

Add wharf between 47°31′36.5″N 055°24′33.9″W
(See Chart No. 1 F13) and 47°31′35.6″N 055°24′31.3″W

DFO(6305015-02)

29-OCT-2010 LNM/D. 24-SEP-2010

Add light Fl G 47°31′34.8″N 055°24′33.6″W
(See Chart No. 1 P1)

(N2010043) LL(116.9) DFO(6305015-03)

24-SEP-2010 LNM/D. 22-MAY-2009

Add foul area dangerous to surface navigation 47°31′52.0″N 055°38′58.0″W
(See Chart No. 1 Kc)

DFO(6305017-01)

Chart no. 4832

22-MAY-2009 LNM/D. 30-JAN-2009

Amend Adjoining Chart/Carte adjacente 4016 to read Adjoining Chart/Carte adjacente 4827 — upper west border of the chart
(See Chart No 1 A20)

DFO(6304355-01)

30-JAN-2009 LNM/D. 17-OCT-2008

Add submarine cable joining 47°28′52.4″N 055°47′53.8″W
(See Chart No 1 L30.1) 47°29′15.2″N 055°47′23.0″W
47°29′15.1″N 055°47′10.1″W
47°29′07.6″N 055°46′56.5″W
47°28′59.7″N 055°46′52.6″W
47°27′45.4″N 055°47′12.6″W
and 47°24′00.5″N 055°52′45.0″W

DFO(6304194-01)

30-JAN-2009 LNM/D. 17-OCT-2008

Add submarine cable joining 47°08′28.8″N 055°31′02.5″W
(See Chart No 1 L30.1) 47°08′44.3″N 055°30′49.1″W
47°09′01.3″N 055°30′46.8″W
47°19′58.1″N 055°39′05.5″W
47°23′34.3″N 055°42′02.6″W
47°23′53.3″N 055°42′37.0″W
47°24′28.1″N 055°44′42.7″W
47°25′01.4″N 055°48′03.0″W
47°25′47.4″N 055°49′09.5″W
47°26′04.4″N 055°49′09.6″W
47°26′35.1″N 055°48′48.4″W
47°27′42.7″N 055°47′06.0″W
47°28′59.0″N 055°46′49.5″W
47°29′09.3″N 055°46′53.6″W
47°29′18.6″N 055°47′09.1″W
47°29′16.9″N 055°47′24.5″W
and 47°28′52.4″N 055°47′54.0″W

DFO(6304194-02)

17-OCT-2008 LNM/D. 30-MAY-2008

Add light Fl(2) RWG 47°06′04.7″N 055°45′02.8″W
(See Chart No 1 P1)

(N2005019) LL(106.5) DFO(6304125-02)

30-MAY-2008 LNM/D. 02-NOV-2007

Chart no. 4832

Replace green port hand lighted pillar bell buoy FlG, marked VF1 with a green port hand lighted can buoy FlG, marked VF1 (See Chart No 1 Qg) — 47°04′39.9″N 055°49′31.0″W — *LL(103) DFO(6303886-01)*

02-NOV-2007 — LNM/D. 07-OCT-2005

(T)Add subsurface mooring at a depth of 1 metre 5 decimetres (5 feet) The mooring is temporary and will be removed by July 2008. The mooring has been removed. Notice 02-NOV-2007(T), DFO (6303670) is cancelled. Cancelled on 20-FEB-09 — 47°15′18.4″N 055°22′14.3″W — *DFO(6303670-04)*

07-OCT-2005 — LNM/D. 03-JUN-2005

Add breakwater between 47°27′05.0″N 055°33′34.0″W and 47°27′05.2″N 055°33′28.2″W

DFO(6302416-01)

07-OCT-2005 — LNM/D. 03-JUN-2005

Reposition light FlG from 47°27′06.5″N 055°33′30.8″W to 47°27′05.2″N 055°33′28.2″W

(N2005039) LL(119.5) DFO(6302416-02)

03-JUN-2005 — LNM/D. 10-DEC-2004

Delete green port hand spar light buoy FlG, marked VFG1 — 47°14′22.0″N 055°21′47.0″W

LL(111.94) DFO(6302218-01)

03-JUN-2005 — LNM/D. 10-DEC-2004

Add legend ″Channel Buoyed/Chenal balisé″ — 47°14′30.0″N 055°22′00.0″W

(N2005003) LL(111.94) DFO(6302218-02)

10-DEC-2004 — LNM/D. 28-MAY-2004

Add abandoned submarine cable joining 47°12′12.7″N 055°52′44.6″W 47°13′25.8″N 055°44′34.8″W and 47°15′51.7″N 055°39′35.3″W

DFO(6302050-01)

Chart no. 4832

28-MAY-2004 LNM/D. 07-MAY-2004

Amend ″FlR 3s 8m 6M″ to read ″QR 1s 8m 6M″ against light 47°14′09.0″N 055°21′30.8″W

(N2004039) LL(112) DFO(6301420-01)

07-MAY-2004 LNM/D. 30-APR-2004

Delete light with legend 2 Lts Fl R 47°06′09.2″N 055°44′53.2″W

LL(108) DFO(6301415-01)

30-APR-2004 LNM/D. 16-APR-2004

Add green port hand spar light buoy FlG, marked VG1 47°06′11.9″N 055°44′13.4″W

(N2002077) LL(111.09) DFO(6301248-01)

16-APR-2004 LNM/D. 26-DEC-2003

Amend Fl to read Fl R 4s 14m 5M against light 47°27′18.0″N 055°29′33.0″W

(N2002103) LL(119) DFO(6300521-01)

26-DEC-2003 LNM/D. 07-NOV-2003

Delete red and white fairway pillar light buoy Mo (A), BELL, marked VG 47°06′27.0″N 055°44′00.0″W

(N2002082) LL(111) DFO(6300471-01)

26-DEC-2003 LNM/D. 07-NOV-2003

Delete front range light and legend 2 Lts F G 47°06′03.7″N 055°45′03.7″W

(N2002120) LL(109) DFO(6300544-01)

26-DEC-2003 LNM/D. 07-NOV-2003

Delete leading line and legend ″244½°″ 47°06′03.7″N 055°45′03.7″W

(N2002120) LL(109) DFO(6300544-02)

26-DEC-2003 LNM/D. 07-NOV-2003

Chart no. 4832

Delete rear range light 47°06′02.0″N 055°45′08.4″W

(N2002121) LL(110) DFO(6300544-03)

26-DEC-2003 LNM/D. 07-NOV-2003

Amend Fl R 3s 17m to read Fl 3s 17m 47°24′13.8″N 055°35′02.5″W

LL(120) DFO(6300972-01)

26-DEC-2003 LNM/D. 07-NOV-2003

Add breakwater between 47°06′09.0″N 055°44′53.5″W
and 47°06′07.0″N 055°44′52.0″W

(N2001065) DFO(6301004-02)

26-DEC-2003 LNM/D. 07-NOV-2003

Delete light FIR 47°06′09.2″N 055°45′53.2″W

(N2001065) LL(108) DFO(6301004-03)

26-DEC-2003 LNM/D. 07-NOV-2003

Add light FIR 47°06′07.9″N 055°44′52.5″W

(N2001065) LL(108) DFO(6301004-05)

11-APR-2003 LNM/D. 04-APR-2003

Delete green, port hand can buoy, marked VE1 47°27′31.0″N 055°29′44.0″W

(N2000260) DFO(6829120-01)

11-APR-2003 LNM/D. 04-APR-2003

Add green port hand spar light buoy FlG, marked VE1 47°27′29.0″N 055°29′41.7″W

(N2000260) LL(116.410) DFO(6829120-02)

26-JUL-2002 LNM/D. 19-JUL-2002

Delete fog signal and beacon 47°21′59.9″N 055°47′45.0″W
With this notification, Notice (619(T)/93) is cancelled. See reference DFO(6005455) appearing in this edition. *LL(127.000) DFO(6300236-01)*

Chart no. 4832

19-JUL-2002 LNM/D. 15-MAR-2002

(T)Add green, port hand spar buoy, marked VFG3 47°14′17.0″N 055°21′48.0″W

Buoy permanently established. Notice DFO 6300004-01 advertised in the July, 2002 issue of the Notice to Mariners monthly publication is now cancelled. See reference DFO(6302218-02) appearing in this edition.
Cancelled on 03-JUN-05 *(N2001087T) DFO(6300004-01)*

19-JUL-2002 LNM/D. 15-MAR-2002

(T)Add green, port hand spar buoy, marked VFG5 47°14′15.0″N 055°21′48.0″W

Buoy permanently established. Notice DFO 6300005-01 advertised in the July, 2002 issue of the Notice to Mariners monthly publication is now cancelled. See reference DFO(6302218-02) appearing in this edition.
Cancelled on 03-JUN-05 *(N2001088T) DFO(6300005-01)*

19-JUL-2002 LNM/D. 15-MAR-2002

Add green port hand spar light buoy FlG, marked VFG1 47°14′22.0″N 055°21′47.0″W

(N2001086) LL(111.94) DFO(6829643-01)

15-MAR-2002 LNM/D. 25-JAN-2002

Add light FIG 47°27′28.0″N 055°37′26.0″W

(N2001085) LL(121.3) DFO(6829642-01)

25-JAN-2002 LNM/D. 18-MAY-2001

Amend FI R 6s 14m to read Fl 47°27′18.0″N 055°29′34.0″W

(N2000037) LL(119) DFO(6828798-01)

25-JAN-2002 LNM/D. 18-MAY-2001

Add light FIG 47°27′06.5″N 055°33′30.8″W

(N2000246) LL(119.5) DFO(6829093-01)

25-JAN-2002 LNM/D. 18-MAY-2001

Chart no. 4832

Delete anchorage symbol 47°28′36.0″N 055°28′17.7″W

DFO(6829829-01)

18-MAY-2001 LNM/D. 11-MAY-2001

Add red light, starboard hand pillar bell buoy FlR, marked VS2 47°26′57.5″N 055°40′02.5″W

(N1999-097) LL(123.000) DFO(6829438-01)

11-MAY-2001 LNM/D. 19-FEB-1999

Replace green port hand spar buoy, marked VFC1, with green light, port hand spar buoy Fl G, marked VFC1 47°13′36.0″N 055°25′06.0″W

(N2000-079) LL(111.1) DFO(6828843-01)

11-MAY-2001 LNM/D. 19-FEB-1999

Replace red starboard hand spar buoy, marked VFC2 with red light, starboard hand spar buoy Fl R, marked VFC2 47°13′42.0″N 055°24′00.0″W

(N2000-080) LL(111.2) DFO(6828844-01)

11-MAY-2001 LNM/D. 19-FEB-1999

Delete green, red, green port bifurcation pillar light buoy, FL (2+1) G, marked VBL 47°29′13.0″N 055°22′43.0″W

(N2000-213) LL(117.5) DFO(6829032-01)

11-MAY-2001 LNM/D. 19-FEB-1999

Delete red and white fairway pillar, light buoy Mo (A), marked VSJ 47°27′36.0″N 055°26′00.0″W

(N2000-214) LL(118.5) DFO(6829033-01)

11-MAY-2001 LNM/D. 19-FEB-1999

Add light, Fl G 47°14′08.2″N 055°21′27.5″W

(N1999-118) LL(112.100) DFO(6829426-01)

11-MAY-2001 LNM/D. 19-FEB-1999

Chart no. 4832

Add green light, port hand spar buoy FlG, marked VW3 — 47°29′59.9″N 055°36′43.1″W

(N1999-098) LL(122.500) DFO(6829437-01)

4832 - Fortune Harbour - New Chart - 02-OCT-1987 - NAD 1983

22-NOV-2019 — LNM/D. 01-NOV-2019

Amend VF2 to read VF4 against buoy marked VF2 — 47°04′22.0″N 055°49′52.1″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA576235 — *(N2019063) LL(105.1) DFO(6308775-01)*

22-NOV-2019 — LNM/D. 01-NOV-2019

Amend VF4 to read VF2 against buoy marked VF4 — 47°04′24.9″N 055°49′52.1″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA576235 — *(N2019064) LL(105.2) DFO(6308776-01)*

22-NOV-2019 — LNM/D. 01-NOV-2019

Replace green port hand can light buoy FlG , marked VF1 with green port hand spar light buoy Fl G, marked VF1 — 47°04′39.7″N 055°49′31.3″W
(N2019066) LL(103) DFO(6308780-01)
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA376233, CA576235

05-FEB-2016 — LNM/D. 07-AUG-2015

Replace depth of 6 metres, 1 decimetres with depth of 5 metres, 2 decimetres — 47°04′36.9″N 055°49′38.2″W
(See Chart No. 1, I10) — *DFO(6307396-01)*
This notice affects Electronic Navigational Chart: CA576235

05-FEB-2016 — LNM/D. 07-AUG-2015

Replace depth of 5 metres, 8 decimetres with depth of 4 metres, 5 decimetres — 47°04′34.7″N 055°49′39.1″W
(See Chart No. 1, I10) — *DFO(6307396-02)*
This notice affects Electronic Navigational Chart: CA576235

05-FEB-2016 — LNM/D. 07-AUG-2015

Chart no. 4832

Replace depth of 5 metres, 2 decimetres with depth of 4 metres, 8 decimetres 47°04′34.5″N 055°49′42.3″W
(See Chart No. 1, I10) *DFO(6307396-03)*
This notice affects Electronic Navigational Chart: CA576235

05-FEB-2016 LNM/D. 07-AUG-2015

Replace depth of 5 metres, 6 decimetres with depth of 5 metres 47°04′32.7″N 055°49′42.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576235 *DFO(6307396-04)*

05-FEB-2016 LNM/D. 07-AUG-2015

Replace depth of 7 metres with depth of 6 metres, 2 decimetres 47°04′27.6″N 055°49′49.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576235 *DFO(6307396-05)*

05-FEB-2016 LNM/D. 07-AUG-2015

Replace depth of 5 metres, 5 decimetres with depth of 4 metres, 6 decimetres 47°04′21.9″N 055°49′51.3″W
(See Chart No. 1, I10) *DFO(6307396-06)*
This notice affects Electronic Navigational Chart: CA576235

30-MAY-2008 LNM/D. 02-NOV-2007

Amend FlG to read FlR against light 47°04′18.4″N 055°49′50.0″W
(See Chart No 1 P16)
LL(103.3) DFO(6303875-01)

30-MAY-2008 LNM/D. 02-NOV-2007

Delete depth of 6 metres, 6 decimetres 47°04′34.9″N 055°49′40.9″W
(See Chart No. 1, I10)
DFO(6303885-01)

30-MAY-2008 LNM/D. 02-NOV-2007

Delete depth of 6 metres, 2 decimetres 47°04′34.0″N 055°49′43.1″W
(See Chart No. 1, I10)
DFO(6303885-02)

30-MAY-2008 LNM/D. 02-NOV-2007

Chart no. 4832

Delete depth of 5 metres, 6 decimetres 47°04′34.3″N 055°49′41.8″W
(See Chart No. 1, I10)

DFO(6303885-03)

30-MAY-2008 LNM/D. 02-NOV-2007

Add depth of 5 metres, 2 decimetres 47°04′34.5″N 055°49′42.2″W
(See Chart No. 1, I10)

DFO(6303885-04)

30-MAY-2008 LNM/D. 02-NOV-2007

Add depth of 5 metres 47°04′34.0″N 055°49′41.5″W
(See Chart No. 1, I10)

DFO(6303885-05)

30-MAY-2008 LNM/D. 02-NOV-2007

Delete depth of 5 metres, 8 decimetres 47°04′30.3″N 055°49′46.4″W
(See Chart No. 1, I10)

DFO(6303885-06)

30-MAY-2008 LNM/D. 02-NOV-2007

Add depth of 4 metres, 2 decimetres 47°04′30.1″N 055°49′46.4″W
(See Chart No. 1, I10)

DFO(6303885-07)

30-MAY-2008 LNM/D. 02-NOV-2007

Replace green port hand lighted pillar bell buoy FlG, marked VF1 with 47°04′39.9″N 055°49′31.0″W
a green port hand lighted can buoy FlG, marked VF1

LL(103) DFO(6303886-01)

30-MAY-2008 LNM/D. 02-NOV-2007

Delete depth of 3 metres, 8 decimetres 47°04′19.3″N 055°49′51.3″W
(See Chart No. 1, I10)

(N2001134) LL(105.3) DFO(6829770-01)

30-MAY-2008 LNM/D. 02-NOV-2007

Add floating dock between 47°04′19.1″N 055°49′51.3″W
(See Chart No 1 F16) and 47°04′19.5″N 055°49′51.0″W

DFO(6829770-02)

Chart no. 4832

30-MAY-2008 LNM/D. 02-NOV-2007

Add light FlR 47°04′19.5″N 055°49′51.0″W
(See Chart No 1 P1)

(N2001134) LL(105.3) DFO(6829770-03)

30-MAY-2008 LNM/D. 02-NOV-2007

Add depth of 3 metres, 7 decimetres 47°04′19.4″N 055°49′51.4″W
(See Chart No. 1, I10)

DFO(6829770-04)

07-NOV-2003 LNM/D. 18-APR-2003

Add red starboard hand spar light buoy FlR, marked VF2 47°04′22.0″N 055°49′52.0″W

(N2002078) LL(105.1) DFO(6300456-01)

07-NOV-2003 LNM/D. 18-APR-2003

Add red starboard hand spar light buoy FlR, marked VF4 47°04′25.0″N 055°49′52.0″W

(N2002079) LL(105.2) DFO(6300457-01)

18-APR-2003 LNM/D. 11-APR-2003

Add breakwater with loose boulders joining 47°04′15.1″N 055°49′54.3″W
47°04′18.3″N 055°49′53.0″W
47°04′18.5″N 055°49′52.6″W
47°04′18.3″N 055°49′52.3″W
and 47°04′15.4″N 055°49′53.6″W

(N2000209) LL(103.3) DFO(6829027-01)

18-APR-2003 LNM/D. 11-APR-2003

Add floating dock between 47°04′15.4″N 055°49′53.6″W
and 47°04′19.1″N 055°49′51.3″W

DFO(6829027-02)

18-APR-2003 LNM/D. 11-APR-2003

Add floating dock between 47°04′16.8″N 055°49′52.7″W
and 47°04′16.4″N 055°49′51.2″W

DFO(6829027-03)

Chart no. 4832

18-APR-2003 LNM/D. 11-APR-2003
Add floating dock between 47°04′17.8″N 055°49′52.1″W
and 47°04′17.4″N 055°49′50.6″W

DFO(6829027-04)

18-APR-2003 LNM/D. 11-APR-2003
Add floating dock between 47°04′18.8″N 055°49′51.5″W
and 47°04′18.4″N 055°49′50.0″W

DFO(6829027-05)

18-APR-2003 LNM/D. 11-APR-2003
Add light FIR 47°04′18.4″N 055°49′50.0″W

(N2000209) LL(103.3) DFO(6829027-06)

18-APR-2003 LNM/D. 11-APR-2003
Delete depth of 1 metre 47°04′17.7″N 055°49′51.3″W

DFO(6829027-07)

18-APR-2003 LNM/D. 11-APR-2003
Delete drying height of 0 metre, 4 decimetres 47°04′16.2″N 055°49′51.8″W

DFO(6829027-08)

18-APR-2003 LNM/D. 11-APR-2003
Add depth of 1 metre, 5 decimetres 47°04′17.3″N 055°49′51.4″W

DFO(6829027-09)

18-APR-2003 LNM/D. 11-APR-2003
Add depth of 1 metre, 8 decimetres 47°04′16.3″N 055°49′51.7″W

DFO(6829027-10)

04-APR-2003 LNM/D. 24-JAN-2003

Chart no. 4832

Add depth of 5 metres, 4 decimetres 47°04′36.1″N 055°49′39.0″W

DFO(6300826-01)

04-APR-2003 LNM/D. 24-JAN-2003
Add depth of 5 metres, 6 decimetres 47°04′34.3″N 055°49′41.8″W

DFO(6300826-02)

04-APR-2003 LNM/D. 24-JAN-2003
Add depth of 4 metres, 3 decimetres 47°04′31.8″N 055°49′43.9″W

DFO(6300826-03)

04-APR-2003 LNM/D. 24-JAN-2003
Add depth of 4 metres, 8 decimetres 47°04′27.4″N 055°49′45.4″W

DFO(6300826-04)

04-APR-2003 LNM/D. 24-JAN-2003
Add depth of 1 metre, 3 decimetres 47°04′27.5″N 055°49′40.8″W

DFO(6300826-05)

04-APR-2003 LNM/D. 24-JAN-2003
Add depth of 5 metres, 3 decimetres 47°04′27.3″N 055°49′46.2″W

DFO(6300826-06)

04-APR-2003 LNM/D. 24-JAN-2003
Add depth of 4 metres, 6 decimetres 47°04′26.0″N 055°49′48.1″W

DFO(6300826-07)

04-APR-2003 LNM/D. 24-JAN-2003
Delete depth of 3 metres, 5 decimetres 47°04′27.5″N 055°49′41.2″W

DFO(6300826-08)

Chart no. 4832

11-MAY-2001 LNM/D. 19-FEB-1999
Add light, Fl G 47°04′21.3″N 055°49′49.3″W

(N2000210) LL(103.4) DFO(6829028-01)

4832 - Grand Bank Harbour - New Chart - 02-OCT-1987 - NAD 1983

17-OCT-2008 LNM/D. 30-MAY-2008
Affix patch 47°06′04.0″N 055°45′00.0″W

(N2005019) LL(106.5) DFO(6304125-01)
PDF

17-OCT-2008 LNM/D. 30-MAY-2008
Amend FRWG to read Fl(2) RWG against light 47°06′04.7″N 055°45′02.8″W
(See Chart No 1 P16)
This action updates the Grand Bank sector light appearing on the patch. *LL(106.5) DFO(6304125-03)*

07-MAY-2004 LNM/D. 30-APR-2004
Delete light Fl R 47°06′09.2″N 055°44′53.2″W

LL(108) DFO(6301415-01)

26-DEC-2003 LNM/D. 07-NOV-2003
Delete front range light F G 10m 47°06′03.7″N 055°45′03.7″W

(N2002120) LL(109) DFO(6300544-01)

26-DEC-2003 LNM/D. 07-NOV-2003
Delete leading line and legend ″064½°″ ″244½°″ 47°06′03.7″N 055°45′03.7″W

(N2002120) LL(109) DFO(6300544-02)

26-DEC-2003 LNM/D. 07-NOV-2003
Delete rear range light and legend F G 15m 47°06′02.0″N 055°45′08.4″W

(N2002121) LL(110) DFO(6300544-03)

Chart no. 4832

26-DEC-2003 LNM/D. 07-NOV-2003

Add breakwater with loose boulders joining 47°06′09.5″N 055°44′53.1″W
47°06′07.9″N 055°44′52.2″W
47°06′07.7″N 055°44′52.3″W
47°06′07.8″N 055°44′52.7″W
and 47°06′08.6″N 055°44′53.6″W

(N2001065) DFO(6301004-02)

26-DEC-2003 LNM/D. 07-NOV-2003

Delete light FIR 47°06′09.2″N 055°45′53.2″W

(N2001065) LL(108) DFO(6301004-03)

26-DEC-2003 LNM/D. 07-NOV-2003

Add light Fl R 47°06′07.9″N 055°44′52.5″W

(N2001065) LL(108) DFO(6301004-05)

26-DEC-2003 LNM/D. 07-NOV-2003

Add floating dock between 47°05′55.8″N 055°45′04.2″W
and 47°05′57.5″N 055°45′02.9″W

(N2000356) DFO(6829240-01)

26-DEC-2003 LNM/D. 07-NOV-2003

Add light FI G 47°05′57.4″N 055°45′02.9″W

(N2000356) LL(106.51) DFO(6829240-02)

11-APR-2003 LNM/D. 04-APR-2003

Amend Fl to read QG against the light 47°06′04.8″N 055°44′57.8″W

(N2001138) LL(106.000) DFO(6829774-01)

24-JAN-2003 LNM/D. 26-JUL-2002

Amend FlR to read QR against light 47°06′06.6″N 055°44′57.2″W

(N2002039) LL(107) DFO(6300282-01)

Fisheries and Oceans Canada | Pêches et Océans Canada
Canadian Coast Guard | Garde côtière canadienne

Chart no. 4832