Chart no. 4849

4849 - Bonavista Harbour - New Chart - 30-DEC-1988 - NAD 1983

11-JAN-2019 LNM/D. 29-JUN-2018

Affix patch 48°38′56.0″N 053°06′48.0″W
PDF
This notice affects Electronic Navigational Chart: CA576310 *DFO(6308542-01)*

29-JUN-2018 LNM/D. 12-MAY-2017

Affix patch 48°39′00.0″N 053°07′00.0″W
PDF
This notice affects Electronic Navigational Chart: CA576310 *DFO(6308316-01)*

24-MAR-2017 LNM/D. 28-OCT-2016

Delete light Fl 48°39′06.1″N 053°07′42.6″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376340, CA576310 *(N2016083P) LL(446) DFO(6307807-01)*

24-JUL-2015 LNM/D. 27-MAR-2015

Affix patch 48°39′00.0″N 053°06′50.0″W
PDF
This notice affects Electronic Navigational Chart: CA576310 *DFO(6307176-01)*

10-FEB-2012 LNM/D. 04-JUN-2010

Delete green port hand lighted spar buoy FlG, marked JB7 48°39′00.1″N 053°07′54.8″W
(See Chart No. 1, Qg)
LL(445.4) DFO(6305912-01)

10-FEB-2012 LNM/D. 04-JUN-2010

Add green port hand lighted spar buoy FlG, marked JB7 48°39′00.1″N 053°07′11.6″W
(See Chart No. 1, Qg)
LL(445.4) DFO(6305912-02)

03-OCT-2008 LNM/D. 28-DEC-2007

Delete green port hand lighted spar buoy FlG, marked JB3 48°39′02.5″N 053°07′54.8″W
(See Chart No 1 Qg) *(N2008008) LL(445.2) DFO(6303961-01)*

Chart no. 4849

03-OCT-2008 LNM/D. 28-DEC-2007

Add green port hand lighted pillar buoy FlG, marked JB5 48°39′02.5″N 053°07′54.8″W

(N2008007) LL(446.1) DFO(6303961-02)

19-OCT-2007 LNM/D. 01-JUN-2007

Add breakwater extension and legend Breakwater/Brise-lames joining 48°38′57.5″N 053°07′06.0″W
(See Chart No 1 Section F 4.3.) 48°38′58.2″N 053°07′06.3″W
48°38′58.3″N 053°07′05.8″W
and 48°38′57.7″N 053°07′05.6″W

DFO(6303605-01)

19-OCT-2007 LNM/D. 01-JUN-2007

Delete light QR 48°38′57.5″N 053°07′06.0″W
(See Chart No 1 Section P 16.)

(N2005105) LL(447) DFO(6303605-02)

19-OCT-2007 LNM/D. 01-JUN-2007

Add light QR 48°38′58.1″N 053°07′06.2″W
(See Chart No 1 Section P 16.)

(N2005105) LL(447) DFO(6303605-03)

19-OCT-2007 LNM/D. 01-JUN-2007

Delete depth of 4 metres, 6 decimetres 48°38′58.2″N 053°07′05.9″W
(See Chart No 1 Section I 10.)

DFO(6303605-04)

01-JUN-2007 LNM/D. 01-SEP-2006

Delete light QR 48°38′57.2″N 053°07′04.5″W

(N2005105) LL(447) DFO(6302708-01)

01-JUN-2007 LNM/D. 01-SEP-2006

Add light QR 48°38′57.5″N 053°07′06.0″W

(N2005105) LL(447) DFO(6302708-02)

01-SEP-2006 LNM/D. 11-AUG-2006

Chart no. 4849

Delete red starboard hand lighted spar buoy FlR, marked JB8 — 48°38′55.5″N 053°06′56.7″W

(N2006093) LL(447.2) DFO(6303002-01)

01-SEP-2006 — LNM/D. 11-AUG-2006

Add green port hand lighted spar buoy FlG, marked JB7 — 48°39′00.1″N 053°07′54.8″W

(N2006102) LL(445.4) DFO(6303013-01)

01-SEP-2006 — LNM/D. 11-AUG-2006

Add green port hand lighted spar buoy FlG, marked JB3 — 48°39′02.5″N 053°07′54.8″W

(N2006103) LL(445.2) DFO(6303014-01)

01-SEP-2006 — LNM/D. 11-AUG-2006

Reposition red starboard hand lighted spar buoy FlR, marked JB6 — from 48°38′56.0″N 053°06′59.5″W to 48°38′55.9″N 053°06′58.2″W

(N2006105) LL(447.1) DFO(6303017-01)

03-JUN-2005 — LNM/D. 28-JAN-2005

Add floating dock — between 48°39′01.0″N 053°06′53.8″W and 48°38′59.7″N 053°06′53.2″W

(N2000371) LL(448.1) DFO(6829260-01)

03-JUN-2005 — LNM/D. 28-JAN-2005

Add light FlG — 48°38′59.7″N 053°06′53.2″W

(N2000371) LL(448.1) DFO(6829260-02)

10-OCT-2003 — LNM/D. 20-JUN-2003

Delete red and white fairway pillar, light and whistle buoy Mo (A), WHIS, marked JB — 48°38′49.8″N 053°08′33.5″W

(N2002060) LL(445) DFO(6300418-01)

25-JAN-2002 — LNM/D. 30-MAR-2001

Chart no. 4849

Amend FG to read FIG 48°39′00.8″N 053°06′50.5″W

(N2000062) LL(448) DFO(6828822-01)

25-JAN-2002 LNM/D. 30-MAR-2001

Replace red starboard hand spar buoy, marked JB6, with red light, starboard hand spar buoy FlR, marked JB6 48°38′56.0″N 053°06′59.5″W

(N2000271) LL(447.1) DFO(6829131-01)

25-JAN-2002 LNM/D. 30-MAR-2001

Replace red starboard hand spar buoy, marked JB8, with red light, starboard hand spar buoy FlR, marked JB8 48°38′55.5″N 053°06′56.7″W

(N2000272) LL(447.2) DFO(6829132-01)

4849 - Catalina and / et Port Union - New Chart - 30-DEC-1988 - NAD 1983

24-DEC-2021 LNM/D. 26-APR-2019

Delete light FlR 48°30′40.3″N 053°04′03.5″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA576394

(N2021229) LL(458) DFO(6309876-01)

04-JUN-2010 LNM/D. 08-MAY-2009

Reposition red starboard hand lighted pillar buoy FlR, marked TC2 from 48°30′13.7″N 053°01′26.6″W to 48°30′12.9″N 053°01′26.5″W
(See Chart No 1 Qf)

(N2010016) LL(452) DFO(6304837-01)

19-DEC-2003 LNM/D. 10-OCT-2003

Amend Fl (3) 12s 28m 18M to read Fl 4s 28m 16M against light 48°30′14.8″N 053°02′37.4″W

(N2003039) LL(453) DFO(6301008-01)

20-JUN-2003 LNM/D. 13-JUN-2003

Chart no. 4849

Replace red starboard hand pillar light buoy FlR, WHIS, marked TC2 with red starboard hand pillar light buoy FlR, marked TC2 — 48°30′14.0″N 053°01′26.3″W
(N2002049) LL(452) DFO(6300408-01)

25-JAN-2002 — LNM/D. 30-MAR-2001

Replace red starboard hand spar buoy, marked TC6 with red light, starboard hand spar buoy FlR, marked TC6 — 48°30′41.0″N 053°04′16.4″W
(N2000273) LL(458.81) DFO(6829133-01)

4849 - Catalina Harbour - New Chart - 30-DEC-1988 - NAD 1983

24-DEC-2021 — LNM/D. 26-APR-2019

Delete light Fl R — 48°30′40.2″N 053°04′03.1″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA576394
(N2021229) LL(458) DFO(6309876-01)

26-APR-2019 — LNM/D. 11-JAN-2019

Affix patch — 48°31′00.0″N 053°04′30.0″W
PDF
This notice affects Electronic Navigational Chart: CA576394
DFO(6308617-01)

27-MAR-2015 — LNM/D. 10-FEB-2012

Amend FlG to read QG against green port hand pillar light buoy, marked TC11 — 48°30′51.1″N 053°04′18.1″W
(See Chart No. 1, Qg)
(N2015011) LL(460) DFO(6307070-01)

This notice affects Electronic Navigational Chart: CA576395

11-AUG-2006 — LNM/D. 26-MAY-2006

Amend ″FR″ to read ″FlR″ against light — 48°30′55.3″N 053°04′30.1″W

(N2006020) LL(461) DFO(6302910-01)

28-JAN-2005 — LNM/D. 19-DEC-2003

Chart no. 4849

Delete light FR 48°30′54.8″N 053°04′32.5″W

(N2004200) LL(461) DFO(6302129-01)

28-JAN-2005 LNM/D. 19-DEC-2003

Delete depth of 4 metres, 9 decimetres 48°30′54.8″N 053°04′32.1″W

DFO(6302129-02)

28-JAN-2005 LNM/D. 19-DEC-2003

Add wharf extension joining 48°30′54.7″N 053°04′32.5″W
(See Chart No 1 F14) 48°30′55.2″N 053°04′30.0″W
48°30′55.4″N 053°04′30.1″W
and 48°30′55.0″N 053°04′32.6″W

DFO(6302129-03)

28-JAN-2005 LNM/D. 19-DEC-2003

Add light FR 48°30′55.3″N 053°04′30.1″W

(N2004200) LL(461) DFO(6302129-04)

28-JAN-2005 LNM/D. 19-DEC-2003

Add depth of 3 metres, 7 decimetres 48°30′55.2″N 053°04′32.3″W

DFO(6302129-05)

28-JAN-2005 LNM/D. 19-DEC-2003

Add depth of 3 metres, 9 decimetres 48°30′55.3″N 053°04′30.0″W

DFO(6302129-06)

28-JAN-2005 LNM/D. 19-DEC-2003

Add depth of 4 metres, 2 decimetres 48°30′54.8″N 053°04′31.1″W

DFO(6302129-07)

07-JUN-2002 LNM/D. 25-JAN-2002

Chart no. 4849

Replace red, starboard hand spar buoy, marked TC10 with red starboard hand spar light buoy FlR, marked TC10 — 48°30′51.0″N 053°04′14.8″W
(N2001012) LL(459.1) DFO(6300280-01)

25-JAN-2002 — LNM/D. 30-MAR-2001

Replace red starboard hand spar buoy, marked TC6 with red light, starboard hand spar buoy FlR, marked TC6 — 48°30′41.0″N 053°04′16.4″W
(N2000273) LL(458.81) DFO(6829133-01)

4849 - Fish Plant / Conserverie de poisson - New Chart - 30-DEC-1988 - NAD 1983

09-SEP-2022 — LNM/D. 24-DEC-2021

Add depth of 1 metre — 47°41′21.9″N 053°13′16.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576398 *DFO(6310229-01)*

09-SEP-2022 — LNM/D. 24-DEC-2021

Add depth of 1.6 metres — 47°41′27.1″N 053°13′03.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576398 *DFO(6310229-02)*

09-SEP-2022 — LNM/D. 24-DEC-2021

Add depth of 0.6 metres — 47°41′27.1″N 053°13′01.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576398 *DFO(6310229-03)*

09-SEP-2022 — LNM/D. 24-DEC-2021

Delete depth of 1.4 metres — 47°41′26.8″N 053°13′00.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576398 *DFO(6310229-04)*

09-SEP-2022 — LNM/D. 24-DEC-2021

Add depth of 1 metre — 47°41′26.9″N 053°13′00.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576398 *DFO(6310229-05)*

Chart no. 4849

09-SEP-2022 LNM/D. 24-DEC-2021

Add depth of 5.5 metres 47°41′21.8″N 053°13′16.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576398 *DFO(6310229-06)*

09-SEP-2022 LNM/D. 24-DEC-2021

Delete depth of 5.8 metres 47°41′21.7″N 053°13′16.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576398 *DFO(6310229-07)*

09-SEP-2022 LNM/D. 24-DEC-2021

Add depth of 5.9 metres 47°41′22.3″N 053°13′12.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576398 *DFO(6310229-08)*

09-SEP-2022 LNM/D. 24-DEC-2021

Add depth of 3.6 metres 47°41′26.0″N 053°13′04.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576398 *DFO(6310229-09)*

09-SEP-2022 LNM/D. 24-DEC-2021

Delete depth of 4.2 metres 47°41′25.8″N 053°13′03.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576398 *DFO(6310229-10)*

09-SEP-2022 LNM/D. 24-DEC-2021

Add depth of 1.2 metres 47°41′27.6″N 053°13′01.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576398 *DFO(6310229-11)*

09-SEP-2022 LNM/D. 24-DEC-2021

Delete depth of 1.2 metres 47°41′27.3″N 053°13′01.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA576398 *DFO(6310229-12)*

13-JUN-2003 LNM/D. 23-MAY-2003

Chart no. 4849

Affix patch 47°42′30.0″N 053°18′30.0″W

DFO(6500109-01)

PDF

30-MAR-2001 LNM/D. 01-OCT-1999

(T)Delete light 47°41′24.6″N 053°12′52.8″W

The original light has been temporarily dismantled to facilitate new construction. A temporary light has been installed. Temporay light discontinued. Original light reconstructed. See reference DFO 6500109 appearing in Edition 6, 13-JUN-2003. With this notification, Notice dated 30-MAR-2001(T), DFO 6829425 is cancelled.
Cancelled on 22-AUG-03

(N2001-009(T)) LL(481.000) DFO(6829425-01)

30-MAR-2001 LNM/D. 01-OCT-1999

(T)Add light, Fl R 47°41′24.4″N 053°12′52.8″W

The original light has been temporarily dismantled to facilitate new construction. A temporary light has been installed.
Temporay light discontinued. Original light reconstructed. See reference DFO 6500109 appearing in Edition 6, 13-JUN-2003. With this notification, Notice dated 30-MAR-2001(T), DFO 6829425 is cancelled.
Cancelled on 18-JUL-03

(N2001-009(T)) DFO(6829425-02)

4849 - Harbour Grace and / et Carbonear - New Chart - 30-DEC-1988 - NAD 1983

12-MAY-2017 LNM/D. 24-MAR-2017

Add breakwater with legend Bkw joining 47°44′17.7″N 053°13′22.1″W
(See Chart No. 1, F4.1) 47°44′14.5″N 053°13′22.2″W
This notice affects Electronic Navigational Chart: CA376120, CA476405 and 47°44′13.0″N 053°13′23.6″W

DFO(6307708-01)

12-MAY-2017 LNM/D. 24-MAR-2017

Add light FlR 47°44′13.0″N 053°13′23.6″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376120, CA476405

(N2016054) LL(477.5) DFO(6307708-02)

Chart no. 4849

28-OCT-2016 LNM/D. 24-JUL-2015

Amend Fl R to read Fl Y against light 47°44′14.5″N 053°13′26.4″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA376120, CA476405, CA576416 *(N2016053) LL(478) DFO(6307707-01)*

26-MAY-2006 LNM/D. 03-JUN-2005

Delete depth of 7 metres 47°40′40.5″N 053°14′40.0″W

DFO(6302811-01)

26-MAY-2006 LNM/D. 03-JUN-2005

Add depth of 0 metres, 2 decimetres, with a bottom quality of Bo 47°40′41.4″N 053°14′40.1″W

DFO(6302811-02)

13-JUN-2003 LNM/D. 23-MAY-2003

Affix patch 47°41′18.0″N 063°13′00.0″W

DFO(6500109-02)

PDF

23-MAY-2003 LNM/D. 26-JUL-2002

Delete red and white fairway pillar light buoy Mo(A), WHIS, marked CC 47°45′00.0″N 053°09′25.5″W

(N2002048) LL(476) DFO(6300407-01)

26-JUL-2002 LNM/D. 07-JUN-2002

Delete light FR 47°40′52.3″N 053°14′22.2″W

(N2002004) LL(482.000) DFO(6300091-01)

30-MAR-2001 LNM/D. 01-OCT-1999

Chart no. 4849

(T)Delete light — 47°41′24.6″N 053°12′52.8″W

The original light has been temporarily dismantled to facilitate new construction. A temporary light has been installed.
Temporay light discontinued. Original light reconstructed. See reference DFO 6500109 appearing in Edition 6, 13-JUN-2003. With this notification, Notice dated 30-MAR-2001(T), DFO 6829425 is cancelled.
Cancelled on 22-AUG-03

(N2001-009(T)) LL(481.000) DFO(6829425-01)

30-MAR-2001 — LNM/D. 01-OCT-1999

(T)Add light, Fl R — 47°41′24.4″N 053°12′52.8″W

The original light has been temporarily dismantled to facilitate new construction. A temporary light has been installed.
Temporay light discontinued. Original light reconstructed. See reference DFO 6500109 appearing in Edition 6, 13-JUN-2003. With this notification, Notice dated 30-MAR-2001(T), DFO 6829425 is cancelled.
Cancelled on 18-JUL-03

(N2001-009(T)) DFO(6829425-02)

4849 - Port Union - New Chart - 30-DEC-1988 - NAD 1983

28-JAN-2005 — LNM/D. 19-DEC-2003

Delete yellow cautionary can buoy, marked Priv 48°30′10.0″N 053°04′36.8″W

DFO(6302206-01)

28-JAN-2005 — LNM/D. 19-DEC-2003

Delete yellow cautionary can buoy, marked Priv 48°30′11.3″N 053°04′44.0″W

DFO(6302206-02)

4849 - Public Wharf / Quai - New Chart - 30-DEC-1988 - NAD 1983

12-MAY-2017 — LNM/D. 24-MAR-2017

Affix patch — 47°44′16.0″N 053°13′25.0″W

PDF

This notice affects Electronic Navigational Chart: CA576416 *DFO(6307708-03)*

Chart no. 4849

28-OCT-2016 LNM/D. 24-JUL-2015

Amend Fl R to read Fl Y against light 47°44′14.5″N 053°13′26.4″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA376120, CA476405, CA576416 *(N2016053) LL(478) DFO(6307707-01)*

4849 - The Admiral's Marina - New Chart - 30-DEC-1988 - NAD 1983

29-JUN-2018 LNM/D. 12-MAY-2017

Affix patch 47°40′24.0″N 053°14′24.0″W
PDF
This notice affects Electronic Navigational Chart: CA576731 *DFO(6308316-02)*

08-MAY-2009 LNM/D. 03-OCT-2008

Delete light FlR 47°40′23.2″N 053°14′22.8″W
(See Chart No 1 P1)
(N2009004) LL(482.71) DFO(6304340-01)

08-MAY-2009 LNM/D. 03-OCT-2008

Add light FlR 47°40′23.3″N 053°14′23.0″W
(See Chart No 1 P1)
(N2009004) LL(482.71) DFO(6304340-02)

08-MAY-2009 LNM/D. 03-OCT-2008

Delete coastline between 47°40′22.3″N 053°14′25.2″W
(See Chart No. 1, C1) and 47°40′23.3″N 053°14′22.5″W

DFO(6304340-03)

08-MAY-2009 LNM/D. 03-OCT-2008

Add wharf extension joining 47°40′22.3″N 053°14′25.2″W
(See Chart No 1 F13) 47°40′23.3″N 053°14′22.9″W
and 47°40′23.2″N 053°14′22.8″W

DFO(6304340-04)

08-MAY-2009 LNM/D. 03-OCT-2008

Chart no. 4849

Add coastline between 47°40′23.2″N 053°14′22.8″W
(See Chart No. 1 C1) and 47°40′23.3″N 053°14′22.5″W

DFO(6304340-05)

08-MAY-2009 LNM/D. 03-OCT-2008

Delete depth of 0 metres, 8 decimetres 47°40′22.5″N 053°14′23.9″W
(See Chart No 1 I10)

DFO(6304340-06)

28-DEC-2007 LNM/D. 19-OCT-2007

Affix patch 47°40′24.0″N 053°14′27.0″W

(N2006117) LL(482.789) DFO(6303760-01)

PDF