Chart no. 8014

8014 - Grand Bank / Grand Banc: Northeast Portion / Partie nord-est - New Edition - 25-JUL-2003 - NAD 1983

19-MAR-2021 LNM/D. 15-MAR-2019

Add private yellow ODAS/SADO lighted pillar buoy Fl(5) Y 20s, Priv 47°14′12.0″N 050°57′00.0″W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA276101 *DFO(6309327-01)*

15-MAR-2019 LNM/D. 28-SEP-2018

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 55 fathoms 47°33′42.0″N 052°35′21.0″W
(See Chart No. 1, L25) *DFO(6308580-01)*
This notice affects Electronic Navigational Chart: CA376015

28-SEP-2018 LNM/D. 21-SEP-2018

Reposition private yellow ODAS/SADO lighted pillar Fl(5)Y 20s from 47°32′20.8″N 052°35′58.4″W
(See Chart No. 1, Q58) to 47°32′07.8″N 052°35′10.8″W

This notice affects Electronic Navigational Chart: CA276101 *DFO(6308451-01)*

28-SEP-2018 LNM/D. 21-SEP-2018

Add private yellow ODAS/SADO lighted pillar Fl(5)Y 20s 47°34′00.0″N 052°37′32.4″W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA276101, CA376015 *DFO(6308451-02)*

21-SEP-2018 LNM/D. 14-JUL-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 fathoms, 2 feet 47°32′14.5″N 052°35′08.0″W
(See Chart No. 1, L25) *DFO(6308414-02)*
This notice affects Electronic Navigational Chart: CA276101, CA376015

14-JUL-2017 LNM/D. 31-MAR-2017

Delete legend Fog Sig against light 47°48′30.5″N 052°47′11.5″W
(See Chart No. 1, R1)
(N2017008) LL(499) DFO(6307942-01)

This notice affects Electronic Navigational Chart: CA176030, CA276101, CA376015

Chart no. 8014

31-MAR-2017 LNM/D. 17-FEB-2017

Add submarine cable joining 47°37′51.0″N 052°39′38.0″W
(See Chart No. 1, L30.1) 47°38′29.0″N 052°38′13.0″W
This notice affects Electronic Navigational Chart: 47°25′36.0″N 052°06′12.0″W
CA276091, CA276101, CA376015, CA376070, CA376075 47°22′00.0″N 051°48′51.0″W
47°19′58.0″N 051°43′40.0″W
47°20′45.0″N 051°25′26.0″W
47°12′36.0″N 051°03′14.0″W
47°12′30.0″N 050°58′43.0″W
47°16′34.0″N 050°33′24.0″W
47°19′14.0″N 050°27′40.0″W
47°19′14.0″N 050°24′23.0″W
47°14′45.0″N 050°11′20.0″W
47°13′12.0″N 050°09′30.0″W
and 46°53′00.0″N 049°10′37.0″W

DFO(6307887-01)

31-MAR-2017 LNM/D. 17-FEB-2017

Add submarine cable joining 47°05′13.0″N 052°53′48.0″W
(See Chart No. 1, L30.1) 47°05′13.0″N 052°51′42.0″W
47°06′00.0″N 052°50′16.0″W
47°05′56.0″N 052°48′26.3″W
47°04′27.0″N 052°41′32.0″W
47°04′10.0″N 052°28′44.8″W
46°59′24.0″N 052°15′20.0″W
46°54′31.0″N 051°47′12.0″W
and 46°53′00.0″N 051°41′37.0″W

DFO(6307887-02)

17-FEB-2017 LNM/D. 26-AUG-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 fathoms, 2 feet. 47°31′22.2″N 052°35′04.2″W
(See Chart No. 1, L25) *DFO(6307843-01)*
This notice affects Electronic Navigational Chart: CA276101, CA376015

26-AUG-2016 LNM/D. 05-FEB-2016

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 31 fathoms (See Chart No. 1, L25) 48°59′24.0″N 051°02′06.0″W
This notice affects Electronic Navigational Chart: CA176030, CA276092 *DFO(6307669-01)*

Chart no. 8014

05-FEB-2016 LNM/D. 25-DEC-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 fathoms, 2 feet (See Chart No. 1, L25) 47°32′14.4″N 052°35′07.8″W
This notice affects Electronic Navigational Chart: CA276101, CA376015 *DFO(6307428-01)*

25-DEC-2015 LNM/D. 04-DEC-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 44 fathoms. 46°54′30.0″N 048°30′15.0″W
(See Chart No. 1, L25) *DFO(6307350-04)*
This notice affects Electronic Navigational Chart: CA276101

04-DEC-2015 LNM/D. 19-JUN-2015

Add submarine cable joining 47°40′18.9″N 048°30′00.0″W
(See Chart No. 1, L30.1) 47°14′05.7″N 050°10′32.9″W
and 46°53′00.0″N 051°26′32.0″W

DFO(6307373-01)

19-JUN-2015 LNM/D. 11-OCT-2013

Add subsurface Ocean Data Acquisition system (ODAS) with known depth of 31 fathoms (See Chart No. 1, L25) 48°59′24.0″N 051°02′06.0″W
This notice affects Electronic Navigational Chart: CA176030, CA276092 *DFO(6307140-03)*

11-OCT-2013 LNM/D. 09-APR-2010

Add private yellow ODAS/SADO lighted pillar buoy Fl (5) Y 20s 47°32′22.0″N 052°35′59.0″W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA276101, CA376015 *DFO(6306453-01)*

09-APR-2010 LNM/D. 21-AUG-2009

Amend Fl to read Fl 5s 108ft 15M against light 46°56′25.9″N 052°53′34.4″W
(See Chart No 1 P16)

LL(512) DFO(6304778-01)

This notice affects Electronic Navigational Chart: CA276091

21-AUG-2009 LNM/D. 06-MAR-2009

Chart no. 8014

Add light Fl 6s 173ft 17M 47°39′18.1″N 052°54′59.2″W
(See Chart No 1 P1)

(N2004004) LL(493) DFO(6304517-02)

06-MAR-2009 LNM/D. 05-NOV-2004

Add submarine cable joining 49°05′00.0″N 052°01′05.3″W
(See Chart No 1 L30.1) 48°33′37.1″N 052°40′45.5″W
48°28′57.6″N 052°50′01.3″W
and 48°19′33.0″N 053°06′00.0″W

DFO(6304222-01)

05-NOV-2004 LNM/D. 19-DEC-2003

Add black and yellow North cardinal pillar light buoy Q 48°11′41.3″N 052°54′56.6″W

(N2002044) LL(471.8) DFO(6300293-01)

19-DEC-2003

Amend Fl (3) 12s 92ft 18M to read Fl 4s 92ft 16M against light 48°30′14.8″N 053°02′36.4″W

(N2003039) LL(453) DFO(6301008-01)