Chart no. 1429

1429 - Canal de la Rive Sud - New Chart - 09-APR-2010 - NAD 1983

08-NOV-2019 LNM/D. 23-AUG-2019

Amend vertical clearance of 67 metres, to read 64 metres (See Chart No. 1, D22) 45°29′49.6″N 073°30′59.8″W

DFO(6410208-01)

This notice affects Electronic Navigational Chart: CA579080

23-AUG-2019 LNM/D. 19-JUL-2019

Amend vertical clearance of 17 metres, to read 16 metres (See Chart No. 1, D22) 45°29′09.5″N 073°30′47.2″W

This notice affects Electronic Navigational Chart: CA579227 *DFO(6410196-01)*

23-AUG-2019 LNM/D. 19-JUL-2019

Amend vertical clearance of 14 metres, to read 12 metres (See Chart No. 1, D22) 45°28′46.4″N 073°30′37.5″W

This notice affects Electronic Navigational Chart: CA579227 *DFO(6410196-02)*

23-AUG-2019 LNM/D. 19-JUL-2019

Amend vertical clearance of 15 metres, to read 14 metres (See Chart No. 1, D22) 45°28′48.6″N 073°30′32.7″W

This notice affects Electronic Navigational Chart: CA579227 *DFO(6410196-03)*

23-AUG-2019 LNM/D. 19-JUL-2019

Amend vertical clearance of 12 metres, to read 10 metres (See Chart No. 1, D22) 45°28′22.3″N 073°30′07.7″W

This notice affects Electronic Navigational Chart: CA579227 *DFO(6410196-04)*

19-JUL-2019 LNM/D. 12-APR-2019

Delete rear leading light Q G 25m12M with leading line (See Chart No. 1, P20.2) 45°25′57.8″N 073°43′32.5″W

This notice affects Electronic Navigational Chart: CA579227 *(Q2019084) LL(1202) DFO(6410166-01)*

12-APR-2019 LNM/D. 23-DEC-2016

Delete depth of 3 metres 7 decimetres (See Chart No. 1, I10) 45°24′25.8″N 073°43′37.5″W

This notice affects Electronic Navigational Chart: CA579227 *DFO(6410084-01)*

Chart no. 1429

12-APR-2019 LNM/D. 23-DEC-2016

Add depth of 3 metres 6 decimetres 45°24′25.5″N 073°43′39.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA579227 *DFO(6410084-02)*

12-APR-2019 LNM/D. 23-DEC-2016

Replace red starboard hand lighted pillar buoy QR, marked A2 with a red starboard hand lighted spar buoy QR, marked A2 45°24′27.7″N 073°43′24.2″W
(Q2018018) LL(5.3) DFO(6410084-03)
(See Chart n° 1, Qf)
This notice affects Electronic Navigational Chart: CA579227

12-APR-2019 LNM/D. 23-DEC-2016

Add Private white and orange speed control lighted pillar buoy FI Y 45°25′53.5″N 073°41′41.4″W
(See chart n° 1, Qo)
This notice affects Electronic Navigational Chart: CA579227 *DFO(6410084-04)*

23-DEC-2016 LNM/D. 14-OCT-2016

Delete depth of 6 metres 9 decimetres 45°29′02.8″N 073°30′45.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA579227 *DFO(6409588-01)*

23-DEC-2016 LNM/D. 14-OCT-2016

Add depth of 6 metres 4 decimetres 45°29′02.2″N 073°30′44.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA579227 *DFO(6409588-02)*

23-DEC-2016 LNM/D. 14-OCT-2016

Add depth of 6 metres 6 decimetres 45°29′10.9″N 073°30′50.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA579227 *DFO(6409588-03)*

23-DEC-2016 LNM/D. 14-OCT-2016

Delete depth of 7 metres 0 decimetres 45°29′15.9″N 073°30′51.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA579080 *DFO(6409588-04)*

23-DEC-2016 LNM/D. 14-OCT-2016

Chart no. 1429

Add depth of 6 metres 2 decimetres 45°29′17.4″N 073°30′51.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA579080 *DFO(6409588-05)*

23-DEC-2016 LNM/D. 14-OCT-2016

Delete depth of 7 metres 2 decimetres 45°29′26.3″N 073°30′55.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA579080 *DFO(6409588-06)*

23-DEC-2016 LNM/D. 14-OCT-2016

Add depth of 6 metres 8 decimetres 45°29′26.3″N 073°30′55.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA579080 *DFO(6409588-07)*

23-DEC-2016 LNM/D. 14-OCT-2016

Delete private red starboard hand spar buoy, marked 0, Priv 45°27′15.2″N 073°31′50.6″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA579227 *(Q2016189) DFO(6409599-01)*

23-DEC-2016 LNM/D. 14-OCT-2016

Delete private red starboard hand spar buoy, marked 2, Priv 45°26′56.8″N 073°32′05.5″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA579227 *(Q2016190) DFO(6409600-01)*

23-DEC-2016 LNM/D. 14-OCT-2016

Delete private red starboard hand spar buoy, marked 4, Priv 45°26′32.3″N 073°32′13.5″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA579227 *(Q2016191) DFO(6409601-01)*

23-DEC-2016 LNM/D. 14-OCT-2016

Delete private red starboard hand spar buoy, marked 6, Priv 45°26′11.1″N 073°32′19.9″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA579227 *(Q2016192) DFO(6409602-01)*

23-DEC-2016 LNM/D. 14-OCT-2016

Delete overhead cable with vertical clearance of 12 metres between 45°28′17.9″N 073°30′13.2″W
(See Chart No. 1, D22, D27) and 45°28′10.2″N 073°30′13.0″W
This notice affects Electronic Navigational Chart:
CA579227 *DFO(6409604-01)*

Chart no. 1429

14-OCT-2016 LNM/D. 29-JAN-2016

Delete overhead cable with vertical clearance of 13 metres
(See Chart No. 1, D22, D27)
This notice affects Electronic Navigational Chart: CA579227

joining 45°28′17.1″N 073°30′14.3″W
45°28′10.0″N 073°30′02.0″W
and 45°28′02.9″N 073°29′49.3″W

DFO(6409511-01)

14-OCT-2016 LNM/D. 29-JAN-2016

Add overhead cable with vertical clearance of 17 metres
(See Chart No. 1, D22, D27)
This notice affects Electronic Navigational Chart: CA579227

joining 45°28′21.3″N 073°30′17.4″W
45°28′19.2″N 073°30′12.7″W
45°28′09.9″N 073°29′51.2″W
and 45°28′04.2″N 073°29′38.2″W

DFO(6409511-02)

14-OCT-2016 LNM/D. 29-JAN-2016

Replace Islet with obstruction with known depth of 0 metres 8 decimetres.
(See Chart No. 1, K10, K41)
This notice affects Electronic Navigational Chart: CA579227

45°28′10.0″N 073°30′02.0″W

DFO(6409511-03)

14-OCT-2016 LNM/D. 29-JAN-2016

Add fixed bridge under construction (2015)
(See Chart No. 1, D20.1, F32)
This notice affects Electronic Navigational Chart: CA579227

joining 45°28′14.2″N 073°32′05.6″W
45°28′12.0″N 073°31′15.9″W
45°28′08.6″N 073°30′33.1″W
45°28′03.7″N 073°29′48.3″W
45°28′01.8″N 073°29′48.7″W
45°28′06.9″N 073°30′38.5″W
45°28′10.0″N 073°31′17.9″W
and 45°28′11.8″N 073°32′04.4″W

DFO(6409511-04)

14-OCT-2016 LNM/D. 29-JAN-2016

Chart no. 1429

Replace note — 45°29′00.0″N 073°42′00.0″W

VITESSE
Les vitesses maximales PAR RAPPORT AU FOND sont les suivantes :
-6 nœuds dans le canal de la Rive Sud.
-10.5 nœuds de l'entrée supérieure du canal de la Rive Sud au lac Saint-Louis, bouée A13.

SPEED
Speed limits OVER THE BOTTOM are as follows:
-6 knots in the Canal de la Rive Sud.
-10.5 knots from the Upper entrance of the Canal de la Rive Sud to Lac Saint-Louis, buoy A13.

with

VITESSE
Se référer au MANUEL DE LA VOIE MARITIME pour les limites de vitesse en vigueur.

SPEED
Refer to SEAWAY HANDBOOK for applicable speed limits.
This notice affects Electronic Navigational Chart: CA579227

DFO(6409527-02)

29-JAN-2016 — LNM/D. 27-MAR-2015

Replace red starboard hand lighted spar buoy Q R, marked A2 with red starboard hand lighted pillar buoy Q R, marked A2 (See Chart No. 1, Qf) — 45°24′27.7″N 073°43′24.2″W

This notice affects Electronic Navigational Chart: CA579227

(Q2015151) LL(5.3) DFO(6409237-01)

29-JAN-2016 — LNM/D. 27-MAR-2015

Delete Constr (2013) against bridge (See Chart No. 1, D22) — 45°28′20.2″N 073°32′49.7″W

This notice affects Electronic Navigational Chart: CA579227

DFO(6409316-01)

29-JAN-2016 — LNM/D. 27-MAR-2015

Delete Ru against wharf (See chart No. 1, F33.1) — 45°27′56.8″N 073°30′20.6″W

This notice affects Electronic Navigational Chart: CA579227

DFO(6409316-02)

27-MAR-2015 — LNM/D. 09-AUG-2013

Chart no. 1429

Add fixed bridge under construction (2013) between 45°28′23.3″N 073°32′53.4″W
(See Chart No. 1, D20.1, F32) and 45°28′17.6″N 073°32′46.6″W
This notice affects Electronic Navigational Chart:
CA579227 *DFO(6408988-01)*

09-AUG-2013 LNM/D. 21-DEC-2012

Add vertical clearance of 9 metres 8 decimetres 45°27′56.9″N 073°31′03.4″W
(See Chart No. 1, D20)
This notice affects Electronic Navigational Chart: CA579227 *DFO(6408835-01)*

21-DEC-2012 LNM/D. 10-AUG-2012

Replace green port hand lighted pillar buoy QG, marked A3 45°24′17.1″N 073°43′44.1″W
with a green port hand lighted spar buoy QG, marked A3 *(Q2012136) LL(6) DFO(6408699-01)*
(See Chart No. 1, Qg, Q24)

This notice affects Electronic Navigational Chart:
CA579227

21-DEC-2012 LNM/D. 10-AUG-2012

Replace green port hand lighted pillar buoy Fl G, marked A1 45°24′26.2″N 073°43′11.3″W
with a green port hand lighted spar buoy Fl G, marked A1 *(Q2012135) LL(5.2) DFO(6408700-01)*
(See Chart No. 1, Qg, Q24)

This notice affects Electronic Navigational Chart:
CA579227

10-AUG-2012 LNM/D. 17-JUN-2011

Amend F Bu 9m6M to read F G 9m12M against light 45°25′56.1″N 073°41′41.7″W
(See Chart No. 1, P16)
(Q2012117) LL(1194) DFO(6408659-01)

10-AUG-2012 LNM/D. 17-JUN-2011

Amend F Bu 18m6M to read F G 18m12M against light 45°25′59.3″N 073°41′31.1″W
(See Chart No. 1, P16)
(Q2012118) LL(1195) DFO(6408660-01)

17-JUN-2011

Chart no. 1429

Add legend Mooring Buoys 45°26′09.7″N 073°43′31.8″W
(See Chart No. 1, Q44)

DFO(6408365-01)

This notice affects Electronic Navigational Chart: CA579227

17-JUN-2011

Add light Fl Y(Priv) 45°26′51.0″N 073°34′06.8″W
(See Chart No. 1, P65)

(Q2011070) DFO(6408377-01)

This notice affects Electronic Navigational Chart: CA579227