Chart no. 2059

2059 - Scotch Bonnet Island to/à Cobourg - New Chart - 31-JUL-1998 - NAD 1983

30-MAY-2014 LNM/D. 01-JAN-2010

Add pipeline Rep (2014) between 43°57′34.8″N 078°05′58.8″W
(See Chart No. 1, L40.1) and 43°57′50.3″N 078°06′07.7″W
This notice affects Electronic Navigational Chart:
CA373234 *DFO(6603974-01)*

01-JAN-2010 LNM/D. 04-NOV-2005

Replace the red and white fairway lighted pillar buoy Mo(A), marked P with a red and white fairway lighted spar buoy Mo(A), marked P. 43°59′57.0″N 077°39′47.1″W
(See Chart No. 1, Qh) *(B2009024) LL(491.8) DFO(6603516-01)*

This notice affects Electronic Navigational Chart:
CA373234

01-JAN-2010 LNM/D. 04-NOV-2005

Replace yellow and black South cardinal lighted pillar buoy Q(6)+LFI 15s, marked MN with a yellow and black South cardinal lighted spar buoy Q(6)+LFI 15s, marked MN. 43°56′05.3″N 078°13′48.9″W
(See Chart No. 1, Q130.3) *(B2009025) LL(497.5) DFO(6603517-01)*

This notice affects Electronic Navigational Chart:
CA373234

04-NOV-2005 LNM/D. 23-MAY-2003

Amend legend Fl 5s10m to read Fl 5s against light 44°01′56.7″N 077°40′37.8″W

(B2005117) LL(1346.6) DFO(6602507-01)

23-MAY-2003 LNM/D. 20-APR-2001

Amend (Priv) Q R 18m to read (Priv) Fl R 5s 18m against light 43°58′28.9″N 077°52′31.7″W

(B2003004) LL(492.4) DFO(6600823-01)

20-APR-2001 LNM/D. 01-OCT-1999

Chart no. 2059

Add light, F Y 7m (Priv) 43°58′27.6″N 077°57′30.7″W
Notice 1722(P)/99 is now cancelled by this action.
(B2001064) LL(492.6) DFO(6601453-01)

01-OCT-1999 LNM/D. 03-SEP-1999

Replace lighted buoy ″MN2″ with lighted south cardinal bouy 43°56′05.0″N 078°13′49.8″W
Q(6)+ LFl 15s marked ″MN″
LL(INL 497.5) DFO(6102575-01)

03-SEP-1999

(P)Add light FY (Priv) 43°58′27.6″N 077°57′30.7″W

With this notification, Notice 1722(P)/99 is cancelled and replaced with a new action. See reference DFO 6601453 appearing in this edition. *DFO(6102215-01)*
Cancelled on 20-APR-01