Chart no. 2120

2120 - Niagara River to/à Long Point - New Edition - 15-APR-2005 - NAD 1983

08-OCT-2021 LNM/D. 13-AUG-2021

Delete yellow cautionary spar buoy, marked Priv 42°39′12.0″N 080°09′12.0″W
(See Chart No. 1, Qm)
This notice affects Electronic Navigational Chart: CA373093, CA473305 *(B2021016) DFO(6604798-01)*

08-OCT-2021 LNM/D. 13-AUG-2021

Delete yellow cautionary spar buoy, marked Priv 42°36′51.0″N 080°07′42.0″W
(See Chart No. 1, Qm)
This notice affects Electronic Navigational Chart: CA373093, CA473305 *(B2021018) DFO(6604800-01)*

13-AUG-2021 LNM/D. 04-MAY-2018

Reposition yellow cautionary spar buoy, marked Priv from 42°34′54.0″N 080°07′03.0″W
(See Chart No. 1, Qm) to 42°34′55.8″N 080°06′54.0″W
This notice affects Electronic Navigational Chart: CA373093, CA473305 *(B2021011) DFO(6604747-01)*

13-AUG-2021 LNM/D. 04-MAY-2018

Add obstruction with known depth of 2.1 metres, Rep (2021) 42°51′28.3″N 079°04′29.3″W
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA373093 *DFO(6604747-02)*

04-MAY-2018 LNM/D. 01-APR-2016

Delete chimney (205) 42°47′48.5″N 080°03′10.8″W
(See Chart No. 1, E22)
This notice affects Electronic Navigational Chart: CA273094, CA373093, CA473305, CA573306 *DFO(6604391-02)*

04-MAY-2018 LNM/D. 01-APR-2016

Delete chimney (Chys) 42°47′51.0″N 080°03′00.0″W
(See Chart No. 1, E22)
This notice affects Electronic Navigational Chart: CA273094, CA373093, CA473305, CA573306 *DFO(6604391-03)*

01-APR-2016 LNM/D. 01-JAN-2016

Chart no. 2120

Amend light characteristics Fl 8s 30m 18M to read Fl 8s 30m 15M — 42°32′55.2″N 080°02′58.1″W
(See Chart No. 1, P16) — *(B2015008) LL(579) DFO(6604193-01)*
This notice affects Electronic Navigational Chart: CA273094, CA373093, CA473305

01-APR-2016 — LNM/D. 01-JAN-2016

Add depth of 2.7 metres — 42°46′14.5″N 080°11′50.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA373093, CA473305 — *DFO(6604199-01)*

01-APR-2016 — LNM/D. 01-JAN-2016

Add depth of 11.3 metres — 42°43′47.5″N 080°05′48.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA373093, CA473305 — *DFO(6604199-02)*

01-APR-2016 — LNM/D. 01-JAN-2016

Add depth of 11.9 metres — 42°42′18.2″N 080°06′40.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA373093, CA473305 — *DFO(6604199-03)*

01-APR-2016 — LNM/D. 01-JAN-2016

Add depth of 12.8 metres — 42°42′48.0″N 080°05′53.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA373093, CA473305 — *DFO(6604199-04)*

01-JAN-2016 — LNM/D. 25-DEC-2015

Add crib with depth of 5.5 metres — 42°47′29.8″N 080°02′52.0″W
(See Chart No. 1, Fb,Ka)
This notice affects Electronic Navigational Chart: CA573306 — *DFO(6604159-01)*

01-JAN-2016 — LNM/D. 25-DEC-2015

Delete crib and depth of 6.1 metres — 42°47′29.8″N 080°02′49.2″W
(See Chart No. 1, Fb and Ia)
This notice affects Electronic Navigational Chart: CA573306 — *DFO(6604159-02)*

Chart no. 2120

25-DEC-2015 LNM/D. 09-OCT-2015

Add depth of 8.1 metres 42°44′53.2″N 080°04′05.0″W
(See Chart No. 1, I10)
DFO(6604143-01)

This notice affects Electronic Navigational Chart: CA473305

25-DEC-2015 LNM/D. 09-OCT-2015

Add depth of 6.4 metres 42°46′36.8″N 080°04′41.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA573306 *DFO(6604143-02)*

25-DEC-2015 LNM/D. 09-OCT-2015

Add depth of 5.7 metres 42°46′23.6″N 080°02′37.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA573306 *DFO(6604143-06)*

25-DEC-2015 LNM/D. 09-OCT-2015

Add depth of 5.5 metres 42°47′30.5″N 080°01′34.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA573306 *DFO(6604143-11)*

25-DEC-2015 LNM/D. 09-OCT-2015

Add depth of 6.0 metres 42°47′08.5″N 080°02′58.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA573306 *DFO(6604143-13)*

09-OCT-2015 LNM/D. 11-SEP-2015

Add obstruction, depth unknown, Rep (2015) 42°37′25.3″N 080°17′27.7″W
(See Chart No. 1, K40)
This notice affects Electronic Navigational Chart: CA373093, CA473305 *DFO(6604134-01)*

11-SEP-2015 LNM/D. 21-AUG-2015

Add wreck WK with known depth of 8.3 metres 42°45′55.0″N 080°03′02.8″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA373093, CA473305, CA573306 *DFO(6604129-01)*

Chart no. 2120

21-AUG-2015 LNM/D. 31-JUL-2015

Add obstruction, depth unknown, Rep (2015) 42°37′16.7″N 080°17′17.2″W
(See Chart No. 1, K40)
This notice affects Electronic Navigational Chart: CA373093, CA473305 *DFO(6604123-01)*

31-JUL-2015 LNM/D. 19-JUN-2015

Add dangerous underwater rock with depth of 2.6 metres, Rep (2015) 42°45′55.2″N 080°11′45.4″W
(See Chart No. 1, K14.1/K14.2)
DFO(6604113-02)
This notice affects Electronic Navigational Chart: CA273094, CA373093, CA473305

24-OCT-2014 LNM/D. 25-JUL-2014

Add pipeline joining 42°38′11.1″N 080°08′14.8″W
(See Chart No. 1, L40.1) 42°35′12.6″N 080°05′15.1″W
This notice affects Electronic Navigational Chart: CA373093, CA473305 and 42°34′58.3″N 080°04′19.3″W
DFO(6604022-01)

25-JUL-2014 LNM/D. 27-JUN-2014

Delete red and white fairway lighted pillar bell buoy Mo(A), marked B. 42°50′08.9″N 078°55′25.4″W
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart: CA273094, CA373093 *DFO(6603987-01)*

25-JUL-2014 LNM/D. 27-JUN-2014

Delete red starboard hand lighted pillar buoy Fl R, marked 2. 42°29′49.1″N 079°21′04.5″W
(See Chart No. 1, Qf) *(USCG:LNM 20/14) DFO(6603988-01)*
This notice affects Electronic Navigational Chart: CA373093

27-JUN-2014 LNM/D. 15-NOV-2013

Add wreck WK with known depth of 23 metres 42°42′08.4″N 080°02′04.1″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA373093, CA473305 *DFO(6603980-01)*

27-JUN-2014 LNM/D. 15-NOV-2013

Chart no. 2120

Add wreck WK with known depth of 26 metres 42°46′15.7″N 079°14′36.5″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA373093 *DFO(6603980-02)*

27-JUN-2014 LNM/D. 15-NOV-2013

Add wreck WK with known depth of 27 metres 42°40′04.6″N 079°23′46.8″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA373093 *DFO(6603980-03)*

27-JUN-2014 LNM/D. 15-NOV-2013

Add wreck WK with known depth of 29 metres 42°39′17.3″N 079°28′35.8″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA373093 *DFO(6603980-04)*

27-JUN-2014 LNM/D. 15-NOV-2013

Add wreck WK with known depth of 30 metres 42°40′05.2″N 079°36′15.0″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA373093 *DFO(6603980-05)*

27-JUN-2014 LNM/D. 15-NOV-2013

Add wreck WK with known depth of 27 metres 42°44′18.6″N 079°36′17.1″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA373093 *DFO(6603980-06)*

27-JUN-2014 LNM/D. 15-NOV-2013

Add wreck WK with known depth of 38 metres 42°37′38.8″N 080°00′54.7″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA373093, CA473305 *DFO(6603980-07)*

27-JUN-2014 LNM/D. 15-NOV-2013

Add wreck WK with known depth of 32 metres 42°39′06.2″N 080°03′08.7″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA373093, CA473305 *DFO(6603980-08)*

27-JUN-2014 LNM/D. 15-NOV-2013

Chart no. 2120

Delete private orange and white mooring spherical buoy 42°51′56.0″N 079°09′15.0″W
(See Chart No. 1, Q40)
This notice affects Electronic Navigational Chart: CA373093 *DFO(6603980-09)*

27-JUN-2014 LNM/D. 15-NOV-2013

Add wreck WK with known depth of 9.1 metres 42°51′55.6″N 079°09′15.2″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA373093 *DFO(6603980-10)*

15-NOV-2013 LNM/D. 01-JAN-2010

Add depth of 4.2 m 42°43′59.8″N 080°03′30.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA373093, CA473305 *DFO(6603922-01)*

15-NOV-2013 LNM/D. 01-JAN-2010

Add depth of 1.4 m 42°44′14.5″N 080°04′00.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA273094, CA373093, CA473305 *DFO(6603922-04)*

15-NOV-2013 LNM/D. 01-JAN-2010

Delete depth of 1.8 m 42°44′14.0″N 080°03′59.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA273094, CA373093, CA473305 *DFO(6603922-05)*

01-JAN-2010 LNM/D. 27-MAR-2009

Replace green port hand lighted pillar buoy Fl G, marked EA11 with green port hand lighted spar buoy Fl G, marked EA11 42°35′46.1″N 080°09′31.0″W *(B2009105) LL(578) DFO(6603521-01)*

This notice affects Electronic Navigational Chart: CA373093, CA473305

01-JAN-2010 LNM/D. 27-MAR-2009

Chart no. 2120

Replace red starboard hand lighted pillar buoy Fl R, marked EA2/2 with red starboard hand lighted spar buoy Fl R, marked EA2/2 — 42°50′24.5″N 079°14′11.4″W
(B2009033) LL(553.6) DFO(6603526-01)

This notice affects Electronic Navigational Chart: CA273094, CA373093

01-JAN-2010 — LNM/D. 27-MAR-2009

Replace red starboard hand lighted pillar buoy Fl R, marked EA4 with red starboard hand lighted spar buoy Fl R, marked EA4 — 42°48′49.2″N 079°31′01.5″W
(B2009034) LL(561) DFO(6603527-01)

This notice affects Electronic Navigational Chart: CA273094, CA373093

01-JAN-2010 — LNM/D. 27-MAR-2009

Amend red starboard hand lighted pillar buoy Fl R, marked EA6 with red starboard hand lighted spar buoy Fl R, marked EA6 — 42°47′39.0″N 079°43′27.8″W
(B2009035) LL(565) DFO(6603528-01)

This notice affects Electronic Navigational Chart: CA273094, CA373093

01-JAN-2010 — LNM/D. 27-MAR-2009

Replace red starboard hand lighted pillar buoy Q R, marked EN2 with red starboard hand lighted spar buoy Q R, marked EN2 — 42°44′23.4″N 080°05′26.0″W
(B2009036) LL(566.04) DFO(6603530-01)

This notice affects Electronic Navigational Chart: CA373093, CA473305, CA573306

01-JAN-2010 — LNM/D. 27-MAR-2009

Replace green port hand lighted pillar buoy Fl G, marked EN1 with green port hand lighted spar buoy Fl G, marked EN1 — 42°44′36.3″N 080°05′45.8″W
(B2009037) LL(566.05) DFO(6603531-01)

This notice affects Electronic Navigational Chart: CA373093, CA473305, CA573306

Chart no. 2120

01-JAN-2010 LNM/D. 27-MAR-2009

Replace red starboard hand lighted pillar buoy Fl R, marked EA8 with red starboard hand lighted spar buoy Fl R, marked EA8 — 42°43′42.2″N 080°03′38.0″W *(B2009048) LL(568.5) DFO(6603542-01)*

This notice affects Electronic Navigational Chart: CA273094, CA373093, CA473305

27-MAR-2009 LNM/D. 15-AUG-2008

Amend legend Fl 10s 15m to read LFl 10s 15m against light
(See Chart No. 1, P10.5) — 42°52′03.2″N 079°15′10.3″W *(B2009004) LL(551.68) DFO(6603366-01)*

This notice affects Electronic Navigational Chart: CA273094, CA373093, CA573010

27-MAR-2009 LNM/D. 15-AUG-2008

Replace red starboard hand lighted pillar buoy Fl R, marked EU4 with red starboard hand lighted spar buoy Fl R, marked EU4
(See Chart No.1, Q7) — 42°52′50.0″N 078°55′16.0″W *LL(552) DFO(6603372-01)*

This notice affects Electronic Navigational Chart: CA373093

15-AUG-2008 LNM/D. 29-FEB-2008

Add note — 42°42′12.0″N 080°23′07.0″W *DFO(6603234-01)*

SILTING
Mariners are cautioned that owing to continuous silting, depths are constantly changing and varying amounts of refilling must be expected.

ENSABLEMENT
Nous avisons les navigateurs que l'ensablement continu modifie les profondeurs constamment et qu'ils doivent tenir compte avec des amoncellements irréguliers de sable.

This notice affects Electronic Navigational Chart: CA373093

Chart no. 2120

15-AUG-2008 LNM/D. 29-FEB-2008

Add note 42°33′33.0″N 079°59′03.0″W

See note SILTING/Voir note ENSABLEMENT *DFO(6603234-02)*

This notice affects Electronic Navigational Chart: CA373093

25-MAY-2007 LNM/D. 09-MAR-2007

Amend legend Fl 10s 15m 15M to read Fl 10s 15m against light 42°52′03.0″N 079°15′10.0″W
(See Chart No. 1, P16) *(B2007004) LL(551.68) DFO(6602911-01)*

This notice affects Electronic Navigational Chart: CA273094, CA373093, CA573010

09-MAR-2007 LNM/D. 27-OCT-2006

Amend Al WG 10s 22m 16M to read Fl G 2.5s 22m against light 42°52′14.0″N 078°54′10.0″W

DFO(6602884-01)

This notice affects Electronic Navigational Chart: CA273094, CA373093

27-OCT-2006 LNM/D. 20-OCT-2006

Amend legend FR (Priv) to read Fl R (Priv) against light 42°39′54.4″N 080°19′43.3″W

(B2006064) LL(573.1) DFO(6602810-01)

This notice affects Electronic Navigational Chart: CA373093, CA473305

27-OCT-2006 LNM/D. 20-OCT-2006

Amend legend Qc R FR to read RLts against tower 42°53′58.0″N 078°57′17.0″W

DFO(6602814-01)

This notice affects Electronic Navigational Chart: CA373093

20-OCT-2006 LNM/D. 22-SEP-2006

Chart no. 2120

Add microwave tower with elevation of 117 m, RLts (Night/Nuit), WLts (Day/Jour) — 42°49′34.4″N 080°04′12.4″W

DFO(6602788-01)

This notice affects Electronic Navigational Chart: CA473305

22-SEP-2006 — LNM/D. 11-AUG-2006

Delete silo — 42°49′21.7″N 079°53′15.4″W

DFO(6602787-01)

This notice affects Electronic Navigational Chart: CA473305

22-SEP-2006 — LNM/D. 11-AUG-2006

Delete silo — 42°49′29.9″N 079°53′07.3″W

DFO(6602787-02)

This notice affects Electronic Navigational Chart: CA473305

11-AUG-2006

Add depth of 1.2m — 42°33′03.6″N 080°01′58.4″W

DFO(6602772-02)

This notice affects Electronic Navigational Chart: CA473305

11-AUG-2006

Add depth awash of 0.0m — 42°33′00.6″N 080°02′24.8″W

DFO(6602772-04)

This notice affects Electronic Navigational Chart: CA473305

2120 - Port Dover - New Edition - 15-APR-2005 - NAD 1983

01-APR-2016 — LNM/D. 01-JAN-2016

Add depth of 3 metres — 42°46′39.2″N 080°11′54.2″W
(See Chart No.1, I10)
This notice affects Electronic Navigational Chart: CA573303 — *DFO(6604198-01)*

19-JUN-2015 — LNM/D. 24-OCT-2014

Chart no. 2120

Add depth of 1.5 metres 42°46′50.3″N 080°11′44.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA573303 *DFO(6604103-03)*

15-AUG-2008 LNM/D. 29-FEB-2008

Add green port hand spar buoy, marked ED7 42°46′48.9″N 080°12′09.6″W

(B2008090) DFO(6603235-01)

This notice affects Electronic Navigational Chart: CA573303

29-FEB-2008 LNM/D. 25-MAY-2007

Delete submarine cable joining 42°46′53.8″N 080°11′40.9″W
(See Chart No. 1, L30.1) 42°46′53.0″N 080°11′39.5″W
and 42°46′51.1″N 080°11′40.7″W

This notice affects Electronic Navigational Chart: *DFO(6603170-01)*
CA373093, CA573303

25-MAY-2007 LNM/D. 09-MAR-2007

Amend legend FR to read FlR against light 42°46′50.8″N 080°11′40.7″W
(See Chart No. 1, P16)

(B2007006) LL(569.5) DFO(6602912-01)

This notice affects Electronic Navigational Chart:
CA473305, CA573303