Chart no. 2223

2223 - Port McNicoll and/et Victoria Harbour - New Chart - 13-APR-1984 - NAD 1927

13-JUL-2018 LNM/D. 04-AUG-2006

Add underwater rock of unknown depth, dangerous to surface navigation, Rep (2018) 44°45′20.4″N 079°47′48.0″W
(See Chart No. 1, K13)

DFO(6604426-01)

This notice affects Electronic Navigational Chart: CA473271

04-AUG-2006 LNM/D. 09-APR-2004

Delete seaplane anchorage symbol 44°45′09.1″N 079°46′39.5″W

DFO(6602563-01)

09-APR-2004 LNM/D. 09-JAN-2004

Replace green port hand pillar light buoy Fl G, marked MV1 with green port hand spar light buoy Fl G, marked MV1 44°45′10.5″N 079°47′12.0″W

(D2003179) LL(884) DFO(6601832-01)

09-JAN-2004 LNM/D. 20-APR-2001

Add red starboard hand spar light buoy FlR, marked MM4 44°46′31.3″N 079°48′06.8″W

(D2003117) LL(883) DFO(6601021-02)

20-APR-2001 LNM/D. 25-FEB-2000

Delete note ″GENERAL INFORMATION / INFORMATION GÉNÉRALE″ and all paragraphs down to and including ″Marinas / Marinas″ below photograph of Port McNicoll and / et Victoria Harbour
Only note entitled ″WARNING / AVERTISSEMENT″, in magenta, concerning cables remains in effect.

DFO(6601458-01)

25-FEB-2000 LNM/D. 30-OCT-1998

Add R 44°44′58.8″N 079°47′57.2″W
On certain copies rock symbol has been removed accidentally.

DFO(6500081-01)

Chart no. 2223

30-OCT-1998 LNM/D. 28-NOV-1997
Add red spar buoy marked ″MM10″ 44°45′39.0″N 079°47′43.0″W

DFO(6100938-01)

28-NOV-1997 LNM/D. 05-JUL-1996
Delete light buoy MM8 44°45′43.0″N 079°47′30.0″W

LL(INL 884) DFO(6100559-01)

28-NOV-1997 LNM/D. 05-JUL-1996
Delete red spar buoy MM6 44°46′00.0″N 079°47′43.0″W

LL(INL 884) DFO(6100559-03)

28-NOV-1997 LNM/D. 05-JUL-1996
Delete green spar buoy MM9 44°45′39.5″N 079°47′22.0″W

LL(INL 884) DFO(6100559-04)

28-NOV-1997 LNM/D. 05-JUL-1996
Delete green spar buoy MM11 44°45′32.5″N 079°47′26.5″W

LL(INL 884) DFO(6100559-05)

28-NOV-1997 LNM/D. 05-JUL-1996
Delete green spar buoy MM13 44°45′25.3″N 079°47′32.5″W

LL(INL 884) DFO(6100559-06)

28-NOV-1997 LNM/D. 05-JUL-1996
Delete starboard bifurcation buoy MM 44°45′02.0″N 079°47′58.5″W

LL(INL 884) DFO(6100559-07)

28-NOV-1997 LNM/D. 05-JUL-1996

Chart no. 2223

Delete green spar buoy MV1 44°45′13.0″N 079°47′12.0″W

LL(INL 884) DFO(6100559-08)

28-NOV-1997 LNM/D. 05-JUL-1996
Add green light buoy ″Fl G″ marked ″MV1″ 44°45′10.5″N 079°47′12.0″W

LL(INL 884) DFO(6100559-09)

28-NOV-1997 LNM/D. 05-JUL-1996
Delete green spar buoy MV3 44°45′12.0″N 079°47′06.0″W

LL(INL 884) DFO(6100559-12)

28-NOV-1997 LNM/D. 05-JUL-1996
Delete range lights 44°45′23.8″N 079°47′08.6″W

LL(INL 884) DFO(6100559-13)

05-JUL-1996 LNM/D. 03-NOV-1995
Add submarine cable joining 44°45′43.8″N 079°46′18.2″W
44°45′50.0″N 079°46′28.0″W
44°45′54.8″N 079°46′36.4″W
44°46′00.0″N 079°46′48.0″W
and 44°46′04.3″N 079°47′00.5″W

DFO(6100153-01)

03-NOV-1995 LNM/D. 09-SEP-1994
Delete marina symbol 44°44′35.0″N 079°48′12.0″W

DFO(6100047-01)

03-NOV-1995 LNM/D. 09-SEP-1994
Add marina symbol 44°45′17.8″N 079°46′44.5″W

DFO(6100048-01)