**Chart no. 2302**

**2302 - St. Ignace Island to/à Passage Island - New Edition - 02-AUG-1985 - US Standard Datum**

**09-FEB-2024** LNM/D. 04-AUG-2023

Amend Fl to read Fl (priv) against light 48°26′09.5″N 088°28′49.7″W
(See Chart 1, P65)
This notice affects Electronic Navigational Chart: CA373070 *(D2023038) LL(1127) DFO(6605208-01)*

**04-AUG-2023** LNM/D. 19-MAY-2023

Delete depth of 10 fathoms 48°39′56.4″N 088°07′48.4″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6605090-01)*

**04-AUG-2023** LNM/D. 19-MAY-2023

Add depth of 7 fathoms 48°39′54.2″N 088°07′46.3″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6605090-02)*

**04-AUG-2023** LNM/D. 19-MAY-2023

Add depth of 9 1/2 fathoms 48°37′06.8″N 088°08′02.8″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6605090-03)*

**19-MAY-2023** LNM/D. 07-APR-2023

Add depth of 4½ fathoms 48°41′00.7″N 088°06′20.5″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6605049-01)*

**19-MAY-2023** LNM/D. 07-APR-2023

Delete depth of 12 fathoms 48°39′33.0″N 088°07′27.3″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6605049-02)*

**19-MAY-2023** LNM/D. 07-APR-2023

Add depth of 5¼ fathoms 48°39′32.5″N 088°07′23.1″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6605049-03)*

**19-MAY-2023** LNM/D. 07-APR-2023

**Chart no. 2302**

Delete depth of 12 fathoms 48°37′44.3″N 088°07′09.4″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6605049-04)*

**19-MAY-2023** LNM/D. 07-APR-2023

Add depth of 5¾ fathoms 48°37′40.5″N 088°07′10.3″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6605049-06)*

**19-MAY-2023** LNM/D. 07-APR-2023

Delete depth of 6½ fathoms 48°45′38.9″N 088°05′04.1″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6605049-07)*

**19-MAY-2023** LNM/D. 07-APR-2023

Add depth of 4 fathoms 48°45′37.3″N 088°05′03.6″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6605049-08)*

**07-APR-2023** LNM/D. 16-SEP-2022

Add obstruction with known depth of 5 Fathoms 48°41′59.5″N 088°05′40.6″W
(See Chart 1, K41)
*DFO(6605031-01)*

**07-APR-2023** LNM/D. 16-SEP-2022

Delete wreck WK with known depth of 13 Fathoms 48°39′52.4″N 088°07′39.4″W
(See Chart 1, K26)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6605031-02)*

**07-APR-2023** LNM/D. 16-SEP-2022

Add wreck WK with known depth of 10 Fathoms 48°39′52.4″N 088°07′39.4″W
(See Chart 1, K26)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6605031-03)*

**07-APR-2023** LNM/D. 16-SEP-2022

Delete depth of 7 fathoms 48°42′02.2″N 088°05′36.0″W
(See Chart 1, I10)
*DFO(6605031-04)*

**Chart no. 2302**

**07-APR-2023** LNM/D. 16-SEP-2022

Delete depth of 8 fathoms 48°41′57.0″N 088°05′40.7″W
(See Chart 1, I10)
*DFO(6605031-05)*

**07-APR-2023** LNM/D. 16-SEP-2022

Delete Rep (2022) against obstruction 48°39′52.7″N 088°07′18.1″W
(See Chart No. 1, K41)
*DFO(6605031-06)*

**16-SEP-2022** LNM/D. 15-MAY-2020

Delete depth of 23 fathoms 48°39′50.8″N 088°07′39.3″W
(See Chart No. 1, I10)
*DFO(6604890-01)*

**16-SEP-2022** LNM/D. 15-MAY-2020

Delete depth of 11 fathoms 48°39′56.4″N 088°07′35.0″W
(See Chart No. 1, I10)
*DFO(6604890-02)*

**16-SEP-2022** LNM/D. 15-MAY-2020

Add wreck WK with known depth of 13 fathoms 48°39′52.4″N 088°07′39.4″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6604890-03)*

**15-MAY-2020** LNM/D. 15-JUN-2007

Add obstruction with known depth of 3 fathoms 48°38′45.6″N 088°04′58.8″W
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA373291 *DFO(6604615-05)*

**15-JUN-2007** LNM/D. 15-DEC-2006

Amend legend 2 Lts FR 29ft & FR 40ft to read 2 Lts FR against lights 48°42′02.0″N 088°05′59.0″W
(See Chart No. 1, P16) *(D2007002) LL(1124) DFO(6602922-01)*

This notice affects Electronic Navigational Chart: CA373291

## Chart no. 2302

**15-DEC-2006** LNM/D. 17-FEB-2006

Amend legend 2 Lts Fl R 4s 29ft & Fl R 4s 40ft to read 2 Lts FR 29ft & FR 40ft against light — 48°42′02.0″N 088°05′59.0″W

*(D2006078) LL(1124) DFO(6602848-01)*

This notice affects Electronic Navigational Chart: CA373291

**17-FEB-2006** LNM/D. 17-JUN-2005

Reposition green port hand spar buoy, marked N3 — from 48°40′38.0″N 088°06′32.0″W to 48°40′34.3″N 088°06′34.4″W

This notice affects Electronic Navigational Chart: CA373291 *(D2005076) DFO(6602594-01)*

**17-JUN-2005** LNM/D. 07-JAN-2005

Replace black, red and black isolated danger conical buoy, marked D with black, red and black isolated danger can buoy, marked D — 48°11′10.0″N 088°24′21.0″W

*LL(16825) DFO(6602363-01)*

**17-JUN-2005** LNM/D. 07-JAN-2005

Replace black, red and black isolated danger pillar buoy, marked D with black, red and black isolated danger can buoy, marked D — 48°11′10.0″N 088°24′21.0″W

*LL(16825) DFO(6602363-02)*

**07-JAN-2005** LNM/D. 03-SEP-2004

Amend legend Fl 5s 99ft 15M to read Fl 5s 99ft 9M against light — 48°36′11.0″N 088°08′33.5″W

*(D2004028) LL(1126) DFO(6602136-01)*

This notice affects Electronic Navigational Chart: CA173289, CA373291

**03-SEP-2004** LNM/D. 28-FEB-2003

Amend legend Lights in Line / Feux en alignement 014½° to read Lights in Line / Feux en alignement 013° — 48°42′12.0″N 088°07′04.0″W

*(D2004084) LL(1125) DFO(6602015-01)*

**28-FEB-2003** LNM/D. 24-JAN-2003

**Chart no. 2302**

Add legend D against black, red, black isolated danger conical buoy 48°11′10.0″N 088°24′21.0″W

*DFO(6500088-01)*

**24-JAN-2003** LNM/D. 12-NOV-1999

Delete red, green, red, starboard bifurcation conical buoy 48°11′10.0″N 088°24′21.0″W

*DFO(6600616-01)*

**24-JAN-2003** LNM/D. 12-NOV-1999

Add black, red, black, isolated danger conical buoy, marked D 48°11′10.0″N 088°24′21.0″W
This buoy is not fitted with topmarks.

*DFO(6600616-02)*