Chart no. 3002

3002 - Queen Charlotte Sound to/à Dixon Entrance - New Edition - 16-DEC-1994 - NAD 1927

17-NOV-2023 LNM/D. 18-AUG-2023

Add Environmentally Sensitive Sea Area with label "Scott Islands Protected Marine Wildlife Area/Zone de protection marine de faune des îles Scott"
(See Chart 1, N22)
joining 50°50′38.2″N 128°10′34.0″W
51°15′05.9″N 128°36′39.6″W
51°14′34.8″N 128°55′39.6″W
51°06′05.2″N 130°08′20.2″W
and 50°45′00.0″N 130°04′28.2″W

DFO(6204818-01)

18-AUG-2023 LNM/D. 04-AUG-2023

Delete radar reflector against light 50°54′18.7″N 127°59′01.6″W
(See Chart 1, S4)

DFO(6204755-02)

04-AUG-2023 LNM/D. 31-MAR-2023

Amend light Fl to read Fl (3) 52°44′32.0″N 132°06′42.1″W
(See Chart 1, P1)

(P2023043) LL(809) DFO(6204760-01)

31-MAR-2023 LNM/D. 06-JAN-2023

Amend Queen Charlotte City to read Village of Daajing Giids 53°15′47.0″N 132°11′28.0″W

DFO(6204727-01)

31-MAR-2023 LNM/D. 06-JAN-2023

Amend Striae Islet to read Striae Islands 54°06′35.0″N 132°12′36.0″W

DFO(6204727-02)

06-JAN-2023 LNM/D. 02-DEC-2022

Add Tuzo Wilson Seamounts 51°27′34.0″N 130°59′10.2″W

DFO(6204693-03)

02-DEC-2022 LNM/D. 25-NOV-2022

Chart no. 3002

Add subsurface Ocean Data Acquisition system (ODAS) with known depth of 22 fathoms (See Chart 1, L25) 51°07′38.0″N 129°28′24.0″W
This notice affects Electronic Navigational Chart: CA370165 *DFO(6204672-01)*

25-NOV-2022 LNM/D. 07-OCT-2022

Delete yellow ODAS/SADO lighted super-buoy Fl (5) Y, marked 46204 (See Chart 1, Q58) 52°25′30.9″N 129°47′24.1″W
DFO(6204669-01)

25-NOV-2022 LNM/D. 07-OCT-2022

Add yellow ODAS/SADO lighted super-buoy Fl (5) Y, marked 46204 (See Chart 1, Q58) 51°23′31.5″N 128°45′54.7″W
DFO(6204669-02)

07-OCT-2022 LNM/D. 09-SEP-2022

Delete yellow ODAS/SADO lighted super-buoy Fl (5) Y, marked 46204 51°23′31.5″N 128°45′54.7″W
(See Chart 1, Q58) *LL(PAC582.5) DFO(6204644-01)*

07-OCT-2022 LNM/D. 09-SEP-2022

Delete yellow ODAS/SADO lighted super-buoy Fl (5) Y, marked 46185 52°25′00.9″N 129°48′54.1″W
(See Chart 1, Q58) *LL(PAC621.5) DFO(6204644-02)*

07-OCT-2022 LNM/D. 09-SEP-2022

Add yellow ODAS/SADO lighted super-buoy Fl (5) Y, marked 46204 52°25′30.9″N 129°47′24.1″W
(See Chart 1, Q58) *LL(PAC582.5) DFO(6204644-03)*

07-OCT-2022 LNM/D. 09-SEP-2022

Add yellow ODAS/SADO lighted super-buoy Fl (5) Y, marked 46185 52°31′39.9″N 130°05′07.9″W
(See Chart 1, Q58) *LL(PAC621.5) DFO(6204644-04)*

09-SEP-2022 LNM/D. 17-DEC-2021

Replace Tow Hill with Taaw Tldáaw 54°04′25.0″N 131°44′16.0″W

DFO(6204625-01)

Chart no. 3002

09-SEP-2022 LNM/D. 17-DEC-2021

Affix patch 53°38′00.9″N 132°26′54.1″W
PDF

DFO(6204625-07)

09-SEP-2022 LNM/D. 17-DEC-2021

Affix patch 53°12′00.9″N 131°53′54.1″W
PDF

DFO(6204625-09)

17-DEC-2021 LNM/D. 26-FEB-2021

Amend Voluntary Protection Zone note to read A Voluntary Protection Zone for shipping is in effect on the West Coast of Haida Gwaii. Within this zone, commercial vessels of 500 gross tons or greater shall observe a minimum distance of 50 nautical miles offshore when transiting, with a few exceptions. For additional information, see monthly notice to mariners or haidagwaii-vpz.ca.
Une zone de protection volontaire pour la navigation est en vigueur sur la côte ouest de Haida Gwaii. Dans cette zone, les navires commerciaux de 500 tonnes brutes ou plus doivent observer une distance minimale de 50 milles marins de la côte lorsqu'ils transitent, à quelques exceptions. Pour en savoir plus, consultez l'Avis aux navigateurs mensuel ou le site web haidagwaii-vpz.ca.
(See Chart No. 1, A14)
53°07′00.0″N 128°00′00.0″W

DFO(6204520-02)

26-FEB-2021 LNM/D. 25-DEC-2020

Add VOLUNTARY PROTECTION ZONE A Trial Voluntary Protection Zone for Shipping on the West Coast of Haida Gwaii is in effect from September 1, 2020 through October 31, 2021. Commercial vessels of 500 gross tonnage or greater shall observe a minimum distance of 50 nautical miles offshore when transiting with a few exceptions. For additional information, see monthly Notice to Mariners or haidagwaii-vpz.ca. ZONE DE PROTECTION VOLONTAIRE Une zone de protection volontaire pour le transport sur la côte ouest de l'archipel Haida Gwaii sera instaurée du 1er septembre 2020 au 31 octobre 2021 dans le cadre d'un essai. Dans cette zone, les bâtiments commerciaux de 500 tonneaux (jauge brute) ou plus doivent se trouver à au moins 50 mille marins de la côte lorsqu'ils transitent le long de la côte ouest de l'archipel Haida Gwaii, à quelques exemptions près. Pour en savoir plus sur le projet de zone de protection volontaire, consultez l'Avis aux navigateurs mensuel ou le site haidagwaii-vpz.ca.
This notice affects Electronic Navigational Chart: CA270390
53°06′00.0″N 128°00′00.0″W

DFO(6204420-01)

Chart no. 3002

25-DEC-2020 LNM/D. 24-JUL-2020

Add submarine cable joining 55°01′00.0″N 131°07′39.0″W
(See Chart No. 1, L30.1) 54°54′07.1″N 131°04′35.4″W
This notice affects Electronic Navigational Chart: 54°47′21.2″N 131°00′04.6″W
CA270390, CA370191, CA470074, CA470315, CA470363, 54°43′29.5″N 130°52′13.5″W
CA470364, CA470370, CA570125 54°42′42.2″N 130°48′02.8″W
54°43′24.9″N 130°44′45.4″W
54°33′52.7″N 130°33′51.9″W
54°19′11.9″N 130°34′22.6″W
54°13′43.1″N 130°26′32.2″W
54°12′59.9″N 130°21′32.5″W
and 54°13′58.9″N 130°20′02.1″W

DFO(6204394-01)

24-JUL-2020 LNM/D. 03-APR-2020

Replace QUEEN CHARLOTTE ISLANDS/ÎLES DE LA REINE-CHARLOTTE with HAIDA GWAII 53°03′35.0″N 132°48′08.0″W
This notice affects Electronic Navigational Chart: CA270390 *DFO(6204340-01)*

03-APR-2020 LNM/D. 27-SEP-2019

Add OIL TANKER MORATORIUM/ VOLUNTARY TANKER EXCLUSION ZONE 53°40′50.0″N 128°10′00.0″W

DFO(6204274-02)

The Oil Tanker Moratorium Act contains restrictions for certain commercial vessels transiting along the BC coast from the northern tip of Vancouver Island to the Canada/United States border in the north. The Pacific States/British Columbia Oil Spill Task Force endorses voluntary measures and minimum distances from shore for certain commercial vessels transiting the West Coast. For additional information, see Sailing Directions, PAC 200.

MORATOIRE SUR LES PÉTROLIERS / ZONE D’EXCLUSION VOLONTAIRE DES PÉTROLIERS

La Loi sur le moratoire relatif aux pétroliers précise des restrictions pour certains navires commerciaux le long de la côte de la Colombie-Britannique entre la pointe nord de l’île de Vancouver jusqu’à la frontière entre le Canada et les États-Unis au nord. Le groupe de travail sur les déversements d’hydrocarbures des États du Pacifique /de la Colombie-Britannique approuve des mesures volontaires et des distances minimales par rapport à la côte pour certains navires commerciaux transitant sur la côte ouest. Pour plus de renseignements, consulter les Instructions nautiques, PAC 200.

This notice affects Electronic Navigational Chart: CA270390

Chart no. 3002

27-SEP-2019 LNM/D. 08-MAR-2019

Amend Q with RACON to read Iso 1s with RACON against light 53°40′24.1″N 130°24′42.7″W
(See Chart No. 1, P1, S3.1)
LL(742.5) DFO(6204097-01)

08-MAR-2019 LNM/D. 28-DEC-2018

Amend light Fl 5s 315ft 17M to read Fl 5s315ft13M against light 51°56′09.3″N 131°00′57.7″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA270084 *LL(770) DFO(6203963-02)*

28-DEC-2018 LNM/D. 25-MAY-2018

Add light Q with RACON 53°40′24.1″N 130°24′42.7″W
(See Chart No. 1, P1, S3.1)
This notice affects Electronic Navigational Chart: CA270390, CA370441, CA470658 *(P2018135) LL(742.5) DFO(6203932-01)*

25-MAY-2018 LNM/D. 04-MAY-2018

Add green port hand lighted pillar buoy Fl G, marked EB7 52°57′52.8″N 129°44′57.7″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA270724, CA470613 *(P2018030) LL(631.1) DFO(6203765-01)*

25-MAY-2018 LNM/D. 04-MAY-2018

Add red starboard hand lighted pillar buoy Fl R, marked EB2 52°50′54.6″N 129°46′12.0″W
(See Chart No. 1, Qf) *(P2018043) LL(631.3) DFO(6203766-01)*
This notice affects Electronic Navigational Chart: CA270724, CA470613

25-MAY-2018 LNM/D. 04-MAY-2018

Add red starboard hand lighted pillar buoy Q R, marked EB4 52°53′25.8″N 129°39′44.3″W
(See Chart No. 1, Qf) *(P2018044) LL(631.4) DFO(6203767-01)*
This notice affects Electronic Navigational Chart: CA270724, CA470613

25-MAY-2018 LNM/D. 04-MAY-2018

Chart no. 3002

Add green port hand lighted pillar buoy Q G, marked EB5 — 52°55′27.1″N 129°31′48.8″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA270724, CA470613 — *(P2018042) LL(631.5) DFO(6203768-01)*

04-MAY-2018 — LNM/D. 02-FEB-2018

Amend Fl to read Fl 6s against light — 54°27′43.1″N 130°57′04.7″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA270390, CA370191, CA470369 — *LL(730.6) DFO(6203727-01)*

04-MAY-2018 — LNM/D. 02-FEB-2018

Amend yellow ODAS/SADO lighted super-buoy Fl(5) Y, marked 46145 to read yellow ODAS/SADO lighted super-buoy Fl(5) Y 20s, marked 46145 — 54°22′07.8″N 132°26′40.8″W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA270390, CA370190 — *LL(801) DFO(6203727-02)*

02-FEB-2018 — LNM/D. 12-JAN-2018

Amend Fl to read Iso against light — 52°57′16.0″N 129°18′29.6″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA270724, CA470730 — *(P2017097) LL(630.2) DFO(6203611-01)*

12-JAN-2018 — LNM/D. 22-DEC-2017

Amend Fl to read Fl 6s against light — 52°56′22.6″N 129°26′16.3″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA270724, CA470730 — *(P2017093) LL(630) DFO(6203606-01)*

22-DEC-2017 — LNM/D. 24-NOV-2017

Amend Fl to read Fl R against light — 53°42′27.3″N 130°24′43.0″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA270390, CA370441, CA470658 — *(P2017075) LL(743) DFO(6203590-01)*

22-DEC-2017 — LNM/D. 24-NOV-2017

Chart no. 3002

Delete radar reflector — 53°42′27.3″N 130°24′43.0″W
(See Chart No. 1, S4)
This notice affects Electronic Navigational Chart: CA270390, CA370441, CA470658 — *DFO(6203590-02)*

22-DEC-2017 — LNM/D. 24-NOV-2017

Add light Fl(3) with RACON — 52°51′36.9″N 129°20′50.7″W
(See Chart No. 1, P1, S3.1)
This notice affects Electronic Navigational Chart: CA270724, CA470730 — *(P2017076) LL(628.5) DFO(6203595-01)*

24-NOV-2017 — LNM/D. 17-NOV-2017

Amend Fl R 15M with Racon to read Fl R 16M with Racon against light — 50°58′14.8″N 127°43′19.0″W
(See Chart No. 1, P1,S3.1) — *LL(576) DFO(6203576-01)*
This notice affects Electronic Navigational Chart: CA270084, CA470307

17-NOV-2017 — LNM/D. 13-OCT-2017

Delete green port hand lighted pillar whistle buoy Fl G, marked C25 — 54°14′53.0″N 131°30′47.0″W
(See Chart No. 1, Qg) — *(P2017061) LL(790) DFO(6203570-01)*
This notice affects Electronic Navigational Chart: CA270390, CA370190

17-NOV-2017 — LNM/D. 13-OCT-2017

Add black, yellow and black East cardinal lighted pillar whistle buoy Q(3) 10s, marked CUT — 54°14′52.9″N 131°30′48.0″W
(See Chart No. 1, Q130.3) — *(P2017061) LL(790) DFO(6203570-02)*
This notice affects Electronic Navigational Chart: CA270390, CA370190

13-OCT-2017 — LNM/D. 04-AUG-2017

Delete green port hand lighted pillar buoy QG with RACON, marked EF9 — 54°16′00.0″N 131°05′24.0″W
(See Chart No. 1, Qg) — *(P2017052) LL(750.5) DFO(6203544-01)*
This notice affects Electronic Navigational Chart: CA270390, CA370190

13-OCT-2017 — LNM/D. 04-AUG-2017

Chart no. 3002

Delete black and yellow North cardinal lighted pillar buoy Q, marked EFJ — 54°17′47.4″N 131°19′36.1″W
(See Chart No. 1, Q130.3) *(P2017053) LL(750.6) DFO(6203545-01)*
This notice affects Electronic Navigational Chart: CA270390, CA370190

04-AUG-2017 LNM/D. 21-APR-2017

Add green port hand lighted pillar buoy Fl G, marked EF5 — 54°08′12.0″N 131°05′00.0″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA270390, CA370731 *(P2017032) LL(749.4) DFO(6203507-01)*

04-AUG-2017 LNM/D. 21-APR-2017

Delete depth of 10 fathoms 4 feet — 54°07′54.0″N 131°05′00.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA270390 *DFO(6203507-02)*

04-AUG-2017 LNM/D. 21-APR-2017

Add green port hand lighted pillar buoy QG, marked EF1 — 54°00′12.0″N 131°05′52.2″W
(See chart No 1, Qg)
This notice affects Electronic Navigational Chart: CA270390, CA370731 *(P2017033) LL(748.5) DFO(6203512-01)*

21-APR-2017 LNM/D. 07-APR-2017

Add restricted area with label ″Hecate Strait and Queen Charlotte Sound Glass Sponge Reefs Marine Protected Area/Zone de protection marine des récifs d′éponges siliceuses du détroit d′Hécate et du bassin de la Reine-Charlotte″ — joining 53°11′52.9″N 130°19′47.2″W
53°09′22.0″N 130°18′53.0″W
53°02′54.5″N 130°25′16.2″W
53°03′06.9″N 130°30′35.6″W
53°07′17.8″N 130°42′03.2″W
53°07′44.5″N 130°46′26.5″W
53°13′28.7″N 130°47′28.7″W
53°19′20.0″N 130°54′24.2″W
53°24′05.4″N 130°48′37.8″W
53°23′40.7″N 130°42′52.2″W
53°18′42.5″N 130°38′09.3″W
53°15′20.6″N 130°33′01.3″W
and 53°11′52.9″N 130°19′47.2″W
(See Chart No. 1, N2.1)

This notice affects Electronic Navigational Chart: CA270724, CA370440 *DFO(6203461-01)*

21-APR-2017 LNM/D. 07-APR-2017

Chart no. 3002

Add restricted area with label ″Hecate Strait and Queen Charlotte Sound Glass Sponge Reefs Marine Protected Area/Zone de protection marine des récifs d'éponges siliceuses du détroit d'Hécate et du bassin de la Reine-Charlotte″
(See Chart No. 1, N2.1)

This notice affects Electronic Navigational Chart: CA270084, CA270724

joining 52°00′24.4″N 129°14′12.6″W
51°55′50.5″N 129°18′13.8″W
51°51′32.5″N 129°36′37.4″W
51°53′00.7″N 129°44′03.4″W
52°05′14.1″N 129°36′14.1″W
52°08′46.0″N 129°33′33.5″W
52°15′42.6″N 129°44′12.3″W
52°29′35.4″N 129°52′32.7″W
52°32′05.4″N 129°53′06.2″W
52°34′05.6″N 129°47′51.4″W
52°25′42.7″N 129°35′12.2″W
52°20′02.8″N 129°29′51.7″W
52°09′52.3″N 129°25′29.5″W
and 52°00′24.4″N 129°14′12.6″W

DFO(6203461-02)

21-APR-2017 LNM/D. 07-APR-2017

Add restricted area with label ″Hecate Strait and Queen Charlotte Sound Glass Sponge Reefs Marine Protected Area/Zone de protection marine des récifs d'éponges siliceuses du détroit d'Hécate et du bassin de la Reine-Charlotte″
(See Chart No. 1, N2.1)

This notice affects Electronic Navigational Chart: CA270084, CA370165

joining 51°24′44.2″N 128°47′58.3″W
51°18′32.5″N 128°40′35.6″W
51°14′57.6″N 128°47′01.2″W
51°14′33.9″N 128°55′45.5″W
51°17′42.3″N 129°00′29.0″W
51°19′24.5″N 129°00′53.6″W
and 51°24′44.2″N 128°47′58.3″W

DFO(6203461-03)

07-APR-2017 LNM/D. 28-OCT-2016

Add black and yellow North cardinal lighted pillar buoy Q, marked EFJ
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: CA270390, CA370190

54°17′47.4″N 131°19′36.1″W

(P2017006) LL(750.6) DFO(6203463-01)

07-APR-2017 LNM/D. 28-OCT-2016

Add green port hand lighted pillar buoy QG with RACON, marked EF9
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA270390, CA370190

54°16′00.0″N 131°05′24.0″W

(P2017007) LL(750.5) DFO(6203464-01)

07-APR-2017 LNM/D. 28-OCT-2016

Chart no. 3002

Amend Yellow-Black-Yellow West cardinal lighted Pillar buoy Q(9) 15s, marked EOB to read Yellow-Black-Yellow West cardinal lighted Pillar buoy Q(9) 15s with Bell, marked EOB — 53°55′35.6″N 130°54′24.5″W
(P2017009) LL(747.5) DFO(6203465-01)

07-APR-2017 — LNM/D. 28-OCT-2016

Add red starboard hand lighted pillar buoy Fl R, marked EF2 — 54°02′32.4″N 130°54′21.6″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA270390, CA370731, CA470314
(P2017011) LL(749.2) DFO(6203466-01)

07-APR-2017 — LNM/D. 28-OCT-2016

Add out of position red starboard hand lighted pillar buoy Fl R, marked E88 — 53°16′17.1″N 130°31′45.3″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA270724
(P2017012) LL(740.5) DFO(6203467-01)

28-OCT-2016 — LNM/D. 08-APR-2016

Add wreck least depth known of 44 fathoms — 54°24′16.2″N 131°11′07.7″W
(See Chart No. 1, K26)
DFO(6203374-01)

08-APR-2016 — LNM/D. 25-MAR-2016

Amend Fl to read Fl 6s against light — 53°38′04.8″N 130°33′52.4″W
(See Chart No. 1,P1)
This notice affects Electronic Navigational Chart: CA270724, CA470622
(P2016036) LL(742) DFO(6203243-01)

25-MAR-2016 — LNM/D. 25-DEC-2015

Amend Q R to read Fl G against light — 53°37′44.1″N 130°32′24.1″W
(See Chart No. 1,P1)
This notice affects Electronic Navigational Chart: CA370299
(P201632) LL(736) DFO(6203239-04)

25-DEC-2015 — LNM/D. 24-OCT-2014

Chart no. 3002

Add Pilots transferred by helicopter within a radius of 1.5 nautical miles of position given — 54°19′00.0″N 131°02′30.0″W
(See Chart No. 1, T1.4,Tb) *DFO(6203161-01)*
This notice affects Electronic Navigational Chart: CA270390, CA370190

24-OCT-2014 LNM/D. 10-OCT-2014

Delete depth of 9 fathoms 52°35′35.0″N 129°18′39.0″W
(See Chart No. 1, I10)
DFO(6202911-15)

24-OCT-2014 LNM/D. 10-OCT-2014

Add depth of 6 fathoms 5 feet 52°35′27.5″N 129°18′40.5″W
(See Chart No. 1, I10)
DFO(6202911-16)

24-OCT-2014 LNM/D. 10-OCT-2014

Delete depth of 15 fathoms 52°33′34.0″N 129°19′20.0″W
(See Chart No. 1, I10)
DFO(6202911-17)

24-OCT-2014 LNM/D. 10-OCT-2014

Add depth of 12 fathoms 52°33′28.5″N 129°19′25.5″W
(See Chart No. 1, I10)
DFO(6202911-18)

10-OCT-2014 LNM/D. 13-JUN-2014

Add depth of 3 fathoms 5 feet 52°27′35.0″N 129°15′53.0″W
(See Chart No. 1, I10)
DFO(6202906-01)

10-OCT-2014 LNM/D. 13-JUN-2014

Delete depth of 21 fathoms 52°27′50.0″N 129°16′00.0″W
(See Chart No. 1, I10)
DFO(6202906-02)

13-JUN-2014 LNM/D. 25-APR-2014

Chart no. 3002

Reposition yellow ODAS/SADO lighted buoy Fl (5) Y, marked 46145 — from 54°23′00.0″N 132°25′40.0″W to 54°22′00.0″N 132°26′38.0″W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA270390
DFO(6202847-02)

25-APR-2014 LNM/D. 26-OCT-2012

Add marine park — joining 52°48′42.0″N 131°39′22.0″W 52°50′05.0″N 131°20′10.0″W 52°26′49.0″N 131°05′19.0″W 52°12′29.0″N 130°49′00.0″W 51°47′58.0″N 130°53′31.0″W 52°00′00.0″N 131°18′00.0″W 52°40′36.0″N 132°13′16.0″W and 52°44′10.0″N 132°06′17.0″W
(See Chart No. 1, Nf)
This notice affects Electronic Navigational Chart: CA270390
DFO(6202727-04)

25-APR-2014 LNM/D. 26-OCT-2012

Add National park, marked NPR/RPN 52°30′00.0″N 131°52′00.0″W
(See Chart No. 1 Ef)
DFO(6202727-05)

25-APR-2014 LNM/D. 26-OCT-2012

Add GWAII HAANAS NATIONAL PARK RESERVE, NATIONAL MARINE CONSERVATION AREA RESERVE AND HAIDA HERITAGE SITE
NPR
RÉSERVE DE PARC NATIONAL GWAII HAANAS, RÉSERVE D′AIRE MARINE NATIONALE DE CONSERVATION ET SITE DU PATRIMOINE HAÏDA
RPN — 53°57′00.0″N 128°05′00.0″W
DFO(6202727-06)
This notice affects Electronic Navigational Chart: CA270390

26-OCT-2012 LNM/D. 28-SEP-2012

Reposition yellow ODAS/SADO lighted buoy Fl (5) Y, marked 46204 — from 51°23′00.0″N 128°44′06.0″W to 51°23′31.3″N 128°45′54.6″W
(See Chart No. 1, Q58)
(P2012048) LL(582.5) DFO(6202619-01)

This notice affects Electronic Navigational Chart: CA270084

Chart no. 3002

26-OCT-2012 LNM/D. 28-SEP-2012

Reposition yellow ODAS/SADO lighted buoy Fl (5) Y, marked 46185 from 52°24′20.0″N 129°47′10.0″W to 52°25′02.6″N 129°48′57.7″W
(See Chart No. 1, Q58)

(P2012049) LL(621.5) DFO(6202620-01)

28-SEP-2012 LNM/D. 17-FEB-2012

Delete depth of 10 fathoms 52°51′02.0″N 129°46′12.0″W
(See Chart No. 1, I10)

DFO(6202603-01)

This notice affects Electronic Navigational Chart: CA270084

28-SEP-2012 LNM/D. 17-FEB-2012

Add depth of 7 fathoms 3 feet 52°50′57.0″N 129°46′03.0″W
(See Chart No. 1, I10)

DFO(6202603-02)

This notice affects Electronic Navigational Chart: CA270084

17-FEB-2012 LNM/D. 10-JUN-2011

Amend Chart/Carte 3802 to read Chart/Carte 3800 54°28′30.0″N 132°26′30.0″W
(See Chart No. 1, A18)

DFO(6202537-01)

10-JUN-2011 LNM/D. 18-SEP-2009

Delete depth of 20 fathoms 54°28′44.0″N 133°03′12.4″W
(See Chart No. 1, I10)

DFO(6202432-01)

10-JUN-2011 LNM/D. 18-SEP-2009

Add depth of 14 fathoms 54°28′57.1″N 133°03′41.7″W
(See Chart No. 1, I10)

DFO(6202432-02)

10-JUN-2011 LNM/D. 18-SEP-2009

Delete depth of 21 fathoms 54°25′26.0″N 133°03′40.9″W
(See Chart No. 1, I10)

DFO(6202432-03)

Chart no. 3002

10-JUN-2011 LNM/D. 18-SEP-2009

Add depth of 15 fathoms 54°25′23.2″N 133°03′38.5″W
(See Chart No. 1, I10)

DFO(6202432-04)

18-SEP-2009 LNM/D. 21-AUG-2009

Add radar transponder beacon against light Fl R 15M 50°58′32.9″N 127°43′34.9″W
(See Chart No. 1, S3.3)

(P2009073) LL(576) DFO(6202100-01)

This notice affects Electronic Navigational Chart:
CA370109, CA470307

21-AUG-2009 LNM/D. 20-MAR-2009

Add submarine cable joining 54°26′06.0″N 133°59′18.1″W
(See Chart No. 1, L30.1) 54°29′58.4″N 133°32′01.8″W
54°35′31.0″N 133°14′57.6″W
54°35′12.1″N 132°59′59.5″W
54°30′23.7″N 132°29′25.9″W
54°30′14.9″N 132°09′12.5″W
54°34′48.4″N 131°58′06.6″W
54°39′55.3″N 131°53′01.0″W
and 55°01′00.0″N 131°53′23.5″W

(USCG:USLNM17 26/09) DFO(6202092-01)

20-MAR-2009 LNM/D. 26-DEC-2008

Add submarine cable between 50°45′00.0″N 133°14′10.0″W
(See Chart No. 1, L30.1) and 51°17′02.0″N 134°00′00.0″W

(USCG:USLNM13 53/08) DFO(6202017-01)

26-DEC-2008 LNM/D. 04-JUL-2008

Delete dangerous underwater rock of 6 feet or less and legend Rep (1999) 52°35′35.0″N 129°28′09.5″W
(See Chart No. 1, K13 and I3.2) *DFO(6201966-01)*

26-DEC-2008 LNM/D. 04-JUL-2008

Chart no. 3002

Delete dangerous underwater rock of 6 feet or less and legend Rep (1999) 52°29′46.0″N 129°29′01.5″W
(See Chart No. 1, K13 and I3.2) *DFO(6201966-05)*

26-DEC-2008 LNM/D. 04-JUL-2008

Add depth of 1 fathom 52°29′47.1″N 129°29′01.1″W
(See Chart No. 1, I10)
DFO(6201966-06)

04-JUL-2008 LNM/D. 30-MAY-2008

Add depth of 0 fathoms 3 feet 53°37′12.8″N 131°50′26.7″W
(See Chart No. 1, I10)
DFO(6201874-01)

04-JUL-2008 LNM/D. 30-MAY-2008

Add depth of 11 fathoms 53°51′24.2″N 131°16′47.1″W
(See Chart No. 1, I10)
DFO(6201874-02)

04-JUL-2008 LNM/D. 30-MAY-2008

Delete depth of 9 fathoms 54°15′36.0″N 130°37′48.0″W
(See Chart No. 1, I10)
DFO(6201874-03)

04-JUL-2008 LNM/D. 30-MAY-2008

Add depth of 6 fathoms 3 feet 54°15′41.1″N 130°38′28.2″W
(See Chart No. 1, I10)
DFO(6201874-04)

04-JUL-2008 LNM/D. 30-MAY-2008

Add depth of 10 fathoms 5 feet 53°53′55.5″N 131°15′31.3″W
(See Chart No. 1, I10)
DFO(6201874-05)

04-JUL-2008 LNM/D. 30-MAY-2008

Add depth of 7 fathoms 3 feet 52°23′19.1″N 129°02′10.6″W
(See Chart No. 1, I10)
DFO(6201874-06)

Chart no. 3002

04-JUL-2008 LNM/D. 30-MAY-2008

Add depth of 1 fathom 2 feet 52°24′48.9″N 128°48′18.7″W
(See Chart No. 1, I10)

DFO(6201874-07)

30-MAY-2008 LNM/D. 14-DEC-2007

Amend 2 Lts Ldg F to read F RWG against light 53°25′13.0″N 131°54′37.0″W

DFO(6201841-01)

14-DEC-2007 LNM/D. 23-NOV-2007

Delete non-dangerous wreck, depth unknown and legend Rep (1989) 50°51′48.6″N 128°11′43.1″W PA
(See Chart No.1, K29) *DFO(6201787-01)*

This notice affects Electronic Navigational Chart: CA370109

23-NOV-2007 LNM/D. 02-MAY-2003

Add tower 53°58′41.1″N 131°32′53.0″W
(See Chart No. 1, E20)

DFO(6201777-01)

23-NOV-2007 LNM/D. 02-MAY-2003

Add light Mo(U) 29m 5M (Priv) 53°58′41.1″N 131°32′53.0″W
(See Chart No. 1, P65)

DFO(6201777-02)

23-NOV-2007 LNM/D. 02-MAY-2003

Add radar reflector against tower 53°58′41.1″N 131°32′53.0″W
(See Chart No. 1, S4)

DFO(6201777-03)

23-NOV-2007 LNM/D. 02-MAY-2003

Add fog signal FogSig20s against tower 53°58′41.1″N 131°32′53.0″W
(See Chart No. 1, R20)

DFO(6201777-04)

02-MAY-2003 LNM/D. 11-APR-2003

Chart no. 3002

Delete Fog Sig 50°46′57.2″N 128°25′32.8″W

(P2003026) LL(66) DFO(6200535-01)

02-MAY-2003 LNM/D. 11-APR-2003
Delete Fog Sig 51°14′54.3″N 127°49′55.7″W

(P2003031) LL(579) DFO(6200535-02)

02-MAY-2003 LNM/D. 11-APR-2003
Delete Fog Sig 52°15′41.9″N 128°43′12.5″W

(P2003033) LL(619) DFO(6200535-11)

11-APR-2003 LNM/D. 14-FEB-2003
Delete light FI 54°42′14.0″N 132°52′18.0″W

DFO(6200521-01)

11-APR-2003 LNM/D. 14-FEB-2003
Add submarine cable joining 50°45′00.0″N 131°36′05.8″W
51°00′00.0″N 132°00′00.0″W
and 53°30′00.0″N 134°00′00.0″W
With this notification, preliminary Notice 2345(P)/1999 is now cancelled for this chart. This action is now permanent.

DFO(6200524-01)

14-FEB-2003 LNM/D. 25-JAN-2002
Delete radiobeacon marked RC 52°15′42.0″N 128°43′18.0″W

DFO(6200492-01)

25-JAN-2002 LNM/D. 26-OCT-2001
Reposition radar transponder beacon (RACON) from 54°11′12.0″N 131°38′46.0″W
to 54°09′40.0″N 131°39′35.2″W

(P2001114) DFO(6201084-01)

26-OCT-2001 LNM/D. 25-MAY-2001

Chart no. 3002

Delete radiobeacon and legend RC 50°46′54.0″N 128°25′30.0″W

(P2001108) LL(66) DFO(6201085-01)

25-MAY-2001 LNM/D. 09-MAR-2001

Amend FW FlR 10s 86ft 19M to read FlR 15M 50°58′33.1″N 127°43′34.8″W

(P2001034P) LL(576) DFO(6201024-01)

09-MAR-2001 LNM/D. 23-FEB-2001

Reposition yellow ODAS/SADO light buoy Fl(5)Y marked 46147 from 51°49′38.0″N 131°12′04.0″W to 51°49′42.0″N 131°13′30.0″W

(CCG-P00-217) LL(769.5) DFO(6200990-01)

09-MAR-2001 LNM/D. 23-FEB-2001

Reposition yellow ODAS/SADO light buoy Fl(5)Y marked 46208 from 52°29′24.0″N 132°42′00.0″W to 52°30′54.0″N 132°41′30.0″W

(CCG-P00-224) LL(812) DFO(6200996-01)

23-FEB-2001 LNM/D. 07-JUL-2000

Reposition yellow ODAS light buoy Fl(5)Y marked 46207 from 50°51′36.0″N 129°54′36.0″W to 50°52′30.7″N 129°54′48.0″W

(CCG-P00-223) LL(67.4) DFO(6200995-01)

07-JUL-2000 LNM/D. 21-APR-2000

Delete Fog Sig 53°29′50.0″N 130°38′00.0″W

(P2000016) LL(734) DFO(6200767-06)

21-APR-2000 LNM/D. 07-APR-2000

Amend Fl(2) 8s 97ft to read Fl(2) 9s 92ft 54°17′41.0″N 130°52′42.0″W

(CCG-P00-008) LL(752) DFO(6200520-01)

07-APR-2000 LNM/D. 10-MAR-2000

Chart no. 3002

Delete light 54°17′41.0″N 130°52′42.0″W

(CCG-P00-006) LL(752) DFO(6200341-01)

10-MAR-2000 LNM/D. 31-DEC-1999

Delete Fog Sig 54°15′23.0″N 133°03′30.0″W

(CCG-P00-001) LL(807) DFO(6200206-01)