Chart no. 3440

3440 - Race Rocks to/à D'Arcy Island - New Edition - 01-JUL-2005 - NAD 1983

03-NOV-2023 LNM/D. 23-JUN-2023

Delete obstruction with known depth of 55 metres 48°24′04.2″N 123°24′32.3″W
(See Chart 1, K41)
This notice affects Electronic Navigational Chart: CA470075, CA570562 *DFO(6204813-01)*

23-JUN-2023 LNM/D. 16-JUN-2023

Delete harbour limit and legend ESQUIMALT between 48°25′22.5″N 123°25′09.0″W
(See Chart 1, N49) and 48°25′22.5″N 123°27′58.0″W
This notice affects Electronic Navigational Chart: CA470075, CA570138 *DFO(6204773-05)*

23-JUN-2023 LNM/D. 16-JUN-2023

Add harbour limit between 48°25′18.1″N 123°25′11.7″W
(See Chart 1, N49) and 48°23′10.2″N 123°25′11.7″W

DFO(6204773-06)

23-JUN-2023 LNM/D. 16-JUN-2023

Add harbour limit and legend ESQUIMALT between 48°23′10.2″N 123°25′11.7″W
(See Chart 1, N49) and 48°22′58.0″N 123°28′59.0″W
This notice affects Electronic Navigational Chart: CA470075 *DFO(6204773-07)*

23-JUN-2023 LNM/D. 16-JUN-2023

Delete harbour limit between 48°23′40.0″N 123°18′18.5″W
(See Chart 1, N49) and 48°23′03.0″N 123°28′47.5″W
This notice affects Electronic Navigational Chart: CA470075 *DFO(6204773-08)*

23-JUN-2023 LNM/D. 16-JUN-2023

Delete VICTORIA 48°23′34.5″N 123°20′19.8″W
This notice affects Electronic Navigational Chart: CA470075

DFO(6204773-09)

23-JUN-2023 LNM/D. 16-JUN-2023

Chart no. 3440

Delete VICTORIA 48°23′15.9″N 123°25′41.5″W
This notice affects Electronic Navigational Chart: CA470075
DFO(6204773-10)

16-JUN-2023 LNM/D. 14-APR-2023

Delete submarine cable joining 48°24′53.9″N 123°23′02.0″W
(See Chart 1, L30.1) 48°24′46.4″N 123°23′06.3″W
This notice affects Electronic Navigational Chart: 48°24′38.8″N 123°23′02.2″W
CA470075, CA570562 and 48°24′23.4″N 123°23′16.3″W
DFO(6204772-01)

16-JUN-2023 LNM/D. 14-APR-2023

Delete cable sign 48°24′54.8″N 123°23′02.3″W
(See Chart 1, Q123)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6204772-02)*

14-APR-2023 LNM/D. 28-OCT-2022

Add lighted offshore ODAS/SADO platform Fl(5) Y(Priv) 48°23′38.1″N 123°18′30.7″W
(See Chart 1, P2)
This notice affects Electronic Navigational Chart: CA470075, CA570214 *DFO(6204733-01)*

28-OCT-2022 LNM/D. 22-APR-2022

Delete depth of 3 metres 48°33′34.6″N 123°16′29.3″W
(See Chart 1, I10)
DFO(6204656-18)

28-OCT-2022 LNM/D. 22-APR-2022

Add depth of 1.0 metre 48°33′35.1″N 123°16′28.0″W
(See Chart 1, I10)
DFO(6204656-19)

28-OCT-2022 LNM/D. 22-APR-2022

Add rock which covers and uncovers with drying height of 0.6 metre 48°33′36.8″N 123°16′34.8″W
(See Chart 1, K11)
DFO(6204656-20)

28-OCT-2022 LNM/D. 22-APR-2022

Chart no. 3440

Add rock which covers and uncovers with drying height of 0.1 metre 48°33′50.7″N 123°15′51.4″W
(See Chart 1, K11)

DFO(6204656-21)

28-OCT-2022 LNM/D. 22-APR-2022

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 228 metres (See Chart 1, L25) 48°29′45.1″N 123°11′30.3″W

DFO(6204660-05)

22-APR-2022 LNM/D. 16-APR-2021

Delete ANCHORAGE PROHIBITED MOUILLANGE INTERDIT 48°23′54.5″N 123°23′17.6″W
This notice affects Electronic Navigational Chart: CA470075

DFO(6204592-03)

22-APR-2022 LNM/D. 16-APR-2021

Delete anchoring prohibited area (See Chart No. 1, N20) between 48°23′03.0″N 123°28′47.0″W and 48°23′40.0″N 123°18′17.0″W

This notice affects Electronic Navigational Chart: CA470075 *DFO(6204592-04)*

16-APR-2021 LNM/D. 18-SEP-2020

Add foul ground (See Chart No. 1, K31) 48°26′41.5″N 123°26′23.7″W
This notice affects Electronic Navigational Chart: CA470075, CA570138

DFO(6204435-01)

16-APR-2021 LNM/D. 18-SEP-2020

Add foul ground (See Chart No. 1, K31) 48°26′58.1″N 123°26′51.0″W
This notice affects Electronic Navigational Chart: CA470075, CA570138

DFO(6204435-02)

18-SEP-2020 LNM/D. 27-MAR-2020

Add outfall pipe (See Chart No. 1, L41.1) joining 48°25′09.7″N 123°23′50.0″W 48°25′06.4″N 123°23′49.7″W and 48°24′14.7″N 123°24′26.1″W
This notice affects Electronic Navigational Chart: CA470075, CA570562

DFO(6204366-01)

27-MAR-2020 LNM/D. 16-AUG-2019

Chart no. 3440

Reposition yellow ODAS/SADO lighted super-buoy Fl(4) Y 20s, marked 46088 (See Chart No. 1, Q58) — from 48°19′53.0″N 123°10′22.0″W to 48°19′56.3″N 123°10′44.1″W

(USCG:District 13 50/19) DFO(6204260-01)

16-AUG-2019 — LNM/D. 21-DEC-2018

Amend F Y 11m to read F G 11m against light (See Chart No. 1, P20.2) — 48°26′33.7″N 123°26′19.1″W

This notice affects Electronic Navigational Chart: CA470075, CA570138 — *(P2019070) LL(200) DFO(6204071-01)*

16-AUG-2019 — LNM/D. 21-DEC-2018

Amend F Y 6m to read F G 6m against light (See Chart No. 1, P20.2) — 48°26′30.9″N 123°26′20.2″W

This notice affects Electronic Navigational Chart: CA470075, CA570138 — *(P2019071) LL(199) DFO(6204071-02)*

16-AUG-2019 — LNM/D. 21-DEC-2018

Replace bearing of 015° with 014° (See Chart No. 1, M1) — 48°25′33.5″N 123°26′47.0″W

This notice affects Electronic Navigational Chart: CA470075 — *(P2019070) LL(200) DFO(6204071-07)*

16-AUG-2019 — LNM/D. 21-DEC-2018

Replace bearing of 195° with 194° (See Chart No. 1, M1) — 48°26′21.0″N 123°26′27.0″W

This notice affects Electronic Navigational Chart: CA470075 — *(P2019070) LL(200) DFO(6204071-08)*

21-DEC-2018 — LNM/D. 20-JUL-2018

Amend Victoria TIDAL INFORMATION/RENSEIGNEMENTS SUR LES MARÉES HHW/PMS 3.4 to read 3.1 — 48°28′20.5″N 123°36′39.0″W

DFO(6203939-01)

20-JUL-2018 — LNM/D. 22-JUN-2018

Delete green port hand lighted pillar buoy Fl G, marked V17 (See Chart No. 1, Qg) — 48°25′49.8″N 123°26′39.2″W

This notice affects Electronic Navigational Chart: CA470075, CA570138 — *(P2018066) LL(198) DFO(6203795-01)*

Chart no. 3440

20-JUL-2018 LNM/D. 22-JUN-2018

Add green port hand lighted pillar buoy Fl G, marked V17 — 48°25′50.1″N 123°26′42.5″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA470075, CA570138 — *(P2018066) LL(198) DFO(6203795-02)*

20-JUL-2018 LNM/D. 22-JUN-2018

Delete depth of 3.1 metres — 48°25′50.3″N 123°26′44.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075 — *DFO(6203795-03)*

22-JUN-2018 LNM/D. 11-MAY-2018

Amend existing outfall to extend 485 metres further. — between 48°23′54.2″N 123°20′48.2″W and 48°23′38.8″N 123°20′45.7″W
This notice affects Electronic Navigational Chart: CA470075, CA570214

DFO(6203792-01)

11-MAY-2018 LNM/D. 30-MAR-2018

Delete breakwater — between 48°24′52.0″N 123°23′13.4″W and 48°24′51.0″N 123°23′12.5″W
(See Chart No. 1, F4.1)
This notice affects Electronic Navigational Chart: CA470075, CA570562 — *DFO(6203756-01)*

30-MAR-2018 LNM/D. 02-MAR-2018

Reposition yellow ODAS/SADO lighted super-buoy Fl Y, marked 46088 — from 48°20′01.5″N 123°09′52.6″W to 48°19′53.1″N 123°10′22.6″W
(See Chart No. 1, Q58)

DFO(6203692-01)

30-MAR-2018 LNM/D. 02-MAR-2018

Amend yellow ODAS/SADO lighted super-buoy Fl Y, marked 46088 to read yellow ODAS/SADO lighted super-buoy Fl (4) Y 20s, marked 46088 — 48°19′53.1″N 123°10′22.6″W
(See Chart No. 1, Q58)

DFO(6203692-02)

02-MAR-2018 LNM/D. 31-MAR-2017

Chart no. 3440

Delete anchoring prohibited area — between 48°25′58.1″N 123°26′18.8″W and 48°26′27.9″N 123°26′11.7″W
(See Chart No. 1, N20)

This notice affects Electronic Navigational Chart: CA470075, CA570138 — *DFO(6203638-01)*

02-MAR-2018 — LNM/D. 31-MAR-2017

Delete anchoring prohibited area — between 48°25′57.9″N 123°26′20.0″W and 48°26′13.5″N 123°26′50.0″W
(See Chart No. 1, N20)

This notice affects Electronic Navigational Chart: CA470075, CA570138 — *DFO(6203638-02)*

02-MAR-2018 — LNM/D. 31-MAR-2017

Add anchoring prohibited area — between 48°26′53.5″N 123°27′01.8″W and 48°26′52.1″N 123°25′58.0″W
(See Chart No. 1, N20)

This notice affects Electronic Navigational Chart: CA470075, CA570138 — *DFO(6203638-03)*

02-MAR-2018 — LNM/D. 31-MAR-2017

Amend Spoil Ground symbol to abandoned Spoil ground symbol — 48°22′17.0″N 123°21′52.0″W
(See Chart No. 1, N62.2)
This notice affects Electronic Navigational Chart: CA470075 — *DFO(6203641-01)*

31-MAR-2017 — LNM/D. 03-MAR-2017

Add floating breakwater, Bkw — between 48°26′16.6″N 123°26′46.9″W and 48°26′19.7″N 123°26′43.2″W
(See Chart No. 1, F4.1)
This notice affects Electronic Navigational Chart: CA470075, CA570138 — *DFO(6203460-01)*

03-MAR-2017 — LNM/D. 18-SEP-2015

Delete port hand daybeacon — 48°25′28.6″N 123°17′22.4″W
(See Chart No. 1, Qt)
This notice affects Electronic Navigational Chart: CA470075, CA570214 — *(P2017003) DFO(6203452-01)*

03-MAR-2017 — LNM/D. 18-SEP-2015

Chart no. 3440

Add black and yellow North cardinal pillar buoy, marked VJ — 48°25′30.6″N 123°17′23.4″W
(See Chart No. 1, Q130.3)
This notice affects Electronic Navigational Chart: CA470075, CA570214 — *(P2017002) DFO(6203452-02)*

18-SEP-2015 — LNM/D. 19-JUN-2015

Add depth of 13.7 metres — 48°25′44.4″N 123°13′13.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075, CA570214 — *DFO(6203086-01)*

18-SEP-2015 — LNM/D. 19-JUN-2015

Delete depth of 15.5 metres — 48°25′43.0″N 123°13′11.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075 — *DFO(6203086-02)*

19-JUN-2015 — LNM/D. 03-OCT-2014

Replace VESSEL TRAFFIC SYSTEM SERVICES DU TRAFIC MARITIME — 48°25′52.0″N 123°36′00.0″W
3rd paragraph note with — *DFO(6203038-07)*

Limits of the Victoria or Seattle Vessel Traffic Services Zones. Applicable vessels must participate fully on the appropriate sector frequency reporting at all calling-in points and upon entering or leaving these zones.

Limites des Zones de services du trafic maritime de Victoria ou de Seattle. Les navires concernés doivent être à l'écoute de la fréquence de secteur approprié et doivent envoyer un compte rendu à chaque point d'appel radio, ainsi qu'à l'entrée et à la sortie de ces zones.

This notice affects Electronic Navigational Chart: CA470075

03-OCT-2014 — LNM/D. 12-SEP-2014

Add depth of 1.5 metres — 48°27′53.5″N 123°02′58.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370367 — *DFO(6202905-01)*

12-SEP-2014 — LNM/D. 27-JUN-2014

Chart no. 3440

Delete radio mast — 48°23′17.0″N 123°29′29.0″W
(See Chart No. 1, E28)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6202898-03)*

12-SEP-2014 LNM/D. 27-JUN-2014

Delete radio mast marked RLts — 48°23′10.5″N 123°29′31.0″W
(See Chart No. 1, E28,P61.1)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6202898-04)*

27-JUN-2014 LNM/D. 13-JUN-2014

Delete fishing prohibited area — joining 48°25′02.0″N 123°27′32.0″W
(See Chart No. 1, N21) — 48°24′57.0″N 123°27′17.0″W
This notice affects Electronic Navigational Chart: — 48°24′50.0″N 123°27′22.0″W
CA470075 — 48°24′54.0″N 123°27′37.0″W
and 48°25′02.0″N 123°27′32.0″W

DFO(6202866-01)

27-JUN-2014 LNM/D. 13-JUN-2014

Add fishing prohibited area — joining 48°24′41.8″N 123°27′03.8″W
(See Chart No. 1, N21) — 48°24′38.4″N 123°26′47.6″W
48°24′30.3″N 123°26′51.7″W
This notice affects Electronic Navigational Chart: — 48°24′33.9″N 123°27′07.8″W
CA470075 — and 48°24′41.8″N 123°27′03.8″W

DFO(6202866-02)

27-JUN-2014 LNM/D. 13-JUN-2014

Add submarine cable — joining 48°25′54.5″N 123°26′18.5″W
(See Chart No. 1, L30.1) — 48°25′52.5″N 123°26′27.5″W
This notice affects Electronic Navigational Chart: — 48°25′48.0″N 123°26′30.0″W
CA470075 — 48°25′01.5″N 123°26′49.5″W
and 48°24′39.0″N 123°26′59.5″W

DFO(6202866-03)

27-JUN-2014 LNM/D. 13-JUN-2014

Delete anchor berth, marked E — 48°24′43.0″N 123°26′41.0″W
(See Chart No. 1, N11.1)

DFO(6202866-04)

This notice affects Electronic Navigational Chart: CA470075

Chart no. 3440

13-JUN-2014 LNM/D. 30-MAY-2014

Delete depth of 31 metres 48°18′31.0″N 123°04′05.0″W
(See Chart No. 1, I10)

DFO(6202846-01)

13-JUN-2014 LNM/D. 30-MAY-2014

Add depth of 23.5 metres 48°18′26.5″N 123°04′13.5″W
(See Chart No. 1, I10)

DFO(6202846-02)

13-JUN-2014 LNM/D. 30-MAY-2014

Add depth of 25.5 metres 48°18′40.0″N 123°04′00.0″W
(See Chart No. 1, I10)

DFO(6202846-03)

13-JUN-2014 LNM/D. 30-MAY-2014

Delete depth of 29.3 metres 48°18′46.0″N 123°04′01.0″W
(See Chart No. 1, I10)

DFO(6202846-04)

13-JUN-2014 LNM/D. 30-MAY-2014

Delete depth of 25.6 metres 48°19′23.5″N 123°03′36.0″W
(See Chart No. 1, I10)

DFO(6202846-05)

13-JUN-2014 LNM/D. 30-MAY-2014

Add depth of 21.5 metres 48°19′30.5″N 123°03′28.0″W
(See Chart No. 1, I10)

DFO(6202846-06)

13-JUN-2014 LNM/D. 30-MAY-2014

Add depth of 16.2 metres 48°19′51.0″N 123°03′08.0″W
(See Chart No. 1, I10)

DFO(6202846-07)

30-MAY-2014 LNM/D. 11-OCT-2013

Chart no. 3440

Delete Custom Office 48°25′29.0″N 123°22′07.0″W
(See Chart No. 1, F61)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6202835-05)*

30-MAY-2014 LNM/D. 11-OCT-2013

Add Custom Office 48°25′17.0″N 123°22′47.0″W
(See Chart No. 1, F61)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6202835-06)*

11-OCT-2013 LNM/D. 15-FEB-2013

Add obstruction, least depth known 113 metres 48°18′00.6″N 123°23′44.5″W
(See Chart No. 1 K41)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6202740-01)*

11-OCT-2013 LNM/D. 15-FEB-2013

Add obstruction, least depth known 55 metres 48°24′04.2″N 123°24′32.3″W
(See Chart No. 1, K41)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6202740-02)*

15-FEB-2013 LNM/D. 30-NOV-2012

Delete depth of 10.1 metres 48°26′45.4″N 123°15′57.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6202678-13)*

15-FEB-2013 LNM/D. 30-NOV-2012

Delete depth of 11 metres 48°25′42.2″N 123°15′18.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6202678-14)*

15-FEB-2013 LNM/D. 30-NOV-2012

Delete depth of 5.5 metres 48°25′43.4″N 123°17′30.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075 *DFO(6202678-15)*

15-FEB-2013 LNM/D. 30-NOV-2012

Add depth of 4.6 metres 48°27′01.5″N 123°17′00.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075, CA570214 *DFO(6202678-16)*

Chart no. 3440

15-FEB-2013 LNM/D. 30-NOV-2012

Add depth of 8 metres 48°26′44.4″N 123°15′54.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075, CA570214 *DFO(6202678-17)*

15-FEB-2013 LNM/D. 30-NOV-2012

Add depth of 7.6 metres 48°25′43.4″N 123°15′19.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075, CA570214 *DFO(6202678-18)*

15-FEB-2013 LNM/D. 30-NOV-2012

Add depth of 2.9 metres 48°25′42.5″N 123°17′29.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075, CA570214 *DFO(6202678-19)*

15-FEB-2013 LNM/D. 30-NOV-2012

Add depth of 2.8 metres 48°25′15.3″N 123°17′21.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470075, CA570214 *DFO(6202678-20)*

30-NOV-2012 LNM/D. 31-AUG-2012

Reposition yellow ODAS/SADO lighted buoy Fl Y, marked 46088 from 48°20′00.0″N 123°10′00.0″W
(See Chart No. 1, Q58) to 48°20′01.4″N 123°09′52.6″W

(NOS:46088) DFO(6202639-01)

31-AUG-2012 LNM/D. 15-JUN-2012

Add wreck, least depth known of 5.3 metres 48°18′42.5″N 123°32′30.5″W
(See Chart No. 1, K26)

DFO(6202588-01)

This notice affects Electronic Navigational Chart: CA470075, CA570101

15-JUN-2012 LNM/D. 08-JUN-2012

Chart no. 3440

Delete depth of 5.5 metres 48°24′12.6″N 123°17′06.8″W
(See Chart No. 1, I10)

DFO(6202566-01)

This notice affects Electronic Navigational Chart: CA470075, CA570214

15-JUN-2012 LNM/D. 08-JUN-2012

Add depth of 4.7 metres 48°24′12.5″N 123°17′06.2″W
(See Chart No. 1, I10)

DFO(6202566-02)

This notice affects Electronic Navigational Chart: CA470075, CA570214

15-JUN-2012 LNM/D. 08-JUN-2012

Add depth of 5.9 metres 48°25′03.7″N 123°14′03.7″W
(See Chart No. 1, I10)

DFO(6202566-06)

This notice affects Electronic Navigational Chart: CA470075, CA570214

08-JUN-2012 LNM/D. 10-JUN-2011

Delete black, red and black isolated danger lighted pillar buoy Fl(2) 5s, marked DH 48°21′05.6″N 123°02′45.7″W
(See Chart No. 1, Q130.4) *LL(16361) DFO(6202564-01)*

10-JUN-2011 LNM/D. 20-MAR-2009

Add submarine pipeline joining 48°21′37.4″N 123°32′09.3″W
(See Chart No. 1, L41.1) 48°21′37.4″N 123°32′07.5″W
and 48°21′31.6″N 123°31′53.6″W

This notice affects Electronic Navigational Chart: CA470075, CA570101 *DFO(6202435-01)*

10-JUN-2011 LNM/D. 20-MAR-2009

Chart no. 3440

Add pipeline sign 48°21′37.4″N 123°32′10.2″W
(See Chart No. 1, Qu)

DFO(6202435-02)

This notice affects Electronic Navigational Chart: CA470075, CA570101

20-MAR-2009 LNM/D. 23-NOV-2007

Replace bifurcation daybeacon with port hand daybeacon 48°25′27.7″N 123°17′39.6″W
(See Chart No. 1, Qt)

(P2009022) DFO(6202011-01)

This notice affects Electronic Navigational Chart: CA470075, CA570214

23-NOV-2007 LNM/D. 19-JAN-2007

Delete depth of 3.7 metres 48°25′15.4″N 123°23′21.3″W
(See Chart No. 1, I10)

DFO(6201780-01)

This notice affects Electronic Navigational Chart: CA470075

23-NOV-2007 LNM/D. 19-JAN-2007

Add depth of 7.6 metres 48°25′16.2″N 123°23′20.3″W
(See Chart No. 1, I10)

DFO(6201780-02)

This notice affects Electronic Navigational Chart: CA470075

19-JAN-2007 LNM/D. 05-JAN-2007

Delete depth of 7 metres 48°18′05.2″N 123°32′01.4″W
(see Chart No. 1 I10)

DFO(6201642-01)

This notice affects Electronic Navigational Chart: CA470075, CA570101

19-JAN-2007 LNM/D. 05-JAN-2007

Chart no. 3440

Add obstruction with known depth of 5 metres — 48°18′06.4″N 123°32′02.1″W
(see Chart No. 1 K41)

DFO(6201642-02)

This notice affects Electronic Navigational Chart: CA470075, CA570101

19-JAN-2007 — LNM/D. 05-JAN-2007

Add submarine cable — joining 48°18′06.4″N 123°32′02.1″W
(see Chart No. 1 L30.1) — 48°18′03.6″N 123°31′53.4″W
48°17′58.9″N 123°31′51.9″W
and 48°17′55.0″N 123°31′53.7″W

This notice affects Electronic Navigational Chart: CA470075, CA570101

DFO(6201642-03)

05-JAN-2007 — LNM/D. 15-DEC-2006

Delete depth of 11 metres — 48°33′05.9″N 123°14′56.8″W

DFO(6201636-01)

This notice affects Electronic Navigational Chart: CA470366

05-JAN-2007 — LNM/D. 15-DEC-2006

Add depth of 5.5 metres — 48°33′03.7″N 123°14′57.2″W

DFO(6201636-02)

This notice affects Electronic Navigational Chart: CA470366

05-JAN-2007 — LNM/D. 15-DEC-2006

Add depth of 9.8 metres — 48°33′16.6″N 123°19′59.0″W

DFO(6201636-03)

This notice affects Electronic Navigational Chart: CA370367, CA470366

15-DEC-2006

Delete yellow cautionary spherical buoy, marked NAVY — 48°23′36.0″N 123°28′36.0″W
(see Chart No. 1 Q22)

DFO(6201578-01)

This notice affects Electronic Navigational Chart: CA470075

Fisheries and Oceans Canada | Pêches et Océans Canada
Canadian Coast Guard | Garde côtière canadienne

Chart no. 3440