Chart no. 3601

3601 - Juan de Fuca Strait to/à Vancouver Harbour - New Edition - 01-JUL-2005 - NAD 1983

12-APR-2024 LNM/D. 05-JAN-2024

Delete radar transponder beacon 48°40′33.9″N 122°42′49.2″W
(See Chart 1, S3.1)

DFO(6204915-01)

12-APR-2024 LNM/D. 05-JAN-2024

Delete radar transponder beacon against buoy 48°45′18.5″N 122°46′30.5″W
(See Chart 1, S3.1)

DFO(6204922-03)

05-JAN-2024 LNM/D. 05-MAY-2023

Delete red starboard hand lighted pillar buoy with AIS 48°24′50.4″N 124°45′01.3″W
(See Chart 1, Qb, S17.2)

DFO(6204797-01)

05-JAN-2024 LNM/D. 05-MAY-2023

Add Starboard Virtual Aid to Navigation with a topmark consisting of a red cone point upward 48°24′48.4″N 124°44′41.5″W
(See Chart 1, S18.2,Q130.1)

DFO(6204797-02)

05-JAN-2024 LNM/D. 05-MAY-2023

Delete traffic separation scheme lighted pillar buoy with magenta circle and legend Racon/AIS 48°29′37.0″N 125°00′00.0″W
(See Chart 1, Q61)

DFO(6204797-03)

05-JAN-2024 LNM/D. 05-MAY-2023

Add Virtual Aid to Navigation 48°29′35.0″N 125°00′00.0″W
(See Chart 1, S18.1)

DFO(6204797-04)

05-MAY-2023 LNM/D. 19-AUG-2022

Delete aero light 48°05′33.0″N 122°55′49.2″W
(See Chart 1, P60)

DFO(6204736-01)

19-AUG-2022 LNM/D. 14-JAN-2022

Chart no. 3601

Delete topmark 48°45′53.4″N 123°00′52.7″W
(See Chart No. 1, Q9)
This notice affects Electronic Navigational Chart: CA370367 *LL(US19815) DFO(6204626-01)*

14-JAN-2022 LNM/D. 30-AUG-2019
Add AIS 48°22′01.5″N 123°02′11.2″W
(See Chart No. 1, S17.2)
DFO(6204523-01)

14-JAN-2022 LNM/D. 30-AUG-2019
Add AIS 48°40′33.7″N 122°42′48.2″W
(See Chart No. 1, S17.2)
This notice affects Electronic Navigational Chart: CA370368 *DFO(6204523-02)*

14-JAN-2022 LNM/D. 30-AUG-2019
Add AIS 48°19′45.3″N 122°58′38.2″W
(See Chart No. 1, S17.2)
DFO(6204523-03)

30-AUG-2019 LNM/D. 21-DEC-2018
Delete depth of 11 metres 49°03′43.5″N 123°42′05.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370145, CA470070 *DFO(6204118-01)*

30-AUG-2019 LNM/D. 21-DEC-2018
Add depth of 7.7 metres 49°03′44.7″N 123°42′09.0″W
(See Chart No. 1, I10)
DFO(6204118-02)

This notice affects Electronic Navigational Chart: CA370145, CA470070

21-DEC-2018 LNM/D. 01-JUN-2018
Amend Victoria TIDAL INFORMATION/RENSEIGNEMENTS SUR LES MARÉES HHW/PMS 3.4 to read 3.1 48°57′13.0″N 125°03′42.0″W
DFO(6203939-01)

01-JUN-2018 LNM/D. 11-MAY-2018

Chart no. 3601

Add Automatic Identification System Transmitter to red starboard hand lighted pillar buoy — 48°24′44.7″N 124°45′05.7″W
(See Chart No. 1, S17.2) — *LL(181.4) DFO(6203759-01)*

01-JUN-2018 — LNM/D. 11-MAY-2018

Add firing practice area with label W-237-E joining — 48°08′59.0″N 125°15′00.0″W
(See Chart No. 1, N30) — 48°08′59.0″N 125°05′00.0″W
48°29′37.0″N 125°09′01.0″W
and 48°29′17.0″N 125°15′00.0″W

DFO(6203788-14)

11-MAY-2018 — LNM/D. 05-MAY-2017

Replace Kuper Island with Penelakut Island — 48°57′45.0″N 123°39′00.0″W
This notice affects Electronic Navigational Chart: CA370145, CA470070, CA570188 — *DFO(6203754-01)*

05-MAY-2017 — LNM/D. 06-MAY-2016

Delete light — 48°19′26.0″N 122°49′09.0″W
(See Chart No. 1, P1)

(P2017024) LL(218.8) DFO(6203488-01)

06-MAY-2016 — LNM/D. 08-APR-2016

Add light Fl R — 48°05′03.7″N 123°01′48.6″W
(See Chart No. 1, P1)

DFO(6203259-01)

08-APR-2016 — LNM/D. 01-JAN-2016

Delete light — 48°19′06.5″N 122°50′37.7″W
(See Chart No. 1, P1)

DFO(6203253-02)

08-APR-2016 — LNM/D. 01-JAN-2016

Add light — 48°19′14.4″N 122°49′51.5″W
(See Chart No. 1, P1)

DFO(6203253-04)

01-JAN-2016 — LNM/D. 02-OCT-2015

Chart no. 3601

Add Automatic Identification System Transmitter to yellow pillar buoy — 48°29′36.8″N 125°00′00.0″W
(See Chart No. 1,S17.2) — *LL(PAC180.8) DFO(6203168-01)*
This notice affects Electronic Navigational Chart: CA270389

02-OCT-2015 — LNM/D. 19-JUN-2015

Delete depth of 4.3 metres — 48°49′29.0″N 123°17′50.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370367, CA470005 — *DFO(6203093-03)*

02-OCT-2015 — LNM/D. 19-JUN-2015

Add depth of 3.6 metres — 48°49′29.1″N 123°17′49.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370367, CA470005 — *DFO(6203093-04)*

19-JUN-2015 — LNM/D. 29-MAY-2015

Replace VESSEL TRAFFIC SYSTEM SERVICES DU TRAFIC MARITIME — 49°04′00.0″N 124°35′00.0″W
3rd paragraph note with — *DFO(6203038-01)*

Limits of Victoria, Prince Rupert or Seattle Vessel Traffic Services Zones. Applicable vessels must participate fully on the appropriate sector frequency reporting at all calling-in points and upon entering or leaving these zones.

Limites des Zones de services du trafic maritime de Victoria, Prince Rupert ou de Seattle. Les navires concernés doivent être à l′écoute de la fréquence de secteur approprié et doivent envoyer un compte rendu à chaque point d′appel radio, ainsi qu′à l′entrée et à la sortie de ces zones.

19-JUN-2015 — LNM/D. 29-MAY-2015

Chart no. 3601

Amend note 49°15′00.0″N 123°10′00.0″W

VANCOUVER TRAFFIC *DFO(6203038-02)*
SECTOR / SECTEUR 3
Channel/Voie 12
156.600Mhz

to read

VICTORIA TRAFFIC
SECTOR / SECTEUR 3
Channel/Voie 12
156.600Mhz

29-MAY-2015 LNM/D. 16-MAR-2012

Amend note 48°33′00.0″N 124°44′30.0″W

TOFINO TRAFFIC to read PRINCE RUPERT TRAFFIC *DFO(6202999-09)*
Channel/Voie 74 Channel/Voie 74
156.725Mhz 156.725Mhz

29-MAY-2015 LNM/D. 16-MAR-2012

Replace VESSEL TRAFFIC SYSTEM SERVICES DU TRAFIC MARITIME 49°04′00.0″N 124°35′00.0″W
3rd paragraph note with *DFO(6202999-10)*

Limits of Vancouver, Prince Rupert or Seattle Vessel Traffic Services Zones. Applicable vessels must participate fully on the appropriate sector frequency reporting at all calling-in points and upon entering or leaving these zones.

Limites des Zones de services du trafic maritime de Vancouver, Prince Rupert ou de Seattle. Les navires concernés doivent être à l′écoute de la fréquence de secteur appropriée et doivent envoyer un compte rendu à chaque point d′appel radio, ainsi qu′à l′entrée et à la sortie de ces zones.

16-MAR-2012 LNM/D. 11-NOV-2011

Reposition port hand lighted pillar buoy from 48°14′48.8″N 122°50′02.7″W
(See Chart No. 1, Qg) to 48°15′23.7″N 122°49′56.2″W

DFO(6202549-04)

Chart no. 3601

11-NOV-2011 LNM/D. 10-SEP-2010

Delete depth of 7.9 metres 48°31′46.0″N 122°40′44.9″W
(See Chart No. 1, I10)

DFO(6202521-01)

This notice affects Electronic Navigational Chart: CA370368

10-SEP-2010 LNM/D. 20-AUG-2010

Add depth of 4.9 metres 48°10′17.9″N 124°47′01.5″W
(See Chart No. 1, I10)

DFO(6202342-02)

This notice affects Electronic Navigational Chart: CA370144

10-SEP-2010 LNM/D. 20-AUG-2010

Delete depth of 18 metres 48°13′23.0″N 124°43′40.0″W
(See Chart No. 1, I10)

DFO(6202342-03)

This notice affects Electronic Navigational Chart: CA370144

10-SEP-2010 LNM/D. 20-AUG-2010

Add depth of 8.8 metres 48°13′19.9″N 124°43′26.9″W
(See Chart No. 1, I10)

DFO(6202342-04)

This notice affects Electronic Navigational Chart: CA370144

10-SEP-2010 LNM/D. 20-AUG-2010

Add depth of 13.4 metres 48°05′48.4″N 124°45′00.8″W
(See Chart No. 1, I10)

DFO(6202342-05)

This notice affects Electronic Navigational Chart: CA370144

10-SEP-2010 LNM/D. 20-AUG-2010

Add depth of 2.7 metres 48°12′49.2″N 124°42′47.3″W
(See Chart No. 1, I10)

DFO(6202342-06)

This notice affects Electronic Navigational Chart: CA370144

Chart no. 3601

20-AUG-2010 LNM/D. 06-AUG-2010

Delete depth of 10.9 metres marked Rep(1942) ED 48°07′49.7″N 124°47′12.3″W
(See Chart No. 1, I10, I1 and I3.2)

(USCG:USLNM13 27/10) DFO(6202290-01)

This notice affects Electronic Navigational Chart: CA270389, CA370144

06-AUG-2010 LNM/D. 30-OCT-2009

Add depth of 8.2 metres 48°11′44.1″N 124°46′57.2″W
(See Chart No. 1, I10)

DFO(6202288-01)

This notice affects Electronic Navigational Chart: CA370144

06-AUG-2010 LNM/D. 30-OCT-2009

Add depth of 2.3 metres 48°11′12.0″N 124°44′08.9″W
(See Chart No. 1, I10)

DFO(6202288-02)

This notice affects Electronic Navigational Chart: CA370144

30-OCT-2009 LNM/D. 18-SEP-2009

Add depth of 6.4 metres with bottom quality of R 48°18′52.0″N 122°53′01.8″W
(See Chart No. 1, I10 and J9.1)

(USCG:USLNM13 39/09) DFO(6202155-01)

This notice affects Electronic Navigational Chart: CA370141

18-SEP-2009 LNM/D. 10-JUL-2009

Add green port hand lighted pillar buoy 48°33′20.1″N 122°45′39.4″W
(See Chart No. 1, Q23 and Qg)

(USCG:USLNM13 32/09) DFO(6202124-01)

This notice affects Electronic Navigational Chart: CA370368

10-JUL-2009 LNM/D. 17-APR-2009

Chart no. 3601

Delete yellow cautionary lighted pillar buoy 48°11′16.2″N 124°49′16.7″W
(See Chart No. 1, Qm)

(USCG:USLNM13) DFO(6202080-01)

This notice affects Electronic Navigational Chart: CA370144

17-APR-2009 LNM/D. 25-JAN-2008

Delete radar transponder beacon against buoy 48°16′25.3″N 123°06′34.6″W
(See Chart No. 1, S3.6)

(USCG:USLNM13 10/09) DFO(6202027-01)

This notice affects Electronic Navigational Chart: CA370141

25-JAN-2008 LNM/D. 28-DEC-2007

Delete radar transponder beacon against buoy 48°12′21.3″N 123°06′34.6″W
(See Chart No. 1, S3.6)

(USCG:USLNM13 51/07) DFO(6201798-01)

This notice affects Electronic Navigational Chart: CA370141

28-DEC-2007 LNM/D. 16-NOV-2007

Add radar transponder beacon against buoy 48°14′04.4″N 123°31′58.7″W
(See Chart No. 1, S3.6)

(P2007106) LL(189.5) DFO(6201797-01)

This notice affects Electronic Navigational Chart: CA370141

16-NOV-2007 LNM/D. 12-OCT-2007

Add depth of 7.9 metres 48°31′46.0″N 122°40′44.9″W
(See Chart No. 1, I10)

(USCG:USLNM13 41/07) DFO(6201774-01)

This notice affects Electronic Navigational Chart: CA370368

16-NOV-2007 LNM/D. 12-OCT-2007

Chart no. 3601

Replace red starboard hand lighted pillar buoy with yellow cautionary lighted pillar buoy
(See Chart No. 1, Qf and Qm)

48°11′16.2″N 124°49′16.7″W

(USCG:USLNM13 41/07) DFO(6201775-01)

This notice affects Electronic Navigational Chart: CA370144

12-OCT-2007

LNM/D. 05-JAN-2007

Delete radio tower
(See Chart No. 1 E28)

49°11′40.0″N 123°12′20.0″W

DFO(6201763-01)

This notice affects Electronic Navigational Chart: CA370145, CA570176

12-OCT-2007

LNM/D. 05-JAN-2007

Delete dome
(See Chart No. 1 Ea)

49°11′55.0″N 123°11′11.0″W

DFO(6201763-10)

This notice affects Electronic Navigational Chart: CA370145, CA570176

12-OCT-2007

LNM/D. 05-JAN-2007

Delete legend Dm

49°11′55.0″N 123°10′48.0″W

DFO(6201763-11)

This notice affects Electronic Navigational Chart: CA370145, CA570176

05-JAN-2007

LNM/D. 01-DEC-2006

Add light
(see Chart No. 1 P1)

48°39′33.1″N 124°49′40.7″W

(P2006210) LL(179.1) DFO(6201614-01)

This notice affects Electronic Navigational Chart: CA370144

05-JAN-2007

LNM/D. 01-DEC-2006

Chart no. 3601

Delete light (see Chart No. 1 P1) — 48°31′53.2″N 124°27′28.8″W

(P2006209) DFO(6201637-01)

This notice affects Electronic Navigational Chart: CA370144, CA570184

01-DEC-2006 — LNM/D. 27-OCT-2006

Delete light (see Chart No. 1 P1) — 48°35′43.8″N 124°43′04.1″W

(P2006165) LL(180.5) DFO(6201573-01)

This notice affects Electronic Navigational Chart: CA370144

27-OCT-2006 — LNM/D. 03-MAR-2006

Delete outer limit of traffic lane (see Chart No. 1 M15) — joining 48°31′56.0″N 125°08′56.8″W, 48°31′05.4″N 125°04′39.4″W and 48°31′05.4″N 124°47′08.5″W

These changes are in effect 0000 Coordinated Universal Time (UTC), on 1 December, 2006.

DFO(6201561-01)

This notice affects Electronic Navigational Chart: CA370144, CA370203

27-OCT-2006 — LNM/D. 03-MAR-2006

Add outer limit of traffic lane (see Chart No. 1 M15) — between 48°32′05.4″N 125°08′58.8″W and 48°32′05.4″N 124°49′54.0″W

These changes are in effect 0000 Coordinated Universal Time (UTC), on 1 December, 2006.

DFO(6201561-02)

This notice affects Electronic Navigational Chart: CA370144, CA370203

27-OCT-2006 — LNM/D. 03-MAR-2006

Add outer limit of traffic lane (see Chart No. 1 M15) — between 48°31′05.4″N 125°04′40.2″W and 48°32′05.4″N 125°04′40.2″W

These changes are in effect 0000 Coordinated Universal Time (UTC), on 1 December, 2006.

DFO(6201561-03)

This notice affects Electronic Navigational Chart: CA370203

27-OCT-2006 — LNM/D. 03-MAR-2006

Chart no. 3601

Add outer limit of traffic lane — between 48°31′05.4″N 125°00′00.0″W and 48°32′05.4″N 125°00′00.0″W
(see Chart No. 1 M15)
These changes are in effect 0000 Coordinated Universal Time (UTC), on 1 December, 2006. *DFO(6201561-04)*

This notice affects Electronic Navigational Chart: CA370203

03-MAR-2006

Delete firing danger area — between 48°22′00.0″N 123°55′05.0″W and 48°22′37.0″N 123°55′05.0″W
[see Chart No 1 N30]

DFO(6201372-01)

This notice affects Electronic Navigational Chart: CA370144

03-MAR-2006

Delete firing danger area — between 48°28′18.0″N 124°17′34.0″W and 48°29′06.0″N 124°17′34.0″W
[see Chart No 1 N30]

DFO(6201372-02)

This notice affects Electronic Navigational Chart: CA370144

03-MAR-2006

Add firing danger area — between 48°22′00.0″N 123°55′05.0″W and 48°28′18.0″N 124°17′34.0″W
[see Chart No 1 N30]

DFO(6201372-03)

This notice affects Electronic Navigational Chart: CA370144