Chart no. 3603

3603 - Ucluelet Inlet to/à Nootka Sound - New Edition - 23-OCT-1981 - NAD 1927

08-DEC-2023 LNM/D. 05-MAY-2023

Delete subsurface Ocean Data Acquisition system (ODAS) with known depth of 1380 metres (See Chart 1, L25) 48°47′01.3″N 126°52′55.9″W
This notice affects Electronic Navigational Chart: CA370208 *DFO(6204832-12)*

05-MAY-2023 LNM/D. 03-MAR-2023

Delete private yellow ODAS/SADO lighted super-buoy Fl (5) Y20s (See Chart 1, Q58) 49°21′10.0″N 126°36′27.3″W
This notice affects Electronic Navigational Chart: CA370208 *DFO(6204763-01)*

03-MAR-2023 LNM/D. 06-JAN-2023

Delete yellow ODAS/SADO lighted super-buoy Fl (5) Y 20s, marked priv 49°11′27.1″N 127°37′09.7″W
(See Chart 1, Q58) *DFO(6204709-01)*

06-JAN-2023 LNM/D. 02-DEC-2022

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 1380 metres (See Chart 1, L25) 48°47′01.3″N 126°52′55.9″W
This notice affects Electronic Navigational Chart: CA370208 *DFO(6204696-06)*

02-DEC-2022 LNM/D. 16-SEP-2022

Add subsurface Ocean Data Acquisition system (ODAS) with known depth of 13 metres (See Chart 1, L25) 49°16′59.4″N 126°36′45.0″W
This notice affects Electronic Navigational Chart: CA370208 *DFO(6204670-01)*

02-DEC-2022 LNM/D. 16-SEP-2022

Add subsurface Ocean Data Acquisition system (ODAS) with known depth of 390 metres (See Chart 1, L25) 49°05′42.6″N 126°55′57.0″W
This notice affects Electronic Navigational Chart: CA370208 *DFO(6204670-02)*

16-SEP-2022 LNM/D. 04-MAR-2022

Add private yellow ODAS/SADO lighted super-buoy Fl (5) Y (See Chart No. 1, Q58) 49°00′07.7″N 125°42′06.7″W
This notice affects Electronic Navigational Chart: CA370203 *DFO(6204639-01)*

04-MAR-2022 LNM/D. 23-APR-2021

Chart no. 3603

Add yellow ODAS/SADO lighted super-buoy Fl (5) Y 20s marked priv 49°11′27.1″N 127°37′09.7″W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA270389, CA370208 *DFO(6204534-01)*

04-MAR-2022 LNM/D. 23-APR-2021

Delete depth of 1452 metres 49°11′28.7″N 127°37′14.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA370208 *DFO(6204534-02)*

04-MAR-2022 LNM/D. 23-APR-2021

Delete obstruction with known depth of 35 metres, marked ODAS/SADO 49°17′19.8″N 126°36′07.5″W
(See Chart No. 1, K41) *DFO(6204541-01)*
This notice affects Electronic Navigational Chart: CA270389, CA370208

04-MAR-2022 LNM/D. 23-APR-2021

Delete obstruction with known depth of 90 metres, marked ODAS/SADO 49°16′00.1″N 126°34′21.7″W
(See Chart No. 1, K41) *DFO(6204541-02)*
This notice affects Electronic Navigational Chart: CA270389, CA370208

04-MAR-2022 LNM/D. 23-APR-2021

Add rock which covers and uncovers with drying height of 0.3 metre 49°17′55.0″N 126°13′14.3″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA370208, CA470342 *DFO(6204543-04)*

04-MAR-2022 LNM/D. 23-APR-2021

Add rock which covers and uncovers with drying height of 1.1 metres 49°24′19.1″N 126°15′02.6″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA370208 *DFO(6204543-07)*

04-MAR-2022 LNM/D. 23-APR-2021

Chart no. 3603

Add submarine cable joining 48°45′14.7″N 125°27′54.7″W
(See Chart No. 1, L30.1) 48°43′40.7″N 125°35′42.4″W
48°43′22.3″N 125°38′16.7″W
48°42′22.8″N 125°42′59.8″W
48°42′22.4″N 125°44′34.4″W
and 48°42′00.7″N 125°46′14.3″W

DFO(6204547-04)

23-APR-2021 LNM/D. 03-APR-2020

Delete yellow ODAS/SADO lighted pillar buoy Fl (5) Y 20s, marked Priv (See Chart No. 1, Q58) 49°00′11.0″N 125°42′10.6″W
This notice affects Electronic Navigational Chart: CA270389, CA370203 *DFO(6204432-01)*

03-APR-2020 LNM/D. 03-JAN-2020

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 2212 metres (See Chart No. 1, L25) 48°50′58.4″N 127°29′51.3″W
This notice affects Electronic Navigational Chart: CA270389, CA370208 *DFO(6204255-07)*

03-APR-2020 LNM/D. 03-JAN-2020

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 2184 metres (See Chart No. 1, L25) 48°51′56.8″N 127°27′00.4″W
This notice affects Electronic Navigational Chart: CA370208 *DFO(6204255-08)*

03-APR-2020 LNM/D. 03-JAN-2020

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 2270 metres (See Chart No. 1, L25) 48°49′48.6″N 127°27′10.5″W
This notice affects Electronic Navigational Chart: CA270389, CA370208 *DFO(6204255-09)*

03-APR-2020 LNM/D. 03-JAN-2020

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 2030 metres (See Chart No. 1, L25) 48°57′21.7″N 127°16′03.5″W
This notice affects Electronic Navigational Chart: CA270389, CA370208 *DFO(6204255-10)*

03-APR-2020 LNM/D. 03-JAN-2020

Chart no. 3603

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 2048 metres (See Chart No. 1, L25) — 48°58′53.8″N 127°14′50.8″W
This notice affects Electronic Navigational Chart: CA270389, CA370208 — *DFO(6204255-11)*

03-APR-2020 — LNM/D. 03-JAN-2020

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 2036 metres (See Chart No. 1, L25) — 48°57′21.6″N 127°13′10.2″W
This notice affects Electronic Navigational Chart: CA270389, CA370208 — *DFO(6204255-12)*

03-APR-2020 — LNM/D. 03-JAN-2020

Reposition yellow ODAS/SADO lighted pillar buoy Fl (5) Y20s, marked Priv (See Chart No. 1, Q58) — from 48°57′28.4″N 125°36′46.2″W to 49°00′11.5″N 125°42′06.6″W
This notice affects Electronic Navigational Chart: CA270389, CA370203 — *(P2020007) LL(134.5) DFO(6204268-01)*

03-JAN-2020 — LNM/D. 05-APR-2019

Add obstruction with known depth of 35 metres, marked ODAS/SADO (See Chart No. 1, K41) — 49°17′19.7″N 126°36′07.4″W
This notice affects Electronic Navigational Chart: CA270389, CA370208 — *DFO(6204229-01)*

03-JAN-2020 — LNM/D. 05-APR-2019

Add obstruction with known depth of 90 metres, marked ODAS/SADO (See Chart No. 1, K41) — 49°16′00.1″N 126°34′21.7″W
This notice affects Electronic Navigational Chart: CA270389, CA370208 — *DFO(6204229-02)*

05-APR-2019 — LNM/D. 11-MAY-2018

Add obstruction with known depth of 1342 metres, and legend ″Unexploded ordnance / Explosifs non-éclatés″ (See Chart No. 1, K41) — 48°44′06.4″N 126°47′11.9″W
This notice affects Electronic Navigational Chart: CA270389, CA370203 — *DFO(6203998-01)*

11-MAY-2018 — LNM/D. 22-JUL-2016

Chart no. 3603

Amend Fl with Fog Sig to read Fl 10s28m10M with FogSig30s against light — 49°20′51.8″N 126°15′30.6″W
(See Chart No. 1, P1) — *LL(117.5) DFO(6203753-01)*
This notice affects Electronic Navigational Chart: CA270389, CA370208, CA470341, CA570093

22-JUL-2016 — LNM/D. 07-FEB-2014

Replace EXERCISE AREA WP ZONE D′EXERCICES WP With — 49°32′20.0″N 125°56′30.0″W

DFO(6203306-07)

EXERCISE AREA WP
Surface and air firings may be conducted in any part of WP if appropriate clearances have been obtained. However, the majority of firings are carried out in two areas designated West Coast Firing Area North (WCFA North), and West Coast Firing Area South. (WCFA South). Pecked lines enclose these areas. For information concerning firing operations call Prince Rupert Traffic on VHF, Channel 74.

ZONE D′EXERCICES WP
Les tirs de surface et aériens peuvent être exécutés dans n′importe quelle partie de la zone WP à condition d′avoir obtenu l′autorisation appropriée. Toutefois, la plupart des tirs sont exécutés à l′intérieur de deux zones désignées West Coast Firing Area North (WCFA North) et West Coast Firing Area South (WCFA South) où des tiretés délimitent ces zones. Pour obtenir des renseignements concernant les exercices de tir, communiquer avec Prince Rupert Traffic par radio VHF, voie 74.

This notice affects Electronic Navigational Chart: CA370208

07-FEB-2014 — LNM/D. 19-JUL-2013

Add yellow ODAS/SADO lighted buoy Fl (5) Y 20s, marked priv (See Chart No. 1, Q58) — 48°57′27.4″N 125°36′48.1″W
This notice affects Electronic Navigational Chart: CA270389, CA370203 — *(P2013039) LL(134.5) DFO(6202769-01)*

19-JUL-2013 — LNM/D. 18-JUN-2010

Add yellow ODAS/SADO lighted Fl (5) Y 20s, marked priv (See Chart No. 1, Q58) — 49°21′10.2″N 126°36′27.4″W
This notice affects Electronic Navigational Chart: CA270389, CA370208 — *(P2013014) LL(114.5) DFO(6202715-01)*

Chart no. 3603

18-JUN-2010 LNM/D. 12-JUN-2009

Add yellow ODAS/SADO light buoy Fl(5) Y, marked Priv 48°53′06.4″N 125°37′58.9″W
(See Chart No. 1, Q58)

DFO(6202243-01)

This notice affects Electronic Navigational Chart: CA370203

12-JUN-2009 LNM/D. 15-FEB-2008

Delete yellow ODAS/SADO lighted buoy, Fl (5) Y marked Priv 49°03′10.7″N 126°06′03.7″W
(See Chart No. 1, Q58)

DFO(6202063-01)

This notice affects Electronic Navigational Chart: CA370208

15-FEB-2008 LNM/D. 08-FEB-2008

Add submarine cable joining 48°42′00.0″N 126°53′35.4″W
(See Chart No. 1, L30.1) 48°43′26.6″N 126°52′32.3″W
48°44′57.1″N 126°46′49.8″W
48°44′35.9″N 126°44′48.2″W
This notice affects Electronic Navigational Chart: 48°46′36.0″N 126°41′24.9″W
CA370203, CA370208 48°47′14.9″N 126°38′50.2″W
48°48′48.7″N 126°20′40.0″W
48°45′45.0″N 126°09′45.1″W
48°43′12.0″N 125°57′39.7″W
48°44′03.0″N 125°50′26.5″W
48°43′01.8″N 125°46′07.4″W
48°43′01.3″N 125°43′49.1″W
48°44′40.3″N 125°35′31.6″W
and 48°45′44.4″N 125°27′54.7″W

DFO(6201807-01)

08-FEB-2008 LNM/D. 23-JUN-2006

Add yellow ODAS/SADO lighted buoy Fl (5) Y, marked Priv 49°03′10.7″N 126°06′03.7″W
(See Chart No.1, Q58)

DFO(6201803-01)

This notice affects Electronic Navigational Chart: CA370208

23-JUN-2006 LNM/D. 02-JUN-2006

Chart no. 3603

Delete light Fl 4s 12m 7M 49°08′13.9″N 125°58′31.4″W
(see Chart No. 1 P1)

(P2006075) LL(126.5) DFO(6201450-01)

This notice affects Electronic Navigational Chart:
CA470333

02-JUN-2006 LNM/D. 18-NOV-2005

Delete yellow ODAS/SADO lighted spherical buoy Fl (5) Y 48°56′21.7″N 125°36′35.5″W
(see Chart No. 1 Q58)

DFO(6201431-01)

This notice affects Electronic Navigational Chart: CA370203

18-NOV-2005 LNM/D. 09-JUL-2004

Delete yellow ODAS/SADO light buoy, Fl Y, marked Priv 49°18′42.0″N 127°42′52.0″W

DFO(6201330-01)

09-JUL-2004 LNM/D. 09-JAN-2004

Add yellow ODAS/SADO light buoy, Fl Y, marked Priv 49°18′42.0″N 127°42′52.0″W

DFO(6201105-01)

09-JAN-2004 LNM/D. 27-JUN-2003

Delete depth of 10.1 metres marked R 49°12′18.0″N 126°07′17.0″W

DFO(6200716-01)

09-JAN-2004 LNM/D. 27-JUN-2003

Add depth of 5.3 metres 49°12′11.3″N 126°07′06.6″W

DFO(6200716-02)

09-JAN-2004 LNM/D. 27-JUN-2003

Add depth of 18.1 metres 49°12′33.5″N 126°09′21.1″W

DFO(6200716-03)

Chart no. 3603

09-JAN-2004 LNM/D. 27-JUN-2003
Add depth of 15.4 metres 49°12′58.1″N 126°08′33.2″W

DFO(6200716-04)

09-JAN-2004 LNM/D. 27-JUN-2003
Add depth of 9.1 metres 49°22′34.8″N 126°21′32.3″W

DFO(6200716-05)

09-JAN-2004 LNM/D. 27-JUN-2003
Delete depth of 29 metres 49°32′45.0″N 126°36′39.0″W

DFO(6200716-06)

09-JAN-2004 LNM/D. 27-JUN-2003
Add depth of 18.7 metres 49°32′39.0″N 126°36′32.7″W

DFO(6200716-07)

27-JUN-2003 LNM/D. 02-MAY-2003
Amend Fl 10s 35m 23M to read Fl 10s 35m 17M 49°06′38.2″N 125°55′19.4″W

DFO(6200571-01)

02-MAY-2003 LNM/D. 17-JAN-2003
Delete Fog Sig (2) 60s 49°35′34.1″N 126°36′50.6″W

(P2003022) LL(105) DFO(6200535-05)

02-MAY-2003 LNM/D. 17-JAN-2003
Delete Fog Sig 60s 49°22′59.3″N 126°32′33.7″W

(P2003024) LL(114) DFO(6200535-06)

02-MAY-2003 LNM/D. 17-JAN-2003

Chart no. 3603

Delete Fog Sig (2) 60s 49°06′38.1″N 125°55′19.9″W

(P2003021) LL(134) DFO(6200535-07)

17-JAN-2003 LNM/D. 29-NOV-2002

Delete red and white light and whistle buoy Mo(A) marked MH 49°19′58.1″N 126°15′34.5″W

(P2002125) LL(116) DFO(6200435-01)

17-JAN-2003 LNM/D. 29-NOV-2002

Delete red and white light and whistle buoy Mo(A) marked ME 49°23′05.5″N 126°25′52.9″W

(P2002126) LL(115) DFO(6200436-01)

29-NOV-2002 LNM/D. 21-JUN-2002

Delete radiobeacon marked RC 49°22′59.4″N 126°32′33.2″W

DFO(6200415-01)

21-JUN-2002 LNM/D. 25-JAN-2002

Add yellow spherical ODAS light buoy, Fl (5) Y 48°56′21.7″N 125°36′35.5″W

DFO(6200043-01)

25-JAN-2002 LNM/D. 30-NOV-2001

Add calling-in point 6 in a northbound and southbound direction. 48°50′30.0″N 125°38′30.0″W

DFO(6201089-01)

25-JAN-2002 LNM/D. 30-NOV-2001

Add calling-in point 7 in a northbound and southbound direction. 49°18′00.0″N 126°38′54.0″W

DFO(6201089-02)

25-JAN-2002 LNM/D. 30-NOV-2001

Add calling-in point 8 in a northbound and southbound direction. 49°30′18.0″N 126°41′18.0″W

DFO(6201089-03)

Chart no. 3603

30-NOV-2001 LNM/D. 24-AUG-2001

Delete firing danger area limit between 49°34′16.0″N 127°43′42.0″W
and 49°28′00.0″N 127°10′00.0″W

DFO(6201086-01)

30-NOV-2001 LNM/D. 24-AUG-2001

Delete legend CYD 110 49°36′12.0″N 127°34′12.0″W

DFO(6201086-02)

30-NOV-2001 LNM/D. 24-AUG-2001

Add firing danger area limit joining 49°30′00.0″N 127°40′00.0″W
49°15′00.0″N 127°40′00.0″W
49°15′00.0″N 127°02′30.0″W
49°24′36.0″N 127°10′12.0″W
49°27′42.0″N 127°11′00.0″W
and 40°30′00.0″N 127°14′00.0″W

DFO(6201086-03)

30-NOV-2001 LNM/D. 24-AUG-2001

Add legend WCFA North 49°22′30.0″N 127°25′00.0″W

DFO(6201086-04)

30-NOV-2001 LNM/D. 24-AUG-2001

Add firing danger area limit joining 49°15′00.0″N 127°40′00.0″W
49°00′00.0″N 127°40′00.0″W
49°00′00.0″N 127°00′00.0″W
49°12′18.0″N 127°00′00.0″W
and 49°15′00.0″N 127°02′30.0″W

DFO(6201086-05)

30-NOV-2001 LNM/D. 24-AUG-2001

Add legend WCFA South 49°07′30.0″N 127°25′00.0″W

DFO(6201086-06)

Chart no. 3603

30-NOV-2001 LNM/D. 24-AUG-2001

Add note 49°40′00.0″N 125°47′00.0″W

EXERCISE AREA WP
Surface and air firings may be conducted in any part of WP if appropriate clearances have been obtained. However, the majority of firings are carried out in two areas designated West Coast Firing Area North (WCFA North), and West Coast Firing Area South (WCFA South). Pecked lines enclose these areas. For information concerning firing operations call Tofino Traffic on VHF Channel 74. *DFO(6201086-07)*

ZONE D′EXERCICES WP
Les tirs de surface et aériens peuvent être exécutés dans n′importe quelle partie de la zone WP à condition d′avoir obtenu l′autorisation appropriée. Toutefois, la plupart des tirs sont exécutés à l′intérieur de deux zones désignées West Coast Firing Area North (WCFA North) et West Coast Firing Area South (WCFA South) où des tiretés délimitent ces zones. Pour obtenir des renseignements concernant les exercices de tir, communiquer avec Tofino Traffic par radio VHF, voie 74.

24-AUG-2001 LNM/D. 23-MAR-2001

Amend F Fl 12s 31m 16M to read Fl 12s 31m 18M against light 49°35′34.2″N 126°36′50.1″W

(P2001085) LL(105) DFO(6201051-01)

23-MAR-2001 LNM/D. 09-MAR-2001

(P)Delete firing danger area limit between 49°34′16.0″N 127°43′42.0″W and 49°28′00.0″N 127°10′00.0″W
This information will be incorporated in the next New Edition of this chart.
With this notification, the preliminary action dated 23-MAR-2001 is now cancelled for this chart. This action has now been made permanent. See reference DFO(6201086) in this edition. *DFO(6201014-10)*
Cancelled on 30-NOV-01

23-MAR-2001 LNM/D. 09-MAR-2001

(P)Delete legend CYD 110 49°36′12.0″N 127°34′12.0″W
This information will be incorporated in the next New Edition. *DFO(6201014-11)*
With this notification, the preliminary action dated 23-MAR-2001 is now cancelled for this chart. This action has now been made permanent. See reference DFO(6201086) in this edition.
Cancelled on 30-NOV-01

Chart no. 3603

23-MAR-2001 LNM/D. 09-MAR-2001

(P)Add firing danger area limit joining 49°30′00.0″N 127°40′00.0″W
49°15′00.0″N 127°40′00.0″W
49°15′00.0″N 127°02′30.0″W
49°24′36.0″N 127°10′12.0″W
49°27′42.0″N 127°11′00.0″W
and 49°30′00.0″N 127°14′00.0″W
This information will be incorporated in the next New Edition.
With this notification, the preliminary action dated 23-MAR-2001 is now cancelled for this chart. This action has now been made permanent. See reference DFO(6201086) in this edition.
Cancelled on 30-NOV-01 *DFO(6201014-12)*

23-MAR-2001 LNM/D. 09-MAR-2001

(P)Add legend WCFA North 49°22′30.0″N 127°25′00.0″W
This information will be incorporated in the next New Edition of this chart. *DFO(6201014-13)*
With this notification, the preliminary action dated 23-MAR-2001 is now cancelled for this chart. This action has now been made permanent. See reference DFO(6201086) in this edition.
Cancelled on 30-NOV-01

23-MAR-2001 LNM/D. 09-MAR-2001

(P)Add firing danger area limit joining 49°15′00.0″N 127°40′00.0″W
49°00′00.0″N 127°40′00.0″W
49°00′00.0″N 127°00′00.0″W
49°12′18.0″N 127°00′00.0″W
and 49°15′00.0″N 127°02′30.0″W
This information will be incorporated in the next New Edition of this chart.
With this notification, the preliminary action dated 23-MAR-2001 is now cancelled for this chart. This action has now been made permanent. See reference DFO(6201086) in this edition. *DFO(6201014-14)*
Cancelled on 30-NOV-01

23-MAR-2001 LNM/D. 09-MAR-2001

(P)Add legend WCFA South 49°07′30.0″N 127°25′00.0″W
This information will be incorporated in the next New Edition of this chart. *DFO(6201014-15)*
With this notification, the preliminary action dated 23-MAR-2001 is now cancelled for this chart. This action has now been made permanent. See reference DFO(6201086) in this edition.
Cancelled on 30-NOV-01

23-MAR-2001 LNM/D. 09-MAR-2001

Chart no. 3603

(P)Add note 49°40′00.0″N 125°47′00.0″W

EXERCISE AREA WP
Surface and air firings may be conducted in any part of WP if appropriate clearances have been obtained. However, the majority of firings are carried out in two areas designated West Coast Firing Area North (WCFA North), and West Coast Firing Area South (WCFA South). Pecked lines enclose these areas. For information concerning firing operations call Tofino Traffic on VHF Channel 74. *DFO(6201014-16)*

ZONE D′EXERCICES WP
Les tirs de surface et aériens peuvent être exécutés dans n′importe quelle partie de la zone WP à condition d′avoir obtenu l′autorisation appropriée. Toutefois, la plupart des tirs sont exécutés à l′intérieur de deux zones désignées West Coast Firing Area North (WCFA North) et West Coast Firing Area South (WCFA South) où des tiretés délimitent ces zones. Pour obtenir des renseignements concernant les exercices de tir, communiquer avec Tofino Traffic par radio VHF, voie 74.
This information will be incorporated in the next New Edition of this chart.
With this notification, the preliminary action dated 23-MAR-2001 is now cancelled for this chart. This action has now been made permanent. See reference DFO(6201086) in this edition.
Cancelled on 30-NOV-01

09-MAR-2001 LNM/D. 20-DEC-1991

Delete yellow spherical light buoy Fl(5)Y (ODAS) 49°02′12.0″N 125°48′00.0″W

(CCG-P00-213) LL(134.2) DFO(6200988-01)