Chart no. 3673

3673 - Clayoquot Sound, Tofino Inlet to/à Millar Channel - New Chart - 01-DEC-1995 - NAD 1983

18-MAR-2022 LNM/D. 04-MAR-2022

Delete depth of 2.5 metres 49°12′41.5″N 125°58′08.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-01)*

18-MAR-2022 LNM/D. 04-MAR-2022

Delete depth of 0.8 metre 49°13′58.3″N 126°00′21.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-05)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add rock which covers and uncovers with drying height of 0.1 metre 49°13′58.4″N 126°00′21.2″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-06)*

18-MAR-2022 LNM/D. 04-MAR-2022

Delete depth of 2.6 metres 49°11′34.3″N 125°55′53.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-07)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add depth of 1.9 metres 49°11′32.4″N 125°55′51.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-08)*

18-MAR-2022 LNM/D. 04-MAR-2022

Delete depth of 14.9 metres 49°16′41.9″N 125°53′20.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-09)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add wreck WK with known depth of 10.0 metres 49°16′42.7″N 125°53′19.7″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-10)*

Chart no. 3673

18-MAR-2022 LNM/D. 04-MAR-2022

Add rock which covers and uncovers with drying height of 0.8 metre 49°13′06.0″N 125°57′36.8″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-11)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add rock which covers and uncovers with drying height of 0.7 metre 49°13′04.4″N 125°57′24.2″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-12)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add rock which covers and uncovers with drying height of 0.3 metre 49°15′46.1″N 125°55′08.3″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-13)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add rock which covers and uncovers with drying height of 0.2 metre 49°15′44.8″N 125°55′26.3″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-14)*

18-MAR-2022 LNM/D. 04-MAR-2022

Replace depth of 1.4 metres with depth of 0.1 metre 49°15′50.4″N 125°52′28.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-15)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add depth of 0.4 metre 49°12′06.9″N 125°56′11.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-16)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add depth of 1.0 metre 49°16′11.0″N 125°54′41.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-17)*

18-MAR-2022 LNM/D. 04-MAR-2022

Chart no. 3673

Add depth of 1.2 metres 49°12′42.5″N 125°58′08.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-18)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add depth of 1.4 metres 49°12′35.4″N 125°56′46.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-19)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add depth of 1.5 metres 49°12′32.5″N 125°57′16.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-20)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add depth of 1.6 metres 49°12′16.4″N 125°56′57.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-21)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add depth of 1.9 metres 49°16′37.6″N 125°52′51.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204546-22)*

18-MAR-2022 LNM/D. 04-MAR-2022

Add outfall pipe (See Chart No. 1, L41.1) joining 49°16′40.9″N 126°03′18.6″W
This notice affects Electronic Navigational Chart: 49°16′49.0″N 126°02′57.6″W
CA470342 49°16′52.1″N 126°02′54.9″W
49°16′58.1″N 126°02′53.6″W
49°17′03.2″N 126°02′43.6″W
49°17′09.5″N 126°02′37.3″W
and 49°17′12.9″N 126°02′26.3″W

DFO(6204549-01)

18-MAR-2022 LNM/D. 04-MAR-2022

Chart no. 3673

Delete outfall pipe (See Chart No. 1, L41.1) joining 49°16′40.9″N 126°03′18.6″W
49°16′43.0″N 126°03′09.5″W
49°16′45.0″N 126°03′06.0″W
49°16′45.9″N 126°03′05.3″W
49°17′04.4″N 126°02′51.4″W
49°17′04.5″N 126°02′51.3″W
49°17′07.1″N 126°02′47.6″W
49°17′07.6″N 126°02′45.9″W
and 49°17′12.9″N 126°02′26.3″W

This notice affects Electronic Navigational Chart: CA470342

DFO(6204549-02)

04-MAR-2022 LNM/D. 10-DEC-2021

Delete depth of 0.8 metre 49°14′00.0″N 125°59′26.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204543-11)*

04-MAR-2022 LNM/D. 10-DEC-2021

Add depth of 0.2 metre 49°14′01.0″N 125°59′26.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204543-12)*

04-MAR-2022 LNM/D. 10-DEC-2021

Delete depth of 0.7 metre 49°14′06.0″N 125°59′19.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204543-13)*

04-MAR-2022 LNM/D. 10-DEC-2021

Add depth of 0.2 metre 49°14′05.7″N 125°59′19.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204543-14)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add rock awash at chart datum 49°18′45.5″N 125°57′41.3″W
(See Chart No. 1, K12)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204513-01)*

10-DEC-2021 LNM/D. 23-JUL-2021

Chart no. 3673

Delete depth of 2 metres 49°15′20.8″N 126°08′43.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204514-01)*

10-DEC-2021 LNM/D. 23-JUL-2021

Delete depth of 1.6 metres 49°15′08.8″N 126°07′35.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204514-02)*

10-DEC-2021 LNM/D. 23-JUL-2021

Delete depth of 0.3 metre 49°14′15.2″N 126°07′24.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204514-04)*

10-DEC-2021 LNM/D. 23-JUL-2021

Delete depth of 1.5 metres 49°14′03.2″N 126°02′56.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204514-05)*

10-DEC-2021 LNM/D. 23-JUL-2021

Delete depth of 0.6 metre 49°15′44.9″N 126°10′46.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204514-07)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add depth of 0.8 metre 49°15′20.8″N 126°08′44.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204514-08)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add depth of 0.6 metre 49°15′08.6″N 126°07′36.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204514-09)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add depth of 0.2 metre 49°14′19.0″N 126°00′06.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204514-11)*

Chart no. 3673

10-DEC-2021 LNM/D. 23-JUL-2021

Add rock awash at chart datum 49°14′03.5″N 126°02′57.3″W
(See Chart No. 1, K12)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204514-12)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add rock which covers and uncovers with drying height of 0.2 metre 49°14′16.0″N 126°07′26.1″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204514-14)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add rock which covers and uncovers with drying height of 0.5 metre 49°15′45.7″N 126°10′46.8″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204514-16)*

10-DEC-2021 LNM/D. 23-JUL-2021

Delete depth of 1.2 metres 49°09′24.3″N 126°00′18.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204515-01)*

10-DEC-2021 LNM/D. 23-JUL-2021

Delete depth of 1.5 metres 49°12′50.2″N 126°02′03.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204515-02)*

10-DEC-2021 LNM/D. 23-JUL-2021

Delete depth of 1.0 metre 49°13′26.9″N 126°03′05.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204515-03)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add depth of 0.8 metre 49°09′10.4″N 125°59′41.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204515-04)*

10-DEC-2021 LNM/D. 23-JUL-2021

Chart no. 3673

Add depth of 0.9 metre 49°09′51.2″N 126°04′59.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204515-05)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add depth of 0.5 metre 49°09′23.5″N 126°00′18.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204515-06)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add depth of 1.9 metres 49°08′48.3″N 125°58′18.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204515-07)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add depth of 3.3 metres 49°09′04.8″N 126°01′52.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204515-08)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add depth of 0.6 metre 49°09′07.6″N 126°01′29.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204515-09)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add rock which covers and uncovers with drying height of 0.3 metre 49°09′26.4″N 126°00′11.7″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204515-10)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add rock which covers and uncovers with drying height of 0.4 metre 49°12′49.9″N 126°02′02.9″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204515-11)*

10-DEC-2021 LNM/D. 23-JUL-2021

Add rock which covers and uncovers with drying height of 0.3 metre 49°13′26.5″N 126°03′06.8″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204515-12)*

Chart no. 3673

23-JUL-2021 LNM/D. 01-JAN-2021

Affix patch 49°08′00.0″N 125°56′00.0″W
PDF
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204381-01)*

01-JAN-2021 LNM/D. 03-JUL-2020

Add rock which covers and uncovers with drying height of 0.3 metre 49°16′38.4″N 126°04′12.8″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204409-10)*

03-JUL-2020 LNM/D. 27-MAR-2020

Add outfall pipe (See Chart No. 1, L41.1) between 49°08′59.6″N 125°54′38.7″W and 49°09′05.6″N 125°54′58.8″W
This notice affects Electronic Navigational Chart: CA470333, CA570088
DFO(6204336-01)

03-JUL-2020 LNM/D. 27-MAR-2020

Delete outfall pipe (See Chart No. 1, L41.1) between 49°08′59.5″N 125°54′38.4″W and 49°09′00.6″N 125°54′44.0″W
This notice affects Electronic Navigational Chart: CA470333
DFO(6204336-02)

27-MAR-2020 LNM/D. 15-NOV-2019

Add marine farm 49°16′45.5″N 125°49′50.3″W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204249-01)*

27-MAR-2020 LNM/D. 15-NOV-2019

Add marine farm 49°18′20.5″N 125°48′57.0″W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA470334 *DFO(6204250-01)*

15-NOV-2019 LNM/D. 11-OCT-2019

Add depth of 0.8 metre 49°15′23.4″N 126°03′34.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204154-01)*

15-NOV-2019 LNM/D. 11-OCT-2019

Chart no. 3673

Add rock which covers and uncovers with drying height of 0.5 metres 49°15′08.3″N 126°03′17.5″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204191-01)*

15-NOV-2019 LNM/D. 11-OCT-2019

Add depth of 1.7 metres 49°14′45.6″N 126°04′41.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470342 *DFO(6204191-02)*

11-OCT-2019 LNM/D. 16-AUG-2019

Add depth of 5.3 metres 49°12′12.5″N 125°55′51.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204129-01)*

11-OCT-2019 LNM/D. 16-AUG-2019

Add depth of 5.7 metres 49°14′05.2″N 125°54′10.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204129-02)*

11-OCT-2019 LNM/D. 16-AUG-2019

Add rock which covers and uncovers with drying height of 1.6 metres 49°13′32.7″N 125°58′21.0″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204129-03)*

11-OCT-2019 LNM/D. 16-AUG-2019

Add depth of 3.2 metres 49°12′34.8″N 126°02′25.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204171-01)*

11-OCT-2019 LNM/D. 16-AUG-2019

Add depth of 7.5 metres 49°10′56.9″N 126°01′46.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204171-02)*

11-OCT-2019 LNM/D. 16-AUG-2019

Add rock awash at chart datum 49°09′36.3″N 126°01′14.4″W
(See Chart No. 1, K12)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204171-03)*

Chart no. 3673

11-OCT-2019 LNM/D. 16-AUG-2019

Add depth of 1.1 metres 49°09′28.0″N 126°02′46.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333 *DFO(6204171-04)*

16-AUG-2019 LNM/D. 01-SEP-2017

Add depth of 9 metres 49°10′45.4″N 125°46′43.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470334, CA570088 *DFO(6204112-01)*

16-AUG-2019 LNM/D. 01-SEP-2017

Add depth of 6.2 metres 49°07′57.2″N 125°51′00.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470333, CA570088 *DFO(6204112-03)*

16-AUG-2019 LNM/D. 01-SEP-2017

Add depth of 2.4 metres 49°12′22.4″N 125°40′00.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470334 *DFO(6204112-10)*

01-SEP-2017 LNM/D. 10-APR-2015

Delete green port hand lighted pillar buoy Fl G, marked Y11 49°13′21.3″N 126°00′30.2″W
(See Chart No. 1, Qg) *(P2017045) LL(123.3) DFO(6203536-01)*
This notice affects Electronic Navigational Chart: CA470333

01-SEP-2017 LNM/D. 10-APR-2015

Add green port hand lighted pillar buoy Fl G, marked Y11 49°13′17.4″N 126°00′08.4″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA470333 *(P2017045) LL(123.3) DFO(6203536-02)*

10-APR-2015 LNM/D. 28-SEP-2012

Chart no. 3673

Add submarine pipeline joining 49°15′31.3″N 125°52′11.6″W
(See Chart No. 1, L41.1) 49°15′35.0″N 125°51′55.1″W
This notice affects Electronic Navigational Chart: 49°16′04.4″N 125°51′46.9″W
CA470333 49°16′15.0″N 125°51′43.7″W
49°16′21.3″N 125°51′46.1″W
49°16′36.9″N 125°51′32.0″W
and 49°16′42.8″N 125°51′36.3″W

DFO(6202985-01)

28-SEP-2012 LNM/D. 14-SEP-2012

Add depth of 11.7 metres 49°09′29.9″N 125°53′37.0″W
(See Chart No. 1, I10)

DFO(6202604-05)

This notice affects Electronic Navigational Chart: CA470333, CA570088

14-SEP-2012 LNM/D. 04-JUL-2008

Delete depth of 11.9 metres 49°10′47.9″N 125°40′22.1″W
(See Chart No. 1, I10)

DFO(6202593-01)

This notice affects Electronic Navigational Chart: CA470334

14-SEP-2012 LNM/D. 04-JUL-2008

Add depth of 4.8 metres 49°10′48.2″N 125°40′20.7″W
(See Chart No. 1, I10)

DFO(6202593-02)

This notice affects Electronic Navigational Chart: CA470334

04-JUL-2008 LNM/D. 02-MAY-2008

Replace ON CERTAIN COPIES ONLY 49°16′36.2″N 125°50′50.6″W
obstruction with depth of 0.6 metres with obstruction with drying height of 0.6 metres *DFO(6201873-01)*
(See Chart No. 1, K41 and I15)

This notice affects Electronic Navigational Chart: CA470333

02-MAY-2008 LNM/D. 13-OCT-2006

Chart no. 3673

Add wreck WK with known depth of 7.9 metres 49°09′23.2″N 125°54′55.7″W
(See Chart No. 1, K26)

DFO(6201817-01)

This notice affects Electronic Navigational Chart: CA470333

13-OCT-2006 LNM/D. 01-SEP-2006

Delete depth of 3.7 metres 49°16′36.2″N 125°50′52.0″W
(see Chart No. 1 I10)

DFO(6201566-01)

This notice affects Electronic Navigational Chart: CA470333

13-OCT-2006 LNM/D. 01-SEP-2006

Add obstruction with drying height of 0.6 metres 49°16′36.2″N 125°50′50.6″W
(see Chart No. 1 K41)

DFO(6201566-02)

This notice affects Electronic Navigational Chart: CA470333

01-SEP-2006 LNM/D. 23-JUN-2006

Replace light Fl with starboard hand daybeacon 49°09′21.9″N 125°40′44.0″W
(see Chart No. 1 P1 and Qt)

(P2006111) LL(131.5) DFO(6201498-01)

This notice affects Electronic Navigational Chart:
CA470334

23-JUN-2006 LNM/D. 12-AUG-2005

Replace port hand daybeacon with light Fl 49°08′28.8″N 125°56′00.5″W
(see Chart No. 1 Qt and P1)

(P2006074) LL(132.5) DFO(6201446-01)

This notice affects Electronic Navigational Chart:
CA470333

23-JUN-2006 LNM/D. 12-AUG-2005

Chart no. 3673

Delete light Fl 4s 12m 6M 49°08′13.2″N 125°58′36.7″W
(see Chart No. 1 P1)

(P2006075) LL(126.5) DFO(6201450-01)

This notice affects Electronic Navigational Chart:
CA470333

12-AUG-2005 LNM/D. 27-JUN-2003

Replace green can buoy marked Y1 with green pillar light buoy Fl G marked Y1 49°07′36.0″N 125°55′24.0″W

(P2005053) LL(133.5) DFO(6201293-01)

27-JUN-2003 LNM/D. 02-MAY-2003

Amend Fl 10s 35m 21M to read Fl 10s 35m 17M 49°06′37.5″N 125°55′24.7″W

DFO(6200571-01)

02-MAY-2003

Delete Fog Sig (2) 60s 49°06′37.5″N 125°55′24.7″W

(P2003021) LL(134) DFO(6200535-07)