Chart no. 3744

3744 - Queen Charlotte Sound - New Edition - 20-MAY-1988 - NAD 1927

27-DEC-2019 LNM/D. 27-SEP-2019

Add depth of 142 Fathoms 51°15′44.6″N 129°45′42.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA270084 *DFO(6204204-03)*

27-DEC-2019 LNM/D. 27-SEP-2019

Delete depth of 284 Fathoms 51°15′52.9″N 129°45′42.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA270084 *DFO(6204204-04)*

27-SEP-2019 LNM/D. 02-AUG-2019

Amend Q 43ft11M with RACON to read Iso 1s43ft11M with RACON against light 53°40′24.8″N 130°24′36.7″W
(See Chart No. 1, P1, S3.1) *LL(742.5) DFO(6204097-01)*

02-AUG-2019 LNM/D. 08-MAR-2019

Amend Chart/ Carte 3724 to read Chart/Carte 3975 52°49′57.0″N 129°39′01.0″W
(See Chart No. 1, A18)
DFO(6204051-06)

02-AUG-2019 LNM/D. 08-MAR-2019

Amend Chart/ Carte 3741 to read Chart/Carte 3976 53°17′35.0″N 130°19′24.0″W
(See Chart No. 1, A18)
DFO(6204051-07)

08-MAR-2019 LNM/D. 28-DEC-2018

Amend light Fl 5s 315ft 14M to read Fl 5s315ft13M against light 51°56′10.0″N 131°00′51.7″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA270084 *LL(770) DFO(6203963-02)*

28-DEC-2018 LNM/D. 25-MAY-2018

Add light Q 43ft11M with RACON 53°40′24.8″N 130°24′36.7″W
(See Chart No. 1, P1, S3.1)
This notice affects Electronic Navigational Chart: CA270390, CA370441, CA470658 *(P2018135) LL(742.5) DFO(6203932-01)*

Chart no. 3744

28-DEC-2018 LNM/D. 25-MAY-2018

Amend Q WR 10m4M to read Q WR 31ft4M against light 53°38′19.7″N 130°28′07.5″W
(See Chart No. 1, P40.1)

LL(736.5) DFO(6203937-01)

28-DEC-2018 LNM/D. 25-MAY-2018

Amend Chart/Carte 3927 to read Chart/Carte 3978 53°40′36.7″N 130°54′26.0″W
(See Chart No. 1, A18)

DFO(6203937-02)

25-MAY-2018 LNM/D. 30-MAR-2018

Add green port hand lighted pillar buoy Fl G, marked EB7 52°57′53.5″N 129°44′51.7″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: *(P2018030) LL(631.1) DFO(6203765-01)*
CA270724, CA470613

25-MAY-2018 LNM/D. 30-MAR-2018

Add red starboard hand lighted pillar buoy Fl R, marked EB2 52°50′55.3″N 129°46′06.0″W
(See Chart No. 1, Qf) *(P2018043) LL(631.3) DFO(6203766-01)*
This notice affects Electronic Navigational Chart:
CA270724, CA470613

25-MAY-2018 LNM/D. 30-MAR-2018

Add red starboard hand lighted pillar buoy Q R, marked EB4 52°53′26.5″N 129°39′38.3″W
(See Chart No. 1, Qf) *(P2018044) LL(631.4) DFO(6203767-01)*
This notice affects Electronic Navigational Chart:
CA270724, CA470613

25-MAY-2018 LNM/D. 30-MAR-2018

Add green port hand lighted pillar buoy Q G, marked EB5 52°55′27.8″N 129°31′42.8″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: *(P2018042) LL(631.5) DFO(6203768-01)*
CA270724, CA470613

30-MAR-2018 LNM/D. 02-MAR-2018

Add note Chart/carte 3980 52°14′00.0″N 128°50′00.0″W
(See Chart No. 1, A18)

DFO(6203703-15)

Chart no. 3744

02-MAR-2018 LNM/D. 02-FEB-2018

Add light Fl R 50°40′15.9″N 128°21′01.8″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA270084 *(P2017101) LL(67) DFO(6203616-02)*

02-FEB-2018 LNM/D. 12-JAN-2018

Amend Fl to read Iso against light 52°57′16.7″N 129°18′23.7″W
(See Chart No. 1, P1)
(P2017097) LL(630.2) DFO(6203611-01)
This notice affects Electronic Navigational Chart: CA270724, CA470730

12-JAN-2018 LNM/D. 22-DEC-2017

Amend Fl to read Fl 6s against light 52°56′23.3″N 129°26′10.3″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA270724, CA470730 *(P2017093) LL(630) DFO(6203606-01)*

22-DEC-2017 LNM/D. 24-NOV-2017

Amend Fl to read Fl R against light 53°42′28.0″N 130°24′37.0″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA270390, CA370441, CA470658 *(P2017075) LL(743) DFO(6203590-01)*

22-DEC-2017 LNM/D. 24-NOV-2017

Delete radar reflector 53°42′28.0″N 130°24′37.0″W
(See Chart No. 1, S4)
This notice affects Electronic Navigational Chart: CA270390, CA370441, CA470658 *DFO(6203590-02)*

22-DEC-2017 LNM/D. 24-NOV-2017

Add light Fl(3) with RACON 52°51′37.6″N 129°20′44.7″W
(See Chart No. 1, P1, S3.1)
This notice affects Electronic Navigational Chart: CA270724, CA470730 *(P2017076) LL(628.5) DFO(6203595-01)*

24-NOV-2017 LNM/D. 23-JUN-2017

Chart no. 3744

Amend Fl R 15M with Racon to read Fl R 10s93ft16M with Racon against light — 50°58′33.2″N 127°43′35.0″W
(See Chart No. 1, P1,S3.1) — *LL(576) DFO(6203576-01)*
This notice affects Electronic Navigational Chart: CA270084, CA470307

24-NOV-2017 — LNM/D. 23-JUN-2017

Amend Fl 6s71ft6M to read Fl 6s71ft5M against light — 51°09′49.7″N 127°47′06.5″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA270084, CA470036 — *LL(578) DFO(6203576-02)*

23-JUN-2017 — LNM/D. 21-APR-2017

Add sector light Q WR 10m4M — 53°38′19.7″N 130°28′07.5″W
red from 80° to 121°, white from 121° to 80°
(See Chart No. 1, P40.1) — *(P2017025) LL(736.5) DFO(6203499-01)*
This notice affects Electronic Navigational Chart: CA270390, CA370441, CA470622

21-APR-2017 — LNM/D. 07-APR-2017

Add restricted area with label ″Hecate Strait and Queen Charlotte Sound Glass Sponge Reefs Marine Protected Area/Zone de protection marine des récifs d′éponges siliceuses du détroit d′Hécate et du bassin de la Reine-Charlotte″ — joining 53°11′53.6″N 130°19′41.2″W
(See Chart No. 1, N2.1) — 53°15′21.3″N 130°32′55.3″W
53°18′43.2″N 130°38′03.3″W
53°23′41.4″N 130°42′46.2″W
53°24′06.1″N 130°48′31.8″W
53°19′20.7″N 130°54′18.2″W
53°13′29.4″N 130°47′22.7″W
This notice affects Electronic Navigational Chart: CA270724, CA370440 — 53°07′45.2″N 130°46′20.5″W
53°07′18.5″N 130°41′57.2″W
53°03′07.6″N 130°30′29.6″W
53°02′55.2″N 130°25′10.2″W
53°09′22.7″N 130°18′47.0″W
and 53°11′53.6″N 130°19′41.2″W

DFO(6203461-01)

21-APR-2017 — LNM/D. 07-APR-2017

Chart no. 3744

Add restricted area with label ″Hecate Strait and Queen Charlotte Sound Glass Sponge Reefs Marine Protected Area/Zone de protection marine des récifs d'éponges siliceuses du détroit d'Hécate et du bassin de la Reine-Charlotte″
(See Chart No. 1, N2.1)

This notice affects Electronic Navigational Chart: CA270084, CA270724

joining 52°00′25.1″N 129°14′06.6″W
52°09′53.0″N 129°25′23.5″W
52°20′03.5″N 129°29′45.7″W
52°25′43.4″N 129°35′06.2″W
52°34′06.3″N 129°47′45.4″W
52°32′06.1″N 129°53′00.2″W
52°29′36.1″N 129°52′26.7″W
52°15′43.3″N 129°44′06.3″W
52°08′46.7″N 129°33′27.5″W
52°05′14.8″N 129°36′08.1″W
51°53′01.4″N 129°43′57.4″W
51°51′33.2″N 129°36′31.4″W
51°55′51.2″N 129°18′07.8″W
and 52°00′25.1″N 129°14′06.6″W

DFO(6203461-02)

21-APR-2017 LNM/D. 07-APR-2017

Add restricted area with label ″Hecate Strait and Queen Charlotte Sound Glass Sponge Reefs Marine Protected Area/Zone de protection marine des récifs d'éponges siliceuses du détroit d'Hécate et du bassin de la Reine-Charlotte″
(See Chart No. 1, N2.1)

This notice affects Electronic Navigational Chart: CA270084, CA370165

joining 51°24′44.9″N 128°47′52.3″W
51°19′25.2″N 129°00′47.6″W
51°17′43.0″N 129°00′23.0″W
51°14′34.6″N 128°55′39.5″W
51°14′58.3″N 128°46′55.2″W
51°18′33.2″N 128°40′29.6″W
and 51°24′44.9″N 128°47′52.3″W

DFO(6203461-03)

07-APR-2017 LNM/D. 05-AUG-2016

Add red starboard hand lighted pillar buoy Fl R, marked E88
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA270724

53°16′17.9″N 130°31′39.3″W

(P2017012) LL(740.5) DFO(6203467-01)

05-AUG-2016 LNM/D. 08-APR-2016

Amend Fl (3) 12s 53ft to read Fl (3) 12s 23ft against light
(See Chart No. 1,P1)
This notice affects Electronic Navigational Chart: CA270724, CA370298

53°32′51.8″N 130°38′02.1″W

DFO(6203319-02)

08-APR-2016 LNM/D. 25-MAR-2016

Chart no. 3744

Amend Fl to read Fl 6s against light — 53°38′05.6″N 130°33′46.4″W
(See Chart No. 1,P1)
This notice affects Electronic Navigational Chart: CA270724, CA470622 — *(P2016036) LL(742) DFO(6203243-01)*

25-MAR-2016 — LNM/D. 01-JAN-2016

Amend Q R to read Fl G against light — 53°37′44.8″N 130°32′18.1″W
(See Chart No. 1,P1)
This notice affects Electronic Navigational Chart: CA270724 — *(P201632) LL(736) DFO(6203239-03)*

01-JAN-2016 — LNM/D. 06-NOV-2015

Amend error showing depth of 14 metres published in Monthly Notice to Mariners Edition 11 to read 14 fathoms — 52°28′38.5″N 129°29′02.6″W
(See Chart No. 1, I10) — *DFO(6203167-04)*
This notice affects Electronic Navigational Chart: CA270724

06-NOV-2015 — LNM/D. 06-FEB-2015

Add depth of 14 metres — 52°28′38.5″N 129°29′02.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA270724 — *DFO(6203120-02)*

06-FEB-2015 — LNM/D. 24-OCT-2014

Delete radar reflector — 50°53′45.0″N 127°55′40.0″W
(See Chart No. 1, S4)
This notice affects Electronic Navigational Chart: CA270084 — *DFO(6202946-02)*

24-OCT-2014 — LNM/D. 22-AUG-2014

Delete depth of 9 fathoms — 52°35′30.0″N 129°18′42.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA270724 — *DFO(6202911-19)*

24-OCT-2014 — LNM/D. 22-AUG-2014

Add depth of 6 fathoms 5 feet — 52°35′28.5″N 129°18′34.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA270724 — *DFO(6202911-20)*

24-OCT-2014 — LNM/D. 22-AUG-2014

Chart no. 3744

Delete depth of 15 fathoms 52°33′30.0″N 129°19′33.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA270724 *DFO(6202911-21)*

24-OCT-2014 LNM/D. 22-AUG-2014

Add depth of 12 fathoms 52°33′29.0″N 129°19′19.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA270724 *DFO(6202911-22)*

22-AUG-2014 LNM/D. 25-APR-2014

Delete depth of 21 fathoms 52°27′50.0″N 129°15′50.0″W
(See Chart No. 1, I10)
DFO(6202892-05)

22-AUG-2014 LNM/D. 25-APR-2014

Add depth of 3 fathoms 5 feet 52°27′36.5″N 129°15′46.5″W
(See Chart No. 1, I10)
DFO(6202892-06)

25-APR-2014 LNM/D. 26-OCT-2012

Add marine park joining 51°56′37.0″N 131°10′54.0″W
(See Chart No. 1, Nf) 51°47′59.0″N 130°53′25.0″W
This notice affects Electronic Navigational Chart: 52°12′30.0″N 130°48′54.0″W
CA270084 52°26′50.0″N 131°05′13.0″W
and 52°35′47.0″N 131°10′54.0″W

DFO(6202727-20)

25-APR-2014 LNM/D. 26-OCT-2012

Add National park, marked NPR/RPN 52°08′00.0″N 130°54′00.0″W
(See Chart No. 1 Ef)
This notice affects Electronic Navigational Chart: CA270084 *DFO(6202727-21)*

25-APR-2014 LNM/D. 26-OCT-2012

Chart no. 3744

Add GWAII HAANAS NATIONAL PARK RESERVE, NATIONAL MARINE CONSERVATION AREA RESERVE AND HAIDA HERITAGE SITE
NPR
RÉSERVE DE PARC NATIONAL GWAII HAANAS, RÉSERVE D'AIRE MARINE NATIONALE DE CONSERVATION ET SITE DU PATRIMOINE HAÏDA
RPN
This notice affects Electronic Navigational Chart: CA270084
53°45′00.0″N 129°25′30.0″W
DFO(6202727-22)

26-OCT-2012

LNM/D. 28-SEP-2012

Reposition yellow ODAS/SADO lighted buoy Fl (5) Y, marked 46204
(See Chart No. 1, Q58)
from 51°22′06.7″N 128°44′54.0″W
to 51°23′31.3″N 128°45′54.6″W
(P2012048) LL(582.5) DFO(6202619-01)

This notice affects Electronic Navigational Chart: CA270084

28-SEP-2012

LNM/D. 17-FEB-2012

Delete depth of 10 fathoms
(See Chart No. 1, I10)
52°51′02.0″N 129°46′12.0″W
DFO(6202603-01)

This notice affects Electronic Navigational Chart: CA270084

28-SEP-2012

LNM/D. 17-FEB-2012

Add depth of 7 fathoms 3 feet
(See Chart No. 1, I10)
52°50′57.0″N 129°46′03.0″W
DFO(6202603-02)

This notice affects Electronic Navigational Chart: CA270084

17-FEB-2012

LNM/D. 25-SEP-2009

Amend Adjoining Chart/Carte adjacente 3802 to read Adjoining Chart/Carte adjacente 3800
(See Chart No. 1, A20)
outside north border at 130°40′00.0″W
DFO(6202537-13)

25-SEP-2009

LNM/D. 18-SEP-2009

Chart no. 3744

Add boarding place, position of a pilot cruising vessel 50°59′00.7″N 127°47′54.2″W
(See Chart No. 1, T1.1)

DFO(6202126-01)

This notice affects Electronic Navigational Chart: CA370109, CA470306

18-SEP-2009 LNM/D. 09-JAN-2009

Add radar transponder beacon against light Fl R 15M 50°58′32.9″N 127°43′34.9″W
(See Chart No. 1, S3.3)

(P2009073) LL(576) DFO(6202100-01)

This notice affects Electronic Navigational Chart: CA370109, CA470307

09-JAN-2009 LNM/D. 26-DEC-2008

Add depth of 8 fathoms 4 feet 52°14′25.9″N 128°30′00.3″W
(See Chart No. 1, I10)

DFO(6201971-02)

09-JAN-2009 LNM/D. 26-DEC-2008

Delete depth of 19 fathoms 52°13′51.3″N 128°30′00.0″W
(See Chart No. 1, I10)

DFO(6201971-03)

09-JAN-2009 LNM/D. 26-DEC-2008

Add depth of 14 fathoms 52°13′49.1″N 128°29′59.6″W
(See Chart No. 1, I10)

DFO(6201971-04)

26-DEC-2008 LNM/D. 14-DEC-2007

Delete dangerous underwater rock of 6 feet or less and legend Rep (1999) 52°35′35.0″N 129°28′09.5″W
(See Chart No. 1, K13 and I3.2)

DFO(6201966-01)

26-DEC-2008 LNM/D. 14-DEC-2007

Chart no. 3744

Delete dangerous underwater rock of 6 feet or less and legend Rep (1999) 52°29′46.0″N 129°29′01.5″W
(See Chart No. 1, K13 and I3.2) *DFO(6201966-05)*

26-DEC-2008 LNM/D. 14-DEC-2007
Add depth of 1 fathom 52°29′47.0″N 129°29′01.2″W
(See Chart No. 1, I10)
DFO(6201966-06)

14-DEC-2007 LNM/D. 03-AUG-2007
Delete non-dangerous wreck, depth unknown and legend Rep (1989) PA 50°51′48.6″N 128°11′43.1″W
(See Chart No.1, K29) *DFO(6201787-01)*

This notice affects Electronic Navigational Chart: CA370109

03-AUG-2007 LNM/D. 22-SEP-2006
Delete depth of 12 fathoms 52°37′00.0″N 129°28′06.0″W

DFO(6201701-01)

03-AUG-2007 LNM/D. 22-SEP-2006
Add depth of 9 fathoms 52°36′52.7″N 129°28′00.4″W

DFO(6201701-02)

22-SEP-2006 LNM/D. 02-MAY-2003
Add depth of 8 fathoms 53°39′13.5″N 130°32′50.6″W

DFO(6201549-02)

This notice affects Electronic Navigational Chart: CA370299

02-MAY-2003 LNM/D. 14-FEB-2003
Delete Fog Sig 50°46′57.2″N 128°25′32.8″W

(P2003026) LL(66) DFO(6200535-01)

Chart no. 3744

02-MAY-2003 LNM/D. 14-FEB-2003
Delete Fog Sig 51°14′54.3″N 127°49′55.7″W

(P2003031) LL(579) DFO(6200535-02)

02-MAY-2003 LNM/D. 14-FEB-2003
Delete Fog Sig 52°15′41.9″N 128°43′12.5″W

(P2003033) LL(619) DFO(6200535-11)

02-MAY-2003 LNM/D. 14-FEB-2003
Delete Fog Sig 52°16′10.9″N 128°24′18.0″W

(P2003034) LL(617) DFO(6200535-12)

14-FEB-2003 LNM/D. 17-JAN-2003
Delete radiobeacon marked RC 52°15′41.9″N 128°43′12.5″W

DFO(6200492-01)

17-JAN-2003 LNM/D. 25-JAN-2002
Reposition yellow ODAS light buoy, Fl (5) Y, marked 46185 from 52°24′30.0″N 129°47′00.0″W to 52°24′58.3″N 129°48′28.8″W

DFO(6200443-01)

25-JAN-2002 LNM/D. 26-OCT-2001
Amend Fl 2s 50ft 11M to read Fl 50ft 9M against light 50°54′20.0″N 127°59′00.0″W

(P2001121) LL(574) DFO(6201093-01)

26-OCT-2001 LNM/D. 25-MAY-2001
Delete radiobeacon and legend RC 50°46′55.0″N 128°25′35.0″W

(P2001108) LL(66) DFO(6201085-01)

25-MAY-2001 LNM/D. 23-FEB-2001

Chart no. 3744

Amend FW FlR 10s 86ft 13M to read FlR 15M 50°58′32.9″N 127°43′34.9″W

(P2001034P) LL(576) DFO(6201024-01)

23-FEB-2001 LNM/D. 07-JUL-2000

Reposition yellow ODAS light buoy Fl(5)Y marked 46204 from 51°23′00.0″N 128°44′17.4″W to 51°22′06.7″N 128°44′54.0″W

(CCG-P00-221) LL(582.5) DFO(6200993-01)

23-FEB-2001 LNM/D. 07-JUL-2000

Reposition yellow ODAS light buoy Fl(5)Y marked 46207 from 50°51′36.0″N 129°54′36.0″W to 50°52′30.7″N 129°54′48.0″W

(CCG-P00-223) LL(67.4) DFO(6200995-01)

07-JUL-2000 LNM/D. 31-DEC-1999

Delete Fog Sig 53°29′28.0″N 130°38′00.0″W

(P2000016) LL(734) DFO(6200767-05)