Chart no. 3921

3921 - Allison Harbour - New Edition - 15-DEC-1995 - NAD 1983

13-FEB-2026 LNM/D. 28-MAR-2025

Delete marine farm 51°06′02.5″N 127°32′43.5″W
(See Chart 1, K48.2)

DFO(6205369-01)

13-FEB-2026 LNM/D. 28-MAR-2025

Add pontoon joining 51°06′03.8″N 127°32′42.8″W
(See Chart 1, F16) 51°06′03.9″N 127°32′41.9″W
51°06′04.3″N 127°32′42.0″W
51°06′04.2″N 127°32′42.9″W
and 51°06′03.8″N 127°32′42.8″W

DFO(6205369-02)

28-MAR-2025 LNM/D. 20-OCT-2023

Add marine farm 51°05′55.8″N 127°32′09.3″W
(See Chart 1, K48.2)

DFO(6205180-01)

28-MAR-2025 LNM/D. 20-OCT-2023

Add marine farm 51°06′02.6″N 127°32′25.4″W
(See Chart 1, K48.2)

DFO(6205180-02)

28-MAR-2025 LNM/D. 20-OCT-2023

Add marine farm 51°06′02.5″N 127°32′43.7″W
(See Chart 1, K48.1, K48.2)

DFO(6205180-03)

21-JUL-2023 LNM/D. 13-FEB-2015

Amend light Fl 4s 13m to read Fl 4s 15m 51°00′00.8″N 127°33′51.1″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: *(P2023026) LL(562) DFO(6204742-01)*
CA470307, CA570098

24-DEC-2010 LNM/D. 31-OCT-2008

Chart no. 3921

Add sounding out of position of 0.4 metres with bottom quality of R marked Rep(2010) 51°02′23.1″N 127°32′03.0″W
(See Chart No. 1, I11, J9.1 and I3.2) *DFO(6202382-01)*

This notice affects Electronic Navigational Chart: CA470036, CA570098

31-OCT-2008 LNM/D. 08-AUG-2008

Add depth of 3.6 metres 51°02′46.3″N 127°33′00.4″W
(See Chart No. 1, I10)

DFO(6201960-01)

This notice affects Electronic Navigational Chart: CA470036

26-OCT-2007 LNM/D. 28-JAN-2005

Delete depth of 15.5 metres 51°02′07.2″N 127°32′56.5″W
(See Chart No. 1 I10)

DFO(6201766-01)

This notice affects Electronic Navigational Chart: CA470036

26-OCT-2007 LNM/D. 28-JAN-2005

Add depth of 3.9 metres 51°02′06.3″N 127°32′55.7″W
(See Chart No. 1 I10)

DFO(6201766-02)

This notice affects Electronic Navigational Chart: CA470036

3921 - Fish Egg Inlet - New Edition - 15-DEC-1995 - NAD 1983

20-OCT-2023 LNM/D. 21-JUL-2023

Add submarine cable joining 51°36′15.1″N 127°51′50.9″W
(See Chart 1, L30.1) 51°36′08.6″N 127°52′08.6″W
and 51°36′08.3″N 127°52′18.0″W

DFO(6204804-02)

13-FEB-2015 LNM/D. 24-DEC-2010

Delete depth of 17.2 metres 51°39′34.7″N 127°49′28.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470358, CA570099 *DFO(6202963-01)*

Chart no. 3921

13-FEB-2015 LNM/D. 24-DEC-2010

Add depth of 12.0 metres 51°39′35.1″N 127°49′27.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA470358, CA570099 *DFO(6202963-02)*

08-AUG-2008 LNM/D. 04-JUL-2008

Delete depth of 5.4 metres 51°37′01.2″N 127°41′25.8″W
(See Chart No. 1, I10)
DFO(6201910-01)

This notice affects Electronic Navigational Chart: CA570099

08-AUG-2008 LNM/D. 04-JUL-2008

Delete depth of 0.3 metres, legend R and legend Rep (2004) 51°37′00.7″N 127°41′25.2″W
(See Chart No. 1, I10 and I3.2)
DFO(6201910-02)

This notice affects Electronic Navigational Chart: CA570099

08-AUG-2008 LNM/D. 04-JUL-2008

Add depth of 1.9 metres with bottom quality of R 51°37′00.7″N 127°41′25.0″W
(See Chart No. 1, I10 and I3.2)
DFO(6201910-03)

This notice affects Electronic Navigational Chart: CA570099

04-JUL-2008 LNM/D. 26-OCT-2007

Add rock which covers and uncovers with drying height of 4 metres 51°39′00.0″N 127°45′33.9″W
(See Chart No. 1, K11)
DFO(6201872-01)

This notice affects Electronic Navigational Chart: CA470358, CA570099

28-JAN-2005 LNM/D. 02-MAY-2003

Add depth of 0.3 metres, legend R, and legend Rep (2004) 51°37′00.7″N 127°41′25.2″W
DFO(6201212-01)

02-MAY-2003 LNM/D. 14-JUL-2000

Chart no. 3921

Delete Fog Sig 30s 51°36′11.9″N 127°51′49.7″W

(P2003032) LL(585) DFO(6200535-13)

14-JUL-2000 LNM/D. 19-JUL-1996

Amend legend Adjoining Chart/Carte adjacente 3727 to read Adjoining Chart/Carte adjacente 3935 outside west border at 51° 37′ 30″N

DFO(6200777-08)