Chart no. 4012

4012 - Yarmouth to / à Halifax - New Edition - 14-FEB-2003 - NAD 1983

12-APR-2024 LNM/D. 01-MAR-2024

Replace depth of 20.1 metres with depth of 15.7 metres 43°49′12.9″N 064°48′52.0″W
(See Chart 1, I10)
DFO(6311065-35)

01-MAR-2024 LNM/D. 16-FEB-2024

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 157 metres 43°53′14.9″N 063°05′46.9″W
(See Chart 1, L25)
DFO(6311005-01)

16-FEB-2024 LNM/D. 17-FEB-2023

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 175 metres 44°40′22.7″N 066°31′51.2″W
(See Chart 1, L25)
DFO(6311006-03)

16-FEB-2024 LNM/D. 17-FEB-2023

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 116 metres 42°50′57.7″N 065°18′50.0″W
(See Chart 1, L25)
DFO(6311006-04)

17-FEB-2023 LNM/D. 20-JAN-2023

Add wreck, least depth unknown, with legend PA Rep (2022) 43°21′00.0″N 065°45′00.0″W
(See Chart 1, K29, B7, I3)
This notice affects Electronic Navigational Chart: CA276206, CA376014, CA476043
DFO(6310555-01)

20-JAN-2023 LNM/D. 16-DEC-2022

Add wreck Wk with known depth of 138 metres 42°46′26.9″N 066°38′46.8″W
(See Chart 1, K26)
This notice affects Electronic Navigational Chart: CA276206 *DFO(6310553-01)*

16-DEC-2022 LNM/D. 25-NOV-2022

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 169 metres 44°41′20.3″N 066°31′56.2″W
(See Chart 1, L25)
DFO(6310472-02)

Chart no. 4012

16-DEC-2022 LNM/D. 25-NOV-2022

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 120 metres 42°54′21.2″N 065°18′53.9″W
(See Chart 1, L25) *DFO(6310472-03)*

This notice affects Electronic Navigational Chart: CA276800

16-DEC-2022 LNM/D. 25-NOV-2022

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 155 metres 42°54′55.4″N 065°19′21.3″W
This notice affects Electronic Navigational Chart: CA276800 *DFO(6310472-04)*

16-DEC-2022 LNM/D. 25-NOV-2022

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 173 meters 43°36′30.7″N 062°52′07.0″W
(See Chart 1, L25) *DFO(6310472-08)*
This notice affects Electronic Navigational Chart: CA276801

16-DEC-2022 LNM/D. 25-NOV-2022

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 163 metres 44°15′00.1″N 063°10′01.3″W
(See Chart 1, L25) *DFO(6310472-10)*
This notice affects Electronic Navigational Chart: CA276801, CA376032

25-NOV-2022 LNM/D. 12-AUG-2022

Delete legend Fog Sig against light 44°30′18.7″N 063°31′15.7″W
(See Chart No 1 R20)
This notice affects Electronic Navigational Chart: CA276801, CA476009 *(F2022018) LL(513) DFO(6310357-01)*

25-NOV-2022 LNM/D. 12-AUG-2022

Delete obstruction, depth unknown PA with legend Rep (2022) 44°19′46.0″N 063°21′15.0″W
(See Chart 1, K40)
This notice affects Electronic Navigational Chart: CA276801, CA476009 *DFO(6310440-01)*

25-NOV-2022 LNM/D. 12-AUG-2022

Chart no. 4012

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 169 metres — 44°41′22.6″N 066°31′42.8″W
(See Chart 1, L25) — *DFO(6310445-01)*
This notice affects Electronic Navigational Chart: CA276206

12-AUG-2022 — LNM/D. 06-MAY-2022

Add obstruction, depth unknown PA with legend Rep (2022) — 44°19′46.8″N 063°21′15.0″W
(See Chart No. 1, K40)
This notice affects Electronic Navigational Chart: CA276801, CA476009 — *DFO(6310190-01)*

06-MAY-2022 — LNM/D. 04-MAR-2022

Amend Fl 5s 25m 19M to read Oc 3s25m19M against light — 43°41′23.2″N 066°08′31.0″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276206, CA376018 — *(F2022001) LL(272) DFO(6310079-01)*

04-MAR-2022 — LNM/D. 25-FEB-2022

Delete legend Fog Sig against light — 44°24′08.7″N 066°12′55.5″W
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart: CA276206, CA376024, CA476028 — *(F2021081) LL(216) DFO(6309915-01)*

04-MAR-2022 — LNM/D. 25-FEB-2022

Delete legend Fog Sig against light — 44°17′12.0″N 066°20′30.0″W
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart: CA276206, CA376024, CA476027 — *(F2021082) LL(221) DFO(6309916-01)*

04-MAR-2022 — LNM/D. 25-FEB-2022

Delete legend Fog Sig against light — 44°14′55.0″N 066°23′23.0″W
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart: CA276206, CA376024 — *(F2021085) LL(223) DFO(6309962-01)*

25-FEB-2022 — LNM/D. 07-JAN-2022

Add private yellow ODAS/SADO lighted conical buoy Fl Y 2.5s, Priv — 44°36′25.9″N 063°59′16.1″W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA276801, CA476195 — *DFO(6309993-01)*

Chart no. 4012

07-JAN-2022 LNM/D. 17-DEC-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 155 metres 42°54′55.4″N 065°19′21.3″W
(See Chart No. 1, L25) *DFO(6309968-01)*
This notice affects Electronic Navigational Chart: CA276800

07-JAN-2022 LNM/D. 17-DEC-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 120 metres 42°54′31.1″N 065°18′53.9″W
(See Chart No. 1, L25) *DFO(6309968-02)*
This notice affects Electronic Navigational Chart: CA276800

07-JAN-2022 LNM/D. 17-DEC-2021

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 179 metres 44°41′34.0″N 066°31′56.0″W
(See Chart No. 1, L25) *DFO(6309973-01)*
This notice affects Electronic Navigational Chart: CA276206

07-JAN-2022 LNM/D. 17-DEC-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 169 metres 44°41′20.3″N 066°31′56.2″W
(See Chart No. 1, L25) *DFO(6309973-02)*
This notice affects Electronic Navigational Chart: CA276206

17-DEC-2021 LNM/D. 20-AUG-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 157 metres 43°53′13.8″N 063°05′45.7″W
(See Chart No. 1, L25) *DFO(6309802-01)*
This notice affects Electronic Navigational Chart: CA176140, CA276801

17-DEC-2021 LNM/D. 20-AUG-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 160 metres 43°53′46.2″N 063°04′46.0″W
(See Chart No. 1, L25) *DFO(6309802-02)*
This notice affects Electronic Navigational Chart: CA276801

17-DEC-2021 LNM/D. 20-AUG-2021

Chart no. 4012

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 228 metres — 43°54′52.1″N 063°03′26.5″W
(See Chart No. 1, L25) — *DFO(6309802-03)*
This notice affects Electronic Navigational Chart: CA176140, CA276801

20-AUG-2021 — LNM/D. 26-FEB-2021

Amend Fl 5s18m12M to read Fl 4s28m7M against light — 44°24′06.0″N 066°12′55.0″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276206, CA376024, CA476028 — *(F2021033) LL(216) DFO(6309457-01)*

20-AUG-2021 — LNM/D. 26-FEB-2021

Delete legend Fog Sig against light — 44°14′12.0″N 064°19′01.0″W
(See Chart No 1 R20)
This notice affects Electronic Navigational Chart: CA276801, CA476664 — *(F2021038) LL(423) DFO(6309461-01)*

26-FEB-2021 — LNM/D. 12-FEB-2021

Add wreck, least depth unknown, PA — 44°47′52.2″N 065°39′01.3″W
(See Chart No. 1, K29, B7)
This notice affects Electronic Navigational Chart: CA276206 — *DFO(6309379-01)*

12-FEB-2021 — LNM/D. 01-JAN-2021

Amend Fl 10s 14m 21M to read Fl 9s14m21M against light — 44°17′13.0″N 066°20′30.0″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276206, CA376024, CA476027 — *(F2020050) LL(221) DFO(6309321-01)*

01-JAN-2021 — LNM/D. 10-JUL-2020

Amend Fl 15s 19m 13M to read LFl 6s19m13M — 44°26′22.5″N 063°45′58.3″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276801, CA476195 — *(F2020049) LL(495) DFO(6309314-01)*

10-JUL-2020 — LNM/D. 19-JUN-2020

Delete depth of 42 metres — 44°37′50.0″N 063°02′50.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801 — *DFO(6309000-02)*

Chart no. 4012

10-JUL-2020 LNM/D. 19-JUN-2020

Add depth of 13.3 metres 44°37′47.4″N 063°02′34.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 *DFO(6309000-03)*

10-JUL-2020 LNM/D. 19-JUN-2020

Delete depth of 35 metres 44°36′56.0″N 063°01′05.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 *DFO(6309000-05)*

10-JUL-2020 LNM/D. 19-JUN-2020

Add depth of 25.1 metres 44°37′01.8″N 063°00′57.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 *DFO(6309000-06)*

10-JUL-2020 LNM/D. 19-JUN-2020

Delete depth of 35 metres 44°36′17.0″N 062°59′36.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801 *DFO(6309000-07)*

10-JUL-2020 LNM/D. 19-JUN-2020

Add depth of 24.9 metres 44°36′28.2″N 062°59′34.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 *DFO(6309000-08)*

19-JUN-2020 LNM/D. 27-MAR-2020

Amend FI 6s 16m 9M to read LFI 6s16m9M against light 43°37′50.0″N 066°01′36.0″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276206, CA376018, CA476048 *(F2020023) LL(283) DFO(6308988-01)*

27-MAR-2020 LNM/D. 20-MAR-2020

Amend Fl 12s24m8M to read LFl 12s24m8M against light 44°13′47.0″N 064°16′31.0″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276801, CA476664 *(F2020003) LL(432) DFO(6308940-01)*

Chart no. 4012

20-MAR-2020 LNM/D. 08-NOV-2019

Amend depth of 87 metres to read 94 metres against subsurface Ocean Data Acquisition system ODAS/SADO 43°29′47.4″N 062°52′09.1″W
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA176140, CA276801 *DFO(6308935-03)*

20-MAR-2020 LNM/D. 08-NOV-2019

Amend depth of 89 metres to read 103 metres against subsurface Ocean Data Acquisition system ODAS/SADO 43°00′09.0″N 065°33′53.0″W
(See Chart No. 1, L25)
This notice affects Electronic Navigational Chart: CA276206 *DFO(6308935-04)*

08-NOV-2019 LNM/D. 25-OCT-2019

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 163 metres 44°14′56.9″N 063°09′53.6″W
(See Chart No. 1, L25) *DFO(6308831-02)*

This notice affects Electronic Navigational Chart: CA276801

25-OCT-2019 LNM/D. 23-AUG-2019

Add yellow ODAS/SADO lighted pillar buoy Fl (5) Y 20s, marked 4400490 44°39′53.3″N 066°21′52.2″W
(See Chart No. 1, Q58) *DFO(6308813-01)*
This notice affects Electronic Navigational Chart: CA276206

23-AUG-2019 LNM/D. 07-DEC-2018

Add depth of 10 metres 44°38′50.9″N 063°07′05.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 *DFO(6308730-03)*

23-AUG-2019 LNM/D. 07-DEC-2018

Delete depth of 14 metres, 6 decimetres 44°37′57.9″N 063°01′01.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801 *DFO(6308730-04)*

23-AUG-2019 LNM/D. 07-DEC-2018

Chart no. 4012

Add depth of 10 metres, 8 decimetres — 44°37′57.9″N 063°01′01.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 — *DFO(6308730-05)*

07-DEC-2018 — LNM/D. 23-NOV-2018

Add yellow ODAS/SADO lighted pillar Fl(5) Y 20s — 44°20′52.0″N 063°18′21.0″W
(See Chart No. 1, Q58)
This notice affects Electronic Navigational Chart: CA176140, CA276801, CA476009 — *DFO(6308508-02)*

23-NOV-2018 — LNM/D. 27-JUL-2018

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 179 metres — 44°41′35.5″N 066°31′53.5″W
(See Chart No. 1, L25) — *DFO(6308498-01)*
This notice affects Electronic Navigational Chart: CA276206

27-JUL-2018 — LNM/D. 29-JUN-2018

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 89 metres — 43°00′09.3″N 065°33′55.2″W
(See Chart No. 1, L25) — *DFO(6308322-01)*
This notice affects Electronic Navigational Chart: CA276206

27-JUL-2018 — LNM/D. 29-JUN-2018

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 87 metres — 43°29′51.4″N 062°52′11.9″W
(See Chart No. 1, L25) — *DFO(6308323-01)*
This notice affects Electronic Navigational Chart: CA176140, CA276801

27-JUL-2018 — LNM/D. 29-JUN-2018

Reposition light Fl 18m7M — from 44°02′01.1″N 064°37′41.8″W
(See Chart No. 1, P1) — to 44°02′03.5″N 064°37′42.5″W
This notice affects Electronic Navigational Chart: CA276800, CA376045, CA476202 — *(F2018021) LL(407) DFO(6308352-01)*

27-JUL-2018 — LNM/D. 29-JUN-2018

Chart no. 4012

Amend Fl 18m7M to read Fl 4s15m7M against light — 44°02′03.5″N 064°37′42.5″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276800, CA376045, CA476202 — *(F2018021) LL(407) DFO(6308352-02)*

29-JUN-2018 — LNM/D. 09-JUN-2017

Amend Fl(2)15s28m10M to read LFl 6s28m11M against light — 43°30′26.2″N 065°20′44.2″W
(See Chart No. 1, P16) — *(F2018019) LL(349) DFO(6308301-01)*

This notice affects Electronic Navigational Chart: CA276800, CA376047

09-JUN-2017 — LNM/D. 05-AUG-2016

Delete light F G — 44°39′55.7″N 065°49′56.9″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA276206, CA476006 — *(F2017006) LL(212) DFO(6307890-01)*

05-AUG-2016 — LNM/D. 06-MAY-2016

Delete legend FogSig against light — 44°26′19.7″N 063°46′00.4″W
(See Chart No 1 R20)
This notice affects Electronic Navigational Chart: CA276801, CA476195 — *(F2016032) LL(495) DFO(6307615-01)*

06-MAY-2016 — LNM/D. 04-DEC-2015

Amend LFl 6s 26m 14M to read LFl 6s 8m 12M against light — 44°39′53.0″N 062°51′51.1″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA176140, CA276801, CA376083 — *(F2016011) LL(580) DFO(6307493-01)*

04-DEC-2015 — LNM/D. 28-AUG-2015

Add submarine cable — joining 44°28′52.0″N 062°39′57.8″W
(See Chart No. 1, L30.1) — 44°26′52.9″N 062°48′43.5″W
This notice affects Electronic Navigational Chart: CA276801 — 44°25′06.1″N 063°05′48.5″W
44°25′29.2″N 063°08′02.9″W
44°33′53.2″N 063°25′29.2″W
and 44°33′34.0″N 063°33′27.0″W

DFO(6307337-01)

Chart no. 4012

28-AUG-2015 LNM/D. 31-JUL-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 173 metres. 43°36′31.4″N 062°52′06.0″W
(See Chart No. 1, L25) *DFO(6307180-01)*
This notice affects Electronic Navigational Chart: CA176140, CA276801

31-JUL-2015 LNM/D. 05-JUN-2015

Amend FogSig (Occas) to read FogSig 43°27′03.8″N 065°28′09.5″W
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart: CA276800, CA376047 *(F2015022) LL(336) DFO(6307210-01)*

05-JUN-2015 LNM/D. 29-MAY-2015

Amend FogSig to read FogSig (Occas) 43°26′59.0″N 065°28′15.0″W
(See Chart No. 1, R20)
This notice affects Electronic Navigational Chart: CA276800, CA376047 *(F2015014) LL(336) DFO(6307115-01)*

29-MAY-2015 LNM/D. 24-APR-2015

Add wreck WK with known depth of 44 metres 44°26′43.9″N 063°57′24.2″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA276801, CA476195 *DFO(6307123-01)*

24-APR-2015 LNM/D. 10-OCT-2014

Delete legend Fog Sig against light 44°41′28.0″N 065°47′00.0″W
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart: CA276206, CA476006 *(F2015009) LL(201) DFO(6307090-01)*

10-OCT-2014 LNM/D. 08-NOV-2013

Delete fog signal Fog Sig against light 43°41′23.1″N 066°08′38.3″W
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart: CA276206, CA376018 *(F2014029) LL(272) DFO(6306854-01)*

08-NOV-2013 LNM/D. 17-MAY-2013

Chart no. 4012

Add maritime limit in general implying: permanent physical obstructions
(See Chart No. 1, N1.1)
This notice affects Electronic Navigational Chart: CA276801, CA376032

joining 44°16′12.0″N 063°18′00.0″W
44°03′58.9″N 063°04′27.6″W
43°51′45.8″N 063°13′38.6″W
43°48′00.0″N 063°20′00.0″W
43°41′33.5″N 063°23′59.8″W
43°38′01.1″N 063°23′58.4″W
43°29′41.3″N 063°30′15.0″W
and 42°50′13.5″N 063°30′15.0″W

DFO(6306496-01)

08-NOV-2013 LNM/D. 17-MAY-2013

Add See/Voir note SCIENTIFIC MOORINGS MOUILLAGES SCIENTIFIQUES
(see Chart 1, A14)

43°25′50.0″N 063°26′00.0″W

DFO(6306496-02)

17-MAY-2013 LNM/D. 08-FEB-2013

Delete depth of 128 metres over artificial feature
(See Chart No 1 Ka)
This notice affects Electronic Navigational Chart: CA276206, CA276800

43°02′07.0″N 065°46′04.6″W

DFO(6306359-01)

17-MAY-2013 LNM/D. 08-FEB-2013

Delete private yellow lighted spar buoy Fl(5) Y 20s
(See Chart No. 1, Q24)
This notice affects Electronic Navigational Chart: CA276206, CA276800

43°02′19.3″N 065°46′04.6″W

DFO(6306359-02)

17-MAY-2013 LNM/D. 08-FEB-2013

Delete private yellow lighted spar buoy Fl(5) Y 20s
(See Chart No. 1, Q24)
This notice affects Electronic Navigational Chart: CA276206, CA276800

43°02′01.1″N 065°46′50.2″W

DFO(6306359-03)

08-FEB-2013 LNM/D. 27-NOV-2012

Add maritime limit in general implying: permanent physical obstructions
(see Chart 1, N1.1)
This notice affects Electronic Navigational Chart: CA276801, CA376032, CA476009

between 44°28′42.0″N 063°32′00.0″W
and 44°16′12.0″N 063°18′00.0″W

DFO(6304781-01)

Chart no. 4012

08-FEB-2013 LNM/D. 27-NOV-2012

Add See/Voir note 44°17′15.0″N 063°12′25.0″W
SCIENTIFIC MOORINGS
MOUILLAGES SCIENTIFIQUES *DFO(6304781-02)*

08-FEB-2013 LNM/D. 27-NOV-2012

Add note: 43°54′00.0″N 065°10′00.0″W
SCIENTIFIC MOORINGS
Acoustic sensors, one metre high and positioned approximately 800 metres apart, along the line, directly on the seabed. Mariners are advised to avoid anchoring or conducting seabed operations in the vicinity of submarine moorings. *DFO(6304781-03)*

MOUILLAGES SCIENTIFIQUES
Des capteurs acoustiques, d'une hauteur d'un mètre et positionnés à intervalles d'environ 800 mètres le long de la ligne, reposent directement sur le fond marin. Nous avisons les navigateurs d'éviter de mouiller ou d'effectuer des travaux sur le fond marin à proximité de ces mouillages sous-marins.

27-NOV-2012 LNM/D. 25-MAY-2012

Add maritime limit in general, usually implying no permanent physical obstructions
(See Chart No. 1,N1.2)
joining 44°29′00.0″N 066°37′00.0″W
44°29′00.0″N 066°30′00.0″W
44°33′00.0″N 066°22′00.0″W
44°40′00.0″N 066°17′00.0″W
44°47′00.0″N 066°17′00.0″W
44°49′00.0″N 066°27′00.0″W
44°42′00.0″N 066°37′00.0″W
and 44°29′00.0″N 066°37′00.0″W

DFO(6305956-01)

27-NOV-2012 LNM/D. 25-MAY-2012

Add See/Voir note RIGHT WHALE CRITICAL HABITAT / HABITAT ESSENTIEL DE LA BALEINE NOIRE 44°39′00.0″N 066°28′00.0″W

DFO(6305956-02)

27-NOV-2012 LNM/D. 25-MAY-2012

Chart no. 4012

Add RIGHT WHALE CRITICAL HABITAT — 44°04′00.0″N 065°00′09.0″W
From July through December, it is recommended that mariners decrease vessel speed, and proceed with extreme caution to avoid marine mammals. For further details, see Notice No. 5 in the Notices to Mariners, Annual Edition. — *DFO(6305956-05)*

HABITAT ESSENTIEL DE LA BALEINE NOIRE
On conseille aux navigateurs de réduire la vitesse de leur navire durant la période de juillet à décembre et d′avancer avec une grande prudence afin d′éviter les mammifères marins. Pour plus de renseignements, voir l′avis nº 5 dans l′édition annuelle des Avis aux navigateurs.

25-MAY-2012 — LNM/D. 13-JAN-2012

Delete legend ″BELL″ against red starboard hand lighted pillar bell buoy FlR — 44°10′13.0″N 066°27′01.3″W
(F2012008) LL(225) DFO(6305979-01)

13-JAN-2012 — LNM/D. 18-NOV-2011

Delete legend Fog Sig against light — 44°26′12.0″N 063°33′48.0″W
(See Chart No. 1, R1, R20)
(F2011193) LL(507) DFO(6305873-01)

This notice affects Electronic Navigational Chart: CA276801, CA476009

18-NOV-2011 — LNM/D. 16-SEP-2011

Delete light Fl 10s 16m 8M — 44°34′53.3″N 063°27′26.7″W
(See Chart No. 1, P1)
(F2011184) LL(545) DFO(6305805-01)

This notice affects Electronic Navigational Chart: CA276801, CA476009

16-SEP-2011 — LNM/D. 12-AUG-2011

Delete light Fl — 44°33′02.6″N 066°02′09.5″W
(See Chart No. 1, P1)
(F2011165) LL(214) DFO(6305694-01)

16-SEP-2011 — LNM/D. 12-AUG-2011

Chart no. 4012

Add light FlG 44°33′08.0″N 066°01′51.0″W
(See Chart No. 1, P1)
(F2011165) LL(214) DFO(6305694-02)

12-AUG-2011 LNM/D. 05-AUG-2011

Add yellow ODAS/SADO lighted spar buoy Fl(5)Y 20s & Q 43°49′52.0″N 062°58′55.3″W
(See Chart No. 1, Q58)
DFO(6305658-01)

12-AUG-2011 LNM/D. 05-AUG-2011

Add obstruction with known depth of 30 metres with legend ODAS/SADO 43°50′29.2″N 062°55′46.3″W
DFO(6305658-03)

12-AUG-2011 LNM/D. 05-AUG-2011

Add obstruction with known depth of 30 metres with legend ODAS/SADO 43°49′46.0″N 062°55′20.2″W
DFO(6305658-04)

05-AUG-2011 LNM/D. 11-FEB-2011

Amend FL 12s 35m 13M to read LFl 12s 35m 13M (Priv) against light 43°47′38.8″N 066°09′19.3″W
(See Chart No. 1, P16) *(F2011102) LL(260) DFO(6305611-01)*

This notice affects Electronic Navigational Chart:
CA576020

11-FEB-2011 LNM/D. 04-JUN-2010

Add depth of 128 metres over artificial feature 43°02′07.0″N 065°46′04.6″W
(See Chart No 1 Ka)
The mooring is temporary. The proposed date of removal is November 2011. *DFO(6305217-01)*

11-FEB-2011 LNM/D. 04-JUN-2010

Add private yellow lighted spar buoy Fl(5) Y 20s 43°02′19.3″N 065°46′04.6″W
(See Chart No 1 Q24)
DFO(6305217-02)

Chart no. 4012

11-FEB-2011 LNM/D. 04-JUN-2010

Add private yellow lighted spar buoy Fl(5) Y 20s 43°02′01.1″N 065°46′50.2″W
(See Chart No 1 Q24)

DFO(6305217-03)

04-JUN-2010 LNM/D. 12-FEB-2010

Amend Fl 20s 49m 16M to read Fl 20s 48m 10M against light 44°30′17.0″N 063°31′16.0″W
(See Chart 1 P16)

LL(513) DFO(6304817-01)

This notice affects Electronic Navigational Chart: CA176140

04-JUN-2010 LNM/D. 12-FEB-2010

Amend Fl 10s 25m 16M to read Fl 10s 25m 10M against light 44°18′43.7″N 064°10′06.4″W
(See Chart 1 P16)

LL(443) DFO(6304833-01)

This notice affects Electronic Navigational Chart: CA176140, CA476664

12-FEB-2010 LNM/D. 13-NOV-2009

Amend Fl 15s 26m 9M to read LFl 6s 26m 14M against light 44°39′53.1″N 062°51′48.3″W
(See Chart 1 P16)

(F2009078) LL(580) DFO(6304719-01)

This notice affects Electronic Navigational Chart: CA176140, CA276801, CA376083

13-NOV-2009 LNM/D. 21-AUG-2009

Delete red starboard hand lighted pillar whistle buoy FlR, WHIS 43°47′25.0″N 064°46′56.0″W
(See Chart No 1 Qf)

(F2006006) LL(392) DFO(6304635-01)

This notice affects Electronic Navigational Chart: CA276800

13-NOV-2009 LNM/D. 21-AUG-2009

Chart no. 4012

Add black, yellow and black East cardinal lighted pillar buoy Q(3) 10s
(See Chart No 1 Q130.3) — 43°48′12.6″N 064°46′27.2″W
(F2006014) LL(394.01) DFO(6304635-02)

This notice affects Electronic Navigational Chart: CA276800

13-NOV-2009 — LNM/D. 21-AUG-2009

Delete depth of 25 metres, 6 decimetres
(See Chart No. 1, I10) — 44°41′04.4″N 062°41′28.9″W
DFO(6304638-01)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009 — LNM/D. 21-AUG-2009

Add depth of 14 metres
(See Chart No. 1, I10) — 44°40′44.8″N 062°41′04.6″W
DFO(6304638-02)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009 — LNM/D. 21-AUG-2009

Add depth of 14 metres
(See Chart No. 1, I10) — 44°40′24.0″N 062°43′08.7″W
DFO(6304638-04)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009 — LNM/D. 21-AUG-2009

Delete depth of 20 metres, 1 decimetre
(See Chart No. 1, I10) — 44°40′41.8″N 062°46′09.2″W
DFO(6304638-05)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009 — LNM/D. 21-AUG-2009

Add depth of 14 metres, 9 decimetres
(See Chart No. 1, I10) — 44°40′44.6″N 062°45′51.4″W
DFO(6304638-06)

This notice affects Electronic Navigational Chart: CA276801

Chart no. 4012

13-NOV-2009 LNM/D. 21-AUG-2009

Delete depth of 29 metres, 3 decimetres 44°39′16.0″N 062°45′27.0″W
(See Chart No. 1, I10)

DFO(6304638-07)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009 LNM/D. 21-AUG-2009

Add depth of 15 metres, 8 decimetres 44°39′19.6″N 062°45′21.7″W
(See Chart No. 1, I10)

DFO(6304638-08)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009 LNM/D. 21-AUG-2009

Delete depth of 33 metres 44°37′02.7″N 062°54′21.4″W
(See Chart No. 1, I10)

DFO(6304641-01)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009 LNM/D. 21-AUG-2009

Delete depth of 25 metres, 6 decimetres 44°37′24.0″N 062°55′16.3″W
(See Chart No. 1, I10)

DFO(6304641-02)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009 LNM/D. 21-AUG-2009

Add depth of 18 metres, 4 decimetres 44°37′08.8″N 062°54′11.3″W
(See Chart No. 1, I10)

DFO(6304641-03)

This notice affects Electronic Navigational Chart: CA276801

13-NOV-2009 LNM/D. 21-AUG-2009

Delete depth of 46 metres 44°35′34.2″N 062°54′26.5″W
(See Chart No. 1, I10)

DFO(6304642-01)

This notice affects Electronic Navigational Chart: CA276801

Chart no. 4012

13-NOV-2009 LNM/D. 21-AUG-2009

Add depth of 29 metres, 8 decimetres 44°35′53.5″N 062°54′14.3″W
(See Chart No. 1, I10)

DFO(6304642-02)

This notice affects Electronic Navigational Chart: CA276801

21-AUG-2009 LNM/D. 07-AUG-2009

Delete private yellow ODAS/SADO lighted super-buoy Fl (5) Y 43°37′39.6″N 066°33′13.2″W
(See Chart No 1 Q58)

DFO(6304496-01)

This notice affects Electronic Navigational Chart: CA276206, CA376044

07-AUG-2009 LNM/D. 24-JUL-2009

Amend Fl 10s 33m 16M to read Fl 10s 33m 10M against light 43°37′21.4″N 065°15′50.0″W
(See Chart No 1 P16)

LL(355) DFO(6304444-01)

This notice affects Electronic Navigational Chart: CA276800, CA376047

24-JUL-2009 LNM/D. 12-JUN-2009

Amend Fl(2) 15s 28m 16M to read Fl(2) 15s 28m 10M against light 43°30′31.0″N 065°20′35.4″W
(See Chart No 1 P16)

LL(349) DFO(6304430-01)

This notice affects Electronic Navigational Chart: CA276800, CA376047

12-JUN-2009 LNM/D. 20-FEB-2009

(T)Add subsurface mooring at a depth of 37 metres 43°02′00.0″N 065°46′01.0″W
The mooring is temporary. The proposed date of removal is November 2009.
The mooring has been removed. Notice 12-June-2009(T), DFO (6304406-01) is cancelled.
Cancelled on 11-FEB-11

DFO(6304406-01)

12-JUN-2009 LNM/D. 20-FEB-2009

Chart no. 4012

(T)Add private yellow cautionary lighted spar buoy Fl Y (See Chart No 1 Qm) — 43°01′58.8″N 065°45′51.4″W
The mooring is temporary. The proposed date of removal is November 2009. — *DFO(6304406-02)*
The mooring has been removed. Notice 12-June-2009(T), DFO (6304406-02) is cancelled.
Cancelled on 11-FEB-11

20-FEB-2009 — LNM/D. 07-NOV-2008

Amend Fl G to read LFl G against light (See Chart No 1 P16) — 44°48′49.0″N 065°32′18.0″W

(F2008139) LL(199) DFO(6304241-01)

This notice affects Electronic Navigational Chart: CA276206

07-NOV-2008 — LNM/D. 31-OCT-2008

Delete circular radiobeacon against light Fl 10s 31m (See Chart No 1 S10) — 43°23′40.0″N 066°00′51.0″W

DFO(6304021-01)

This notice affects Electronic Navigational Chart: CA276206, CA376014

31-OCT-2008 — LNM/D. 26-SEP-2008

Amend FG 22m to read FlR 22m against light (See Chart No 1 P 16) — 44°29′30.4″N 063°55′00.0″W

(F2008110) LL(487) DFO(6304027-01)

This notice affects Electronic Navigational Chart: CA476195

26-SEP-2008 — LNM/D. 04-APR-2008

Amend Fl 5s 43m 22M to read Fl 6s 43m 23M against light (See Chart No 1 P16) — 44°26′12.0″N 063°33′48.0″W

(F2008068) LL(507) DFO(6303952-01)

This notice affects Electronic Navigational Chart: CA476009

04-APR-2008 — LNM/D. 07-MAR-2008

Chart no. 4012

(T)Add scientific subsurface mooring at a depth of 196 metres below the surface — 44°02′58.0″N 063°04′58.0″W
Proposed date of removal is June 2008. — *DFO(6303821-01)*
The mooring has been removed. Notice 04-April-2008(T), DFO (6303821) is now cancelled.
Cancelled on 26-SEP-08

07-MAR-2008 — LNM/D. 18-JAN-2008

Amend Roseway Basin Right Whale Conservation Area / Zone de préservation des baleines noires du Bassin Roseway to read — 42°54′00.0″N 065°42′30.0″W
See CAUTION NO. 2/Voir ATTENTION nº2 — *DFO(6303813-01)*

This notice affects Electronic Navigational Chart: CA276800

07-MAR-2008 — LNM/D. 18-JAN-2008

Add note: — 43°57′00.0″N 065°42′00.0″W
CAUTION NO. 2
Roseway Basin Seasonal Area to be Avoided. In order to significantly reduce the risk of ship strikes of the highly endangered North Atlantic right whale, it is recommended that ships of 300 gross tonnage and upwards solely in transit during the period of June 1st through December 31st should avoid this area. — *DFO(6303813-02)*

ATTENTION nº2
Zone du bassin Roseway à éviter sur une base saisonnière. On recommande aux navires de 300 tonnes brut et plus et transitant dans cette zone de conservation, d'éviter cette dernière durant la période allant du 1er juin au 31 décembre afin de réduire considérablement le risque de collision entre les navires et les baleines noires de l'Atlantique Nord, dont l'espèce est en voie de disparition.

(See Chart No 1 Section A 14.)

This notice affects Electronic Navigational Chart: CA276800

18-JAN-2008 — LNM/D. 10-AUG-2007

Chart no. 4012

Add limit of restricted area joining 42°40′00.3″N 065°28′58.9″W
(See Chart No 1 N2.1) 42°47′00.0″N 064°59′00.0″W
43°16′00.0″N 064°55′00.0″W
42°52′00.0″N 066°05′00.0″W
and 42°40′00.3″N 065°33′37.7″W

This notice affects Electronic Navigational Chart: CA276800

DFO(6303773-01)

18-JAN-2008 LNM/D. 10-AUG-2007

Add legend Roseway Basin Right Whale Conservation Area / Zone de préservation des baleines noires du Bassin Roseway 42°54′00.0″N 065°42′30.0″W

DFO(6303773-02)

10-AUG-2007 LNM/D. 06-JUL-2007

Delete BELL against red starboard hand lighted pillar bell buoy FlR 44°18′17.0″N 066°25′55.0″W

(F2007068) LL(220) DFO(6303543-01)

This notice affects Electronic Navigational Chart: CA276206

06-JUL-2007 LNM/D. 09-FEB-2007

(T)Add yellow ODAS/SADO lighted super-buoy Fl (5) Y 44°17′18.0″N 063°14′18.0″W
Proposed date of removal is November 2007
Caution note advertised on Chart 4320. See Notice 14-December-2007, DFO(6303647). Notice 6-July-2007(T), DFO(6303535) is now cancelled.
Cancelled on 14-DEC-07

DFO(6303535-01)

06-JUL-2007 LNM/D. 09-FEB-2007

(T)Add yellow ODAS/SADO lighted super-buoy Fl (5) Y 44°17′46.3″N 063°14′19.0″W
Proposed date of removal is November 2007
Caution note advertised on Chart 4320. See Notice 14-December-2007, DFO(6303647). Notice 6-July-2007(T), DFO(6303535) is now cancelled.
Cancelled on 14-DEC-07

DFO(6303535-02)

06-JUL-2007 LNM/D. 09-FEB-2007

Chart no. 4012

(T)Add yellow ODAS/SADO lighted super-buoy Fl (5) Y — 44°17′50.6″N 063°15′41.6″W
Proposed date of removal is November 2007
Caution note advertised on Chart 4320. See Notice 14-December-2007, DFO(6303647). Notice 6-July-2007(T), DFO(6303535) is now cancelled.
Cancelled on 14-DEC-07
DFO(6303535-03)

06-JUL-2007 — LNM/D. 09-FEB-2007

(T)Add yellow ODAS/SADO lighted super-buoy Fl (5) Y — 44°17′15.7″N 063°14′12.7″W
Proposed date of removal is November 2007
Caution note advertised on Chart 4320. See Notice 14-December-2007, DFO(6303647). Notice 6-July-2007(T), DFO(6303535) is now cancelled.
Cancelled on 14-DEC-07
DFO(6303535-04)

06-JUL-2007 — LNM/D. 09-FEB-2007

(T)Add subsurface mooring — 44°17′15.6″N 063°14′12.6″W
Proposed date of removal is November 2007
Caution note advertised on Chart 4320. See Notice 14-December-2007, DFO(6303647). Notice 6-July-2007(T), DFO(6303535) is now cancelled.
Cancelled on 14-DEC-07
DFO(6303535-05)

09-FEB-2007 — LNM/D. 17-NOV-2006

Delete red and white fairway lighted pillar bell buoy Mo(A), BELL — 44°00′52.8″N 064°37′47.8″W
(F2006174) LL(406) DFO(6303264-01)

09-FEB-2007 — LNM/D. 17-NOV-2006

Delete legend ″BELL″ against green port hand lighted pillar bell buoy FlG, BELL — 44°03′23.3″N 064°31′28.8″W
(F2006176) LL(413) DFO(6303266-01)

17-NOV-2006 — LNM/D. 10-NOV-2006

Reposition yellow ODAS/SADO light buoy Fl (5) Y, marked PRIV — from 43°37′31.2″N 066°37′16.2″W to 43°37′39.6″N 066°33′13.2″W

This notice affects Electronic Navigational Chart: CA276206, CA276800
DFO(6303157-01)

10-NOV-2006 — LNM/D. 14-JUL-2006

Chart no. 4012

Delete legend ′WHIS′ against red and white fairway lighted pillar whistle buoy Mo(A), WHIS — 43°37′34.0″N 065°13′51.0″W

(F2006108) LL(357) DFO(6303065-01)

This notice affects Electronic Navigational Chart: CA276800

14-JUL-2006 — LNM/D. 30-JUN-2006

Delete legend ″BELL″ against red starboard hand lighted pillar bell buoy FlR — 43°36′38.0″N 066°12′45.0″W

(F2006087) LL(273) DFO(6302894-01)

This notice affects Electronic Navigational Chart: CA276206, CA276800, CA376018

14-JUL-2006 — LNM/D. 30-JUN-2006

Replace port hand pillar buoy symbol with a red starboard hand pillar buoy symbol — 43°36′38.0″N 066°12′45.0″W

DFO(6302894-02)

This notice affects Electronic Navigational Chart: CA276206, CA276800

30-JUN-2006 — LNM/D. 28-APR-2006

Delete light ″LFl 12s 30m 9M″ — 43°48′34.0″N 064°47′21.0″W

(F2006083) LL(393) DFO(6302886-01)

This notice affects Electronic Navigational Chart: CA276800

28-APR-2006 — LNM/D. 21-APR-2006

Amend ″Fl 12s 24m 8M″ to read ″LFl 12s 24m 11M″ against light — 44°06′10.6″N 064°32′23.3″W

LL(415) DFO(6302776-02)

This notice affects Electronic Navigational Chart: CA276800

21-APR-2006 — LNM/D. 10-MAR-2006

Amend ″Fl 10s 14m 12M″ to read ″Fl 10s 14m 21M″ against light — 44°17′13.0″N 066°20′31.2″W

LL(221) DFO(6302775-01)

This notice affects Electronic Navigational Chart: CA276800

Chart no. 4012

10-MAR-2006 LNM/D. 24-FEB-2006

Delete legend ′WHIS′ against yellow and black South cardinal lighted pillar whistle buoy Q (6)+LFl 15s, WHIS — 43°21′00.0″N 065°26′15.0″W

(F2005148) LL(338) DFO(6302731-01)

This notice affects Electronic Navigational Chart: CA276800

10-MAR-2006 LNM/D. 24-FEB-2006

Delete legend ′WHIS′ against red and white fairway lighted pillar whistle buoy Mo(A), WHIS — 43°26′33.0″N 065°24′00.0″W

(F2006008) LL(347) DFO(6302739-01)

This notice affects Electronic Navigational Chart: CA276800

10-MAR-2006 LNM/D. 24-FEB-2006

Delete legend ″WHIS″ against red and white fairway pillar light buoy Mo(A), WHIS — 43°53′31.0″N 064°42′20.0″W

(F2006012) LL(395) DFO(6302744-01)

This notice affects Electronic Navigational Chart: CA276800

24-FEB-2006 LNM/D. 25-NOV-2005

Add red starboard hand lighted pillar buoy FlR — 43°38′27.0″N 065°02′15.0″W

(F2006009) LL(382.01) DFO(6302740-02)

This notice affects Electronic Navigational Chart: CA276800, CA576040

25-NOV-2005 LNM/D. 18-NOV-2005

Delete legend ″BELL″ against red starboard hand pillar light and bell buoy FlR, BELL — 43°45′10.3″N 066°09′41.0″W

(F2005088) LL(268) DFO(6302598-01)

This notice affects Electronic Navigational Chart: CA376018

18-NOV-2005 LNM/D. 23-SEP-2005

Chart no. 4012

Delete legend ″Fog Sig″ against light 43°27′23.2″N 065°44′36.2″W

(F2005085) LL(307) DFO(6302558-01)

23-SEP-2005 LNM/D. 06-MAY-2005

Delete red starboard hand pillar light and whistle buoy FlR, WHIS 43°36′54.0″N 065°01′45.0″W

(F2005051) LL(382) DFO(6302472-01)

This notice affects Electronic Navigational Chart: CA276800

06-MAY-2005 LNM/D. 08-APR-2005

Delete red starboard hand conical buoy 43°20′08.3″N 065°58′45.9″W

(F2004211) DFO(6302220-01)

06-MAY-2005 LNM/D. 08-APR-2005

Add black, yellow and black East cardinal pillar light buoy Q(3) 10s 43°20′36.0″N 065°58′30.0″W

(F2004211) LL(290.2) DFO(6302220-02)

08-APR-2005 LNM/D. 04-MAR-2005

Delete rock awash 43°20′36.0″N 065°58′54.0″W

DFO(6302248-01)

08-APR-2005 LNM/D. 04-MAR-2005

Add rock which covers and uncovers with drying height of 0.4 metres 43°20′27.2″N 065°59′11.0″W

DFO(6302248-02)

04-MAR-2005 LNM/D. 25-FEB-2005

Delete red and white fairway pillar light and bell buoy Mo(A), BELL 43°31′33.3″N 066°05′20.0″W

(F2004196) LL(274) DFO(6302190-01)

04-MAR-2005 LNM/D. 25-FEB-2005

Chart no. 4012

Add yellow and black South cardinal pillar light buoy ′Q(6)+LFl 15s′ — 43°30′45.3″N 066°02′31.0″W

(F2004207) LL(274.2) DFO(6302202-01)

04-MAR-2005 — LNM/D. 25-FEB-2005

Add black and yellow North cardinal pillar light buoy Q — 43°33′23.5″N 066°03′00.0″W

(F2004210) LL(274.4) DFO(6302205-01)

This notice affects Electronic Navigational Chart: CA376018

25-FEB-2005 — LNM/D. 11-FEB-2005

Replace red starboard hand pillar light and whistle buoy FlR, WHIS with red and white fairway pillar, light buoy Mo (A) — 43°20′12.3″N 065°40′45.9″W

(F2004205) LL(325) DFO(6302200-01)

11-FEB-2005 — LNM/D. 21-JAN-2005

Delete legend ″WHIS″ against red, green and red starboard bifurcation pillar light and whistle buoy Fl(2+1) R, WHIS — 43°58′58.0″N 066°18′26.0″W

(F2004198) LL(245) DFO(6302192-01)

This notice affects Electronic Navigational Chart: CA376018

11-FEB-2005 — LNM/D. 21-JAN-2005

Delete legend ″WHIS″ against red, green and red starboard bifurcation pillar light and whistle buoy Fl(2+1) R, WHIS — 43°49′00.3″N 066°29′58.0″W

(F2004200) LL(251) DFO(6302194-01)

This notice affects Electronic Navigational Chart: CA376018

11-FEB-2005 — LNM/D. 21-JAN-2005

Delete legend ″WHIS″ against green port hand pillar light and whistle buoy FlG, WHIS — 43°53′00.3″N 066°26′10.0″W

(F2004201) LL(251.5) DFO(6302196-01)

This notice affects Electronic Navigational Chart: CA376018

Chart no. 4012

21-JAN-2005 LNM/D. 14-JAN-2005

Delete red and white fairway pillar light and bell buoy Mo (A), BELL — 44°33′15.0″N 066°02′20.0″W

(F2004187) LL(213) DFO(6302148-01)

21-JAN-2005 LNM/D. 14-JAN-2005

Add red and white fairway pillar light buoy Mo (A) — 44°33′20.0″N 066°02′40.0″W

(F2004187) LL(213) DFO(6302148-02)

14-JAN-2005 LNM/D. 07-JAN-2005

Delete red starboard hand pillar light and bell buoy FlR, BELL — 43°18′36.0″N 066°00′00.0″W

(F2004185) LL(290) DFO(6302146-01)

07-JAN-2005 LNM/D. 22-OCT-2004

Amend legend ′Fl 5s 25m 12M′ to read ′Fl 5s 25m 19M′ against light 43°41′23.1″N 066°08′38.3″W

LL(272) DFO(6302112-01)

This notice affects Electronic Navigational Chart: CA376018

22-OCT-2004 LNM/D. 15-OCT-2004

Delete red and white fairway pillar light buoy Mo(A), WHIS — 44°42′38.0″N 065°46′05.0″W

(F2004110) LL(200) DFO(6301914-01)

15-OCT-2004 LNM/D. 09-JUL-2004

Delete legend ″BELL″ against green port hand pillar light buoy FlG, BELL — 44°12′02.0″N 066°23′11.0″W

(F2004117) LL(224) DFO(6301906-01)

09-JUL-2004 LNM/D. 02-JUL-2004

(T)Delete light — 43°48′34.0″N 064°47′21.0″W

Light has been temporarily discontinued.
Notice 2004-07-09(T) is cancelled. Light is discontinued. *LL(393) DFO(6301436-01)*
See DFO reference (6302886) appearing in this edition.
Cancelled on 30-JUN-06

09-JUL-2004 LNM/D. 02-JUL-2004

Chart no. 4012

Delete red and white fairway pillar light buoy Mo(A), WHIS 44°00′00.0″N 064°36′00.0″W

LL(406) DFO(6301576-01)

09-JUL-2004 LNM/D. 02-JUL-2004

Add red and white fairway pillar light buoy Mo(A), BELL 44°00′52.8″N 064°37′47.8″W

LL(406) DFO(6301576-02)

02-JUL-2004 LNM/D. 25-JUN-2004

Amend ″Fl 10s 14m 22M″ to read ″Fl 10s 14m 10M″ against light 43°27′23.2″N 065°44′36.2″W

(F2004059) LL(307) DFO(6301606-01)

02-JUL-2004 LNM/D. 25-JUN-2004

Amend ″Fl 6s 16m 16M″ to read ″Fl 6s 16m 9M″ against light 43°37′42.6″N 066°01′34.9″W

LL(283) DFO(6301613-01)

25-JUN-2004 LNM/D. 28-MAY-2004

Add light flash against buoy marked SN 43°31′01.5″N 065°18′50.0″W

LL(353) DFO(6301230-01)

25-JUN-2004 LNM/D. 28-MAY-2004

Amend ″Fl 15s 17m 16M″ to read ″LFl 15s 17m 12M″ against light 43°39′18.3″N 065°05′55.9″W

LL(370) DFO(6301232-01)

25-JUN-2004 LNM/D. 28-MAY-2004

Amend ″Fl (3) 10s 16m 16M″ to read ″Mo (D) 10s 15m 12M″ against light 43°26′59.0″N 065°28′15.0″W

LL(336) DFO(6301236-01)

25-JUN-2004 LNM/D. 28-MAY-2004

Amend ″Fl 10s 30m 13M″ to read ″LFl 12s 30m 9M″ against light 43°48′34.0″N 064°47′21.0″W

LL(393) DFO(6301237-01)

Chart no. 4012

28-MAY-2004 LNM/D. 14-MAY-2004

Delete radar transponder beacon Racon against red and white fairway pillar light buoy Mo (A), WHIS 44°21′45.0″N 063°24′15.0″W

(F2004054) LL(510) DFO(6301423-01)

14-MAY-2004 LNM/D. 07-MAY-2004

Delete legend ″Fog Sig″ against light Iso 6s 44m 12M 44°26′22.4″N 064°04′59.7″W

(F2004017) LL(469) DFO(6301330-01)

07-MAY-2004 LNM/D. 27-FEB-2004

Add yellow cautionary can light buoy Fl Y, marked NAVY 44°05′58.4″N 063°30′03.0″W

DFO(6301249-01)

07-MAY-2004 LNM/D. 27-FEB-2004

Amend ″LFl 12s 17m 16M″ to read ″LFl 12s 17m 8M″ against light 43°28′07.7″N 065°22′43.4″W

(F2004022) LL(348) DFO(6301317-01)

07-MAY-2004 LNM/D. 27-FEB-2004

Amend ″WHIS″ to read ″BELL″ against red starboard pillar light buoy FlR 44°18′10.0″N 066°25′40.0″W

(F2004004) LL(220) DFO(6301319-01)

07-MAY-2004 LNM/D. 27-FEB-2004

Amend ″WHIS″ to read ″BELL″ against red starboard pillar light buoy FlR 44°10′15.0″N 066°27′00.0″W

(F2004005) LL(225) DFO(6301320-01)

07-MAY-2004 LNM/D. 27-FEB-2004

Amend ″WHIS″ to read ″BELL″ against red starboard hand pillar light buoy FlR, WHIS 43°18′36.0″N 066°00′02.0″W

(F2004006) LL(290) DFO(6301321-01)

07-MAY-2004 LNM/D. 27-FEB-2004

Chart no. 4012

Amend ″WHIS″ to read ″BELL″ against red and white fairway pillar light buoy Mo(A), WHIS — 43°31′33.3″N 066°05′06.0″W

(F2004007) LL(274) DFO(6301322-01)

07-MAY-2004 — LNM/D. 27-FEB-2004

Amend ″Fl 10s 16m 13M″ to read ″Fl 10s 16m 8M″ against light — 44°34′51.7″N 063°27′28.1″W

(F2004016) LL(545) DFO(6301329-01)

27-FEB-2004 — LNM/D. 09-JAN-2004

Delete red and white fairway pillar light buoy Mo(A), WHIS 44°36′03.0″N 063°09′57.0″W

DFO(6301154-01)

09-JAN-2004 — LNM/D. 21-NOV-2003

Delete legend ″Fog Sig″ — 44°18′43.7″N 064°10′06.4″W

(F2003058) LL(443) DFO(6301102-01)

21-NOV-2003 — LNM/D. 07-NOV-2003

Add non-dangerous wreck, depth unknown 43°00′15.0″N 066°02′00.0″W

DFO(6301061-01)

07-NOV-2003 — LNM/D. 08-AUG-2003

Delete yellow ODAS/SADO light buoy, Fl (5) Y 43°37′10.0″N 066°33′12.0″W

DFO(6301094-01)

08-AUG-2003

Add yellow ODAS/SADO light buoy, Fl (5) Y, marked PRIV 43°37′31.2″N 066°37′16.2″W

DFO(6300964-01)