Chart no. 4021

4021 - Pointe Amour à / to Cape Whittle et / and Cape George - New Edition - 01-NOV-2002 - NAD 1983

26-AUG-2022 LNM/D. 29-APR-2022

Delete depth of 7 fathoms 3 feet 50°28′21.4″N 059°30′04.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6310192-01)*

26-AUG-2022 LNM/D. 29-APR-2022

Delete depth of 15 fathoms 50°27′15.7″N 059°29′30.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6310192-02)*

26-AUG-2022 LNM/D. 29-APR-2022

Add depth of 6 fathoms 5 feet 50°27′31.8″N 059°29′37.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6310192-03)*

26-AUG-2022 LNM/D. 29-APR-2022

Add depth of 3 fathoms 1 foot 50°28′14.5″N 059°30′05.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6310192-04)*

29-APR-2022 LNM/D. 29-OCT-2021

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 5 meters 51°16′36.9″N 057°32′05.6″W
(See Chart No. 1, L25) *DFO(6310064-01)*
This notice affects Electronic Navigational Chart: CA276138

29-OCT-2021 LNM/D. 15-OCT-2021

Amend Fl G 6s48ft to read Fl G 6s58ft against light 50°28′13.5″N 059°27′29.2″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276138 *LL(1558.7) DFO(6309561-01)*

15-OCT-2021 LNM/D. 09-JUL-2021

Amend Fl6s221ft5M to read Fl 4s221ft5M against light 49°06′29.0″N 058°25′39.0″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276138, CA476190, CA576191 *(N2021118) LL(196) DFO(6309595-01)*

Chart no. 4021

09-JUL-2021 LNM/D. 14-MAY-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 55 fathoms 50°59′35.4″N 058°24′00.6″W
(See Chart No. 1, L25) *DFO(6309414-01)*
This notice affects Electronic Navigational Chart: CA276138

09-JUL-2021 LNM/D. 14-MAY-2021

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 49 fathoms 49°11′25.0″N 058°47′12.0″W
(See Chart No. 1, L25) *DFO(6309414-05)*
This notice affects Electronic Navigational Chart: CA276138

09-JUL-2021 LNM/D. 14-MAY-2021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 44 fathoms 49°11′18.0″N 058°47′03.6″W
(See Chart No. 1, L25) *DFO(6309414-06)*
This notice affects Electronic Navigational Chart: CA276138

14-MAY-2021 LNM/D. 09-APR-2021

Add drying height of 1 fathom 1 foot 50°42′23.2″N 058°55′47.4″W
(See Chart No. 1, I15)
DFO(6309430-01)

14-MAY-2021 LNM/D. 09-APR-2021

Amend note Carte / Chart 4474 to read Carte / Chart 4967 (See Chart No. 1, A18) 50°48′12.0″N 058°41′30.0″W
DFO(6309430-02)

14-MAY-2021 LNM/D. 09-APR-2021

Delete Carte / Chart 4469 (See Chart No. 1, A18) 50°23′46.0″N 058°55′43.0″W
DFO(6309430-03)

09-APR-2021 LNM/D. 12-FEB-2021

Amend note Carte / Chart 4473 to read Carte / Chart 4968 (See Chart No. 1, A18) 51°00′47.0″N 058°31′13.0″W
DFO(6309391-01)

12-FEB-2021 LNM/D. 23-OCT-2020

Chart no. 4021

Amend note Carte / Chart 4472 to read Carte / Chart 4969 51°06′18.0″N 058°14′12.0″W
(See Chart No. 1, A18)
DFO(6309339-01)

23-OCT-2020 LNM/D. 03-JUL-2020

Amend Fl6s80ft5M to read Fl 4s80ft6M against light 49°28′54.0″N 058°08′04.0″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276138, CA476708, CA576711 *(N2020077) LL(199) DFO(6309161-01)*

03-JUL-2020 LNM/D. 27-MAR-2020

Delete depth of 22 fathoms 50°51′54.2″N 057°06′06.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308825-02)*

03-JUL-2020 LNM/D. 27-MAR-2020

Add depth of 20 fathoms 50°52′06.1″N 057°06′13.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308825-03)*

03-JUL-2020 LNM/D. 27-MAR-2020

Delete depth of 18 fathoms 50°54′32.1″N 057°05′33.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308825-04)*

03-JUL-2020 LNM/D. 27-MAR-2020

Add depth of 15 fathoms 50°54′25.7″N 057°05′20.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308825-05)*

03-JUL-2020 LNM/D. 27-MAR-2020

Add depth of 11 fathoms 50°56′04.2″N 057°05′51.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308825-06)*

03-JUL-2020 LNM/D. 27-MAR-2020

Delete depth of 12 fathoms 50°55′29.1″N 057°12′47.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308825-07)*

Chart no. 4021

03-JUL-2020 LNM/D. 27-MAR-2020

Add depth of 10 fathoms, 5 feet 50°55′36.1″N 057°12′38.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308825-08)*

27-MAR-2020 LNM/D. 06-MAR-2020

Delete depth of 6 fathoms, 5 feet 50°41′35.4″N 057°26′06.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308865-01)*

27-MAR-2020 LNM/D. 06-MAR-2020

Add depth of 6 fathoms, 2 feet 50°41′28.0″N 057°26′30.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308865-02)*

06-MAR-2020 LNM/D. 14-FEB-2020

Amend Iso R 2s38ft to read Iso 2s42ft7M against light 51°19′18.0″N 057°50′36.0″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276138, CA479249 *(Q2019176) LL(1539.13) DFO(6410266-01)*

14-FEB-2020 LNM/D. 03-JAN-2020

Add depth of 12 fathoms 50°40′47.4″N 057°21′51.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308902-02)*

14-FEB-2020 LNM/D. 03-JAN-2020

Delete depth of 12 fathoms 50°41′27.5″N 057°22′21.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308902-03)*

14-FEB-2020 LNM/D. 03-JAN-2020

Add depth of 9 fathoms 50°41′32.1″N 057°22′21.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308902-04)*

14-FEB-2020 LNM/D. 03-JAN-2020

Chart no. 4021

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 49 fathoms — 49°11′26.4″N 058°47′14.4″W
(See Chart No. 1, L25) *DFO(6308916-03)*
This notice affects Electronic Navigational Chart: CA179245, CA276138

03-JAN-2020 LNM/D. 12-JUL-2019

Replace depth of 6 fathoms with depth of 1 fathom — 48°48′50.0″N 058°36′21.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308642-03)*

03-JAN-2020 LNM/D. 12-JUL-2019

Add depth of 9 fathoms — 48°35′32.3″N 058°45′54.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308642-09)*

03-JAN-2020 LNM/D. 12-JUL-2019

Delete depth of 10 fathoms — 48°40′48.0″N 058°45′44.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308642-12)*

03-JAN-2020 LNM/D. 12-JUL-2019

Add depth of 7 fathoms — 48°40′43.4″N 058°45′40.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308642-13)*

03-JAN-2020 LNM/D. 12-JUL-2019

Replace depth of 8 fathoms with depth of 6 fathoms — 48°41′03.7″N 058°52′57.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308642-20)*

12-JUL-2019 LNM/D. 15-MAR-2019

Delete yellow ODAS/SADO lighted superbuoy Fl(5) Y, marked IML-2 — 49°30′00.0″N 060°03′55.0″W
(See Chart No. 1, Q58) *(Q2019079) LL(1563.2) DFO(6410151-01)*
This notice affects Electronic Navigational Chart: CA179245, CA279043

15-MAR-2019 LNM/D. 28-SEP-2018

Chart no. 4021

Replace depth of 11 fathoms with depth of 9 fathoms 48°46′31.4″N 058°39′04.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308583-01)*

28-SEP-2018 LNM/D. 22-JUN-2018

Amend note Carte / Chart 4471 to read Carte / Chart 4970 51°15′47.1″N 057°48′47.0″W
(See Chart No. 1, A18)
DFO(6308430-01)

28-SEP-2018 LNM/D. 22-JUN-2018

Amend note Carte / Chart 4470 to read Carte / Chart 4971 51°20′48.5″N 057°25′06.0″W
(See Chart No. 1, A18)
DFO(6308430-02)

22-JUN-2018 LNM/D. 13-OCT-2017

Delete depth of 2 fathoms, 4 feet 49°18′48.8″N 058°15′36.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA179245, CA276138, CA476190 *DFO(6308275-01)*

22-JUN-2018 LNM/D. 13-OCT-2017

Add rock which covers and uncovers with drying height unknown 49°18′48.8″N 058°15′36.0″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA179245, CA276138, CA476190 *DFO(6308275-02)*

13-OCT-2017 LNM/D. 14-JUL-2017

Add wreck, least depth unknown with legend Rep (2017) 51°05′11.4″N 057°14′23.4″W
(See Chart No. 1, K29, I3.2)
This notice affects Electronic Navigational Chart: CA276138 *DFO(6308065-01)*

14-JUL-2017 LNM/D. 30-JUN-2017

Add depth of 15 fathoms, 2 feet 48°30′21.1″N 058°39′41.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138, CA476085 *DFO(6307902-03)*

14-JUL-2017 LNM/D. 30-JUN-2017

Chart no. 4021

Add depth of 9 fathoms — 48°26′07.5″N 058°45′26.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138, CA476085 — *DFO(6307902-04)*

14-JUL-2017 — LNM/D. 30-JUN-2017

Replace depth of 9 fathoms, 4 feet with depth of 6 fathoms — 48°27′28.6″N 058°29′03.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138, CA476085 — *DFO(6307902-10)*

14-JUL-2017 — LNM/D. 30-JUN-2017

Replace depth of 9 fathoms, 4 feet with depth of 8 fathoms, 1 foot — 48°28′12.4″N 058°27′27.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276138 — *DFO(6307902-12)*

30-JUN-2017 — LNM/D. 02-DEC-2016

Delete light Fl R, — 50°01′36.0″N 057°42′47.3″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA276138 — *(N2017011) LL(203) DFO(6307906-01)*

02-DEC-2016 — LNM/D. 21-OCT-2016

Add subsurface Ocean Data Acquisition system (ODAS/SADO) with known depth of 5 fathoms — 51°16′36.9″N 057°32′05.6″W
(See Chart No. 1, L25) — *DFO(6307699-09)*
This notice affects Electronic Navigational Chart: CA276138

21-OCT-2016 — LNM/D. 06-MAY-2016

Add submarine cable area — joining 51°21′50.0″N 056°38′40.0″W
(See Chart No. 1, L30.2) — 51°22′14.0″N 056°39′08.0″W
This notice affects Electronic Navigational Chart: CA276138, CA376094 — 51°21′12.0″N 056°54′31.0″W
51°22′53.0″N 056°56′21.0″W
51°24′48.0″N 056°54′51.0″W
51°25′33.0″N 056°57′08.0″W
51°26′18.0″N 056°56′32.0″W
51°25′11.0″N 056°53′15.0″W
51°22′38.0″N 056°54′20.0″W
51°23′11.0″N 056°39′16.0″W
and 51°22′10.0″N 056°37′32.0″W

DFO(6307716-01)

Chart no. 4021

06-MAY-2016 LNM/D. 25-DEC-2015

Delete fog signal Fog Sig against light 51°27′37.7″N 056°51′29.3″W
(See Chart No. 1, R1)
This notice affects Electronic Navigational Chart: CA276138, CA376094 *(N2016002) LL(227) DFO(6307500-01)*

25-DEC-2015 LNM/D. 27-JUN-2014

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 21 fathoms. 48°55′40.0″N 058°52′40.0″W
(See Chart No. 1, L25) *DFO(6307350-02)*
This notice affects Electronic Navigational Chart: CA276138

27-JUN-2014 LNM/D. 01-FEB-2013

Amend Fl 2½s139ft17M to read Fl 2½s146ft12M against light 50°18′15.0″N 059°39′16.0″W
(See Chart No. 1, P16)
LL(1562.0) DFO(6408936-01)

01-FEB-2013 LNM/D. 22-APR-2011

Delete depth of 6 fathoms 0 feet 50°25′51.4″N 059°28′23.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA179172, CA276138 *DFO(6408718-04)*

01-FEB-2013 LNM/D. 22-APR-2011

Add depth of 5 fathoms 5 feet 50°25′44.1″N 059°28′17.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA179172, CA276138 *DFO(6408718-05)*

01-FEB-2013 LNM/D. 22-APR-2011

Add depth of 6 fathoms 2 feet 50°20′54.8″N 059°38′18.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA179172, CA279043 *DFO(6408718-07)*

01-FEB-2013 LNM/D. 22-APR-2011

Delete depth of 8 fathoms 0 feet 50°15′26.1″N 059°46′58.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA279043 *DFO(6408718-13)*

Chart no. 4021

01-FEB-2013 LNM/D. 22-APR-2011

Add depth of 4 fathoms 2 feet 50°15′26.3″N 059°47′00.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA279043 *DFO(6408718-14)*

01-FEB-2013 LNM/D. 22-APR-2011

Delete depth of 12 fathoms 0 feet 50°13′55.2″N 059°48′17.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA279043 *DFO(6408718-15)*

01-FEB-2013 LNM/D. 22-APR-2011

Add depth of 5 fathoms 3 feet 50°13′54.6″N 059°48′10.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA279043 *DFO(6408718-16)*

01-FEB-2013 LNM/D. 22-APR-2011

Delete depth of 12 fathoms 50°11′54.9″N 059°50′35.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA279043 *DFO(6408718-23)*

01-FEB-2013 LNM/D. 22-APR-2011

Add depth of 7 fathoms 1 foot 50°12′05.2″N 059°50′16.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA279043 *DFO(6408718-24)*

22-APR-2011 LNM/D. 24-SEP-2010

Delete depth of 3 fathoms 3 feet 50°26′24.0″N 059°27′12.7″W
(See Chart No. 1, I10)
DFO(6408326-05)

22-APR-2011 LNM/D. 24-SEP-2010

Add depth of 2 fathoms 5 feet 50°26′23.5″N 059°27′06.2″W
(See Chart No. 1, I10)
DFO(6408326-06)

24-SEP-2010 LNM/D. 30-JUL-2010

Chart no. 4021

Amend Fl 4s 116ft to read Fl 4s 113ft 6M against light 49°08′48.0″N 058°22′07.0″W
(See Chart No. 1 P16)

(N2010044) LL(192) DFO(6305018-01)

This notice affects Electronic Navigational Chart:
CA476190

30-JUL-2010 LNM/D. 07-AUG-2009

Amend Fl 5s 96ft to read Fl 5s 96ft 15M against light 50°41′54.6″N 057°24′36.8″W
(See Chart No 1 P16)

LL(211) DFO(6304958-01)

07-AUG-2009 LNM/D. 21-NOV-2008

Delete light Fl 6s 54ft 5M 50°14′23.0″N 057°35′35.0″W
(See Chart No 1 P1)

(N2009016) LL(207) DFO(6304431-01)

This notice affects Electronic Navigational Chart:
CA276138

21-NOV-2008 LNM/D. 14-SEP-2007

Amend Fl 15s 108ft 8M to read Fl 15s 108ft 17M against light 50°37′58.9″N 057°19′19.9″W
(See Chart No 1 P16)

LL(208.0) DFO(6304132-01)

14-SEP-2007 LNM/D. 06-JUL-2007

Add depth of 8 fathoms, 4 feet 51°19′42.0″N 056°47′24.0″W

DFO(6303529-01)

14-SEP-2007 LNM/D. 06-JUL-2007

Add yellow ODAS/SADO lighted buoy Fl (5)Y, marked IML-2 49°30′00.0″N 060°04′00.0″W
(See Chart No 1 Section Q 58.)

LL(1563.2) DFO(6303531-01)

14-SEP-2007 LNM/D. 06-JUL-2007

Delete red starboard hand lighted spar buoy FlR, marked XU2 48°47′50.0″N 058°45′12.0″W

DFO(6303532-01)

Chart no. 4021

06-JUL-2007 LNM/D. 01-JUN-2007

Amend legend Fl 6s 99ft 14M to read Fl 15s 74ft 13M against light — 50°45′12.4″N 058°45′20.9″W

(Q2007039) LL(1543) DFO(6407472-01)

This notice affects Electronic Navigational Chart: CA276138

01-JUN-2007 LNM/D. 25-MAR-2005

Delete depth of 25 fathoms — 51°27′27.0″N 056°45′40.0″W

DFO(6303488-01)

This notice affects Electronic Navigational Chart: CA276138

01-JUN-2007 LNM/D. 25-MAR-2005

Delete depth of 28 fathoms — 51°27′57.0″N 056°44′30.0″W

DFO(6303488-02)

This notice affects Electronic Navigational Chart: CA276138

01-JUN-2007 LNM/D. 25-MAR-2005

Delete depth of 25 fathoms — 51°29′30.0″N 056°41′52.0″W

DFO(6303488-03)

This notice affects Electronic Navigational Chart: CA276138

01-JUN-2007 LNM/D. 25-MAR-2005

Add depth of 33 fathoms — 51°27′36.0″N 056°45′36.0″W

DFO(6303488-04)

This notice affects Electronic Navigational Chart: CA276138

01-JUN-2007 LNM/D. 25-MAR-2005

Add depth of 31 fathoms — 51°29′26.0″N 056°42′03.0″W

DFO(6303488-05)

This notice affects Electronic Navigational Chart: CA276138

25-MAR-2005 LNM/D. 05-MAR-2004

Chart no. 4021

Replace rock which does not cover with a dangerous underwater rock of 6 ft (2m) or less and the legend ″Rep (2005)″. 50°28′01.7″N 059°29′00.5″W

DFO(6406866-01)

05-MAR-2004 LNM/D. 27-FEB-2004

Amend Fl 6s 64ft 7M to read Fl 6s 92ft 7M against light 51°21′22.4″N 057°41′41.4″W

(L2003376) LL(1539) DFO(6405729-01)

27-FEB-2004

Delete red and white fairway, pillar light buoy Mo (A), marked X4 WHIS 48°49′33.0″N 058°44′30.0″W

(N2002043) LL(187.5) DFO(6300289-01)