Chart no. 4234

4234 - Country Harbour - New Chart - 10-APR-1987 - NAD 1983

15-APR-2022 LNM/D. 11-MAR-2022

Replace depth of 8 metres with depth of 6.5 metres 45°13′08.5″N 061°44′09.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476111 *DFO(6310054-01)*

15-APR-2022 LNM/D. 11-MAR-2022

Delete depth of 17.4 metres 45°13′02.0″N 061°44′02.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476111 *DFO(6310054-02)*

15-APR-2022 LNM/D. 11-MAR-2022

Add depth of 12.7 metres 45°13′02.9″N 061°44′01.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476111 *DFO(6310054-03)*

15-APR-2022 LNM/D. 11-MAR-2022

Delete depth of 12.5 metres 45°12′52.5″N 061°43′41.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476111 *DFO(6310054-04)*

15-APR-2022 LNM/D. 11-MAR-2022

Add depth of 11.3 metres 45°12′52.2″N 061°43′45.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476111 *DFO(6310054-05)*

15-APR-2022 LNM/D. 11-MAR-2022

Replace depth of 11.6 metres with depth of 10.6 metres 45°11′07.6″N 061°42′37.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476111 *DFO(6310054-06)*

15-APR-2022 LNM/D. 11-MAR-2022

Replace depth of 21.9 metres with depth of 16.2 metres 45°10′45.2″N 061°42′26.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476111 *DFO(6310054-07)*

15-APR-2022 LNM/D. 11-MAR-2022

Chart no. 4234

Add depth of 14.2 metres — 45°09′15.2″N 061°39′28.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109, CA476111 — *DFO(6310054-08)*

24-DEC-2021 — LNM/D. 18-JUN-2021

Delete legend See/Voir note GAS PIPELINES/GAZODUCS — 45°09′07.0″N 061°38′45.0″W
This notice affects Electronic Navigational Chart: CA376109, CA476111 — *DFO(6309793-02)*

24-DEC-2021 — LNM/D. 18-JUN-2021

Replace pipeline, Gas/Gaz with abandoned pipeline — between 45°09′10.1″N 061°37′57.6″W and 45°09′00.0″N 061°38′08.8″W
(See Chart No. 1, L40.1, L44)
This notice affects Electronic Navigational Chart: CA376109, CA476111 — *DFO(6309793-03)*

24-DEC-2021 — LNM/D. 18-JUN-2021

Replace pipeline, Gas/Gaz with abandoned pipeline — between 45°09′17.0″N 061°37′57.6″W and 45°09′00.3″N 061°38′27.7″W
(See Chart No. 1, L40.1, L44)
This notice affects Electronic Navigational Chart: CA376109, CA476111 — *DFO(6309793-04)*

14-JAN-2011 — LNM/D. 23-APR-2010

Add pipeline with legend Gas/Gaz — between 45°09′17.4″N 061°37′57.5″W and 45°09′00.3″N 061°38′27.9″W
(See Chart No 1 L40.1)

DFO(6305191-01)

This notice affects Electronic Navigational Chart: CA476111

10-JUL-2009 — LNM/D. 24-APR-2009

(P)Add pipeline and legend Gas/Gaz — joining 45°09′17.7″N 061°37′57.0″W 45°09′05.9″N 061°38′19.0″W and 45°09′00.0″N 061°38′29.9″W
(See Chart No 1 L40.1)
Encana will commence constructing a gas pipeline from Goldboro to the Deep Panuke Gasfield in July 2009. The proposed completion date is October 2009. The work is completed. Notice 10-JUL-2009(P), DFO(6304485-1) is cancelled.
Cancelled on 14-JAN-11 — *DFO(6304485-01)*

24-APR-2009 — LNM/D. 27-FEB-2009

Chart no. 4234

Delete light F 25m 12M 45°09′52.8″N 061°39′16.5″W
(See Chart No 1 P1)

(G2009010) LL(637) DFO(6304315-01)

This notice affects Electronic Navigational Chart:
CA376109, CA476111

27-FEB-2009 LNM/D. 13-FEB-2009

(T)Add private yellow cautionary lighted spar buoy Fl Y 45°09′09.2″N 061°37′59.8″W
(See Chart No 1 Qm)
The mooring is temporary and will be removed by October 2009. *DFO(6304249-03)*
Goldboro Construction completed. Notice 27-FEB-2009(T), DFO(6304249-3) is cancelled.
Cancelled on 06-NOV-09

13-FEB-2009 LNM/D. 28-NOV-2008

Replace green port hand can buoy, marked TT7 with green port hand lighted spar buoy QG, marked TT7 45°09′34.0″N 061°39′20.0″W
(See Chart No 1 Qg)

(G2008088) LL(636.04) DFO(6304204-01)

This notice affects Electronic Navigational Chart: CA376109

24-NOV-2000 LNM/D. 19-MAR-1999

Add gas pipeline between 45°09′10.7″N 061°37′57.5″W and 45°09′00.3″N 061°38′09.6″W

(H2000-003) DFO(6828774-01)

24-NOV-2000 LNM/D. 19-MAR-1999

Add legend ″Gas/Gaz″ 45°09′04.5″N 061°38′12.0″W

(H2000-003) DFO(6828774-02)

24-NOV-2000 LNM/D. 19-MAR-1999

Add legend ″See/Voir note GAS PIPELINES/GAZODUCS″ 45°09′08.0″N 061°38′43.0″W

(H200-003) DFO(6828774-03)

Chart no. 4234

4234 - Country Island to / à Barren Island - New Chart - 10-APR-1987 - NAD 1983

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 7.8 metres 44°55′07.8″N 062°04′31.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310183-18)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 15.8 metres 44°53′58.0″N 062°04′36.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310183-19)*

22-JUL-2022 LNM/D. 15-JUL-2022

Replace depth of 9.9 metres with depth of 9.1 metres 44°55′05.9″N 062°04′14.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310183-20)*

22-JUL-2022 LNM/D. 15-JUL-2022

Replace depth of 11 metres with depth of 9.6 metres 44°57′15.4″N 062°03′27.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310183-21)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 5.3 metres 44°55′54.2″N 062°03′05.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-01)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 18.2 metres 44°55′12.6″N 062°02′39.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-03)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 9.5 metres 44°55′32.6″N 062°02′30.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-04)*

22-JUL-2022 LNM/D. 15-JUL-2022

Chart no. 4234

Add depth of 8.4 metres 44°54′38.1″N 062°02′10.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-05)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 4.7 metres 44°54′36.6″N 062°01′37.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-06)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 3 metres 44°55′00.4″N 062°01′55.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-07)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 7 metres 44°54′42.8″N 062°00′45.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-08)*

22-JUL-2022 LNM/D. 15-JUL-2022

Replace depth of 8.9 metres with depth of 8.1 metres 44°54′41.0″N 062°00′12.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-09)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 4.2 metres 44°56′10.8″N 062°01′06.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-10)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 9.8 metres 44°56′07.1″N 062°00′50.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-11)*

22-JUL-2022 LNM/D. 15-JUL-2022

Replace depth of 6.7 metres with depth of 6.1 metres 44°57′47.4″N 062°02′40.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-12)*

Chart no. 4234

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 9.6 metres 44°58′09.8″N 062°01′55.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-13)*

22-JUL-2022 LNM/D. 15-JUL-2022

Replace depth of 8.9 metres with depth of 8.2 metres 44°57′34.4″N 062°01′14.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-14)*

22-JUL-2022 LNM/D. 15-JUL-2022

Replace depth of 5.2 metres with depth of 4.7 metres 44°56′50.8″N 062°00′48.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-15)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 3.9 metres 44°56′15.0″N 062°00′14.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-16)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 9.1 metres 44°56′28.0″N 061°57′53.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-17)*

22-JUL-2022 LNM/D. 15-JUL-2022

Replace depth of 13.5 metres with depth of 12.7 metres 44°55′03.0″N 061°57′40.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-19)*

22-JUL-2022 LNM/D. 15-JUL-2022

Delete wreck PA, depth unknown 44°55′37.7″N 061°56′57.1″W
(See Chart No. 1, K28 , B7)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-20)*

22-JUL-2022 LNM/D. 15-JUL-2022

Chart no. 4234

Delete depth of 11.5 metres 44°56′04.5″N 061°57′00.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-23)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add depth of 9.7 metres 44°56′06.6″N 061°57′04.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-24)*

22-JUL-2022 LNM/D. 15-JUL-2022

Delete depth of 20.6 metres 44°55′13.5″N 062°02′47.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-25)*

22-JUL-2022 LNM/D. 15-JUL-2022

Add wreck with known depth of 26.3 metres 44°55′41.2″N 061°57′02.6″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310184-26)*

15-JUL-2022 LNM/D. 15-APR-2022

Replace depth of 5.5 metres with depth of 4.8 metres 44°51′56.7″N 062°04′25.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276204, CA376109 *DFO(6310119-01)*

15-JUL-2022 LNM/D. 15-APR-2022

Delete depth of 20.6 metres 44°52′07.0″N 062°05′08.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310119-02)*

15-JUL-2022 LNM/D. 15-APR-2022

Add depth of 16.6 metres 44°52′08.2″N 062°05′02.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310119-03)*

15-JUL-2022 LNM/D. 15-APR-2022

Delete depth of 21.3 metres 44°52′18.5″N 062°04′27.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310119-04)*

Chart no. 4234

15-JUL-2022 LNM/D. 15-APR-2022

Add depth of 15.2 metres 44°52′15.7″N 062°04′28.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310119-05)*

15-JUL-2022 LNM/D. 15-APR-2022

Replace depth of 9.4 metres with depth of 9.1 metres 44°52′42.2″N 062°04′38.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310119-06)*

15-JUL-2022 LNM/D. 15-APR-2022

Add depth of 17.9 metres 44°53′12.0″N 062°06′13.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109, CA476104 *DFO(6310119-07)*

15-APR-2022 LNM/D. 11-MAR-2022

Add depth of 14.2 metres 45°09′15.2″N 061°39′28.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109, CA476111 *DFO(6310054-08)*

15-APR-2022 LNM/D. 11-MAR-2022

Add depth of 23.9 metres 45°02′56.0″N 061°36′14.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310054-09)*

15-APR-2022 LNM/D. 11-MAR-2022

Delete depth of 18.9 metres 45°02′09.5″N 061°40′18.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310054-10)*

15-APR-2022 LNM/D. 11-MAR-2022

Add depth of 17.3 metres 45°02′05.0″N 061°40′13.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6310054-11)*

15-APR-2022 LNM/D. 11-MAR-2022

Chart no. 4234

Delete depth of 24 metres — 45°01′51.0″N 061°43′58.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 — *DFO(6310054-12)*

15-APR-2022 — LNM/D. 11-MAR-2022

Add depth of 17.5 metres — 45°01′48.8″N 061°43′54.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 — *DFO(6310054-13)*

24-DEC-2021 — LNM/D. 18-JUN-2021

Delete note — 45°10′58.0″N 061°35′20.0″W
GAS PIPELINES Gas pipelines and wells contain natural gas under pressure and damage to these installations could create an immediate fire hazard. Mariners are cautioned not to anchor or trawl near pipelines or wellheads.
GAZODUCS Les gazoducs et les puits à gaz contiennent du gaz sous pression et du dommage à ces installations pourraient créer un danger de feu immédiat. Les navires ne devraient ni mouiller ni chaluter près de pipelines ou de têtes de puits.
This notice affects Electronic Navigational Chart: CA376109 — *DFO(6309793-01)*

24-DEC-2021 — LNM/D. 18-JUN-2021

Delete legend See/Voir note GAS PIPELINES/GAZODUCS — 45°07′57.0″N 061°37′40.0″W
This notice affects Electronic Navigational Chart: CA376109, CA476111 — *DFO(6309793-02)*

24-DEC-2021 — LNM/D. 18-JUN-2021

Replace pipeline, Gas/Gaz with abandoned pipeline — joining 45°09′24.0″N 061°37′40.8″W
(See Chart No. 1, L40.1, L44) — 45°08′48.5″N 061°38′22.7″W
This notice affects Electronic Navigational Chart: CA376109, CA476111 — 45°08′09.7″N 061°38′34.7″W
45°07′42.9″N 061°38′23.4″W
45°05′42.1″N 061°34′59.1″W
and 45°02′53.3″N 061°32′13.9″W

DFO(6309793-03)

24-DEC-2021 — LNM/D. 18-JUN-2021

Chart no. 4234

Replace pipeline, Gas/Gaz with abandoned pipeline joining 45°09′25.2″N 061°37′43.4″W
(See Chart No. 1, L40.1, L44) 45°09′01.8″N 061°38′26.5″W
This notice affects Electronic Navigational Chart: 45°08′39.9″N 061°38′48.4″W
CA376109, CA476111 45°08′12.1″N 061°38′55.3″W
45°07′43.2″N 061°38′43.1″W
45°06′04.0″N 061°36′12.8″W
and 45°02′24.8″N 061°32′15.6″W

DFO(6309793-04)

18-JUN-2021 LNM/D. 30-APR-2021

Add depth of 6.9 metres 45°08′35.4″N 061°36′39.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309441-01)*

30-APR-2021 LNM/D. 18-DEC-2020

Add wreck, least depth unknown, dangerous to surface navigation 44°55′37.2″N 061°56′57.0″W
with legend ′PA′
(See Chart No. 1, K28, B7) *DFO(6309403-01)*
This notice affects Electronic Navigational Chart: CA376109

18-DEC-2020 LNM/D. 03-AUG-2018

Delete depth of 3.8 metres 44°56′35.6″N 062°00′32.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-07)*

18-DEC-2020 LNM/D. 03-AUG-2018

Add depth of 1.8 metres 44°56′36.5″N 062°00′29.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-08)*

18-DEC-2020 LNM/D. 03-AUG-2018

Delete depth of 13.2 metres 44°58′10.5″N 061°58′00.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-09)*

18-DEC-2020 LNM/D. 03-AUG-2018

Add depth of 7 metres 44°58′08.5″N 061°57′56.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-10)*

Chart no. 4234

18-DEC-2020 LNM/D. 03-AUG-2018

Replace depth of 3.5 metres with depth of 3.1 metres 45°00′00.4″N 062°02′12.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-11)*

18-DEC-2020 LNM/D. 03-AUG-2018

Add depth of 1.2 metres 45°00′06.7″N 062°04′02.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-12)*

18-DEC-2020 LNM/D. 03-AUG-2018

Replace depth of 2.2 metres with depth of 1.5 metres 45°01′28.5″N 061°59′38.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-13)*

18-DEC-2020 LNM/D. 03-AUG-2018

Delete depth of 2.1 metres 45°01′24.0″N 061°58′55.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-14)*

18-DEC-2020 LNM/D. 03-AUG-2018

Add depth of 1.1 metres 45°01′22.8″N 061°58′56.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-15)*

18-DEC-2020 LNM/D. 03-AUG-2018

Delete depth of 10.7 metres 45°00′21.0″N 061°55′24.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-16)*

18-DEC-2020 LNM/D. 03-AUG-2018

Add depth of 5.1 metres 45°00′17.1″N 061°55′27.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6309279-17)*

18-DEC-2020 LNM/D. 03-AUG-2018

Chart no. 4234

Add depth of 8.5 metres — 45°01′49.8″N 061°51′19.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 — *DFO(6309279-18)*

18-DEC-2020 — LNM/D. 03-AUG-2018

Delete depth of 5.2 metres — 45°03′18.0″N 061°44′44.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 — *DFO(6309279-19)*

18-DEC-2020 — LNM/D. 03-AUG-2018

Add depth of 4.4 metres — 45°03′20.8″N 061°44′49.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 — *DFO(6309279-20)*

03-AUG-2018 — LNM/D. 06-OCT-2017

Reposition green port hand can buoy, marked VM9 — from 45°00′30.0″N 061°57′31.0″W
(See Chart No. 1, Qg) — to 45°00′29.4″N 061°57′28.2″W
This notice affects Electronic Navigational Chart: CA376109 — *(F2018015) DFO(6308295-01)*

03-AUG-2018 — LNM/D. 06-OCT-2017

Reposition red starboard hand conical buoy, marked VM18 — from 45°01′29.0″N 061°59′28.0″W
(See Chart No. 1, Qf) — to 45°01′26.1″N 061°59′31.8″W
This notice affects Electronic Navigational Chart: CA376109 — *(F2018017) DFO(6308297-01)*

03-AUG-2018 — LNM/D. 06-OCT-2017

Add pilot boarding station — 45°02′00.0″N 061°33′00.0″W
(See Chart No. 1, T1.1)
This notice affects Electronic Navigational Chart: CA376109 — *DFO(6308388-04)*

06-OCT-2017 — LNM/D. 28-JUL-2017

Amend ″WHIS″ to read ″BELL″ against red and white fairway pillar light buoy Mo(A), marked TT — 45°02′15.3″N 061°32′32.9″W
(See Chart No. 1, R15, R14) — *(G2017091) LL(635) DFO(6308058-01)*
This notice affects Electronic Navigational Chart: CA276204, CA376109

28-JUL-2017 — LNM/D. 03-MAR-2017

Chart no. 4234

Replace depth of 3 metres with depth of 2 metres, 2 decimetres 45°01′31.9″N 061°58′23.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6308010-01)*

03-MAR-2017 LNM/D. 11-MAR-2016

Add flame tower with elevation of 61 metres 45°10′30.0″N 061°36′56.0″W
(See Chart No. 1, E23)
DFO(6307845-01)

This notice affects Electronic Navigational Chart: CA276204, CA376109

11-MAR-2016 LNM/D. 08-JAN-2016

Add wreck Wk with known depth of 18 metres, 2 decimetres. 45°07′30.2″N 061°37′05.0″W
(See Chart No. 1, K26)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6307464-01)*

08-JAN-2016 LNM/D. 29-JUN-2012

Delete depth of 3 metres, 4 decimetres 44°57′47.3″N 062°04′28.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6307378-01)*

08-JAN-2016 LNM/D. 29-JUN-2012

Add depth of 2 metres, 6 decimetres 44°57′45.6″N 062°04′27.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6307378-02)*

08-JAN-2016 LNM/D. 29-JUN-2012

Delete depth of 12 metres, 2 decimetres 44°56′50.0″N 062°05′33.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6307378-03)*

08-JAN-2016 LNM/D. 29-JUN-2012

Add depth of 6 metres, 5 decimetres 44°56′52.1″N 062°05′29.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 *DFO(6307378-04)*

08-JAN-2016 LNM/D. 29-JUN-2012

Chart no. 4234

Delete depth of 11 metres — 44°56′45.2″N 062°05′57.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 — *DFO(6307378-05)*

08-JAN-2016 — LNM/D. 29-JUN-2012

Add depth of 4 metres, 2 decimetres — 44°56′47.3″N 062°06′00.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376109 — *DFO(6307378-06)*

11-MAY-2012 — LNM/D. 12-AUG-2011

Amend FR 6m 8M to read FlR against light — 45°08′43.2″N 061°36′09.2″W
(See Chart No. 1, P1)

(G2012026) LL(638) DFO(6305969-01)

This notice affects Electronic Navigational Chart:
CA376109

12-AUG-2011 — LNM/D. 27-MAY-2011

Reposition green port hand lighted pillar bell buoy FlG, marked VV1 — from 44°53′02.0″N 062°06′27.0″W to 44°52′59.8″N 062°06′16.3″W
(See Chart No. 1, Qg)

(F2011151) LL(608) DFO(6305651-01)

This notice affects Electronic Navigational Chart:
CA376109

14-JAN-2011 — LNM/D. 23-APR-2010

Add pipeline with legend Gas/Gaz — joining 45°09′24.9″N 061°37′43.6″W
(See Chart No 1 L40.1) — 45°09′01.5″N 061°38′26.1″W
45°08′39.9″N 061°38′47.1″W
45°08′12.2″N 061°38′54.0″W
This notice affects Electronic Navigational Chart: — 45°07′44.3″N 061°38′42.5″W
CA476111 — 45°07′29.9″N 061°38′26.6″W
45°06′02.9″N 061°36′10.7″W
45°04′46.0″N 061°34′54.7″W
and 45°02′24.2″N 061°32′13.5″W

DFO(6305191-01)

23-APR-2010 — LNM/D. 01-JAN-2010

Chart no. 4234

Amend Iso 8s 20m 12M to read Fl 3s 21m 17M against light 45°05′24.0″N 061°42′01.7″W
(See Chart 1 P16)

(G2010012) LL(629) DFO(6304754-01)

This notice affects Electronic Navigational Chart:
CA176140, CA376109

01-JAN-2010 LNM/D. 31-JUL-2009

Delete light FR 45°06′19.1″N 061°43′22.7″W
(See Chart No 1 P1)

(G2009153) LL(631) DFO(6304658-01)

01-JAN-2010 LNM/D. 31-JUL-2009

Add light Iso R 45°06′18.8″N 061°43′21.9″W
(See Chart No 1 P1)

(G2009154) LL(631.2) DFO(6304659-01)

This notice affects Electronic Navigational Chart:
CA376109

01-JAN-2010 LNM/D. 31-JUL-2009

Add rescue station 45°06′26.0″N 061°43′16.0″W
(See Chart No 1 T12)

DFO(6304664-01)

This notice affects Electronic Navigational Chart: CA576110

31-JUL-2009 LNM/D. 10-JUL-2009

Delete BELL against red starboard hand lighted pillar bell buoy FlR, marked TT2 45°04′28.0″N 061°33′04.0″W
(See Chart No 1 Qf)

(G2009055) LL(635.5) DFO(6304458-01)

This notice affects Electronic Navigational Chart:
CA376109

31-JUL-2009 LNM/D. 10-JUL-2009

Chart no. 4234

Delete red starboard hand lighted pillar bell buoy FlR, BELL, marked TT4. 45°06′24.0″N 061°35′05.0″W
(See Chart No 1 Qf)
(G2009056) LL(636) DFO(6304459-01)

This notice affects Electronic Navigational Chart:
CA376109

31-JUL-2009 LNM/D. 10-JUL-2009

Add red starboard hand lighted pillar buoy QR, marked TT4. 45°05′54.6″N 061°34′36.3″W
(See Chart No 1 Qf)
(G2009056) LL(636) DFO(6304459-02)

This notice affects Electronic Navigational Chart:
CA376109

10-JUL-2009 LNM/D. 24-APR-2009

(P)Add pipeline and legend Gas/Gaz joining 45°09′24.7″N 061°37′44.1″W
(See Chart No 1 L40.1) 45°08′19.3″N 061°39′45.4″W
Encana will commence constructing a gas pipeline from Goldboro to the Deep Panuke Gasfield in July 2009. The proposed completion date is October 2009. 45°06′31.7″N 061°36′53.8″W
45°06′31.5″N 061°36′36.8″W
45°06′08.5″N 061°36′23.4″W
The work is completed. Notice 10-JUL-2009(P), DFO(6304485-2) is cancelled. and 45°02′24.3″N 061°32′13.5″W
Cancelled on 14-JAN-11 *DFO(6304485-02)*

24-APR-2009 LNM/D. 27-FEB-2009

Delete light F 25m 12M 45°09′52.8″N 061°39′16.5″W
(See Chart No 1 P1)
(G2009010) LL(637) DFO(6304315-01)

This notice affects Electronic Navigational Chart:
CA376109, CA476111

27-FEB-2009 LNM/D. 13-FEB-2009

(T)Add private yellow cautionary lighted spar buoy Fl Y 45°09′19.1″N 061°37′48.0″W
(See Chart No 1 Qm)
The mooring is temporary and will be removed by October 2009. *DFO(6304249-01)*
Goldboro Construction completed. Notice 27-FEB-2009(T), DFO(6304249-1) is cancelled.
Cancelled on 06-NOV-09

Chart no. 4234

27-FEB-2009 LNM/D. 13-FEB-2009

(T)Add private yellow cautionary lighted spar buoy Fl Y 45°09′14.1″N 061°37′53.9″W
(See Chart No 1 Qm)
The mooring is temporary and will be removed by October 2009. *DFO(6304249-02)*
Goldboro Construction completed. Notice 27-FEB-2009(T), DFO(6304249-2) is cancelled.
Cancelled on 06-NOV-09

27-FEB-2009 LNM/D. 13-FEB-2009

(T)Add private yellow cautionary lighted spar buoy Fl Y 45°09′09.2″N 061°37′59.8″W
(See Chart No 1 Qm)
The mooring is temporary and will be removed by October 2009. *DFO(6304249-03)*
Goldboro Construction completed. Notice 27-FEB-2009(T), DFO(6304249-3) is cancelled.
Cancelled on 06-NOV-09

13-FEB-2009 LNM/D. 28-NOV-2008

Replace green port hand can buoy, marked TT7 with green port hand lighted spar buoy QG, marked TT7 45°09′34.0″N 061°39′20.0″W
(See Chart No 1 Qg) *(G2008088) LL(636.04) DFO(6304204-01)*

This notice affects Electronic Navigational Chart: CA376109

26-SEP-2008 LNM/D. 28-DEC-2007

Add green port hand lighted spar buoy FlG, marked V1 45°05′02.0″N 061°42′04.0″W
(See Chart No 1 Qg)
(G2008013) LL(626.9) DFO(6303890-01)

This notice affects Electronic Navigational Chart: CA376109

26-SEP-2008 LNM/D. 28-DEC-2007

Amend VC to read V against red and white fairway lighted pillar bell buoy Mo(A) 45°01′13.0″N 061°39′09.0″W
(See Chart No 1 Qh) *(G2008025) LL(632) DFO(6303902-01)*

This notice affects Electronic Navigational Chart: CA376109

Chart no. 4234

26-SEP-2008 LNM/D. 28-DEC-2007

Delete green port hand spar buoy, marked VC1 45°05′02.0″N 061°42′04.0″W
(See Chart No 1 Qg)

(G2008030) DFO(6303907-01)

This notice affects Electronic Navigational Chart: CA376109

26-SEP-2008 LNM/D. 28-DEC-2007

Delete rear range/leading light FR with leading line and bearing legend 320½º 45°06′27.6″N 061°43′32.5″W
(See Chart No 1Pe)

(G2008045) LL(631.1) DFO(6303982-01)

This notice affects Electronic Navigational Chart: CA376109

28-DEC-2007 LNM/D. 10-AUG-2007

Delete green port hand spar buoy, marked TU1 45°02′36.0″N 061°37′42.0″W
(See Chart No 1 Qg)

(G2007175) LL(5634.41) DFO(6303727-01)

10-AUG-2007 LNM/D. 27-JUL-2007

Add depth of 2 metres, 6 decimetres 45°00′46.3″N 061°59′46.1″W

DFO(6303586-01)

10-AUG-2007 LNM/D. 27-JUL-2007

Add depth of 2 metres, 9 decimetres 45°01′18.2″N 061°59′32.0″W

DFO(6303586-02)

10-AUG-2007 LNM/D. 27-JUL-2007

Add depth of 1 metre, 4 decimetres 45°01′27.2″N 061°59′30.8″W

DFO(6303586-03)

27-JUL-2007 LNM/D. 06-JUL-2007

Chart no. 4234

Amend FlG to read QG against green port hand lighted spar buoy, marked TY5 — 45°05′11.0″N 061°38′32.5″W

(G2007070) LL(633.02) DFO(6303580-01)

06-JUL-2007 — LNM/D. 24-MAR-2006

Replace red, green and red starboard bifurcation lighted pillar bell buoy Fl(2+1)R, marked TY with yellow and black South cardinal lighted pillar buoy Q(6)+LFl 15s, marked TY — 45°04′33.0″N 061°37′20.0″W

(G2007044) LL(633) DFO(6303456-01)

This notice affects Electronic Navigational Chart: CA376067

06-JUL-2007 — LNM/D. 24-MAR-2006

Add light FlG against green port hand spar buoy, marked TY5 — 45°05′11.0″N 061°38′32.5″W

(G2007070) LL(5633.02) DFO(6303478-01)

06-JUL-2007 — LNM/D. 24-MAR-2006

Reposition red starboard hand spar buoy, marked TY4 — from 45°05′01.0″N 061°38′04.0″W to 45°05′04.0″N 061°37′57.0″W

(G2007072) LL(5633.01) DFO(6303484-01)

06-JUL-2007 — LNM/D. 24-MAR-2006

Delete BELL against yellow and black South cardinal lighted pillar bell buoy Q(6)+LFl 15s, marked TU — 45°02′45.0″N 061°35′12.0″W

(G2007078) LL(634.4) DFO(6303485-01)

This notice affects Electronic Navigational Chart: CA376061

24-MAR-2006 — LNM/D. 11-FEB-2005

Delete anchorage symbol 44°57′41.4″N 062°05′28.0″W

DFO(6302755-01)

24-MAR-2006 — LNM/D. 11-FEB-2005

Chart no. 4234

Add marine farm 44°57′42.0″N 062°05′48.0″W

DFO(6302755-02)

11-FEB-2005 LNM/D. 25-JUN-2004

Amend ″Fl 20s 17m 16M″ to read ″LFl 20s 16m 10M″ against light 45°05′59.8″N 061°32′31.9″W

LL(639) DFO(6302110-01)

11-FEB-2005 LNM/D. 25-JUN-2004

Amend ″Fl 10s 22m 20M″ to read ″Fl 10s 22m 15M″ against light 44°59′15.8″N 061°57′58.4″W

LL(615) DFO(6302110-02)

25-JUN-2004 LNM/D. 24-NOV-2000

Amend ″Bn R″ to read ″2 Bns″ 45°00′39.4″N 061°57′12.6″W

(G2004063) DFO(6301439-01)

24-NOV-2000 LNM/D. 19-MAR-1999

Add gas pipeline joining 45°09′24.0″N 061°37′41.0″W
45°08′47.7″N 061°38′24.1″W
45°08′33.5″N 061°38′31.7″W
45°08′09.2″N 061°38′35.3″W
45°07′42.3″N 061°38′23.2″W
45°07′24.8″N 061°38′02.2″W
45°05′42.3″N 061°35′00.4″W
45°04′09.8″N 061°33′42.0″W
and 45°02′52.5″N 061°32′13.5″W

(H2000-003) DFO(6828773-01)

24-NOV-2000 LNM/D. 19-MAR-1999

Add legend ″Gas/Gaz″ 45°07′06.0″N 061°37′24.0″W

(H2000-003) DFO(6828773-02)

24-NOV-2000 LNM/D. 19-MAR-1999

Chart no. 4234

Add legend ″See/Voir note GAS PIPELINES/GAZODUCS″ 45°07′57.5″N 061°37′36.0″W

(H2000-003) DFO(6828773-03)

24-NOV-2000 LNM/D. 19-MAR-1999

Add note ″GAS PIPELINES Gas pipelines and wells contain natural gas under pressure and damage to these installations could create an immediate fire hazard. Mariners are cautioned not to anchor or trawl near pipelines or wellheads. GAZODUCS Les gazoducs et les puits à gaz contiennent du gaz sous pression et du dommage à ces installations pourraient créer un danger de feu immédiat. Les navires ne devraient ni mouiller ni chaluter près de pipelines ou de têtes de puits.″ 45°05′55.0″N 061°54′18.0″W

(H2000-003) DFO(6828773-04)

4234 - Port Bickerton - New Chart - 10-APR-1987 - NAD 1983

11-MAR-2022 LNM/D. 24-DEC-2021

Affix patch 45°06′19.0″N 061°43′21.0″W
PDF
This notice affects Electronic Navigational Chart: CA376109, CA576110

DFO(6309979-01)

27-MAY-2011 LNM/D. 14-JAN-2011

Delete depth of 2 metres, 1 decimetre 45°06′18.1″N 061°43′22.9″W
(See Chart No. 1, I10)

DFO(6305441-01)

27-MAY-2011 LNM/D. 14-JAN-2011

Add depth of 1 metre, 8 decimetres 45°06′19.0″N 061°43′24.0″W
(See Chart No. 1, I10)

DFO(6305441-02)

27-MAY-2011 LNM/D. 14-JAN-2011

Add depth of 2 metres 45°06′14.4″N 061°43′21.9″W
(See Chart No. 1, I10)

DFO(6305441-03)

27-MAY-2011 LNM/D. 14-JAN-2011

Chart no. 4234

Add depth of 0 metres, 9 decimetres 45°06′13.3″N 061°43′25.0″W
(See Chart No. 1, I10)

DFO(6305441-04)

27-MAY-2011 LNM/D. 14-JAN-2011

Add depth of 1 metre, 9 decimetres 45°06′17.1″N 061°43′22.5″W
(See Chart No. 1, I10)

DFO(6305441-05)

27-MAY-2011 LNM/D. 14-JAN-2011

Add depth of 3 metres, 3 decimetres 45°05′58.3″N 061°43′06.2″W
(See Chart No. 1, I10)

DFO(6305441-06)

27-MAY-2011 LNM/D. 14-JAN-2011

Delete depth of 2 metres, 9 decimetres 45°05′39.3″N 061°43′29.6″W
(See Chart No. 1, I10)

DFO(6305442-01)

27-MAY-2011 LNM/D. 14-JAN-2011

Delete depth of 2 metres, 7 decimetres 45°05′33.4″N 061°42′58.6″W
(See Chart No. 1, I10)

DFO(6305442-02)

27-MAY-2011 LNM/D. 14-JAN-2011

Add depth of 0 metres, 2 decimetres 45°05′44.2″N 061°43′40.1″W
(See Chart No. 1, I10)

DFO(6305442-03)

27-MAY-2011 LNM/D. 14-JAN-2011

Add depth of 1 metre, 6 decimetres 45°05′39.0″N 061°43′31.2″W
(See Chart No. 1, I10)

DFO(6305442-04)

27-MAY-2011 LNM/D. 14-JAN-2011

Add depth of 2 metres, 3 decimetres 45°05′37.5″N 061°43′25.9″W
(See Chart No. 1, I10)

DFO(6305442-05)

Chart no. 4234

27-MAY-2011 LNM/D. 14-JAN-2011

Add awash 0 metres 45°05′39.8″N 061°43′23.3″W
(See Chart No. 1, Kb)

DFO(6305442-06)

27-MAY-2011 LNM/D. 14-JAN-2011

Add depth of 1 metre, 8 decimetres 45°05′35.8″N 061°43′13.2″W
(See Chart No. 1, I10)

DFO(6305442-07)

27-MAY-2011 LNM/D. 14-JAN-2011

Add depth of 2 metres 45°05′33.1″N 061°42′58.8″W
(See Chart No. 1, I10)

DFO(6305442-08)

27-MAY-2011 LNM/D. 14-JAN-2011

Add depth of 1 metre, 9 decimetres 45°05′35.2″N 061°42′57.0″W
(See Chart No. 1, I10)

DFO(6305442-09)

27-MAY-2011 LNM/D. 14-JAN-2011

Add depth of 1 metre, 2 decimetres 45°05′32.6″N 061°42′52.3″W
(See Chart No. 1, I10)

DFO(6305442-10)

23-APR-2010 LNM/D. 01-JAN-2010

Amend Iso 8s 20m 12M to read Fl 3s 21m 17M against light 45°05′24.0″N 061°42′01.7″W
(See Chart 1 P16)

(G2010012) LL(629) DFO(6304754-01)

This notice affects Electronic Navigational Chart:
CA176140, CA376109

01-JAN-2010 LNM/D. 31-JUL-2009

Amend FlR to read Iso R against light 45°05′40.8″N 061°43′28.5″W
(See Chart No 1 P16)

(G2009150) LL(629.8) DFO(6304655-01)

01-JAN-2010 LNM/D. 31-JUL-2009

Chart no. 4234

Amend FG 4m to read FlG against light 45°05′41.8″N 061°43′35.1″W
(See Chart No 1 P16)
(G2009151) LL(629.9) DFO(6304657-01)

01-JAN-2010 LNM/D. 31-JUL-2009

Delete light FR 4m 45°06′19.1″N 061°43′22.7″W
(See Chart No 1 P1)
(G2009153) LL(631) DFO(6304658-01)

01-JAN-2010 LNM/D. 31-JUL-2009

Add light Iso R 4s 45°06′18.8″N 061°43′21.9″W
(See Chart No 1 P1)
(G2009154) LL(631.2) DFO(6304659-01)

This notice affects Electronic Navigational Chart:
CA376109

01-JAN-2010 LNM/D. 31-JUL-2009

Add rescue station 45°06′25.0″N 061°43′23.0″W
(See Chart No 1 T12)
DFO(6304664-01)

This notice affects Electronic Navigational Chart: CA576110

01-JAN-2010 LNM/D. 31-JUL-2009

Delete radio tower, Ro Tr, with elevation of 31m, RLts 45°06′19.2″N 061°43′23.1″W
(See Chart No 1 E28)
DFO(6304665-01)

This notice affects Electronic Navigational Chart: CA576110

01-JAN-2010 LNM/D. 31-JUL-2009

Add radio tower, Ro Tr, with elevation of 30m, RLts 45°06′23.5″N 061°43′18.9″W
(See Chart No 1 E28)
DFO(6304665-02)

01-JAN-2010 LNM/D. 31-JUL-2009

Chart no. 4234

Replace wharf with submerged ruins with legend Ru joining 45°05′37.8″N 061°43′37.0″W
(See Chart No 1 F33.1) 45°05′36.8″N 061°43′36.6″W
and 45°05′36.7″N 061°43′37.1″W

DFO(6304666-01)

01-JAN-2010 LNM/D. 31-JUL-2009

Delete legend Public 45°05′36.5″N 061°43′39.8″W

DFO(6304666-02)

01-JAN-2010 LNM/D. 31-JUL-2009

Delete legend Ru 45°05′39.6″N 061°43′37.9″W

DFO(6304666-03)

28-NOV-2008 LNM/D. 07-NOV-2008

Add green port hand spar buoy, marked V7 45°06′13.9″N 061°43′23.6″W
(See Chart No 1 Qg)

(G2008072) DFO(6304144-01)

07-NOV-2008 LNM/D. 26-SEP-2008

Delete red starboard hand lighted pillar buoy FlR, marked VC10 45°05′33.5″N 061°43′10.5″W
(See Chart No 1 Qf) *(G2008054) LL(626) DFO(6304071-01)*

07-NOV-2008 LNM/D. 26-SEP-2008

Delete red starboard hand spar buoy, marked VC16 45°05′44.0″N 061°43′41.0″W
(See Chart No 1 Qf)

(G2008055) DFO(6304072-01)

07-NOV-2008 LNM/D. 26-SEP-2008

Delete red starboard hand lighted pillar buoy FlR, marked VD2 45°05′43.0″N 061°42′57.0″W
(See Chart No 1 Qf) *(G2008056) LL(626.5) DFO(6304073-01)*

26-SEP-2008 LNM/D. 28-DEC-2007

Chart no. 4234

Delete rear range/leading light FG 7m with leading line and bearing legend 118º 298º
(See Chart No 1Pe) — 45°05′47.0″N 061°43′50.0″W

(G2008012) LL(630.1) DFO(6303889-01)

26-SEP-2008 — LNM/D. 28-DEC-2007

Add green port hand lighted spar buoy FlG, marked V1
(See Chart No 1 Qg) — 45°05′02.0″N 061°42′04.0″W

(G2008013) LL(626.9) DFO(6303890-01)

This notice affects Electronic Navigational Chart:
CA376109

26-SEP-2008 — LNM/D. 28-DEC-2007

Add green, red and green port bifurcation lighted spar buoy Fl(2+1)6s G, marked VCC
(See Chart No 1 Qj) — 45°05′36.2″N 061°42′33.0″W

(G2008014) LL(627.1) DFO(6303891-01)

26-SEP-2008 — LNM/D. 28-DEC-2007

Add green port hand lighted spar buoy FlG, marked V3
(See Chart No 1 Qg) — 45°05′42.7″N 061°42′38.3″W

(G2008015) LL(627.5) DFO(6303892-01)

26-SEP-2008 — LNM/D. 28-DEC-2007

Add red starboard hand lighted spar buoy FlR, marked V4
(See Chart No 1 Qf) — 45°05′55.9″N 061°43′03.9″W

(G2008016) LL(628.1) DFO(6303893-01)

26-SEP-2008 — LNM/D. 28-DEC-2007

Add red starboard hand lighted spar buoy QR, marked V6
(See Chart No 1 Qf) — 45°06′12.2″N 061°43′22.1″W

(G2008017) LL(628.5) DFO(6303894-01)

26-SEP-2008 — LNM/D. 28-DEC-2007

Add green port hand lighted spar buoy QG, marked VC1
(See Chart No 1 Qg) — 45°05′34.3″N 061°42′53.7″W

(G2008018) LL(626.1) DFO(6303895-01)

Chart no. 4234

26-SEP-2008 LNM/D. 28-DEC-2007

Add red starboard hand lighted spar buoy FlR, marked VC2 45°05′34.5″N 061°42′56.0″W
(See Chart No 1 Qf)
(G2008019) LL(626.2) DFO(6303896-01)

26-SEP-2008 LNM/D. 28-DEC-2007

Add green port hand lighted spar buoy FlG, marked VC3 45°05′33.6″N 061°43′00.4″W
(See Chart No 1 Qg)
(G2008020) LL(626.3) DFO(6303897-01)

26-SEP-2008 LNM/D. 28-DEC-2007

Add red starboard hand lighted spar buoy QR, marked VC4 45°05′34.7″N 061°43′14.2″W
(See Chart No 1 Qf)
(G2008021) LL(626.4) DFO(6303898-01)

26-SEP-2008 LNM/D. 28-DEC-2007

Add green port hand lighted spar buoy FlG, marked VC5 45°05′34.4″N 061°43′15.8″W
(See Chart No 1 Qg)
(G2008022) LL(626.6) DFO(6303899-01)

26-SEP-2008 LNM/D. 28-DEC-2007

Add green port hand lighted spar buoy FlG, marked VC7 45°05′37.9″N 061°43′26.0″W
(See Chart No 1 Qg)
(G2008023) LL(626.7) DFO(6303900-01)

26-SEP-2008 LNM/D. 28-DEC-2007

Amend VC14 to read VC8 against red starboard hand spar buoy 45°05′43.5″N 061°43′35.5″W
(G2008024) DFO(6303901-01)

26-SEP-2008 LNM/D. 28-DEC-2007

Delete green port hand lighted pillar buoy FlG, marked VC3 45°05′34.0″N 061°42′41.4″W
(See Chart No 1 Qg)
(G2008029) LL(627) DFO(6303906-01)

26-SEP-2008 LNM/D. 28-DEC-2007

Chart no. 4234

Delete green port hand spar buoy, marked VC1 — 45°05′02.0″N 061°42′03.5″W
(See Chart No 1 Qg)

(G2008030) DFO(6303907-01)

This notice affects Electronic Navigational Chart: CA376109

26-SEP-2008 — LNM/D. 28-DEC-2007

Delete rear range/leading light FR 12m with leading line and bearing legend 140½º 320½º — 45°06′27.6″N 061°43′32.5″W
(See Chart No 1Pe)

(G2008045) LL(631.1) DFO(6303982-01)

This notice affects Electronic Navigational Chart: CA376109

4234 - St Marys River - New Chart - 10-APR-1987 - NAD 1983

29-JUN-2012 — LNM/D. 11-MAY-2012

Reposition red starboard hand conical buoy, marked VK24 — from 45°04′00.4″N 061°54′46.2″W to 45°04′08.3″N 061°54′51.9″W
(See Chart No. 1, Qf)

(F2012029) DFO(6306049-01)

This notice affects Electronic Navigational Chart: CA476112

29-JUN-2012 — LNM/D. 11-MAY-2012

Reposition green port hand can buoy, marked VK25 — from 45°04′06.0″N 061°54′57.0″W to 45°04′10.1″N 061°55′00.2″W
(See Chart No. 1, Qg)

(F2012030) DFO(6306050-01)

This notice affects Electronic Navigational Chart: CA476112

29-JUN-2012 — LNM/D. 11-MAY-2012

Reposition green port hand can buoy, marked VK27 — from 45°04′10.0″N 061°55′09.0″W to 45°04′13.6″N 061°55′11.6″W
(See Chart No. 1, Qg)

(F2012031) DFO(6306051-01)

This notice affects Electronic Navigational Chart: CA476112

Fisheries and Oceans Canada | Pêches et Océans Canada
Canadian Coast Guard | Garde côtière canadienne

Chart no. 4234