Chart no. 4236

4236 - Ship Harbour and Approaches / et les approches - New Edition - 13-JUL-2001 - NAD 1983

25-DEC-2020 LNM/D. 16-OCT-2020

Add depth of 3.4 metres 44°43′12.0″N 062°44′31.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083, CA476084 *DFO(6309298-05)*

25-DEC-2020 LNM/D. 16-OCT-2020

Add depth of 8.3 metres 44°43′19.5″N 062°44′34.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083, CA476084 *DFO(6309298-06)*

25-DEC-2020 LNM/D. 16-OCT-2020

Replace depth of 18.9 metres with depth of 16 metres 44°43′30.6″N 062°42′38.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083, CA476084 *DFO(6309298-07)*

25-DEC-2020 LNM/D. 16-OCT-2020

Replace depth of 14.9 metres with depth of 11.5 metres 44°44′24.9″N 062°43′31.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083, CA476084 *DFO(6309298-08)*

25-OCT-2019 LNM/D. 23-AUG-2019

Add light Fl R against red starboard hand spar buoy, marked YM8 44°46′18.5″N 062°47′55.0″W
(See Chart No. 1, Qf) *(F2019032) LL(586.01) DFO(6308783-01)*
This notice affects Electronic Navigational Chart: CA476089

31-MAY-2019 LNM/D. 28-DEC-2018

Replace depth of 0.9 metres with depth of 0.2 metres. 44°46′09.0″N 062°45′46.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476084 *DFO(6308647-03)*

28-JUL-2017 LNM/D. 15-JUL-2016

Chart no. 4236

Add marine farm 44°45′06.3″N 062°45′53.9″W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA476084 *DFO(6307855-06)*

30-APR-2010 LNM/D. 23-APR-2010

Add marine farm 44°44′10.0″N 062°48′29.0″W
(See Chart No. 1, K48.2)
DFO(6304779-01)

27-FEB-2009 LNM/D. 20-JUN-2008

Amend Fl G 12s 23m 8M to read LFl G 6s 23m 4M against light 44°44′55.6″N 062°45′24.2″W
(See Chart No 1 P16) *(F2008175) LL(585) DFO(6304263-01)*

This notice affects Electronic Navigational Chart:
CA376083, CA476084

08-OCT-2004 LNM/D. 02-APR-2004

Amend ′Fl 4s 26m 8M′ to read ′Fl 4s 26m 6M′ against light 44°43′14.7″N 062°47′59.4″W

LL(583) DFO(6301942-01)

4236 - Taylors Head to / à Shut-in Island - New Edition - 13-JUL-2001 - NAD 1983

25-DEC-2020 LNM/D. 16-OCT-2020

Replace depth of 19.5 metres with depth of 9.7 metres 44°49′03.1″N 062°31′57.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 *DFO(6309298-01)*

25-DEC-2020 LNM/D. 16-OCT-2020

Add depth of 3.4 metres 44°43′12.0″N 062°44′31.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083, CA476084 *DFO(6309298-05)*

25-DEC-2020 LNM/D. 16-OCT-2020

Chart no. 4236

Add depth of 8.3 metres 44°43′19.5″N 062°44′34.4″W
(See Chart No. 1, I10)
DFO(6309298-06)

This notice affects Electronic Navigational Chart: CA376083, CA476084

25-DEC-2020 LNM/D. 16-OCT-2020

Replace depth of 18.9 metres with depth of 16 metres 44°43′30.6″N 062°42′38.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083, CA476084 *DFO(6309298-07)*

25-DEC-2020 LNM/D. 16-OCT-2020

Replace depth of 14.9 metres with depth of 11.5 metres 44°44′24.9″N 062°43′31.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083, CA476084 *DFO(6309298-08)*

25-DEC-2020 LNM/D. 16-OCT-2020

Add depth of 7.5 metres 44°45′26.3″N 062°40′40.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6309298-09)*

25-DEC-2020 LNM/D. 16-OCT-2020

Add depth of 1.4 metres 44°40′25.0″N 063°09′44.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6309298-10)*

25-DEC-2020 LNM/D. 16-OCT-2020

Delete depth of 3.7 metres 44°40′24.6″N 063°09′47.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6309298-11)*

25-DEC-2020 LNM/D. 16-OCT-2020

Add depth of 1.8 metres 44°40′59.3″N 063°04′10.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6309298-12)*

25-DEC-2020 LNM/D. 16-OCT-2020

Chart no. 4236

Add rock which covers and uncovers 44°37′27.0″N 063°16′13.5″W
(See Chart No. 1, K11)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6309298-13)*

25-DEC-2020 LNM/D. 16-OCT-2020

Add depth of 1.8 metres 44°40′44.6″N 063°11′51.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6309298-14)*

25-DEC-2020 LNM/D. 16-OCT-2020

Delete sector light F RWG, and limits of arcs of visibility. 44°49′21.8″N 062°35′54.3″W
(See Chart No. 1, P40.1)
This notice affects Electronic Navigational Chart: CA376083 *(F2020047) LL(591) DFO(6309299-01)*

25-DEC-2020 LNM/D. 16-OCT-2020

Add abandoned lighthouse with legend Lt Ho/Phare Aband 44°49′21.8″N 062°35′54.3″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6309299-02)*

16-OCT-2020 LNM/D. 10-JUL-2020

Add light Fl G against green port hand spar buoy, marked YA3 44°46′42.3″N 062°34′41.9″W
(See Chart No. 1, Qg) *(F2020034) LL(590.01) DFO(6309237-01)*
This notice affects Electronic Navigational Chart: CA376083

16-OCT-2020 LNM/D. 10-JUL-2020

Add light Fl R against red starboard hand spar buoy, marked YA4 44°46′42.4″N 062°33′48.4″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA376102 *(F2020035) DFO(6309238-01)*

16-OCT-2020 LNM/D. 10-JUL-2020

Add green port hand lighted spar buoy Q G, marked YA5 44°47′24.3″N 062°34′29.4″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA376083 *(F2020036) LL(590.03) DFO(6309239-01)*

16-OCT-2020 LNM/D. 10-JUL-2020

Chart no. 4236

Add red starboard hand lighted spar buoy Fl R, marked YA6 — 44°47′28.0″N 062°34′01.3″W
(See Chart No. 1, Qf) — *(F2020037) LL(590.04) DFO(6309240-01)*
This notice affects Electronic Navigational Chart: CA376102

16-OCT-2020 — LNM/D. 10-JUL-2020

Add green port hand lighted spar buoy Fl G, marked YA7 — 44°48′36.8″N 062°35′56.3″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA376083 — *(F2020038) LL(590.05) DFO(6309241-01)*

16-OCT-2020 — LNM/D. 10-JUL-2020

Add red starboard hand lighted spar buoy Fl R, marked YA8 — 44°48′42.9″N 062°35′34.9″W
(See Chart No. 1, Qf) — *(F2020039) LL(590.06) DFO(6309242-01)*
This notice affects Electronic Navigational Chart: CA376083

10-JUL-2020 — LNM/D. 13-MAR-2020

Add depth of 25.6 metres — 44°37′43.2″N 063°05′58.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 — *DFO(6309000-01)*

10-JUL-2020 — LNM/D. 13-MAR-2020

Add depth of 13.3 metres — 44°37′47.4″N 063°02′34.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 — *DFO(6309000-03)*

10-JUL-2020 — LNM/D. 13-MAR-2020

Add depth of 12.5 metres — 44°37′52.2″N 063°00′58.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 — *DFO(6309000-04)*

10-JUL-2020 — LNM/D. 13-MAR-2020

Delete depth of 35 metres — 44°37′02.3″N 063°00′51.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 — *DFO(6309000-05)*

Chart no. 4236

10-JUL-2020 LNM/D. 13-MAR-2020

Add depth of 25.1 metres 44°37′01.8″N 063°00′57.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 *DFO(6309000-06)*

10-JUL-2020 LNM/D. 13-MAR-2020

Add depth of 24.9 metres 44°36′28.2″N 062°59′34.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 *DFO(6309000-08)*

10-JUL-2020 LNM/D. 13-MAR-2020

Add depth of 11.9 metres 44°36′09.6″N 062°58′01.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 *DFO(6309000-09)*

06-DEC-2019 LNM/D. 25-OCT-2019

Delete BELL against black, yellow and black East cardinal lighted pillar buoy Q(3) 10s, marked YS 44°39′50.3″N 062°50′30.6″W
(See Chart No 1 Q130.3) *(F2019038) LL(580.3) DFO(6308835-01)*
This notice affects Electronic Navigational Chart: CA376083

25-OCT-2019 LNM/D. 23-AUG-2019

Affix patch 44°40′00.0″N 063°00′00.0″W
PDF
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308802-01)*

25-OCT-2019 LNM/D. 23-AUG-2019

Add depth of 7.7 metres 44°39′49.8″N 063°07′25.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308802-03)*

23-AUG-2019 LNM/D. 31-MAY-2019

Add depth of 7 metres, 3 decimetres 44°38′58.3″N 063°12′43.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308730-02)*

Chart no. 4236

23-AUG-2019 LNM/D. 31-MAY-2019

Add depth of 10 metres 44°38′50.9″N 063°07′05.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 *DFO(6308730-03)*

23-AUG-2019 LNM/D. 31-MAY-2019

Add depth of 10 metres, 8 decimetres 44°37′57.9″N 063°01′01.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801, CA376083 *DFO(6308730-05)*

31-MAY-2019 LNM/D. 28-DEC-2018

Replace depth of 1.5 metres with depth of 0.4 metres. 44°46′57.0″N 062°38′31.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308647-02)*

31-MAY-2019 LNM/D. 28-DEC-2018

Add depth of 4.1 metres. 44°40′45.0″N 062°57′31.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308647-04)*

31-MAY-2019 LNM/D. 28-DEC-2018

Add depth of 4.7 metres. 44°39′09.6″N 063°00′56.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308648-01)*

31-MAY-2019 LNM/D. 28-DEC-2018

Add depth of 4.6 metres 44°40′16.8″N 063°10′29.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308648-04)*

31-MAY-2019 LNM/D. 28-DEC-2018

Add depth of 0.1 metres 44°41′04.2″N 063°11′03.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308648-05)*

31-MAY-2019 LNM/D. 28-DEC-2018

Chart no. 4236

Replace depth of 2.3 metres with depth of 0.4 metres — 44°38′04.8″N 063°16′38.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 — *DFO(6308648-06)*

28-DEC-2018 — LNM/D. 16-NOV-2018

Amend ″LFlR 12s 9m 5M″ to read ″Fl R 9m8M″ against light — 44°47′40.9″N 062°39′00.5″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA376083 — *(F2018045) LL(589) DFO(6308528-01)*

16-NOV-2018 — LNM/D. 03-AUG-2018

Affix patch — 44°40′00.0″N 063°05′00.0″W
PDF
This notice affects Electronic Navigational Chart: CA376083 — *DFO(6308506-01)*

03-AUG-2018 — LNM/D. 29-JUN-2018

Replace ON CERTAIN COPIES depth of 2.2 metres with depth of 1.4 metres. — 44°42′03.8″N 062°50′49.7″W
(See Chart No. 1, I10) — *DFO(6308389-01)*

29-JUN-2018 — LNM/D. 17-NOV-2017

Add light FlG against green port hand spar buoy, marked YE5 — 44°46′56.4″N 062°38′22.0″W
(See Chart No. 1, Qg) — *(F2018010 & F2018012) LL(588.03) DFO(6308286-01)*

This notice affects Electronic Navigational Chart: CA376083

17-NOV-2017 — LNM/D. 15-SEP-2017

Add depth of 5 metres, 1 decimetre — 44°39′36.5″N 062°56′00.7″W
(See Chart No. 1, I10)
DFO(6308122-01)

This notice affects Electronic Navigational Chart: CA376083

17-NOV-2017 — LNM/D. 15-SEP-2017

Add drying height of 0 metres, 8 decimetres — 44°36′59.6″N 063°16′48.7″W
(See Chart No. 1, I15)
This notice affects Electronic Navigational Chart: CA376083, CA476009 — *DFO(6308122-02)*

Chart no. 4236

15-SEP-2017 LNM/D. 11-AUG-2017

Affix patch 44°45′00.0″N 063°10′00.0″W
PDF
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308031-01)*

11-AUG-2017 LNM/D. 28-JUL-2017

Add depth of 4 metres, 1 decimetre 44°46′41.2″N 062°40′21.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308020-01)*

11-AUG-2017 LNM/D. 28-JUL-2017

Delete depth of 2 metres, 7 decimetres 44°48′13.0″N 062°38′50.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308020-02)*

11-AUG-2017 LNM/D. 28-JUL-2017

Add depth of 1 metre, 5 decimetres 44°48′10.4″N 062°38′55.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308020-03)*

11-AUG-2017 LNM/D. 28-JUL-2017

Delete depth of 1 metre, 5 decimetres 44°48′41.2″N 062°37′22.2″W

(See Chart No. 1, I10) *DFO(6308020-04)*
This notice affects Electronic Navigational Chart: CA376083

11-AUG-2017 LNM/D. 28-JUL-2017

Add depth of 0 metres, 7 decimetres 44°48′41.3″N 062°37′17.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308020-05)*

11-AUG-2017 LNM/D. 28-JUL-2017

Replace depth of 7 metres with depth of 5 metres, 8 decimetres 44°47′41.7″N 062°34′47.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308020-06)*

11-AUG-2017 LNM/D. 28-JUL-2017

Chart no. 4236

Replace depth of 4 metres, 6 decimetres with depth of 3 metres, 4 decimetres — 44°46′33.4″N 062°35′42.8″W
(See Chart No. 1, I10) — *DFO(6308020-07)*
This notice affects Electronic Navigational Chart: CA376083

11-AUG-2017 — LNM/D. 28-JUL-2017

Add depth of 3 metres — 44°46′37.4″N 062°36′18.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 — *DFO(6308020-08)*

11-AUG-2017 — LNM/D. 28-JUL-2017

Add depth of 2 metres, 4 decimetres — 44°49′34.6″N 062°31′03.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376102 — *DFO(6308020-09)*

11-AUG-2017 — LNM/D. 28-JUL-2017

Replace depth of 2 metres, 2 decimetres with depth of 1 metre, 4 decimetres — 44°42′03.8″N 062°50′49.7″W
(See Chart No. 1, I10) — *DFO(6308024-01)*
This notice affects Electronic Navigational Chart: CA376083

28-JUL-2017 — LNM/D. 15-JUL-2016

Delete depth of 11 metres — 44°41′27.8″N 062°58′39.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 — *DFO(6308009-01)*

28-JUL-2017 — LNM/D. 15-JUL-2016

Add depth of 3 metres, 6 decimetres — 44°41′28.3″N 062°58′33.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 — *DFO(6308009-02)*

28-JUL-2017 — LNM/D. 15-JUL-2016

Replace depth of 1 metre, 8 decimetres with depth of 0 metres, 6 decimetres — 44°41′56.8″N 062°55′47.5″W
(See Chart No. 1, I10) — *DFO(6308009-03)*
This notice affects Electronic Navigational Chart: CA376083

28-JUL-2017 — LNM/D. 15-JUL-2016

Chart no. 4236

Add depth of 1 metre, 3 decimetres 44°42′57.8″N 062°45′48.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376083 *DFO(6308009-04)*

15-JUL-2016 LNM/D. 08-JUL-2016

Replace red starboard hand spar buoy, marked YV10, with red starboard hand lighted spar buoy QR, marked YV10 44°41′05.4″N 063°04′41.2″W
(See Chart No. 1, Qf) *(F2016028) LL(566.03) DFO(6307600-01)*
This notice affects Electronic Navigational Chart: CA376083

15-JUL-2016 LNM/D. 08-JUL-2016

Reposition red starboard hand lighted spar buoy QR, marked YV10 from 44°41′05.4″N 063°04′41.2″W
to 44°41′09.6″N 063°04′45.6″W
(See Chart No. 1, Q7)
This notice affects Electronic Navigational Chart: CA376083 *(F2016028) LL(566.03) DFO(6307600-02)*

15-JUL-2016 LNM/D. 08-JUL-2016

Add light QG against green port hand spar buoy , marked YV7 44°40′44.0″N 063°04′23.4″W
(See Chart No. 1, Q7) *(F2016024) LL(566.02) DFO(6307600-03)*
This notice affects Electronic Navigational Chart: CA376083

15-JUL-2016 LNM/D. 08-JUL-2016

Delete green port hand spar buoy, marked YV11 44°41′23.2″N 063°04′49.6″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA376083 *(F2016025) DFO(6307600-04)*

15-JUL-2016 LNM/D. 08-JUL-2016

Delete red starboard hand spar buoy, marked YV12 44°41′19.2″N 063°04′44.1″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA376083 *(F2016027) DFO(6307600-05)*

15-JUL-2016 LNM/D. 08-JUL-2016

Delete green port hand spar buoy, marked YV13 44°41′30.0″N 063°04′44.0″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA376083 *(F2016026) DFO(6307600-06)*

Chart no. 4236

15-JUL-2016 LNM/D. 08-JUL-2016

Add Note ″Channel Buoyed/Chenal balisé″ 44°41′37.8″N 063°05′11.7″W
This notice affects Electronic Navigational Chart: CA376083
DFO(6307600-07)

08-JUL-2016 LNM/D. 06-MAY-2016

Add red starboard hand lighted spar buoy FlR, marked HJ2/2 44°41′16.4″N 063°13′52.7″W
(See Chart No. 1, Qf) *(F2016021) LL(564.22) DFO(6307590-01)*
This notice affects Electronic Navigational Chart: CA376083

08-JUL-2016 LNM/D. 06-MAY-2016

Delete green port hand spar buoy, marked YV5 44°39′52.5″N 063°04′26.5″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA376083 *(F2016031) DFO(6307602-01)*

06-MAY-2016 LNM/D. 15-NOV-2013

Amend LFl 6s 26m 14M to read LFl 6s 8m 12M against light 44°39′53.2″N 062°51′48.1″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA176140, CA276801, CA376083 *(F2016011) LL(580) DFO(6307493-01)*

15-NOV-2013 LNM/D. 10-JUN-2011

Delete red starboard hand spar buoy, marked HW2 44°37′59.0″N 063°18′28.0″W
(See Chart No. 1, Qf)
This notice affects Electronic Navigational Chart: CA376083, CA476009 *(F2013030) DFO(6306520-01)*

15-NOV-2013 LNM/D. 10-JUN-2011

Delete red and white fairway can buoy, marked HW 44°37′31.0″N 063°18′15.0″W
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart: CA376083, CA476009 *(F2013031) DFO(6306520-02)*

10-JUN-2011 LNM/D. 01-APR-2011

Chart no. 4236

Delete depth of 1metre, 8 decimetres 44°42′05.0″N 063°10′15.2″W
(See Chart No. 1, I10)

DFO(6305471-01)

This notice affects Electronic Navigational Chart: CA376083

10-JUN-2011 LNM/D. 01-APR-2011

Delete depth of 3 metres, 7 decimetres 44°41′26.2″N 063°10′17.2″W
(See Chart No. 1, I10)

DFO(6305471-02)

This notice affects Electronic Navigational Chart: CA376083

10-JUN-2011 LNM/D. 01-APR-2011

Add depth of 0 metres 8 decimetres 44°42′00.0″N 063°10′16.2″W
(See Chart No. 1, I10)

DFO(6305471-05)

This notice affects Electronic Navigational Chart: CA376083

10-JUN-2011 LNM/D. 01-APR-2011

Add depth of 2 metres, 5 decimetres 44°41′22.5″N 063°10′14.4″W
(See Chart No. 1, I10)

DFO(6305471-06)

This notice affects Electronic Navigational Chart: CA376083

10-JUN-2011 LNM/D. 01-APR-2011

Add depth of 1 metre, 7 decimetres 44°40′49.5″N 063°10′34.8″W
(See Chart No. 1, I10)

DFO(6305471-07)

This notice affects Electronic Navigational Chart: CA376083

10-JUN-2011 LNM/D. 01-APR-2011

Add depth of 1 metre, 2 decimetres 44°41′49.2″N 063°10′25.3″W
(See Chart No. 1, I10)

DFO(6305471-09)

This notice affects Electronic Navigational Chart: CA376083

Chart no. 4236

10-JUN-2011 LNM/D. 01-APR-2011

Add depth of 3 metres 44°41′30.2″N 063°10′26.6″W
(See Chart No. 1, I10)

DFO(6305471-11)

This notice affects Electronic Navigational Chart: CA376083

01-APR-2011 LNM/D. 30-APR-2010

Amend FlR 12s 13m 6M to read LFlR 12s 9m 5M against light 44°47′40.3″N 062°39′01.4″W
(See Chart No 1 P16) *(F2011038) LL(589) DFO(6305337-01)*

23-APR-2010 LNM/D. 12-FEB-2010

Amend Q to read QR against light 44°41′41.7″N 063°04′41.6″W
(See Chart 1 P16)

(F2010011) LL(568) DFO(6304786-01)

This notice affects Electronic Navigational Chart: CA376083

12-FEB-2010 LNM/D. 27-MAR-2009

Amend Fl 15s 26m 9M to read LFl 6s 26m 14M against light 44°39′53.1″N 062°51′48.3″W
(See Chart 1 P16)

(F2009078) LL(580) DFO(6304719-01)

This notice affects Electronic Navigational Chart: CA176140, CA276801, CA376083

27-MAR-2009 LNM/D. 27-FEB-2009

Add depth of 0 metres, 5 decimetres 44°46′23.3″N 063°01′42.3″W
(See Chart No. 1, I10)

DFO(6304268-01)

This notice affects Electronic Navigational Chart: CA376083

27-FEB-2009 LNM/D. 20-JUN-2008

Chart no. 4236

Amend Fl G 12s 23m 8M to read LFl G 6s 23m 4M against light — 44°44′55.6″N 062°45′24.2″W
(See Chart No 1 P16) *(F2008175) LL(585) DFO(6304263-01)*

This notice affects Electronic Navigational Chart:
CA376083, CA476084

20-JUN-2008 LNM/D. 06-MAY-2005
Affix patch 44°44′00.0″N 063°01′00.0″W

DFO(6303955-01)

PDF

06-MAY-2005 LNM/D. 08-OCT-2004
Replace red starboard hand pillar light buoy marked HX2, with red starboard hand spar light buoy FlR, marked HX2 — 44°37′20.0″N 063°16′14.0″W
(F2005001) LL(563.2) DFO(6302230-01)

08-OCT-2004 LNM/D. 02-APR-2004
Delete light FR 44°38′17.2″N 063°16′37.2″W

(F2004105) LL(563.5) DFO(6301888-01)

08-OCT-2004 LNM/D. 02-APR-2004
Amend ′Fl 14s 26m 8M′ to read ′Fl 4s 26m 6M′ against light 44°43′14.7″N 062°47′59.4″W

LL(583) DFO(6301942-01)

02-APR-2004 LNM/D. 09-MAY-2003
Delete green, port hand spar buoy, marked HX5 44°37′42.2″N 063°16′30.4″W

DFO(6301225-01)

02-APR-2004 LNM/D. 09-MAY-2003
Delete green, port hand spar buoy, marked HX7 44°38′07.0″N 063°16′33.0″W

DFO(6301225-02)

Chart no. 4236

02-APR-2004 LNM/D. 09-MAY-2003

Add legend ″Channel Buoyed/Chenal balisé″ 44°37′50.0″N 063°16′30.0″W

DFO(6301225-03)

4236 - Continuation A - New Edition - 13-JUL-2001 - NAD 1983

16-JUL-2021 LNM/D. 25-DEC-2020

Add marine farm 44°48′10.5″N 062°50′03.5″W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA476089 *DFO(6309507-01)*

16-JUL-2021 LNM/D. 25-DEC-2020

Add marine farm 44°48′34.4″N 062°50′26.7″W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA476089 *DFO(6309507-02)*

16-JUL-2021 LNM/D. 25-DEC-2020

Add marine farm 44°48′29.8″N 062°51′57.5″W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA476089 *DFO(6309507-03)*

25-DEC-2020 LNM/D. 16-OCT-2020

Replace depth of 5.8 metres with depth of 4.5 metres 44°48′04.2″N 062°50′28.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476089 *DFO(6309298-02)*

25-DEC-2020 LNM/D. 16-OCT-2020

Delete depth of 13.7 metres 44°47′51.1″N 062°50′02.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476089 *DFO(6309298-03)*

25-DEC-2020 LNM/D. 16-OCT-2020

Add depth of 7.5 metres 44°47′48.0″N 062°50′00.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476089 *DFO(6309298-04)*

13-MAR-2020 LNM/D. 06-DEC-2019

Chart no. 4236

Reposition green port hand spar buoy, marked YM23 — from 44°48′23.5″N 062°51′31.8″W
(See Chart No. 1, Qg) — to 44°48′24.1″N 062°51′36.0″W
This notice affects Electronic Navigational Chart: CA476089 — *(F2020002) DFO(6308939-01)*

25-OCT-2019 — LNM/D. 23-AUG-2019

Add light Fl R against red starboard hand spar buoy, marked YM8 — 44°46′18.5″N 062°47′55.0″W
(See Chart No. 1, Qf) — *(F2019032) LL(586.01) DFO(6308783-01)*
This notice affects Electronic Navigational Chart: CA476089

25-OCT-2019 — LNM/D. 23-AUG-2019

Add light Fl R against red starboard hand spar buoy, marked YM12 — 44°46′57.0″N 062°49′09.3″W
(See Chart No. 1, Qf) — *(F2019033) LL(586.03) DFO(6308784-01)*
This notice affects Electronic Navigational Chart: CA476089

25-OCT-2019 — LNM/D. 23-AUG-2019

Add light Q G against green port hand spar buoy, marked YM17 — 44°48′08.0″N 062°50′30.1″W
(See Chart No. 1, Qg) — *(F2019034) LL(586.07) DFO(6308785-01)*
This notice affects Electronic Navigational Chart: CA476089

25-OCT-2019 — LNM/D. 23-AUG-2019

Add light Fl R against red starboard hand spar buoy, marked YM14 — 44°47′57.2″N 062°50′10.0″W
(See Chart No. 1, Qf) — *(F2019035) LL(586.04) DFO(6308786-01)*
This notice affects Electronic Navigational Chart: CA476089

09-MAY-2003

Amend YM5 to read YM25 aginst the buoy 44°48′36.6″N 062°52′07.5″W

DFO(6300874-01)