Chart no. 4384

4384 - Pearl Island to / à Cape La Have - New Edition - 10-JAN-2003 - NAD 1983

26-MAY-2023 LNM/D. 03-DEC-2021

Delete depth of 4.9 metres 44°22′33.5″N 064°18′54.7″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6310663-05)*

26-MAY-2023 LNM/D. 03-DEC-2021

Add depth of 1.2 metres 44°22′32.9″N 064°18′52.8″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6310663-06)*

03-DEC-2021 LNM/D. 20-AUG-2021

Add private yellow ODAS/SADO lighted pillar buoy Fl Y 2.5s, Priv 44°17′56.4″N 064°07′30.0″W
(See Chart No. 1, Q58) *DFO(6309780-01)*
This notice affects Electronic Navigational Chart: CA476664

20-AUG-2021 LNM/D. 26-FEB-2021

Delete legend FogSig20s against light 44°14′14.6″N 064°18′59.1″W
(See Chart No 1 R20)
This notice affects Electronic Navigational Chart: CA276801, CA476664 *(F2021038) LL(423) DFO(6309461-01)*

20-AUG-2021 LNM/D. 26-FEB-2021

Amend F 24m11M to read F 23m13M against light 44°14′14.6″N 064°18′59.1″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276801, CA476664 *LL(423) DFO(6309461-02)*

26-FEB-2021 LNM/D. 18-DEC-2020

Amend Fl to read LFl against light 44°22′01.5″N 064°12′04.1″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA476199 *(F2021003) LL(446) DFO(6309338-01)*

18-DEC-2020 LNM/D. 24-JUL-2020

Replace depth of 5.5 metres with depth of 4.4 metres 44°15′50.7″N 064°21′51.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6309301-11)*

Chart no. 4384

18-DEC-2020 LNM/D. 24-JUL-2020

Replace depth of 7.6 metres with depth of 6.4 metres 44°15′34.2″N 064°20′51.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6309301-22)*

18-DEC-2020 LNM/D. 24-JUL-2020

Replace depth of 7.9 metres with depth of 6.7 metres 44°15′34.2″N 064°21′06.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6309301-23)*

18-DEC-2020 LNM/D. 24-JUL-2020

Replace depth of 7 metres with depth of 5.8 metres 44°15′34.9″N 064°21′48.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6309301-28)*

24-JUL-2020 LNM/D. 27-MAR-2020

Add drying height of 0.1 metres 44°17′14.1″N 064°21′02.4″W
(See Chart No. 1, I15)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6309105-02)*

27-MAR-2020 LNM/D. 01-DEC-2017

Amend Fl 12s24m8M to read LFl 12s24m8M against light 44°13′43.6″N 064°16′27.7″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276801, CA476664 *(F2020003) LL(432) DFO(6308940-01)*

01-DEC-2017 LNM/D. 25-AUG-2017

Delete depth of 7.3 metres 44°20′47.1″N 064°17′37.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6308145-02)*

01-DEC-2017 LNM/D. 25-AUG-2017

Add depth of 6.4 metres 44°20′49.2″N 064°17′37.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6308145-03)*

25-AUG-2017 LNM/D. 05-AUG-2016

Chart no. 4384

Replace depth of 4 metres, 3 decimetres with depth of 2 metres, 1 decimetre — 44°14′47.4″N 064°21′55.2″W
(See Chart No. 1, I10) — *DFO(6308029-01)*
This notice affects Electronic Navigational Chart: CA476664

25-AUG-2017 — LNM/D. 05-AUG-2016

Delete depth of 2 metres, 7 decimetres — 44°14′31.9″N 064°22′09.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 — *DFO(6308029-05)*

25-AUG-2017 — LNM/D. 05-AUG-2016

Delete depth of 3 metres — 44°14′31.7″N 064°22′14.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 — *DFO(6308029-06)*

25-AUG-2017 — LNM/D. 05-AUG-2016

Add depth of 1 metre, 8 decimetres — 44°14′31.3″N 064°22′11.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 — *DFO(6308029-07)*

05-AUG-2016 — LNM/D. 17-JUN-2016

Delete legend Fog Sig against light — 44°09′31.9″N 064°28′50.7″W
(See Chart No 1 R20)
This notice affects Electronic Navigational Chart: CA476664 — *(F2016034) LL(417.5) DFO(6307628-01)*

17-JUN-2016 — LNM/D. 06-MAY-2016

Amend Fl to read Q(6)+LFl 15s against light — 44°16′01.2″N 064°21′50.2″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA476664 — *(F2016017) LL(428) DFO(6307540-01)*

06-MAY-2016 — LNM/D. 12-FEB-2016

Delete depth of 7 metres, 3 decimeters — 44°15′25.2″N 064°20′07.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 — *DFO(6307499-02)*

06-MAY-2016 — LNM/D. 12-FEB-2016

Chart no. 4384

Add depth of 4 metres, 9 decimetres — 44°15′28.6″N 064°20′08.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 — *DFO(6307499-03)*

06-MAY-2016 — LNM/D. 12-FEB-2016

Add depth of 3 metres, 4 decimetres — 44°15′55.4″N 064°20′07.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 — *DFO(6307499-04)*

06-MAY-2016 — LNM/D. 12-FEB-2016

Add depth of 3 metres — 44°15′53.4″N 064°20′20.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 — *DFO(6307499-09)*

12-FEB-2016 — LNM/D. 31-JUL-2015

Amend Fog Sig to read Fog Sig (Occas) against light — 44°21′37.0″N 064°17′46.7″W
(See Chart No. 1, P50)
This notice affects Electronic Navigational Chart: CA476664 — *(F2015033) LL(438) DFO(6307385-01)*

31-JUL-2015 — LNM/D. 06-FEB-2015

Delete submarine cable — between 44°19′44.0″N 064°16′44.0″W and 44°18′56.6″N 064°10′22.2″W
(See Chart No. 1, L30.1)
This notice affects Electronic Navigational Chart: CA476664 — *DFO(6307178-01)*

06-FEB-2015 — LNM/D. 28-NOV-2014

Amend FG to read LFlG against light — 44°20′59.2″N 064°12′15.0″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA476664 — *(F2014039) LL(444) DFO(6306999-01)*

28-NOV-2014 — LNM/D. 12-SEP-2014

Add depth of 4 metres, 6 decimetres — 44°16′56.5″N 064°20′49.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 — *DFO(6306969-01)*

28-NOV-2014 — LNM/D. 12-SEP-2014

Chart no. 4384

Delete depth of 6 metres, 1 decimetre 44°16′54.7″N 064°20′47.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-02)*

28-NOV-2014 LNM/D. 12-SEP-2014

Delete depth of 5 metres, 2 decimetres 44°16′35.7″N 064°20′38.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-03)*

28-NOV-2014 LNM/D. 12-SEP-2014

Add depth of 3 metres, 8 decimetres 44°16′33.0″N 064°20′37.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-04)*

28-NOV-2014 LNM/D. 12-SEP-2014

Delete depth of 6 metres, 7 decimetres 44°16′34.4″N 064°20′50.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-05)*

28-NOV-2014 LNM/D. 12-SEP-2014

Add depth of 5 metres, 6 decimetres 44°16′32.5″N 064°20′50.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-06)*

28-NOV-2014 LNM/D. 12-SEP-2014

Delete depth of 7 metres, 6 decimetres 44°16′31.3″N 064°20′42.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276801 *DFO(6306969-07)*

28-NOV-2014 LNM/D. 12-SEP-2014

Add depth of 2 metres, 5 decimetres 44°16′26.2″N 064°20′58.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-08)*

28-NOV-2014 LNM/D. 12-SEP-2014

Delete depth of 4 metres, 6 decimetres 44°16′26.3″N 064°21′01.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-09)*

Chart no. 4384

28-NOV-2014 LNM/D. 12-SEP-2014

Delete depth of 4 mètres, 6 décimètres 44°16′23.8″N 064°20′57.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-10)*

28-NOV-2014 LNM/D. 12-SEP-2014

Add depth of 3 metres, 7 decimetres 44°16′13.2″N 064°20′40.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-11)*

28-NOV-2014 LNM/D. 12-SEP-2014

Delete depth of 4 metres, 9 decimetres 44°16′11.6″N 064°20′36.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-12)*

28-NOV-2014 LNM/D. 12-SEP-2014

Add depth of 4 metres, 3 decimetres 44°16′15.0″N 064°21′20.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-13)*

28-NOV-2014 LNM/D. 12-SEP-2014

Replace depth of 5 metres, 5 decimetres with depth of 3 metres, 8 decimetres 44°16′16.0″N 064°21′25.9″W
(See Chart No. 1, I10) *DFO(6306969-14)*
This notice affects Electronic Navigational Chart: CA476664

28-NOV-2014 LNM/D. 12-SEP-2014

Delete depth of 4 metres 44°16′04.9″N 064°21′38.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-15)*

28-NOV-2014 LNM/D. 12-SEP-2014

Add depth of 1 metre, 7 decimetres 44°16′02.9″N 064°21′38.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-16)*

28-NOV-2014 LNM/D. 12-SEP-2014

Chart no. 4384

Delete depth of 6 metres, 4 decimetres 44°16′38.1″N 064°20′43.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-18)*

28-NOV-2014 LNM/D. 12-SEP-2014

Delete depth of 6 metres, 1 decimetre 44°16′41.5″N 064°20′49.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-19)*

28-NOV-2014 LNM/D. 12-SEP-2014

Add depth of 4 metres, 9 decimetres 44°16′41.8″N 064°20′44.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476664 *DFO(6306969-20)*

12-SEP-2014 LNM/D. 28-FEB-2014

Delete pilot boarding station 44°22′01.0″N 064°08′57.0″W
(See Chart No. 1, T1.1)
This notice affects Electronic Navigational Chart: CA476199 *DFO(6306826-01)*

28-FEB-2014 LNM/D. 23-AUG-2013

Amend FR to read Iso R 4s against light 44°21′37.0″N 064°17′46.7″W
(See Chart No 1 P16)
This notice affects Electronic Navigational Chart: CA476664 *(F2014001) LL(438) DFO(6306672-01)*

23-AUG-2013 LNM/D. 23-NOV-2012

Add rock which covers and uncovers with drying height of 1 metre, 5 decimetres 44°22′53.0″N 064°11′51.0″W
(See Chart No. 1, K11) *DFO(6306466-01)*
This notice affects Electronic Navigational Chart: CA476199, CA476664

23-AUG-2013 LNM/D. 23-NOV-2012

Add rock with known depth of 1 metre, 4 decimetres outside the corresponding depth area, dangerous to surface navigation 44°22′49.5″N 064°12′00.1″W
(See Chart No. 1, K14/K14.2) *DFO(6306466-02)*
This notice affects Electronic Navigational Chart: CA476199, CA476664

Chart no. 4384

23-AUG-2013 LNM/D. 23-NOV-2012

Add rock with known depth of 1 metre, 8 decimetres outside the corresponding depth area, dangerous to surface navigation 44°21′51.9″N 064°11′47.5″W
(See Chart No. 1, K14/K14.2)
This notice affects Electronic Navigational Chart: CA476199, CA476664

DFO(6306466-03)

23-NOV-2012 LNM/D. 20-MAY-2011

Reposition green port hand spar buoy, marked EC51 from 44°21′01.1″N 064°11′58.9″W
(See Chart No. 1, Qg) to 44°21′03.1″N 064°11′59.8″W

(F2012051) DFO(6306229-01)

20-MAY-2011 LNM/D. 13-MAY-2011

Delete depth of 8 metres, 5 decimetres 44°09′40.2″N 064°28′34.8″W
(See Chart No. 1, I10)

DFO(6305440-01)

This notice affects Electronic Navigational Chart: CA476664

20-MAY-2011 LNM/D. 13-MAY-2011

Delete depth of 3 metres, 4 decimetres 44°09′39.2″N 064°28′43.0″W
(See Chart No. 1, I10)

DFO(6305440-02)

This notice affects Electronic Navigational Chart: CA476664

20-MAY-2011 LNM/D. 13-MAY-2011

Add depth of 1 metre, 1 decimetre 44°09′40.4″N 064°28′40.3″W
(See Chart No. 1, I10)

DFO(6305440-03)

This notice affects Electronic Navigational Chart: CA476664

20-MAY-2011 LNM/D. 13-MAY-2011

Add depth of 0 metres, 6 decimetres 44°09′35.1″N 064°28′41.4″W
(See Chart No. 1, I10)

DFO(6305440-04)

This notice affects Electronic Navigational Chart: CA476664

Chart no. 4384

13-MAY-2011 LNM/D. 04-JUN-2010

Delete depth of 5 metres, 2 decimetres 44°14′32.1″N 064°22′15.4″W
(See Chart No. 1, I10)

DFO(6305432-06)

This notice affects Electronic Navigational Chart: CA476664

13-MAY-2011 LNM/D. 04-JUN-2010

Delete depth of 2 metres, 7 decimetres 44°14′06.0″N 064°22′04.0″W
(See Chart No. 1, I10)

DFO(6305432-07)

This notice affects Electronic Navigational Chart: CA476664

13-MAY-2011 LNM/D. 04-JUN-2010

Delete depth of 5 metres, 5 decimetres 44°13′51.5″N 064°22′27.2″W
(See Chart No. 1, I10)

DFO(6305432-11)

This notice affects Electronic Navigational Chart: CA476664

13-MAY-2011 LNM/D. 04-JUN-2010

Add depth of 3 metres, 7 decimetres 44°13′35.0″N 064°22′47.6″W
(See Chart No. 1, I10)

DFO(6305432-12)

This notice affects Electronic Navigational Chart: CA476664

13-MAY-2011 LNM/D. 04-JUN-2010

Add depth of 3 metres 44°14′31.6″N 064°22′14.6″W
(See Chart No. 1, I10)

DFO(6305432-14)

This notice affects Electronic Navigational Chart: CA476664

13-MAY-2011 LNM/D. 04-JUN-2010

Add depth of 1 metre, 5 decimetres 44°14′05.9″N 064°22′04.2″W
(See Chart No. 1, I10)

DFO(6305432-15)

This notice affects Electronic Navigational Chart: CA476664

Chart no. 4384

13-MAY-2011 LNM/D. 04-JUN-2010

Add depth of 4 metres, 3 decimetres 44°14′47.2″N 064°21′55.5″W
(See Chart No. 1, I10)

DFO(6305432-16)

This notice affects Electronic Navigational Chart: CA476664

13-MAY-2011 LNM/D. 04-JUN-2010

Add depth of 3 metres 44°13′53.2″N 064°22′25.6″W
(See Chart No. 1, I10)

DFO(6305432-17)

This notice affects Electronic Navigational Chart: CA476664

04-JUN-2010 LNM/D. 05-MAR-2010

Amend Fl 10s 25m 13M to read Fl 10s 25m 10M against light 44°18′43.7″N 064°10′06.4″W
(See Chart 1 P16)

LL(443) DFO(6304833-01)

This notice affects Electronic Navigational Chart: CA176140, CA476664

05-MAR-2010 LNM/D. 01-MAY-2009

Amend FG (Occas) FogSig to read Iso G FogSig against light 44°09′32.0″N 064°28′51.0″W
(See Chart No 1 P10.3) *(F2010004) LL(417.5) DFO(6304737-01)*

This notice affects Electronic Navigational Chart: CA476664

01-MAY-2009 LNM/D. 22-AUG-2008

Amend FR to read Fl against light 44°16′01.2″N 064°21′50.2″W
(See Chart No 1 P16)

(F2009004) LL(428) DFO(6304319-01)

This notice affects Electronic Navigational Chart: CA476664

22-AUG-2008 LNM/D. 21-DEC-2007

Chart no. 4384

Add black, red and black isolated danger lighted spar buoy Fl (2) 5s, marked EF
(See Chart No 1 Q130.4) — 44°19′56.5″N 064°13′22.6″W
(F2008029) LL(435.5) DFO(6303914-01)

21-DEC-2007 — LNM/D. 21-SEP-2007

Add light FlG against green port hand spar buoy, marked TU53
(See Chart No 1, Qg) — 44°09′36.8″N 064°28′40.3″W
(F2007094) LL(417.81) DFO(6303692-01)

21-DEC-2007 — LNM/D. 21-SEP-2007

Add red starboard hand lighted spar buoy FlR, marked TU54
(See Chart No 1, Qf) — 44°09′37.7″N 064°28′48.2″W
(F2007097) LL(419) DFO(6303705-01)

21-SEP-2007 — LNM/D. 27-OCT-2006

Delete green port hand lighted pillar bell buoy FlG, BELL, marked TU51 — 44°09′36.3″N 064°28′12.8″W
(F2007076) LL(417.8) DFO(6303623-01)

21-SEP-2007 — LNM/D. 27-OCT-2006

Add red and white fairway lighted pillar buoy Mo(A), marked TU — 44°09′36.3″N 064°28′17.8″W
(F2007077) LL(418) DFO(6303623-02)

27-OCT-2006 — LNM/D. 24-MAR-2006

Reposition green port hand spar buoy, marked TU53 — from 44°09′35.3″N 064°28′44.8″W to 44°09′36.8″N 064°28′40.3″W
(F2006132) LL(5417.81) DFO(6303095-01)

24-MAR-2006 — LNM/D. 05-MAR-2004

Add non-dangerous wreck 44°09′10.0″N 064°19′36.0″W
DFO(6302754-01)

05-MAR-2004 — LNM/D. 09-JAN-2004

Chart no. 4384

Add dangerous wreck, depth unknown 44°14′36.0″N 064°19′48.0″W

DFO(6301065-01)

09-JAN-2004

Delete legend ″FogSig (2) 60s″ 44°18′43.7″N 064°10′06.4″W

(F2003058) LL(443) DFO(6301102-01)