Chart no. 4425

4425 - Covehead Bay - New Edition - 01-NOV-2002 - NAD 1983

27-MAR-2020 LNM/D. 11-OCT-2019

Affix patch 46°25′40.0″N 063°08′30.0″W
PDF

DFO(6308841-01)

27-MAR-2020 LNM/D. 11-OCT-2019

Affix patch 46°24′30.0″N 063°07′30.0″W
PDF

DFO(6308841-02)

11-OCT-2019 LNM/D. 26-APR-2019

Replace depth of 4 feet with drying height of 1 foot 46°25′19.2″N 063°08′56.4″W
(See Chart No. 1, I10, I15)

DFO(6308731-04)

16-OCT-2009 LNM/D. 12-SEP-2008

Delete front range/leading light QG 57ft 46°25′28.5″N 063°08′53.4″W
(See Chart No 1 P20.2)

(G2009129) LL(1052) DFO(6304597-01)

16-OCT-2009 LNM/D. 12-SEP-2008

Delete rear range/leading light Iso G 4sec 72ft with leading line 46°25′26.6″N 063°08′54.1″W
(See Chart No 1 P20.2)

(G2009130) LL(1053) DFO(6304597-02)

14-MAR-2008 LNM/D. 28-DEC-2007

Replace green port hand lighted pillar bell buoy FlG, marked JJ1 with red and white fairway lighted spar buoy Mo(A), marked JJ 46°26′54.2″N 063°08′18.7″W
(See Chart No 1 Qg and Qh)

(G2007055) LL(1050) DFO(6303464-01)

4425 - Entrance to / Entrée à St.Peters Bay - New Edition - 01-NOV-2002 - NAD 1983

12-SEP-2008 LNM/D. 14-MAR-2008

Chart no. 4425

Add light Q G 46°25′59.7″N 062°42′46.5″W
(See Chart No 1 P1)
(G2008042) LL(1046.5) DFO(6303979-01)

14-DEC-2007 LNM/D. 29-JUN-2007
Delete front range/leading light QR 20ft 46°26′29.4″N 062°44′25.0″W
(See Chart No 1Pe)
(G2007145) LL(1045) DFO(6303661-01)

14-DEC-2007 LNM/D. 29-JUN-2007
Delete rear range/leading light Iso R 41ft with leading line and legend See CAUTION/Voir ATTENTION 46°26′15.8″N 062°44′13.5″W
(See Chart No 1Pe) *(G2007147) LL(1046) DFO(6303661-02)*

4425 - Harbours on the North Shore / Hâvres sur la Côte Nord - New Edition - 01-NOV-2002 - NAD 1983

08-MAR-2019 LNM/D. 06-JAN-2017
Amend ′1.6 feet (0.5 metres)′ to read ′0.9 feet (0.3 metres)′ against the note ′DEPTHS/LES PROFONDEURS′ Title block of chart: Depths
(See Chart No. 1, A13) *DFO(6308577-02)*

4425 - Savage Harbour - New Edition - 01-NOV-2002 - NAD 1983

11-OCT-2019 LNM/D. 26-APR-2019
Replace depth of 3 feet with drying height of 1 foot 46°25′46.8″N 062°50′13.8″W
(See Chart No. 1, I10, I15)
DFO(6308731-05)

11-OCT-2019 LNM/D. 26-APR-2019
Replace depth of 4 feet with drying height of 0 feet 46°25′31.8″N 062°50′20.4″W
(See Chart No. 1, I10, I15)
DFO(6308731-06)

28-SEP-2012 LNM/D. 14-SEP-2012

Chart no. 4425

Add marine farm 46°25′00.0″N 062°49′36.9″W
(See Chart No. 1, K48.2)
DFO(6306169-01)

04-MAR-2011 LNM/D. 26-NOV-2010

Delete green port hand lighted pillar buoy FlG, marked JE9 46°25′44.5″N 062°50′05.0″W
(See Chart No. 1, Qg)
LL(1047.028) DFO(6305265-01)

26-NOV-2010 LNM/D. 16-OCT-2009

Add green port hand lighted pillar buoy FlG, marked JE9 46°25′44.5″N 062°50′05.0″W
(See Chart No. 1, Qg) *(G2010176) LL(1047.028) DFO(6305116-01)*

14-MAR-2008 LNM/D. 28-DEC-2007

Replace red starboard hand lighted pillar bell buoy FlR, marked JE2 with red and white fairway lighted spar buoy Mo(A), marked JE 46°26′46.2″N 062°49′29.6″W
(See Chart No 1 Qf and Qh) *(G2007063) LL(1046.8) DFO(6303472-01)*

18-JUL-2003

Delete legend ″FlR″ 46°25′54.0″N 062°50′04.0″W

DFO(6300940-01)

4425 - St. Peters Bay - New Edition - 01-NOV-2002 - NAD 1983

09-JUL-2021 LNM/D. 23-APR-2021

Reposition red and white fairway lighted pillar buoy Mo(A), marked JD from 46°27′09.2″N 062°44′21.6″W to 46°27′31.9″N 062°44′21.1″W
(See Chart No. 1, Qh)
This notice affects Electronic Navigational Chart: CA276286 *(G2021034) LL(1043.1) DFO(6309466-01)*

26-APR-2019 LNM/D. 08-MAR-2019

Chart no. 4425

Add legend See CAUTION/Voir ATTENTION 46°27′24.0″N 062°44′30.0″W

DFO(6308569-03)

12-SEP-2008 LNM/D. 14-MAR-2008

Add light Q G 46°25′59.7″N 062°42′46.5″W
(See Chart No 1 P1)

(G2008042) LL(1046.5) DFO(6303979-01)

14-MAR-2008 LNM/D. 28-DEC-2007

Replace red and white fairway spherical buoy, marked JD with red and white fairway lighted spar buoy Mo(A), marked JD 46°27′09.2″N 062°44′21.6″W
(See Chart No 1 Qh)

(G2007073) LL(1043.1) DFO(6303516-01)

28-DEC-2007 LNM/D. 14-DEC-2007

Delete light Fl 46°26′30.9″N 062°44′51.3″W
(See Chart No 1 P16)

(G2007172) LL(1044) DFO(6303735-01)

14-DEC-2007 LNM/D. 29-JUN-2007

Delete front range/leading light QR 20ft 46°26′29.4″N 062°44′25.0″W
(See Chart No 1Pe)

(G2007145) LL(1045) DFO(6303661-01)

14-DEC-2007 LNM/D. 29-JUN-2007

Delete rear range/leading light Iso R 41ft with leading line and legend See CAUTION/Voir ATTENTION 46°26′15.8″N 062°44′13.5″W
(See Chart No 1Pe)

(G2007147) LL(1046) DFO(6303661-02)

29-JUN-2007 LNM/D. 18-JUL-2003

Delete green port hand lighted pillar bell buoy FlG, marked JD1 46°28′05.2″N 062°44′12.6″W

(G2007050) LL(1043) DFO(6303461-01)

Chart no. 4425

4425 - Tracadie Bay - New Edition - 01-NOV-2002 - NAD 1983

23-APR-2021 LNM/D. 23-OCT-2020

Affix patch 46°24′42.0″N 063°01′09.0″W
PDF

DFO(6309420-01)

23-OCT-2020 LNM/D. 27-MAR-2020

Replace depth of 5 feet with drying height of 1 foot 46°21′51.6″N 062°59′24.0″W
(See Chart No. 1, I10, I15)

DFO(6309145-01)

23-OCT-2020 LNM/D. 27-MAR-2020

Replace depth of 6 feet with depth of 4 feet 46°22′48.0″N 063°01′27.7″W
(See Chart No. 1, I10)

DFO(6309145-02)

23-OCT-2020 LNM/D. 27-MAR-2020

Delete depth of 10 feet 46°24′46.8″N 062°59′24.6″W
(See Chart No. 1, I10)

DFO(6309145-03)

23-OCT-2020 LNM/D. 27-MAR-2020

Add depth of 7 feet 46°24′46.4″N 062°59′22.1″W
(See Chart No. 1, I10)

DFO(6309145-04)

23-OCT-2020 LNM/D. 27-MAR-2020

Delete depth of 1 foot 46°24′45.7″N 063°02′24.5″W
(See Chart No. 1, I10)

DFO(6309145-05)

23-OCT-2020 LNM/D. 27-MAR-2020

Add drying height of 4 feet 46°24′47.2″N 063°02′24.4″W
(See Chart No. 1, I15)

DFO(6309145-06)

23-OCT-2020 LNM/D. 27-MAR-2020

Chart no. 4425

Delete depth of 9 feet 46°24′58.8″N 063°02′30.6″W
(See Chart No. 1, I10)
DFO(6309145-07)

23-OCT-2020 LNM/D. 27-MAR-2020
Add depth of 2 feet 46°25′00.2″N 063°02′30.5″W
(See Chart No. 1, I10)
DFO(6309145-08)

23-OCT-2020 LNM/D. 27-MAR-2020
Add depth of 3 feet 46°24′16.7″N 062°58′44.9″W
(See Chart No. 1, I10)
DFO(6309145-09)

11-OCT-2019 LNM/D. 26-APR-2019
Replace depth of 15 feet with drying height of 0 feet 46°24′40.8″N 063°02′24.6″W
(See Chart No. 1, I10, I15)
DFO(6308731-07)

11-OCT-2019 LNM/D. 26-APR-2019
Replace depth of 9 feet with drying height of 0 feet 46°24′56.6″N 063°02′26.5″W
(See Chart No. 1, I10, I15)
DFO(6308731-08)

11-OCT-2019 LNM/D. 26-APR-2019
Replace depth of 23 feet with depth of 3 feet 46°24′47.2″N 063°00′33.0″W
(See Chart No. 1, I10)
DFO(6308731-09)

11-OCT-2019 LNM/D. 26-APR-2019
Delete dredged area with depth of 6 feet (1976) 46°24′33.5″N 063°01′47.9″W
(See Chart No. 1, I22)
DFO(6308731-10)

11-OCT-2019 LNM/D. 26-APR-2019
Add drying height of 1 foot 46°24′32.4″N 063°01′46.8″W
(See Chart No. 1, I15)
DFO(6308731-11)

Chart no. 4425

26-APR-2019 LNM/D. 08-MAR-2019

Reposition legend Channel Buoyed/Chenal balisé from 46°25′17.0″N 063°02′15.0″W
to 46°25′09.0″N 063°00′40.0″W

DFO(6308569-01)

26-APR-2019 LNM/D. 08-MAR-2019

Add legend See CAUTION/Voir ATTENTION 46°25′12.0″N 063°01′26.0″W

DFO(6308569-02)

06-JAN-2017 LNM/D. 22-JUL-2016

Delete light FlR 46°24′14.3″N 063°01′41.0″W
(See Chart No. 1, P1)

(G2016131) LL(1049.8) DFO(6307724-01)

22-JUL-2016 LNM/D. 04-DEC-2015

Add red starboard hand lighted conical buoy FlR, marked JH2 46°25′09.6″N 063°01′01.8″W
(See Chart No. 1, Qf)

(G2016054) LL(1049.121) DFO(6307563-01)

22-JUL-2016 LNM/D. 04-DEC-2015

Add green port hand lighted can buoy FlG, marked JH1 46°25′10.2″N 063°00′58.2″W
(See Chart No. 1, Qg)

(G2016071) LL(1049.11) DFO(6307563-02)

22-JUL-2016 LNM/D. 04-DEC-2015

Add Channel Buoyed/Chenal balisé 46°24′02.4″N 063°01′03.0″W

DFO(6307563-03)

04-DEC-2015 LNM/D. 30-NOV-2012

Add marine farm 46°23′27.0″N 062°59′42.0″W
(See Chart No. 1, K48.2)

DFO(6307344-01)

30-NOV-2012 LNM/D. 28-SEP-2012

Chart no. 4425

Add marine farm 46°24′41.1″N 062°59′41.0″W
(See Chart No. 1, K48.2)
DFO(6306233-01)

14-SEP-2012 LNM/D. 04-MAR-2011

Delete front range/leading light Iso R 20ft 46°24′34.9″N 063°02′29.5″W
(See Chart No. 1, P20.2)
(G2012166) LL(1048) DFO(6306160-01)

This notice affects Electronic Navigational Chart:
CA276286

14-SEP-2012 LNM/D. 04-MAR-2011

Delete rear range/leading light Iso R 35ft with leading line and legend See CAUTION/Voir ATTENTION 46°24′31.2″N 063°02′30.0″W
(See Chart No. 1, P20.2) *(G2012168) LL(1049) DFO(6306161-01)*

This notice affects Electronic Navigational Chart:
CA276286

14-MAR-2008 LNM/D. 28-DEC-2007

Replace green port hand lighted pillar bell buoy FlG, marked JH1 with red and white fairway lighted spar buoy Mo(A), marked JH 46°26′03.2″N 063°02′01.6″W
(See Chart No 1 Qg and Qh) *(G2007053) LL(1047.5) DFO(6303462-01)*