Chart no. 4449

4449 - Chéticamp Harbour - New Edition - 03-JUL-1998 - NAD 1983

05-JAN-2018 LNM/D. 27-OCT-2017

Affix patch 46°38′00.0″N 061°00′00.0″W
PDF

DFO(6308055-01)

27-OCT-2017 LNM/D. 26-FEB-2016

Affix patch Located to the right of the Firing Practice and Exercise Areas note and below the Source Class Diagram.
PDF

DFO(6308099-05)

05-DEC-2014 LNM/D. 17-OCT-2014

Delete Sector light FRWG 10m, and limits of arcs of visibility. 46°37′47.4″N 061°00′46.2″W
(See Chart No. 1, P40.1)

(G2014200) LL(866.75) DFO(6307006-01)

17-OCT-2014 LNM/D. 14-JUN-2013

Replace red starboard hand lighted pillar buoy FlR, marked VD8 with red starboard hand lighted spar buoy FlR, marked VD8 46°38′32.4″N 061°00′34.8″W
(See Chart No. 1, Qf)

(G2014101) LL(866.1) DFO(6306865-01)

17-OCT-2014 LNM/D. 14-JUN-2013

Replace green port hand lighted pillar buoy FlG, marked VD9 with green port hand lighted spar buoy QG, marked VD9 46°38′32.2″N 061°00′33.5″W
(See Chart No. 1, Qg)

(G2014102) LL(866.2) DFO(6306865-02)

17-OCT-2014 LNM/D. 14-JUN-2013

Delete green port hand spar buoy, marked VD13 46°38′19.5″N 061°00′36.9″W
(See Chart No. 1, Qg)

(G2014129) DFO(6306865-03)

17-OCT-2014 LNM/D. 14-JUN-2013

Add green port hand lighted spar buoy QG, marked VD13 46°38′19.5″N 061°00′36.9″W
(See Chart No. 1, Qg)

(G2014104) LL(866.4) DFO(6306865-04)

Chart no. 4449

17-OCT-2014 LNM/D. 14-JUN-2013

Replace red starboard hand lighted pillar buoy FlR, marked VD14 with red starboard hand lighted spar buoy FlR, marked VD14 46°38′12.5″N 061°00′40.1″W
(See Chart No. 1, Qf) *(G2014130) LL(866.6) DFO(6306865-05)*

17-OCT-2014 LNM/D. 14-JUN-2013

Replace green port hand lighted pillar buoy FlG, marked VD15 with green port hand lighted spar buoy QG, marked VD15 46°38′13.1″N 061°00′38.9″W
(See Chart No. 1, Qg) *(G2014131) LL(866.5) DFO(6306865-06)*

17-OCT-2014 LNM/D. 14-JUN-2013

Delete green port hand lighted pillar buoy FlG, marked VD19 46°37′49.2″N 061°00′49.3″W
(See Chart No. 1, Qg) *(G2014132) LL(866.7) DFO(6306865-07)*

17-OCT-2014 LNM/D. 14-JUN-2013

Delete red Starboard hand lighted pillar buoy FlR, marked VD20 46°37′28.5″N 061°01′16.1″W
(See Chart No. 1, Qf) *(G2014133) LL(866.8) DFO(6306892-01)*

17-OCT-2014 LNM/D. 14-JUN-2013

Delete green port hand lighted pillar buoy FlG, marked VD21 46°37′02.3″N 061°01′27.3″W
(See Chart No. 1, Qg) *(G2014134) LL(866.9) DFO(6306892-02)*

17-OCT-2014 LNM/D. 14-JUN-2013

Delete red starboard hand lighted pillar buoy FlR, marked VD22 46°36′18.3″N 061°01′48.3″W
(See Chart No. 1, Qf) *(G2014135) LL(866.95) DFO(6306892-03)*

17-OCT-2014 LNM/D. 14-JUN-2013

Delete red starboard hand spar buoy, marked VD14.2 46°37′35.3″N 061°01′13.3″W
(See Chart No. 1, Qf)
(G2014136) DFO(6306892-04)

17-OCT-2014 LNM/D. 14-JUN-2013

Chart no. 4449

Delete red starboard hand spar buoy, marked VD10 46°38′25.8″N 061°00′36.5″W
(See Chart No. 1, Qf)
(G2014138) DFO(6306892-05)

17-OCT-2014 LNM/D. 14-JUN-2013

Add red starboard hand lighted spar buoy FlR, marked VD10 46°38′25.8″N 061°00′36.5″W
(See Chart No. 1, Qf) *(G2014137) LL(866.3) DFO(6306892-06)*

14-JUN-2013 LNM/D. 10-FEB-2012

Reposition Green Port hand lighted pillar buoy FlG, marked VD9 from 46°38′32.2″N 061°00′32.8″W to 46°38′32.2″N 061°00′33.5″W
(See Chart No. 1, Qg)
(G2013022) LL(866.2) DFO(6306373-01)

14-JUN-2013 LNM/D. 10-FEB-2012

Delete green port hand lighted pillar buoy FlG, marked VD13 46°38′12.6″N 061°00′38.3″W
(See Chart No. 1, Qg) *(G2013023) LL(866.5) DFO(6306374-01)*

14-JUN-2013 LNM/D. 10-FEB-2012

Add green port hand lighted pillar buoy FlG, marked VD15 46°38′13.1″N 061°00′38.9″W
(See Chart No. 1, Qg) *(G2013023) LL(866.5) DFO(6306374-02)*

14-JUN-2013 LNM/D. 10-FEB-2012

Add red starboard hand spar buoy, marked VD10 (See Chart No. 1, Qf) 46°38′25.8″N 061°00′36.5″W
(G2013025) DFO(6306376-01)

14-JUN-2013 LNM/D. 10-FEB-2012

Add green port hand spar buoy marked VD11 46°38′25.8″N 061°00′35.2″W
(See Chart No. 1, Qg)
(G2013026) DFO(6306377-01)

14-JUN-2013 LNM/D. 10-FEB-2012

Add red starboard hand spar buoy, marked VD12 46°38′19.7″N 061°00′38.2″W
(See Chart No. 1, Qf)
(G2013027) DFO(6306378-01)

Chart no. 4449

14-JUN-2013 LNM/D. 10-FEB-2012

Add green port hand spar buoy, marked VD13 46°38′19.5″N 061°00′36.9″W
(See Chart No. 1, Qg)

(G2013028) DFO(6306379-01)

10-FEB-2012 LNM/D. 27-NOV-2009

Delete legend Fog Sig 30s against light 46°38′58.4″N 061°01′35.2″W
(See Chart No. 1, R1, R20)

(G2012002) LL(867) DFO(6305909-01)

27-AUG-2004 LNM/D. 11-JUN-2004

Amend FY to read FlR against light 46°36′10.5″N 061°03′11.3″W

(G2004137) LL(868) DFO(6301774-01)

11-JUN-2004

Delete red starboard hand spar buoy, marked VD16 46°36′55.3″N 061°01′34.3″W

(G2004076) DFO(6301453-01)

4449 - Grand Etang Harbour - New Edition - 03-JUL-1998 - NAD 1983

26-FEB-2016 LNM/D. 18-SEP-2015

Amend FlY 10m to read OcY 10s10m16M against light 46°32′54.1″N 061°02′31.4″W
(See Chart No. 1, P16)

(G2016001) LL(869) DFO(6307443-01)

26-FEB-2016 LNM/D. 18-SEP-2015

Amend FlY 17m to read OcY 10s18m16M against light 46°32′50.0″N 061°02′24.3″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA276286 *(G2016002) LL(870.0) DFO(6307443-02)*

26-FEB-2016 LNM/D. 18-SEP-2015

Amend Fl to read Fl 4s 7M against light 46°32′54.1″N 061°02′31.4″W
(See Chart No. 1, P16)

LL(869) DFO(6307443-03)

Chart no. 4449

26-FEB-2016 LNM/D. 18-SEP-2015

Amend Fl to read Fl 4s7M against light 46°32′50.0″N 061°02′24.3″W
(See Chart No. 1, P16)

LL(870) DFO(6307443-04)

18-SEP-2015 LNM/D. 05-DEC-2014

Affix patch 46°33′00.0″N 061°02′40.0″W
PDF

DFO(6307252-01)

06-JAN-2006 LNM/D. 26-AUG-2005

Amend ″F R″ to read ″Q R″ against light 46°33′03.3″N 061°02′49.2″W

(G2005169) LL(868.6) DFO(6302621-01)

06-JAN-2006 LNM/D. 26-AUG-2005

Add light ″Q G″ 46°33′03.9″N 061°02′46.5″W

(G2005170) LL(868.5) DFO(6302622-01)

26-AUG-2005 LNM/D. 24-DEC-2004

Amend ″FY 10m″ to read ″Oc Y 10m″ against front range light 46°32′54.1″N 061°02′31.4″W

(G2005071) LL(869) DFO(6302418-01)

26-AUG-2005 LNM/D. 24-DEC-2004

Amend ″FY 17m″ to read ″Oc Y 17m″ against rear range light 46°32′50.0″N 061°02′24.3″W

(G2005070) LL(870) DFO(6302418-02)

4449 - Margaree Harbour - New Edition - 03-JUL-1998 - NAD 1983

29-OCT-2021 LNM/D. 28-DEC-2018

Reposition red starboard hand conical buoy, marked VH14 from 46°26′26.9″N 061°06′26.5″W
(See Chart No. 1, Qf) to 46°26′23.5″N 061°06′24.0″W

(G2021137) DFO(6309644-01)

Chart no. 4449

29-OCT-2021 LNM/D. 28-DEC-2018

Reposition red starboard hand conical buoy, marked VH16 from 46°26′25.2″N 061°06′25.1″W
(See Chart No. 1, Qf) to 46°26′19.2″N 061°06′21.8″W

(G2021138) DFO(6309645-01)

29-OCT-2021 LNM/D. 28-DEC-2018

Reposition red starboard hand conical buoy, marked VH10.2 from 46°26′27.1″N 061°06′36.2″W
(See Chart No. 1, Qf) to 46°26′27.4″N 061°06′35.2″W

(G2021140) DFO(6309647-01)

29-OCT-2021 LNM/D. 28-DEC-2018

Reposition red starboard hand lighted pillar buoy Fl R, marked VH8 from 46°26′29.2″N 061°06′47.3″W
(See Chart No. 1, Qf) to 46°26′29.1″N 061°06′46.8″W

(G2021141) LL(873.1) DFO(6309648-01)

28-DEC-2018 LNM/D. 05-JAN-2018

Affix patch 46°26′40.0″N 061°06′40.0″W
PDF

DFO(6308540-01)

27-NOV-2009 LNM/D. 06-JAN-2006

Reposition green port hand lighted pillar buoy QG, marked VH11 from 46°26′31.3″N 061°06′32.3″W
(See Chart No 1 Qg) to 46°26′30.9″N 061°06′30.3″W

(G2009135) LL(873.23) DFO(6304604-01)

27-NOV-2009 LNM/D. 06-JAN-2006

Add green port hand can buoy, marked VH9/1 46°26′29.1″N 061°06′34.8″W
(See Chart No 1 Qg)

(G2009136) DFO(6304605-01)

24-DEC-2004 LNM/D. 27-AUG-2004

Amend Fl to read FlG against light 46°26′34.4″N 061°06′47.7″W

(G2004182) LL(873.2) DFO(6302062-01)

Chart no. 4449