Canadian Coast Guard | Garde côtière canadienne

Chart no. 4642

4642 - Great St. Lawrence Harbour - New Edition - 08-NOV-2002 - NAD 1983

22-AUG-2025 LNM/D. 10-JAN-2025

Delete wreck showing a portion of superstructure, with legend PA 46°55′00.2″N 055°23′12.5″W
(See Chart 1, K24, B7)

DFO(6312035-01)

05-JUL-2024 LNM/D. 15-SEP-2023

Delete light Fl R 46°55′39.8″N 055°21′46.0″W
(See Chart 1, P1)

(N2024056) LL(73.3) DFO(6311182-01)

19-NOV-2021 LNM/D. 11-OCT-2019

Add wreck showing a portion of superstructure, with legend PA 46°55′00.2″N 055°23′12.5″W
(See Chart No. 1, K24, B7)

DFO(6309740-01)

18-MAR-2011 LNM/D. 26-FEB-2010

Delete circular radiobeacon with legend R 46°55′41.8″N 055°22′46.6″W
(See Chart No 1 S15)

DFO(6305286-01)

26-FEB-2010 LNM/D. 19-FEB-2010

Amend Fl 15s 88ft 11M to read Fl 15s 88ft 17M against light 46°53′52.8″N 055°20′51.2″W
(See Chart No 1 P16)

LL(73) DFO(6304696-01)

This notice affects Electronic Navigational Chart: CA276091

19-FEB-2010 LNM/D. 06-NOV-2009

Delete coastline between 46°55′41.3″N 055°21′41.4″W
(See Chart 1 C1) and 46°55′41.8″N 055°21′41.9″W

DFO(6304606-01)

19-FEB-2010 LNM/D. 06-NOV-2009

Add wharf joining 46°55′41.3″N 055°21′41.4″W
(See Chart No 1 F14) 46°55′39.8″N 055°21′46.0″W
46°55′40.4″N 055°21′46.5″W
and 46°55′41.8″N 055°21′41.9″W

DFO(6304606-03)

Chart no. 4642

19-FEB-2010 LNM/D. 06-NOV-2009

Add light FlR 46°55′39.8″N 055°21′46.0″W
(See Chart No 1 P1)
(N2009043) LL(73.3) DFO(6304606-04)

4642 - Great St. Lawrence Harbour: Inner Portion / Partie Intérieure - New Edition - 08-NOV-2002 - NAD 1983

22-AUG-2025 LNM/D. 10-JAN-2025

Delete wreck showing a portion of superstructure, with legend PA 46°55′00.3″N 055°23′12.4″W
(See Chart 1, K24, B7)
DFO(6312035-01)

19-NOV-2021 LNM/D. 11-OCT-2019

Add wreck showing a portion of superstructure, with legend PA 46°55′00.2″N 055°23′12.5″W
(See Chart No. 1, K24, B7)
DFO(6309740-01)

4642 - Lamaline Harbour - New Edition - 08-NOV-2002 - NAD 1983

10-JAN-2025 LNM/D. 16-AUG-2024

Delete green port hand lighted spar buoy QG, marked PAG1 46°50′28.5″N 055°44′36.2″W
(See Chart 1, Qc) *(N2024152) LL(75.54) DFO(6311486-01)*

10-JAN-2025 LNM/D. 16-AUG-2024

Delete green port hand lighted spar buoy Fl G, marked PAG3 46°50′56.8″N 055°44′23.2″W
(See Chart 1, Qc) *(N2024153) LL(75.53) DFO(6311487-01)*

16-AUG-2024 LNM/D. 05-JUL-2024

Delete red starboard hand lighted spar buoy Fl R, marked PG4 46°51′21.1″N 055°49′55.0″W
(See Chart 1, Qb) *(N2024118) LL(78.3) DFO(6311321-01)*

05-JUL-2024 LNM/D. 15-SEP-2023

Delete green port hand lighted spar buoy Fl G, marked PG3 46°51′24.3″N 055°50′00.3″W
(See Chart 1, Qc) *(N2024061) LL(78.35) DFO(6311206-01)*

Chart no. 4642

05-JUL-2024 LNM/D. 15-SEP-2023

Delete red starboard hand lighted spar buoy Fl R, marked PG2 46°51′03.8″N 055°50′13.9″W
(See Chart 1, Qb) *(N2024063) LL(78.5) DFO(6311207-01)*

15-SEP-2023 LNM/D. 06-MAY-2022

Delete fog signal, marked Fog Sig 46°51′27.5″N 055°44′36.1″W
(See Chart 1, R1)
This notice affects Electronic Navigational Chart: CA376164 *(N2023086) DFO(6310738-01)*

06-MAY-2022 LNM/D. 08-APR-2022

Amend FlG to read Q G against green port hand lighted spar buoy, marked PL1 46°51′08.0″N 055°47′31.8″W
(See Chart No. 1, Qg) *(N2022051) LL(78.12) DFO(6310075-01)*

08-APR-2022 LNM/D. 25-FEB-2022

Amend Fl G to read Q G against green port lighted spar buoy, marked PL5 46°51′42.5″N 055°47′53.1″W
(See Chart No. 1, Qg) *(N2022039) LL(78.13) DFO(6310042-01)*

25-FEB-2022 LNM/D. 19-NOV-2021

Amend FlR to read Q R against red starboard hand lighted spar buoy, marked PL2 46°51′07.8″N 055°47′25.2″W
(See Chart No. 1, Qf) *(N2021267) LL(78.1) DFO(6309999-01)*

11-OCT-2019 LNM/D. 06-SEP-2019

Amend Fl4s64ft12M to read Fl 4s64ft16M against light 46°50′48.2″N 055°47′51.3″W
(See Chart No. 1, P16)
LL(76.0) DFO(6308728-03)

06-SEP-2019 LNM/D. 11-JAN-2019

Delete green port hand lighted can buoy FlG, marked PN1 46°50′37.4″N 055°48′45.7″W
(See Chart No. 1, Qg) *(N2019044P) LL(78.2) DFO(6308733-01)*

11-JAN-2019 LNM/D. 05-DEC-2014

Chart no. 4642

Add submarine cable joining 46°48′53.5″N 055°50′43.9″W
(See Chart No. 1, L30.1) 46°49′09.7″N 055°50′22.5″W
This notice affects Electronic Navigational Chart: 46°49′36.0″N 055°50′00.0″W
CA376164 46°49′54.8″N 055°49′30.0″W
46°51′10.2″N 055°48′30.8″W
and 46°51′12.1″N 055°48′27.4″W

DFO(6308456-04)

05-DEC-2014 LNM/D. 25-APR-2014

Add legend Fog Sig 30s against light 46°50′48.0″N 055°47′51.5″W
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart: *(N2014079) LL(76) DFO(6307007-02)*
CA276091, CA376164

25-APR-2014 LNM/D. 18-MAR-2011

Delete legend Fog Sig 30s against light 46°50′48.0″N 055°47′51.5″W
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart: *(N2014020) LL(76) DFO(6306716-01)*
CA276091, CA376164

25-APR-2014 LNM/D. 18-MAR-2011

Delete legend Fog Sig 20s 46°51′06.8″N 055°49′39.2″W
(See Chart No. 1, R1, R20)
This notice affects Electronic Navigational Chart: *(N2014021) LL(78.51) DFO(6306716-02)*
CA376164

06-NOV-2009 LNM/D. 28-AUG-2009

Delete light FlG 46°51′22.4″N 055°48′20.3″W
(See Chart No 1 P1)

(N2009006) LL(75.52) DFO(6304354-01)

This notice affects Electronic Navigational Chart:
CA376164

06-NOV-2009 LNM/D. 28-AUG-2009

Add breakwater with legend Bkw joining 46°51′24.0″N 055°48′23.7″W
(See Chart 1 F4.1) 46°51′24.9″N 055°48′17.8″W
and 46°51′22.4″N 055°48′16.8″W

This notice affects Electronic Navigational Chart: *DFO(6304354-02)*
CA376164

Chart no. 4642

06-NOV-2009 LNM/D. 28-AUG-2009

Add light FlR 46°51′22.4″N 055°48′16.8″W
(See Chart No 1 P1)

(N2009006) LL(75.52) DFO(6304354-03)

This notice affects Electronic Navigational Chart:
CA376164

06-NOV-2009 LNM/D. 28-AUG-2009

Amend PL3/1 to read PL5 against green port hand lighted spar buoy FlG 46°51′42.5″N 055°47′53.1″W
(See Chart No 1 Q11) *(N2009044) LL(78.13) DFO(6304616-01)*

06-NOV-2009 LNM/D. 28-AUG-2009

Amend PL3 to read PL7 against green port hand lighted spar buoy FlG 46°51′35.1″N 055°48′13.3″W
(See Chart No 1 Q11) *(N2009045) LL(76.1) DFO(6304617-01)*

06-NOV-2009 LNM/D. 28-AUG-2009

Add red starboard hand lighted spar buoy FlR, marked PL4 46°51′32.3″N 055°47′39.9″W
(See Chart No 1 Qf) *(N2009046) LL(78.18) DFO(6304618-01)*

06-NOV-2009 LNM/D. 28-AUG-2009

Add green port hand lighted spar buoy FlG, marked PL3 46°51′27.8″N 055°47′41.1″W
(See Chart No 1 Qg)

(N2009047) LL(78.19) DFO(6304622-01)

28-AUG-2009 LNM/D. 14-OCT-2005

Delete green port hand lighted spar buoy FlG, marked PG5. 46°51′31.4″N 055°48′42.0″W
(See Chart No 1 Qg) *(N2009022) LL(78.36) DFO(6304521-01)*

14-OCT-2005 LNM/D. 20-AUG-2004

Amend legend ″PAG1″ to read ″PAG3″ against porthand buoy 46°50′56.8″N 055°44′23.2″W

(N2005062) LL(75.53) DFO(6302489-01)

Chart no. 4642

14-OCT-2005 LNM/D. 20-AUG-2004

Add green port hand lighted spar buoy QG, marked PAG1 46°50′28.4″N 055°44′36.2″W

(N2005063) LL(75.54) DFO(6302490-01)

20-AUG-2004 LNM/D. 25-JUN-2004

Delete red starboard hand spar light buoy FlR, marked PG4 46°51′09.8″N 055°49′53.2″W

(N2004113) LL(78.3) DFO(6301612-01)

20-AUG-2004 LNM/D. 25-JUN-2004

Add red starboard hand spar light buoy FlR, marked PG4 46°51′21.2″N 055°49′55.0″W

(N2004113) LL(78.3) DFO(6301612-02)

20-AUG-2004 LNM/D. 25-JUN-2004

Delete green port hand spar light buoy FlG, marked PL3/1 46°51′33.0″N 055°48′07.5″W

(N2004114) LL(78.13) DFO(6301618-01)

20-AUG-2004 LNM/D. 25-JUN-2004

Add green port hand spar light buoy FlG, marked PL3/1 46°51′42.5″N 055°47′53.1″W

(N2004114) LL(78.13) DFO(6301618-02)

20-AUG-2004 LNM/D. 25-JUN-2004

Delete green port hand spar light buoy FlG, marked PL3 46°51′39.8″N 055°47′50.2″W

(N2004115) LL(76.1) DFO(6301619-01)

20-AUG-2004 LNM/D. 25-JUN-2004

Add green port hand spar light buoy FlG, marked PL3 46°51′35.1″N 055°48′13.3″W

(N2004115) LL(76.1) DFO(6301619-02)

20-AUG-2004 LNM/D. 25-JUN-2004

Reposition red starboard hand spar light buoy FlR, marked PG2 from 46°51′06.8″N 055°50′12.2″W to 46°51′03.7″N 055°50′13.9″W

(N2004116) LL(78.5) DFO(6301622-01)

Chart no. 4642

20-AUG-2004 LNM/D. 25-JUN-2004

Delete green port hand spar light buoy FlG, marked PG3 46°51′20.8″N 055°49′56.2″W

(N2004117) LL(78.35) DFO(6301623-01)

20-AUG-2004 LNM/D. 25-JUN-2004

Add green port hand spar light buoy FlG, marked PG3 46°51′24.3″N 055°50′00.3″W

(N2004117) LL(78.35) DFO(6301623-02)

25-JUN-2004

Add green porthand spar light buoy, FlG, marked PL1 46°51′07.9″N 055°47′31.8″W

(N2004044) LL(78.12) DFO(6301461-01)