**Chart no. 4825**

**4825 - Burgeo - New Chart - 01-MAR-2002 - NAD 1983**

**23-AUG-2013** LNM/D. 29-MAR-2013

Delete depth of 29 metres, 2 decimetres 47°36′23.4″N 057°36′02.6″W
(See Chart No. 1, I10)

*DFO(6306408-01)*

**23-AUG-2013** LNM/D. 29-MAR-2013

Add depth of 27 metres, 6 decimetres 47°36′24.0″N 057°36′01.8″W
(See Chart No. 1, I10)

*DFO(6306408-02)*

**23-AUG-2013** LNM/D. 29-MAR-2013

Delete depth of 7 metres, 8 decimetres 47°36′17.5″N 057°36′45.5″W
(See Chart No. 1, I10)

*DFO(6306408-03)*

**23-AUG-2013** LNM/D. 29-MAR-2013

Add depth of 3 metres, 9 decimetres 47°36′17.1″N 057°36′44.5″W
(See Chart No. 1, I10)

*DFO(6306408-04)*

**23-AUG-2013** LNM/D. 29-MAR-2013

Replace depth of 13 metres, 3 decimetres with depth of 9 metres, 6 decimetres 47°36′19.6″N 057°36′45.7″W
(See Chart No. 1, I10)

*DFO(6306408-05)*

**23-AUG-2013** LNM/D. 29-MAR-2013

Add depth of 6 metres, 7 decimetres 47°36′21.5″N 057°36′38.1″W
(See Chart No. 1, I10)

*DFO(6306408-06)*

**23-AUG-2013** LNM/D. 29-MAR-2013

Delete depth of 12 metres, 6 decimetres 47°36′21.6″N 057°36′40.9″W
(See Chart No. 1, I10)

*DFO(6306408-07)*

**23-AUG-2013** LNM/D. 29-MAR-2013

## Chart no. 4825

Replace depth of 20 metres, 3 decimetres with depth of 17 metres, 4 decimetres — 47°36′24.6″N 057°36′35.9″W
(See Chart No. 1, I10)
*DFO(6306408-08)*

**23-AUG-2013** LNM/D. 29-MAR-2013

Replace depth of 12 metres, 3 decimetres with depth of 9 metres, 7 decimetres — 47°36′26.8″N 057°36′45.3″W
(See Chart No. 1, I10)
*DFO(6306408-09)*

**23-AUG-2013** LNM/D. 29-MAR-2013

Replace depth of 8 metres, 1 decimetre with depth of 5 metres, 3 decimetres — 47°36′33.9″N 057°36′26.4″W
(See Chart No. 1, I10)
*DFO(6306408-10)*

**21-SEP-2012** LNM/D. 28-OCT-2011

Delete ferry route — joining 47°36′31.2″N 057°36′34.5″W
(See Chart No. 1, M50) 47°36′24.0″N 057°36′34.8″W
47°36′21.9″N 057°36′37.7″W
47°36′19.7″N 057°36′46.2″W
47°36′18.6″N 057°37′00.8″W
and 47°36′13.0″N 057°37′21.9″W

*DFO(6305927-01)*

**28-OCT-2011** LNM/D. 14-OCT-2011

Add green port hand lighted pillar buoy FlG, marked QV9 — 47°36′15.5″N 057°35′23.5″W
(See Chart No. 1, Qg)
*(N2011076) LL(144.6) DFO(6305766-01)*

**28-OCT-2011** LNM/D. 14-OCT-2011

Add green port hand lighted pillar buoy FlG, marked QV7 — 47°36′24.6″N 057°35′41.4″W
(See Chart No. 1, Qg)
*(N2011077) LL(144.58) DFO(6305767-01)*

**28-OCT-2011** LNM/D. 14-OCT-2011

Add red starboard hand lighted pillar buoy FlR, marked QV8 — 47°36′24.6″N 057°35′37.2″W
(See Chart No. 1, Qf)
*(N2011078) LL(144.59) DFO(6305768-01)*

## Chart no. 4825

**30-JAN-2009** LNM/D. 31-OCT-2008

Add submarine cable joining 47°36′39.7″N 057°36′23.2″W
(See Chart No 1 L30.1) 47°36′33.7″N 057°36′23.7″W
47°36′31.4″N 057°36′22.8″W
47°36′29.9″N 057°36′20.9″W
47°36′29.2″N 057°36′17.7″W
47°36′29.9″N 057°36′10.7″W
47°36′53.5″N 057°35′11.5″W
and 47°36′55.0″N 057°34′58.5″W

*DFO(6304184-02)*

**30-JAN-2009** LNM/D. 31-OCT-2008

Add submarine cable joining 47°36′59.2″N 057°34′58.5″W
(See Chart No 1 L30.1) 47°36′56.3″N 057°35′12.4″W
47°36′32.3″N 057°36′08.5″W
47°36′30.2″N 057°36′22.2″W
and 47°36′39.7″N 057°36′23.1″W

*DFO(6304184-04)*

**31-AUG-2007** LNM/D. 03-NOV-2006

Reposition red starboard hand lighted pillar buoy FlR, marked QF2
from 47°36′33.6″N 057°36′20.9″W
to 47°36′33.6″N 057°36′17.0″W

*(N2007024) LL(145.9) DFO(6303560-01)*

**02-JUL-2004** LNM/D. 27-FEB-2004

Delete depth of 5 metres 1 decimetre 47°36′51.0″N 057°36′25.7″W

*DFO(6301627-01)*

**02-JUL-2004** LNM/D. 27-FEB-2004

Add depth of 0 metres 3 decimetres 47°36′51.8″N 057°36′25.4″W

*DFO(6301627-02)*

**02-JUL-2004** LNM/D. 27-FEB-2004

Add depth of 4 metres 9 decimetres 47°36′51.1″N 057°36′26.0″W

*DFO(6301627-03)*

## Chart no. 4825

**27-SEP-2002**

Reposition green port hand spar light buoy FlG, marked QG5.1 — from 47°37′00.6″N 057°36′15.0″W to 47°37′01.1″N 057°36′25.1″W

*(N2002085) LL(958.5) DFO(6300496-02)*

### 4825 - Burgeo and / et Ramea Islands - New Chart - 01-MAR-2002 - NAD 1983

**06-DEC-2019** — LNM/D. 08-DEC-2017

Affix patch — 47°38′00.0″N 057°32′00.0″W
PDF
This notice affects Electronic Navigational Chart: CA476622 *DFO(6308812-01)*

**06-DEC-2019** — LNM/D. 08-DEC-2017

Affix patch — 47°38′00.0″N 057°28′00.0″W
PDF
This notice affects Electronic Navigational Chart: CA476622 *DFO(6308812-02)*

**08-DEC-2017** — LNM/D. 17-MAR-2017

Replace depth of 9.8 metres with depth of 8.2 metres — 47°35′55.4″N 057°42′18.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276284, CA376616, CA476622 *DFO(6308153-01)*

**08-DEC-2017** — LNM/D. 17-MAR-2017

Delete depth of 12.8 metres — 47°36′50.7″N 057°41′30.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476622 *DFO(6308153-02)*

**08-DEC-2017** — LNM/D. 17-MAR-2017

Delete depth of 8.2 metres — 47°36′52.5″N 057°41′23.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376616, CA476622 *DFO(6308153-03)*

**08-DEC-2017** — LNM/D. 17-MAR-2017

**Chart no. 4825**

Add depth of 4 metres — 47°36′51.9″N 057°41′28.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376616, CA476622 — *DFO(6308153-04)*

**08-DEC-2017** — LNM/D. 17-MAR-2017

Replace depth of 17 metres with depth of 7.8 metres — 47°34′25.5″N 057°38′05.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA276284, CA376619, CA476622 — *DFO(6308153-05)*

**08-DEC-2017** — LNM/D. 17-MAR-2017

Add depth of 9.1 metres — 47°37′54.2″N 057°33′59.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376619, CA476622 — *DFO(6308153-06)*

**08-DEC-2017** — LNM/D. 17-MAR-2017

Add depth of 6.2 metres — 47°37′38.5″N 057°32′07.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476622 — *DFO(6308153-07)*

**08-DEC-2017** — LNM/D. 17-MAR-2017

Replace depth of 31 metres with depth of 2.4 metres — 47°37′50.9″N 057°31′36.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA376619, CA476622 — *DFO(6308153-08)*

**08-DEC-2017** — LNM/D. 17-MAR-2017

Delete depth of 20.1 metres — 47°37′20.6″N 057°29′08.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476622 — *DFO(6308153-09)*

**08-DEC-2017** — LNM/D. 17-MAR-2017

Delete depth of 20.1 metres — 47°37′18.0″N 057°29′04.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476622 — *DFO(6308153-10)*

**08-DEC-2017** — LNM/D. 17-MAR-2017

## Chart no. 4825

Delete depth of 12.8 metres 47°37′18.2″N 057°29′08.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476622 *DFO(6308153-11)*

**08-DEC-2017** LNM/D. 17-MAR-2017

Add depth of 9.3 metres 47°37′18.9″N 057°29′05.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476622 *DFO(6308153-12)*

**08-DEC-2017** LNM/D. 17-MAR-2017

Add depth of 7.1 metres 47°37′32.1″N 057°28′17.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476622 *DFO(6308153-14)*

**08-DEC-2017** LNM/D. 17-MAR-2017

Delete depth of 18.1 metres 47°37′55.0″N 057°34′03.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476622 *DFO(6308153-16)*

**17-MAR-2017** LNM/D. 03-FEB-2017

Delete black, yellow and black East cardinal lighted pillar buoy Q(3)10s, marked QV 47°35′54.6″N 057°37′39.9″W
(See Chart No. 1, Q130.3) *(N2016077P) LL(144.3) DFO(6307798-01)*
This notice affects Electronic Navigational Chart:
CA376619, CA476622

**03-FEB-2017** LNM/D. 01-APR-2016

Affix patch 47°35′00.0″N 057°41′00.0″W
PDF
This notice affects Electronic Navigational Chart: CA476622 *DFO(6307860-01)*

**01-APR-2016** LNM/D. 14-AUG-2015

Add depth of 12 metres, 3 decimetres 47°36′04.1″N 057°41′45.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476622 *DFO(6307497-03)*

**14-AUG-2015** LNM/D. 12-JUN-2015

**Chart no. 4825**

Affix patch 47°34′18.0″N 057°42′00.0″W
PDF

*DFO(6307248-01)*

**12-JUN-2015** LNM/D. 08-AUG-2014

Delete depth of 10 metres, 1 decimetre 47°34′20.5″N 057°42′03.6″W
(See Chart No. 1, I10)

*DFO(6307139-01)*

**12-JUN-2015** LNM/D. 08-AUG-2014

Add depth of 3 metres, 3 decimetres 47°34′18.5″N 057°42′02.5″W
(See Chart No. 1, I10)

*DFO(6307139-02)*

**23-AUG-2013** LNM/D. 29-MAR-2013

Affix patch 47°38′00.0″N 057°36′00.0″W
PDF

*DFO(6306408-11)*

**23-AUG-2013** LNM/D. 29-MAR-2013

Affix patch 47°36′00.0″N 057°36′00.0″W
PDF

*DFO(6306408-12)*

**29-MAR-2013** LNM/D. 21-SEP-2012

Add depth of 13 metres, 3 decimetres 47°34′17.5″N 057°41′47.7″W
(See Chart No. 1, I10)

*DFO(6306336-01)*

**29-MAR-2013** LNM/D. 21-SEP-2012

Add depth of 9 metres, 9 decimetres 47°34′26.9″N 057°41′45.4″W
(See Chart No. 1, I10)

*DFO(6306336-03)*

**21-SEP-2012** LNM/D. 28-OCT-2011

## Chart no. 4825

Delete ferry route joining 47°36′31.2″N 057°36′34.5″W
(See Chart No. 1, M50) 47°36′24.2″N 057°36′35.3″W
Ferry route between LaPoile and Burgeo is 47°36′20.2″N 057°36′42.9″W
discontinued 47°36′19.0″N 057°36′58.1″W
47°35′42.0″N 057°39′27.9″W
and 47°35′23.0″N 057°42′30.0″W

*DFO(6305927-01)*

**28-OCT-2011** LNM/D. 14-OCT-2011

Add green port hand lighted pillar buoy FlG, marked QV9 47°36′15.5″N 057°35′23.5″W
(See Chart No. 1, Qg)

*(N2011076) LL(144.6) DFO(6305766-01)*

**14-OCT-2011** LNM/D. 30-JAN-2009

Add light FlG 47°31′15.2″N 057°23′12.7″W
(See Chart No. 1, P1)

*(N2011060) LL(139.85) DFO(6305738-01)*

**30-JAN-2009** LNM/D. 31-OCT-2008

Add submarine cable joining 47°36′29.9″N 057°36′10.7″W
(See Chart No 1 L30.1) 47°36′53.5″N 057°35′11.5″W
47°36′55.4″N 057°34′54.8″W
47°36′54.2″N 057°34′39.1″W
47°36′41.5″N 057°34′20.8″W
47°36′26.7″N 057°34′18.7″W
47°36′13.8″N 057°33′59.7″W
47°35′31.4″N 057°34′09.9″W
47°35′23.1″N 057°34′16.8″W
47°34′15.4″N 057°36′31.4″W
47°32′39.5″N 057°39′54.0″W
47°32′33.2″N 057°40′30.9″W
and 47°32′52.1″N 057°42′30.0″W

*DFO(6304184-01)*

**30-JAN-2009** LNM/D. 31-OCT-2008

**Chart no. 4825**

Add submarine cable joining 47°32′43.2″N 057°16′00.0″W
(See Chart No 1 L30.1) 47°34′47.3″N 057°30′56.1″W
47°35′49.8″N 057°32′42.7″W
47°36′26.7″N 057°33′04.0″W
47°36′46.3″N 057°34′17.1″W
47°36′56.7″N 057°34′36.0″W
47°36′59.3″N 057°34′59.6″W
47°36′56.3″N 057°35′12.4″W
and 47°36′32.3″N 057°36′08.5″W

*DFO(6304184-03)*

**31-OCT-2008** LNM/D. 31-AUG-2007

Delete depth of 16 metres, 5 decimetres 47°30′01.9″N 057°23′25.0″W
(See Chart No. 1, I10)

*DFO(6304083-01)*

**31-OCT-2008** LNM/D. 31-AUG-2007

Delete depth of 27 metres, 4 decimetres 47°29′58.8″N 057°23′22.9″W
(See Chart No. 1, I10)

*DFO(6304083-02)*

**31-OCT-2008** LNM/D. 31-AUG-2007

Add depth of 10 metres, 4 decimetres 47°30′00.2″N 057°23′25.5″W
(See Chart No. 1, I10)

*DFO(6304083-03)*

**31-OCT-2008** LNM/D. 31-AUG-2007

Add depth of 5 metres, 1 decimetre 47°30′03.5″N 057°23′33.8″W
(See Chart No. 1, I10)

*DFO(6304083-04)*

**31-OCT-2008** LNM/D. 31-AUG-2007

Delete depth of 27 metres, 4 decimetres 47°29′50.9″N 057°23′48.0″W
(See Chart No. 1, I10)

*DFO(6304083-05)*

**31-OCT-2008** LNM/D. 31-AUG-2007

**Chart no. 4825**

Delete depth of 15 metres, 5 decimetres 47°29′52.4″N 057°23′38.0″W
(See Chart No. 1, I10)

*DFO(6304083-06)*

**31-OCT-2008** LNM/D. 31-AUG-2007

Add depth of 9 metres, 2 decimetres 47°29′52.4″N 057°23′50.1″W
(See Chart No. 1, I10)

*DFO(6304083-07)*

**31-OCT-2008** LNM/D. 31-AUG-2007

Add depth of 11 metres 47°27′48.6″N 057°16′34.2″W
(See Chart No. 1, I10)

*DFO(6304083-09)*

**31-OCT-2008** LNM/D. 31-AUG-2007

Delete depth of 42 metres 47°28′09.8″N 057°16′37.0″W
(See Chart No. 1, I10)

*DFO(6304083-10)*

**31-OCT-2008** LNM/D. 31-AUG-2007

Add depth of 16 metres, 4 decimetres 47°28′08.1″N 057°16′35.3″W
(See Chart No. 1, I10)

*DFO(6304083-11)*

**31-OCT-2008** LNM/D. 31-AUG-2007

Add depth of 12 metres, 4 decimetres 47°29′50.5″N 057°23′38.9″W
(See Chart No. 1, I10)

*DFO(6304083-24)*

**03-NOV-2006** LNM/D. 08-JUL-2005

Amend ″Adjoining Chart/Carte adjacente 4633″ to read ″Adjoining Chart/Carte adjacente 4826″ centre of east border

*DFO(6303058-01)*

**03-NOV-2006** LNM/D. 08-JUL-2005

Amend ″Adjoining Chart/Carte adjacente 4633″ to read ″Adjoining Chart/Carte adjacente 4826 ″ right side of north border

*DFO(6303058-02)*

## Chart no. 4825

**03-NOV-2006** LNM/D. 08-JUL-2005

Amend ″Adjoining Chart/Carte adjacente 4634″ to read ″Adjoining Chart/Carte adjacente 4824 ″ centre of west border

*DFO(6303058-03)*

**08-JUL-2005** LNM/D. 10-JUN-2005

Delete green port hand lighted pillar buoy FlG, marked QS1 47°29′44.9″N 057°27′03.2″W

*(N2005026) LL(140.9) DFO(6302329-01)*

**10-JUN-2005** LNM/D. 31-DEC-2004

Delete green port hand pillar light buoy FlG, marked QV3 47°35′53.5″N 057°37′39.4″W

*(N2005018) LL(144.3) DFO(6302284-01)*

**10-JUN-2005** LNM/D. 31-DEC-2004

Add black, yellow and black East cardinal pillar light buoy ″Q(3) 10s″, marked QV 47°35′54.6″N 057°37′39.9″W

*(N2005018) LL(144.3) DFO(6302284-02)*

**31-DEC-2004** LNM/D. 10-DEC-2004

Amend ″Fl 3s 38m 13M″ to read ″Fl 3s 38m 14M″ against light 47°30′44.9″N 057°24′31.5″W

*LL(141) DFO(6302111-03)*

**10-DEC-2004** LNM/D. 27-AUG-2004

Delete green port hand pillar light and whistle buoy FlG, WHIS marked Q29 47°31′54.4″N 057°18′57.1″W

*(N2004184) LL(140) DFO(6302057-01)*

**27-FEB-2004** LNM/D. 27-SEP-2002

Replace red starboard hand pillar light buoy FlR, WHIS, marked QS2, with red starboard hand spar light buoy FlR, marked QS2 47°30′16.8″N 057°25′04.1″W

*(N2003059) LL(140.7) DFO(6301163-01)*

**27-FEB-2004** LNM/D. 27-SEP-2002

**Chart no. 4825**

Replace red starboard hand pillar light buoy FlR, BELL, marked QQ2, with red starboard hand spar light buoy FlR, marked QQ2 — 47°29′55.7″N 057°21′48.1″W

*(N2003060) LL(140.5) DFO(6301164-01)*

**4825 - Ship Cove - New Chart - 01-MAR-2002 - NAD 1983**

**08-AUG-2014** — LNM/D. 23-AUG-2013

Add floating dock with legend ′Flo′ joining (See Chart No. 1, F16) — 47°31′19.2″N 057°23′13.8″W
47°31′19.0″N 057°23′14.5″W
and 47°31′18.0″N 057°23′13.8″W

*DFO(6306761-01)*

**14-OCT-2011** — LNM/D. 30-JAN-2009

Add light FlG (See Chart No. 1, P1) — 47°31′15.2″N 057°23′12.7″W

*(N2011060) LL(139.85) DFO(6305738-01)*

**27-AUG-2004** — LNM/D. 02-JUL-2004

Add green port hand spar light buoy FlG, marked QR5/1 — 47°31′19.4″N 057°22′50.6″W

*(N2004118) LL(140.54) DFO(6301626-01)*