Chart no. 4831

4831 - Fortune Bay: Northern Portion / Partie Nord - New Chart - 26-DEC-1986 - NAD 1983

03-JUL-2026 LNM/D. 22-NOV-2024

Add marine farm 47°39′52.0″N 055°23′03.0″W
(See Chart 1, K48.2)
DFO(6312213-01)

03-JUL-2026 LNM/D. 22-NOV-2024

Add marine farm 47°34′08.0″N 055°24′04.0″W
(See Chart 1, K48.2)
DFO(6312213-02)

22-NOV-2024 LNM/D. 16-AUG-2024

Amend Fl 3s17m to read Fl 5s17m against light 47°24′13.9″N 055°35′02.1″W
(See Chart 1, P16)
(N2024158) LL(120) DFO(6311491-01)

16-AUG-2024 LNM/D. 26-JUL-2024

Add light Fl Y 5s 47°29′16.5″N 055°25′15.4″W
(See Chart 1, P1)
(N2024106) LL(118.1) DFO(6311306-01)

16-AUG-2024 LNM/D. 26-JUL-2024

Amend Fl G to read Fl G 5s against light 47°27′05.3″N 055°33′27.5″W
(See Chart 1, P16)
(N2024107) LL(119.5) DFO(6311307-01)

26-JUL-2024 LNM/D. 28-APR-2023

Amend light Fl 4s62m to read Fl 5s62m against light 47°33′28.6″N 054°52′33.3″W
(See Chart 1, P16)
(N2024088) LL(113) DFO(6311259-01)

28-APR-2023 LNM/D. 30-SEP-2022

Add green port hand lighted spar buoy Fl G, marked VJK1 47°37′38.0″N 054°52′55.4″W
(See Chart 1, Qc) *(N2023053) LL(113.07) DFO(6310652-01)*
This notice affects Electronic Navigational Chart: CA376316

30-SEP-2022 LNM/D. 12-NOV-2021

Chart no. 4831

Add marine farm limits — joining 47°39′26.6″N 055°08′35.8″W
(See Chart No. 1, K48.1) — 47°39′20.9″N 055°08′19.2″W
This notice affects Electronic Navigational Chart: — 47°39′51.1″N 055°07′57.6″W
CA376316 — 47°39′56.6″N 055°08′14.3″W
and 47°39′26.6″N 055°08′35.8″W

DFO(6310318-01)

12-NOV-2021 — LNM/D. 24-SEP-2021

Amend FlR 4s to read Fl Y 4s against light — 47°38′08.4″N 055°12′40.4″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: *(N2021165) LL(115.9) DFO(6309729-01)*
CA376316

24-SEP-2021 — LNM/D. 18-SEP-2020

Add light Fl G — 47°37′56.3″N 054°53′07.9″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: *(N2021078) LL(113.06) DFO(6309554-01)*
CA376316

24-SEP-2021 — LNM/D. 18-SEP-2020

Add pier — between 47°37′55.5″N 054°53′10.5″W
(See Chart No. 1, F14) — and 47°37′56.3″N 054°53′07.9″W
This notice affects Electronic Navigational Chart:
CA376316 — *DFO(6309554-02)*

18-SEP-2020 — LNM/D. 31-JUL-2020

Delete light F R — 47°39′51.0″N 054°43′40.0″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376316 — *DFO(6309183-01)*

18-SEP-2020 — LNM/D. 31-JUL-2020

Delete pier — between 47°39′50.7″N 054°43′40.2″W
(See Chart No. 1, F14) — and 47°39′52.0″N 054°43′39.8″W
This notice affects Electronic Navigational Chart:
CA376316 — *DFO(6309183-02)*

31-JUL-2020 — LNM/D. 10-APR-2020

Amend Fl3s62m to read Fl 4s62m against light — 47°33′28.5″N 054°52′33.0″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: *(N2020038) LL(113) DFO(6309013-01)*
CA276274, CA376316

Chart no. 4831

10-APR-2020 LNM/D. 31-AUG-2018

Add marine farm 47°38′36.1″N 055°08′56.1″W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA376316 *DFO(6308949-01)*

31-AUG-2018 LNM/D. 14-JUL-2017

Add marine farm 47°39′30.7″N 055°22′06.6″W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA376316 *DFO(6308406-01)*

31-AUG-2018 LNM/D. 14-JUL-2017

Add marine farm 47°39′52.0″N 055°22′31.0″W
(See Chart No. 1, K48.2)
This notice affects Electronic Navigational Chart: CA376316 *DFO(6308406-02)*

14-JUL-2017 LNM/D. 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°31′25.7″N 055°20′26.4″W
(See Chart No. 1, L25) *DFO(6307974-03)*
This notice affects Electronic Navigational Chart: CA376233

14-JUL-2017 LNM/D. 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°38′22.9″N 055°17′49.6″W
(See Chart No. 1, L25) *DFO(6307974-04)*
This notice affects Electronic Navigational Chart: CA376316

14-JUL-2017 LNM/D. 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°26′03.4″N 055°29′27.3″W
(See Chart No. 1, L25) *DFO(6307974-06)*
This notice affects Electronic Navigational Chart: CA376233

14-JUL-2017 LNM/D. 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°38′08.1″N 055°23′11.7″W
(See Chart No. 1, L25) *DFO(6307974-07)*
This notice affects Electronic Navigational Chart: CA276274, CA376316

Chart no. 4831

14-JUL-2017 LNM/D. 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°34′47.3″N 055°10′05.0″W
(See Chart No. 1, L25) *DFO(6307974-08)*
This notice affects Electronic Navigational Chart: CA376316

14-JUL-2017 LNM/D. 14-APR-2017

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°28′43.2″N 055°09′57.1″W
(See Chart No. 1, L25) *DFO(6307974-09)*
This notice affects Electronic Navigational Chart: CA376316

14-APR-2017 LNM/D. 05-FEB-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°42′17.0″N 055°23′02.7″W
(See Chart No. 1, L25) *DFO(6307848-01)*
This notice affects Electronic Navigational Chart: CA376316

14-APR-2017 LNM/D. 05-FEB-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°38′08.1″N 055°23′11.7″W
(See Chart No. 1, L25) *DFO(6307848-02)*
This notice affects Electronic Navigational Chart: CA276274, CA376316

14-APR-2017 LNM/D. 05-FEB-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°37′59.1″N 055°26′25.1″W
(See Chart No. 1, L25) *DFO(6307848-03)*
This notice affects Electronic Navigational Chart: CA376316

14-APR-2017 LNM/D. 05-FEB-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°38′22.9″N 055°17′49.6″W
(See Chart No. 1, L25) *DFO(6307848-04)*
This notice affects Electronic Navigational Chart: CA376316

14-APR-2017 LNM/D. 05-FEB-2016

Chart no. 4831

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres 47°37′57.0″N 055°16′39.0″W
(See Chart No. 1, L25) *DFO(6307848-06)*
This notice affects Electronic Navigational Chart: CA276274, CA376316

14-APR-2017 LNM/D. 05-FEB-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°34′47.3″N 055°10′05.0″W
(See Chart No. 1, L25) *DFO(6307848-07)*
This notice affects Electronic Navigational Chart: CA376316

14-APR-2017 LNM/D. 05-FEB-2016

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres 47°33′29.4″N 055°19′44.4″W
(See Chart No. 1, L25) *DFO(6307848-08)*
This notice affects Electronic Navigational Chart: CA276274, CA376233

14-APR-2017 LNM/D. 05-FEB-2016

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres 47°33′26.0″N 055°19′54.0″W
(See Chart No. 1, L25) *DFO(6307848-09)*
This notice affects Electronic Navigational Chart: CA376233

14-APR-2017 LNM/D. 05-FEB-2016

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres 47°32′57.0″N 055°16′39.0″W
(See Chart No. 1, L25) *DFO(6307848-10)*
This notice affects Electronic Navigational Chart: CA276274, CA376316

14-APR-2017 LNM/D. 05-FEB-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°31′25.7″N 055°20′26.4″W
(See Chart No. 1, L25) *DFO(6307848-11)*
This notice affects Electronic Navigational Chart: CA376233

14-APR-2017 LNM/D. 05-FEB-2016

Chart no. 4831

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°28′43.2″N 055°09′57.1″W
(See Chart No. 1, L25) *DFO(6307848-12)*
This notice affects Electronic Navigational Chart: CA376316

14-APR-2017 LNM/D. 05-FEB-2016

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 8 metres 47°26′03.4″N 055°29′27.3″W
(See Chart No. 1, L25) *DFO(6307848-13)*
This notice affects Electronic Navigational Chart: CA376233

14-APR-2017 LNM/D. 05-FEB-2016

Delete subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres 47°38′09.6″N 055°16′51.6″W
(See Chart No. 1, L25) *DFO(6307848-16)*
This notice affects Electronic Navigational Chart: CA376316

05-FEB-2016 LNM/D. 07-AUG-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres 47°32′57.0″N 055°16′39.0″W
(See Chart No. 1, L25) *DFO(6307401-01)*
This notice affects Electronic Navigational Chart: CA276274, CA376316

07-AUG-2015 LNM/D. 20-MAR-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres. 47°37′57.0″N 055°16′39.0″W
(See Chart No. 1, L25) *DFO(6307179-01)*
This notice affects Electronic Navigational Chart: CA276274, CA376316

07-AUG-2015 LNM/D. 20-MAR-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres. 47°38′09.6″N 055°16′51.6″W
(See Chart No. 1, L25) *DFO(6307179-02)*
This notice affects Electronic Navigational Chart: CA376316

07-AUG-2015 LNM/D. 20-MAR-2015

Chart no. 4831

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 10 metres. 47°33′29.4″N 055°19′44.4″W
(See Chart No. 1, L25) *DFO(6307179-03)*
This notice affects Electronic Navigational Chart: CA276274, CA376233

07-AUG-2015 LNM/D. 20-MAR-2015

Add subsurface Ocean Data Acquisition system ODAS/SADO with known depth of 50 metres. 47°33′26.4″N 055°19′55.8″W
(See Chart No. 1, L25) *DFO(6307179-04)*
This notice affects Electronic Navigational Chart: CA376233

20-MAR-2015 LNM/D. 10-JAN-2014

Delete light Fl6s50m 47°34′42.0″N 055°07′05.0″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA276274, CA376316 *(N2015008) LL(115) DFO(6307061-01)*

10-JAN-2014 LNM/D. 20-DEC-2013

Add yellow and black South cardinal lighted spar buoy VQ(6)+ LFl10s, marked VRE 47°38′08.1″N 055°12′46.0″W
(See Chart No. 1, Q130.3) *(N2013029) LL(115.8) DFO(6306564-01)*

20-DEC-2013 LNM/D. 29-MAR-2013

Delete red starboard hand lighted spar buoy FlR, marked VV2 47°36′18.0″N 055°06′35.4″W
(See Chart No. 1, Qf) *(N2013016) LL(115.2) DFO(6306542-01)*

29-MAR-2013 LNM/D. 29-OCT-2010

Add marine farm 47°33′18.0″N 055°23′28.4″W
(See Chart No. 1, K48.2)
DFO(6306337-01)

29-OCT-2010 LNM/D. 23-JUL-2010

Add wharf between 47°31′36.5″N 055°24′33.9″W
(See Chart No. 1 F13) and 47°31′34.8″N 055°24′33.6″W

DFO(6305015-01)

29-OCT-2010 LNM/D. 23-JUL-2010

Chart no. 4831

Add wharf between 47°31′36.5″N 055°24′33.9″W
(See Chart No. 1 F13) and 47°31′35.6″N 055°24′31.3″W

DFO(6305015-02)

29-OCT-2010 LNM/D. 23-JUL-2010

Add light Fl G 47°31′34.8″N 055°24′33.6″W
(See Chart No. 1 P1)

(N2010043) LL(116.9) DFO(6305015-03)

23-JUL-2010 LNM/D. 18-JUN-2010

Delete light FR 47°40′48.0″N 055°25′48.0″W
(See Chart 1 P16)

(N2010033) LL(116.3) DFO(6304906-01)

23-JUL-2010 LNM/D. 18-JUN-2010

Add extension to wharf between 47°40′48.0″N 055°25′48.0″W
(See Chart 1 F14) and 47°40′49.6″N 055°25′46.2″W

DFO(6304906-02)

23-JUL-2010 LNM/D. 18-JUN-2010

Add light FlR 47°40′49.6″N 055°25′46.2″W
(See Chart 1 P16)

(N2010033) LL(116.3) DFO(6304906-03)

18-JUN-2010 LNM/D. 02-JAN-2009

Add light FlR 4s 47°38′08.4″N 055°12′41.5″W
(See Chart 1 P16)

LL(115.9) DFO(6304801-01)

02-JAN-2009 LNM/D. 19-SEP-2008

Add yellow and black South cardinal lighted pillar buoy 47°34′37.0″N 055°09′29.0″W
VQ(6)+LFl 10s, marked VL
(See Chart No 1 Qm) *(N2008045) LL(114.9) DFO(6304169-01)*

19-SEP-2008 LNM/D. 29-AUG-2008

Chart no. 4831

Add black and yellow North cardinal lighted pillar buoy Q, marked VB 47°35′52.7″N 055°19′41.9″W
(See Chart No 1 Q130.3) *(N2008027) LL(116.6) DFO(6304018-01)*

29-AUG-2008 LNM/D. 02-NOV-2007

Add dangerous underwater rock of 2 metres or less, reported 2008 47°35′48.0″N 054°59′00.3″W
(See Chart No 1 K13, I3.2)
DFO(6303999-01)

02-NOV-2007 LNM/D. 11-AUG-2006

Add green port hand lighted spar buoy FlG, marked VJF1 47°31′48.0″N 054°55′30.0″W

(N2007051) LL(113.6) DFO(6303641-01)

11-AUG-2006 LNM/D. 26-MAY-2006

Add red starboard hand lighted spar buoy FlR, marked VM2 47°35′06.5″N 054°53′05.1″W

(N2006018) LL(113.08) DFO(6302897-01)

26-MAY-2006 LNM/D. 07-OCT-2005

Add light FlR 47°32′51.0″N 054°52′52.0″W

(N1998117) LL(113.2) DFO(6300722-01)

07-OCT-2005 LNM/D. 16-APR-2004

Add breakwater between 47°27′05.0″N 055°33′34.0″W
and 47°27′05.2″N 055°33′28.2″W

DFO(6302416-01)

07-OCT-2005 LNM/D. 16-APR-2004

Reposition light FlG from 47°27′06.5″N 055°33′30.8″W
to 47°27′05.2″N 055°33′28.2″W

(N2005039) LL(119.5) DFO(6302416-02)

16-APR-2004 LNM/D. 26-DEC-2003

Chart no. 4831

Amend Fl to read Fl R 4s 14m 5M against light 47°27′18.0″N 055°29′33.0″W

(N2002103) LL(119) DFO(6300521-01)

26-DEC-2003 LNM/D. 11-APR-2003

Amend Fl R 3s 17m to read Fl 3s 17m 47°24′13.8″N 055°35′02.5″W

LL(120) DFO(6300972-01)

11-APR-2003 LNM/D. 15-MAR-2002

Delete green, port hand can buoy, marked VE1 47°27′29.0″N 055°29′44.0″W

(N2000260) DFO(6829120-01)

11-APR-2003 LNM/D. 15-MAR-2002

Add green port hand spar light buoy FlG, marked VE1 47°27′29.0″N 055°29′41.7″W

(N2000260) LL(116.410) DFO(6829120-02)

11-APR-2003 LNM/D. 15-MAR-2002

Replace red, starboard hand spar buoy, marked VV2 with red starboard hand spar light buoy FlR, marked VV2 47°36′18.0″N 055°06′35.4″W

(N2001130) LL(115.2) DFO(6829755-01)

11-APR-2003 LNM/D. 15-MAR-2002

Replace green, port hand spar buoy, marked VS1, with green port hand spar light buoy FlG, marked VS1 47°31′47.8″N 054°57′09.2″W

(N2001131) LL(113.4) DFO(6829756-01)

15-MAR-2002 LNM/D. 25-JAN-2002

Add non-dangerous wreck 47°34′56.4″N 054°56′14.4″W

(N2002001) DFO(6300102-01)

25-JAN-2002 LNM/D. 07-DEC-2001

Amend FI R 6s 14m to read Fl 47°27′18.0″N 055°29′33.0″W

(N2000037) LL(119) DFO(6828798-01)

Chart no. 4831

25-JAN-2002 LNM/D. 07-DEC-2001

Add light FIG 47°27′06.5″N 055°33′30.8″W

(N2000246) LL(119.5) DFO(6829093-01)

25-JAN-2002 LNM/D. 07-DEC-2001

Delete anchorage symbol 47°28′36.0″N 055°28′18.0″W

DFO(6829829-01)

07-DEC-2001 LNM/D. 11-MAY-2001

Replace green port hand spar buoy, marked VD5, with green light, port hand spar buoy FlG, marked VD5 47°35′47.8″N 055°25′00.0″W

(N2000261) LL(116.4) DFO(6829121-01)

07-DEC-2001 LNM/D. 11-MAY-2001

Add submerged wreck 47°31′41.5″N 054°58′02.3″W

(N2001146) DFO(6829827-01)

11-MAY-2001 LNM/D. 12-MAR-1999

Delete green, red, green port bifurcation pillar light buoy, FL (2+1) G, marked VBL 47°29′13.0″N 055°22′43.0″W

(N2000-213) LL(117.5) DFO(6829032-01)

11-MAY-2001 LNM/D. 12-MAR-1999

Delete red and white fairway pillar, light buoy Mo (A), marked VSJ 47°27′36.0″N 055°26′00.0″W

(N2000-214) LL(118.5) DFO(6829033-01)