Chart no. 4843

4843 - Head of / Fond de St Mary's Bay - New Edition - 26-DEC-2003 - NAD 1983

28-APR-2023 LNM/D. 14-APR-2023

Delete legend BELL against red starboard hand lighted pillar buoy Fl R, marked MH2 — 46°53′35.4″N 053°37′36.3″W
(See Chart No. 1, Qf) — *(N2023047) LL(7.5) DFO(6310646-01)*
This notice affects Electronic Navigational Chart: CA376135

28-APR-2023 LNM/D. 14-APR-2023

Reposition red starboard hand lighted spar buoy Q R, marked MH6 — from 46°57′50.8″N 053°31′37.5″W to 46°57′53.1″N 053°31′39.8″W
(See Chart 1, Qb)
This notice affects Electronic Navigational Chart: CA476294 — *(N2023048) LL(8.12) DFO(6310647-01)*

14-APR-2023 LNM/D. 04-MAR-2022

Amend Fl 3s 20m to read Fl 4s20m against light — 47°00′46.0″N 053°41′04.1″W
(See Chart 1, P16)
This notice affects Electronic Navigational Chart: CA476294 — *(N2023002) LL(9) DFO(6310586-01)*

26-NOV-2021 LNM/D. 03-SEP-2021

Affix patch — 46°58′00.0″N 053°31′30.0″W
PDF
This notice affects Electronic Navigational Chart: CA376293 — *DFO(6309792-03)*

03-SEP-2021 LNM/D. 16-JUL-2010

Delete light Fl G — 46°57′52.9″N 053°31′46.1″W
(See Chart No.1, P1)
This notice affects Electronic Navigational Chart: CA376293, CA476294 — *(N2021082) LL(8.21) DFO(6309562-01)*

16-JUL-2010 LNM/D. 27-JUL-2007

Reposition red, green and red starboard bifurcation lighted pillar buoy Fl(2+1)R, marked MS — from 46°56′12.0″N 053°43′09.0″W to 46°56′08.6″N 053°43′09.0″W
(See Chart No 1 Qi)

(N2010016) LL(8.7) DFO(6304954-01)

This notice affects Electronic Navigational Chart: CA376135

Chart no. 4843

31-DEC-2004

Delete legend ″WHIS″ against red, green and red starboard bifurcation pillar light and whistle buoy Fl(2+1) R, WHIS marked MS — 46°56′12.0″N 053°43′09.0″W — *(N2004192) LL(8.7) DFO(6302103-01)*

4843 - St Mary's Harbour and Adjacent Anchorages / et mouillages adjacents - New Edition - 26-DEC-2003 - NAD 1983

14-APR-2023 — LNM/D. 04-MAR-2022

Amend Fl 3s 20m to read Fl 4s20m against light — 47°00′45.7″N 053°41′03.0″W
(See Chart 1, P16)
This notice affects Electronic Navigational Chart: CA476294 — *(N2023002) LL(9) DFO(6310586-01)*

04-MAR-2022 — LNM/D. 26-NOV-2021

Amend Fl R to read Q R against red starboard hand lighted spar buoy, marked MH6 — 46°57′50.9″N 053°31′37.8″W
(See Chart No. 1, Qf) — *(N2021271) LL(8.12) DFO(6310002-01)*
This notice affects Electronic Navigational Chart: CA376293, CA476294

26-NOV-2021 — LNM/D. 03-SEP-2021

Delete NOTE Wharf Plan - illustrated in Sailing Directions ATL 102. NOTE Plan du quai - illustré dans les Instructions nautiques ATL 102. — 46°58′29.0″N 053°32′23.0″W — *DFO(6309792-01)*
(See Chart No. 1, A14)
This notice affects Electronic Navigational Chart: CA376293, CA476294

26-NOV-2021 — LNM/D. 03-SEP-2021

Delete legend ′See NOTE/Voir NOTE′ — 46°57′48.0″N 053°32′09.0″W
(See Chart No. 1, A14)
This notice affects Electronic Navigational Chart: CA376293, CA476294 — *DFO(6309792-02)*

26-NOV-2021 — LNM/D. 03-SEP-2021

Affix patch — 46°58′00.0″N 053°31′30.0″W
PDF
This notice affects Electronic Navigational Chart: CA476294 — *DFO(6309792-04)*

Chart no. 4843

03-SEP-2021 LNM/D. 16-JUL-2010

Delete light Fl G 46°57′52.9″N 053°31′46.1″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: *(N2021082) LL(8.21) DFO(6309562-01)*
CA376293, CA476294

27-JUL-2007 LNM/D. 31-DEC-2004

(T)Add subsurface scientific mooring at a depth of 18 metres below the surface and marked by a red buoy 47°03′54.6″N 053°34′58.8″W
Proposed date of removal is September 2007. *DFO(6303578-01)*
This buoy is permanently discontinued. Notice 27-July-2007(T), DFO(6303578) is now cancelled.
Cancelled on 08-FEB-08

27-JUL-2007 LNM/D. 31-DEC-2004

(T)Add subsurface scientific mooring at a depth of 30 metres below the surface and marked by a red buoy 47°03′43.2″N 053°35′33.0″W
Proposed date of removal is September 2007. *DFO(6303578-02)*
This buoy is permanently discontinued. Notice 27-July-2007(T), DFO(6303578) is now cancelled.
Cancelled on 08-FEB-08

27-JUL-2007 LNM/D. 31-DEC-2004

(T)Add subsurface scientific mooring at a depth of 43 metres below the surface and marked by a red buoy 47°03′33.6″N 053°35′52.2″W
Proposed date of removal is September 2007. *DFO(6303578-03)*
This buoy is permanently discontinued. Notice 27-July-2007(T), DFO(6303578) is now cancelled.
Cancelled on 08-FEB-08