Chart no. 4851

4851 - Bull Arm - New Edition - 30-SEP-2016 - World Geodetic System 1984

24-NOV-2023 LNM/D. 15-SEP-2023

Add obstruction with known depth of 8.8 metres 47°48′28.1″N 053°52′58.3″W
(See Chart 1, K41)
This notice affects Electronic Navigational Chart: CA576486 *DFO(6310944-01)*

24-NOV-2023 LNM/D. 15-SEP-2023

Add note Entry Prohibited 47°48′34.9″N 053°52′08.8″W
(See Chart No. 1, A14)
This notice affects Electronic Navigational Chart: CA576486 *DFO(6310944-05)*

4851 - Trinity Bay: Southern Portion / Partie Sud - New Edition - 30-SEP-2016 - World Geodetic System 1984

24-NOV-2023 LNM/D. 15-SEP-2023

Delete note See/Voir note CONSTRUCTION 47°48′15.1″N 053°51′09.8″W
(See Chart No. 1, A14)
DFO(6310944-02)

24-NOV-2023 LNM/D. 15-SEP-2023

Delete note CONSTRUCTION 47°47′10.0″N 053°55′21.4″W
This area is temporarily established as a construction zone. Mariners may enter the area only in the event of an emergency. *DFO(6310944-03)*
CONSTRUCTION
Cette zone a été provisoirement désignée comme zone de construction. Les navigateurs ne peuvent y pénétrer sauf en cas d'urgence.
(See Chart No. 1, A14)

24-NOV-2023 LNM/D. 15-SEP-2023

Add note Entry Prohibited 47°48′15.1″N 053°51′09.8″W
(See Chart No. 1, A14)
DFO(6310944-04)

15-SEP-2023 LNM/D. 14-JUL-2023

Add light Fl G 5s2M 47°36′59.5″N 053°30′42.1″W
(See Chart 1, P1)
This notice affects Electronic Navigational Chart: CA376153 *(N2023082) LL(467.02) DFO(6310734-01)*

Chart no. 4851

15-SEP-2023 LNM/D. 14-JUL-2023

Amend Fl 3s63m5M to read Fl 5s62m4M against light — 47°37′57.7″N 053°33′47.5″W
(See Chart 1, P16)
This notice affects Electronic Navigational Chart: CA376153 — *(N2023098) LL(467) DFO(6310794-01)*

14-JUL-2023 LNM/D. 26-MAY-2023

Add red starboard hand lighted spar buoy Fl R, marked TA2 — 47°31′15.8″N 053°40′10.5″W
(See Chart 1, Qb) — *(N2023069) LL(467.05) DFO(6310687-01)*

This notice affects Electronic Navigational Chart: CA376153

14-JUL-2023 LNM/D. 26-MAY-2023

Reposition green port hand lighted pillar buoy Fl G, marked TB1 — from 47°40′52.8″N 053°48′26.6″W to 47°40′58.5″N 053°48′28.5″W
(See Chart 1, Qc)
This notice affects Electronic Navigational Chart: CA376153 — *(N2023071) LL(467.24) DFO(6310689-01)*

26-MAY-2023 LNM/D. 14-APR-2023

Delete depth of 3.4 metres — 47°35′35.9″N 053°33′17.5″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA376153 — *DFO(6310634-01)*

26-MAY-2023 LNM/D. 14-APR-2023

Add depth of 2 metres — 47°35′32.5″N 053°33′16.5″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA376153 — *DFO(6310634-02)*

26-MAY-2023 LNM/D. 14-APR-2023

Add depth of 4.6 metres — 47°35′34.3″N 053°33′00.4″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA376153 — *DFO(6310634-03)*

14-APR-2023 LNM/D. 03-MAR-2023

Chart no. 4851

Amend Fl R to read Fl R 5s3m4M against light — 47°40′49.5″N 053°49′36.7″W
(See Chart 1, P16)
This notice affects Electronic Navigational Chart: *(N2023021) LL(467.27) DFO(6310605-01)*
CA376153

03-MAR-2023 — LNM/D. 01-JUL-2022

Delete Note — 47°34′13.0″N 053°41′12.0″W
DIAGRAM / DIAGRAMME
See Sailing Directions — *DFO(6310566-01)*
Voir Instructions nautiques
(See Chart No. 1, A18)

01-JUL-2022 — LNM/D. 14-JAN-2022

Amend Fl 3s38m7M to read Fl 4s38m5M against light — 48°05′41.1″N 053°32′43.1″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: *(N2022064) LL(465) DFO(6310096-01)*
CA376153, CA476051

01-JUL-2022 — LNM/D. 14-JAN-2022

Add red starboard hand lighted spar buoy Fl R, marked TV6 — 48°05′44.0″N 053°53′01.4″W
(See Chart No. 1, Qf) *(N2022074) LL(466.08) DFO(6310107-02)*
This notice affects Electronic Navigational Chart:
CA376153, CA476051

14-JAN-2022 — LNM/D. 19-NOV-2021

Add green port hand lighted spar buoy Q G, marked TG7 — 47°38′17.6″N 053°44′12.6″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: *(N2021173) LL(467.18) DFO(6309895-01)*
CA376153

14-JAN-2022 — LNM/D. 19-NOV-2021

Add red starboard hand lighted spar buoy Fl R, marked TG8 — 47°38′15.0″N 053°44′12.3″W
(See Chart No. 1, Qf) *(N2021174) LL(467.19) DFO(6309896-01)*
This notice affects Electronic Navigational Chart:
CA376153

19-NOV-2021 — LNM/D. 08-FEB-2019

Chart no. 4851

Amend Iso R to read Fl R against light — 47°34′03.5″N 053°39′59.2″W
(See Chart No. 1, P16)
This notice affects Electronic Navigational Chart: CA376153, CA576815 — *(N2021147) LL(466.9) DFO(6309716-01)*

19-NOV-2021 — LNM/D. 08-FEB-2019

Add light Q G — 47°34′04.1″N 053°39′57.7″W
(See Chart No. 1, P1)
This notice affects Electronic Navigational Chart: CA376153, CA576815 — *(N2021154) LL(466.88) DFO(6309723-01)*

08-FEB-2019 — LNM/D. 14-APR-2017

Delete pier — between 47°31′58.1″N 053°33′05.7″W
(See Chart No. 1, F14) — and 47°31′56.9″N 053°33′06.0″W

This notice affects Electronic Navigational Chart: CA376153 — *DFO(6308523-01)*

08-FEB-2019 — LNM/D. 14-APR-2017

Add pier — between 47°31′58.1″N 053°33′05.7″W
(See Chart No. 1, F14) — and 47°31′56.2″N 053°33′09.1″W

This notice affects Electronic Navigational Chart: CA376153 — *DFO(6308523-02)*

08-FEB-2019 — LNM/D. 14-APR-2017

Reposition light Fl G — from 47°31′58.1″N 053°33′05.7″W
(See Chart No. 1, P16) — to 47°31′56.2″N 053°33′09.1″W
This notice affects Electronic Navigational Chart: CA376153 — *(N2018105) LL(467.08) DFO(6308523-03)*

14-APR-2017 — LNM/D. 31-MAR-2017

Replace ON CERTAIN COPIES — 47°38′25.2″N 053°44′46.8″W
red starboard hand spar light buoy FlG, marked TG1, with green port hand spar light buoy FlG, marked TG1 — *DFO(6307897-01)*
(See Chart No. 1, Qg)

14-APR-2017 — LNM/D. 31-MAR-2017

Chart no. 4851

Replace ON CERTAIN COPIES 47°38′14.5″N 053°44′40.0″W
red starboard hand spar light buoy FlG, marked TG3, with green port hand spar light buoy FlG, marked TG3
(See Chart No. 1, Qg) *DFO(6307897-02)*

14-APR-2017 LNM/D. 31-MAR-2017

Add ON CERTAIN COPIES 47°48′33.5″N 053°51′19.9″W
legend ODAS/SADO against buoy
(See Chart No. 1, Q58) *DFO(6307897-03)*

31-MAR-2017 LNM/D. 03-MAR-2017

Delete On certain copies 47°38′36.0″N 053°30′22.0″W
light FlG
(See Chart No. 1, P1) *(N2017006) LL(467.01) DFO(6307881-01)*

31-MAR-2017 LNM/D. 03-MAR-2017

Delete On certain copies between 47°38′36.0″N 053°30′22.0″W
breakwater and legend Bkw and 47°38′37.0″N 053°30′24.0″W
(See Chart No. 1, F4.1)
DFO(6307881-02)

03-MAR-2017

Reposition ON CERTAIN COPIES from 47°35′55.0″N 053°33′30.0″W
red starboard hand lighted spar buoy FlR, marked TN2 to 47°35′39.0″N 053°33′17.4″W
(See Chart No. 1, Qf) *DFO(6307870-01)*
This notice affects Electronic Navigational Chart: CA376153