Chart no. 4912

4912 - Miramichi - New Edition - 27-JAN-2006 - NAD 1983

03-NOV-2023 LNM/D. 23-SEP-2022

Replace depth of 6.9 metres with depth of 6.6 metres 47°08′11.4″N 065°12′08.2″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310883-01)*

03-NOV-2023 LNM/D. 23-SEP-2022

Replace depth of 5.6 metres with depth of 5.3 metres 47°08′07.2″N 065°11′35.9″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310883-02)*

03-NOV-2023 LNM/D. 23-SEP-2022

Replace depth of 6 metres with depth of 5.7 metres 47°07′51.0″N 065°09′49.8″W
(See Chart 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310883-03)*

23-SEP-2022 LNM/D. 15-APR-2022

Replace depth of 7 metres with depth of 6.1 metres 47°07′36.8″N 065°07′50.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310314-09)*

23-SEP-2022 LNM/D. 15-APR-2022

Replace depth of 5.4 metres with depth of 5.1 metres 47°07′56.4″N 065°10′33.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310314-10)*

23-SEP-2022 LNM/D. 15-APR-2022

Replace depth of 5.6 metres with depth of 5.3 metres 47°08′04.2″N 065°11′20.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310314-11)*

23-SEP-2022 LNM/D. 15-APR-2022

Replace depth of 7.3 metres with depth of 7 metres 47°04′40.4″N 065°23′27.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310314-12)*

23-SEP-2022 LNM/D. 15-APR-2022

Chart no. 4912

Delete depth of 7 metres 47°04′28.8″N 065°24′12.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310314-13)*

23-SEP-2022 LNM/D. 15-APR-2022

Add depth of 6.5 metres 47°04′28.1″N 065°24′12.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310314-14)*

23-SEP-2022 LNM/D. 15-APR-2022

Replace depth of 6.5 metres with depth of 6.1 metres 47°04′20.1″N 065°24′25.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310314-15)*

23-SEP-2022 LNM/D. 15-APR-2022

Delete depth of 6.1 metres 47°04′11.3″N 065°24′35.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310314-16)*

23-SEP-2022 LNM/D. 15-APR-2022

Add depth of 5.7 metres 47°04′11.2″N 065°24′33.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310314-17)*

23-SEP-2022 LNM/D. 15-APR-2022

Replace depth of 7.9 metres with depth of 7.5 metres 47°03′56.7″N 065°25′05.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310314-18)*

15-APR-2022 LNM/D. 05-MAR-2021

Replace depth of 8.1 metres with depth of 7.7 metres 47°07′54.1″N 065°12′35.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310055-04)*

15-APR-2022 LNM/D. 05-MAR-2021

Replace depth of 6.4 metres with depth of 6.1 metres 47°07′46.1″N 065°09′10.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310055-23)*

Chart no. 4912

15-APR-2022 LNM/D. 05-MAR-2021

Delete depth of 5.9 metres 47°07′59.6″N 065°10′37.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310055-26)*

15-APR-2022 LNM/D. 05-MAR-2021

Add depth of 5.6 metres 47°07′58.8″N 065°10′38.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310055-27)*

15-APR-2022 LNM/D. 05-MAR-2021

Delete depth of 5.8 metres 47°08′04.5″N 065°11′07.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310055-28)*

15-APR-2022 LNM/D. 05-MAR-2021

Add depth of 5.5 metres 47°08′04.0″N 065°11′08.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310055-29)*

15-APR-2022 LNM/D. 05-MAR-2021

Replace depth of 6 metres with depth of 5.4 metres 47°08′07.3″N 065°11′32.7″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310055-30)*

05-MAR-2021 LNM/D. 05-JUN-2020

Delete note: ENSABLEMENT En raison d'ensablement continuel les profondeurs normales et la présentation des isobathes changent constamment. Les navigateurs sont avisés d'être prudents en naviguant dans ces eaux. SILTING Due to continuous silting, the normal depths and the presentation of the bathymetric contours are constantly changing. Mariners are warned to exercise due caution when navigation in these waters. 47°11′18.0″N 065°10′41.6″W *DFO(6309333-08)*

This notice affects Electronic Navigational Chart: CA476125, CA476133

05-MAR-2021 LNM/D. 05-JUN-2020

Chart no. 4912

Add note: ENSABLEMENT En raison d'un envasement continuel, les profondeurs et la représentation des contours dans le chenal d'approche de la rivière Miramichi changent constamment. Le chenal ne fait plus l'objet de dragage. On conseille aux navigateurs qui n'ont pas de connaissances locales de ne pas emprunter cette voie. SILTING Owing to continual silting, the depths and presentation of contours in the approach channel to the Miramichi River are constantly changing and dredging in the area has been discontinued. Mariners should not attempt to enter without local knowledge.
This notice affects Electronic Navigational Chart: CA476125, CA476133
47°11′18.0″N 065°10′41.6″W
DFO(6309333-09)

05-MAR-2021 LNM/D. 05-JUN-2020

Amend 5.5 mètres (2017) to read 5.4 mètres (2020) against the note ATTENTION and 5.5 metres (2017) to read 5.4 metres (2020) against the note CAUTION
This notice affects Electronic Navigational Chart: CA476125, CA476133
47°10′52.0″N 065°10′42.2″W
DFO(6309333-10)

05-JUN-2020 LNM/D. 27-OCT-2017

Replace depth of 6.3 metres with depth of 5.8 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125
47°08′04.3″N 065°11′07.3″W
DFO(6308947-08)

05-JUN-2020 LNM/D. 27-OCT-2017

Add depth of 5.6 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125
47°08′06.9″N 065°11′35.9″W
DFO(6308947-09)

05-JUN-2020 LNM/D. 27-OCT-2017

Replace depth of 6.7 metres with depth of 6.1 metres
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125
47°08′08.4″N 065°12′03.6″W
DFO(6308947-10)

05-JUN-2020 LNM/D. 27-OCT-2017

Add submerged wreck Wk
(See Chart No. 1, K23)
This notice affects Electronic Navigational Chart: CA476125
47°03′39.2″N 065°26′36.8″W
DFO(6308947-12)

27-OCT-2017 LNM/D. 29-SEP-2017

Chart no. 4912

Delete depth of 8 metres, 0 decimetres — 47°07′18.0″N 065°13′31.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 — *DFO(6308089-01)*

27-OCT-2017 — LNM/D. 29-SEP-2017

Replace depth of 7 metres, 6 decimetres with depth of 6 metres, 7 decimetres — 47°06′45.8″N 065°14′47.0″W
(See Chart No. 1, I10) — *DFO(6308089-02)*
This notice affects Electronic Navigational Chart: CA476125

29-SEP-2017 — LNM/D. 09-SEP-2016

Amend 6.2 mètres (2010) to read 5.5 mètres (2017) against the note ATTENTION and 6.2 metres (2010) to read 5.5 metres (2017) against the note CAUTION — 47°10′50.0″N 065°10′42.0″W
This notice affects Electronic Navigational Chart: CA476125 — *DFO(6308051-02)*

09-SEP-2016 — LNM/D. 04-MAR-2016

Delete depth of 6 metres — 47°08′04.7″N 065°11′17.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 — *DFO(6307552-02)*

09-SEP-2016 — LNM/D. 04-MAR-2016

Add depth of 5 metres, 6 decimetres — 47°08′04.4″N 065°11′20.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 — *DFO(6307552-03)*

07-FEB-2014 — LNM/D. 09-SEP-2011

Replace depth of 9 metres with depth of 8 metres, 5 decimetres — 47°07′18.1″N 065°05′44.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476133 — *DFO(6306579-06)*

07-FEB-2014 — LNM/D. 09-SEP-2011

Replace depth of 8 metres with depth of 7 metres, 3 decimetres — 47°07′22.9″N 065°06′38.4″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476133 — *DFO(6306579-07)*

07-FEB-2014 — LNM/D. 09-SEP-2011

Chart no. 4912

Replace depth of 8 metres, 1 decimetre with depth of 7 metres, 4 decimetres — 47°07′30.8″N 065°07′23.5″W
(See Chart No. 1, I10) *DFO(6306579-08)*
This notice affects Electronic Navigational Chart: CA476133

07-FEB-2014 LNM/D. 09-SEP-2011

Replace depth of 6 metres, 4 decimetres with depth of 5 metres, 7 decimetres — 47°07′44.0″N 065°08′41.0″W
(See Chart No. 1, I10) *DFO(6306580-01)*
This notice affects Electronic Navigational Chart: CA476125

07-FEB-2014 LNM/D. 09-SEP-2011

Add depth of 6 metres, 4 decimetres — 47°07′46.1″N 065°09′09.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6306580-02)*

07-FEB-2014 LNM/D. 09-SEP-2011

Delete depth of 5 metres, 9 decimetres — 47°07′48.3″N 065°09′35.2″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6306580-03)*

07-FEB-2014 LNM/D. 09-SEP-2011

Add depth of 4 metres, 9 decimetres — 47°07′48.7″N 065°09′39.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6306580-04)*

07-FEB-2014 LNM/D. 09-SEP-2011

Delete depth of 6 metres, 7 decimetres — 47°07′51.4″N 065°09′48.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6306580-05)*

07-FEB-2014 LNM/D. 09-SEP-2011

Add depth of 6 metres — 47°07′51.4″N 065°09′50.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6306580-06)*

07-FEB-2014 LNM/D. 09-SEP-2011

Chart no. 4912

Replace depth of 6 metres, 1 decimetre with depth of 5 metres, 6 decimetres — 47°07′54.5″N 065°09′55.1″W
(See Chart No. 1, I10) — *DFO(6306580-07)*
This notice affects Electronic Navigational Chart: CA476125

07-FEB-2014 — LNM/D. 09-SEP-2011

Replace depth of 6 metres, 4 decimetres with depth of 5 metres, 9 decimetres — 47°07′59.5″N 065°10′37.3″W
(See Chart No. 1, I10) — *DFO(6306580-08)*
This notice affects Electronic Navigational Chart: CA476125

07-FEB-2014 — LNM/D. 09-SEP-2011

Replace depth of 6 metres, 1 decimetre with depth of 5 metres, 3 decimetres — 47°08′01.1″N 065°10′40.9″W
(See Chart No. 1, I10) — *DFO(6306580-09)*
This notice affects Electronic Navigational Chart: CA476125

07-FEB-2014 — LNM/D. 09-SEP-2011

Replace depth of 5 metres, 7 decimetres with depth of 4 metres, 9 decimetres — 47°08′03.1″N 065°10′52.4″W
(See Chart No. 1, I10) — *DFO(6306580-10)*
This notice affects Electronic Navigational Chart: CA476125

07-FEB-2014 — LNM/D. 09-SEP-2011

Replace depth of 5 metres, 7 decimetres with depth of 5 metres, 2 decimetres — 47°08′09.3″N 065°11′35.7″W
(See Chart No. 1, I10) — *DFO(6306580-11)*
This notice affects Electronic Navigational Chart: CA476125

07-FEB-2014 — LNM/D. 09-SEP-2011

Affix patch — 47°05′00.0″N 065°20′00.0″W
PDF
This notice affects Electronic Navigational Chart: CA476125 — *DFO(6306580-12)*

07-FEB-2014 — LNM/D. 09-SEP-2011

Delete depth of 3 metres, 4 decimetres — 47°04′53.4″N 065°22′44.3″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 — *DFO(6306580-13)*

Chart no. 4912

07-FEB-2014 LNM/D. 09-SEP-2011

Add depth of 4 metres, 8 decimetres 47°04′52.0″N 065°22′42.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6306580-14)*

07-FEB-2014 LNM/D. 09-SEP-2011

Replace depth of 12 metres with depth of 11 metres, 5 decimetres 47°04′49.1″N 065°22′55.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6306580-15)*

07-FEB-2014 LNM/D. 09-SEP-2011

Add depth of 4 metres 47°04′30.2″N 065°24′16.0″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6306580-16)*

07-FEB-2014 LNM/D. 09-SEP-2011

Add depth of 6 metres, 5 decimetres 47°04′20.3″N 065°24′25.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6306580-17)*

07-FEB-2014 LNM/D. 09-SEP-2011

Delete depth of 11 metres 47°04′18.9″N 065°24′29.6″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6306580-18)*

07-FEB-2014 LNM/D. 09-SEP-2011

Add depth of 11 metres 47°04′18.2″N 065°24′31.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6306580-19)*

09-SEP-2011 LNM/D. 04-MAR-2011

Delete depth of 7 metres, 5 decimetres 47°03′50.6″N 065°25′22.8″W
(See Chart No. 1, I10)

DFO(6305691-01)

This notice affects Electronic Navigational Chart: CA476125

09-SEP-2011 LNM/D. 04-MAR-2011

Chart no. 4912

Add depth of 7 metres, 2 decimetres 47°03′50.9″N 065°25′23.0″W
(See Chart No. 1, I10)

DFO(6305691-02)

This notice affects Electronic Navigational Chart: CA476125

09-SEP-2011 LNM/D. 04-MAR-2011

Delete depth of 6 metres, 4 decimetres 47°08′07.6″N 065°11′32.1″W
(See Chart No. 1, I10)

DFO(6305691-03)

09-SEP-2011 LNM/D. 04-MAR-2011

Add depth of 6 metres 47°08′07.1″N 065°11′32.3″W
(See Chart No. 1, I10)

DFO(6305691-04)

This notice affects Electronic Navigational Chart: CA476125

09-SEP-2011 LNM/D. 04-MAR-2011

Delete depth of 6 metres, 3 decimetres 47°08′05.5″N 065°11′19.3″W
(See Chart No. 1, I10)

DFO(6305691-05)

09-SEP-2011 LNM/D. 04-MAR-2011

Add depth of 6 metres 47°08′04.7″N 065°11′17.3″W
(See Chart No. 1, I10)

DFO(6305691-06)

This notice affects Electronic Navigational Chart: CA476125

09-SEP-2011 LNM/D. 04-MAR-2011

Delete depth of 6 metres, 4 decimetres 47°04′49.4″N 065°19′35.7″W
(See Chart No. 1, I10)

DFO(6305691-09)

09-SEP-2011 LNM/D. 04-MAR-2011

Chart no. 4912

Add depth of 5 metres, 3 decimetres 47°04′48.1″N 065°19′33.9″W
(See Chart No. 1, I10)

DFO(6305691-10)

This notice affects Electronic Navigational Chart: CA476125

04-MAR-2011 LNM/D. 20-AUG-2010

Amend QY 10m to read Iso Y 10m against front range light 47°06′02.1″N 065°19′28.5″W
(See Chart No 1 P20.2) *(G2011013) LL(1198.8) DFO(6305231-01)*

This notice affects Electronic Navigational Chart: CA476125

04-MAR-2011 LNM/D. 20-AUG-2010

Amend Q 9m to read Iso 9m against front range light 47°06′48.9″N 065°16′30.0″W
(See Chart No 1 P20.2)

(G2011015) LL(1202.5) DFO(6305233-01)

This notice affects Electronic Navigational Chart: CA476125

04-MAR-2011 LNM/D. 20-AUG-2010

Amend QR 21m to read Iso R 21m against front range light 47°05′02.9″N 065°22′29.4″W
(See Chart No 1 P20.2)

(G2011016) LL(1207) DFO(6305234-01)

This notice affects Electronic Navigational Chart: CA476125

04-MAR-2011 LNM/D. 20-AUG-2010

Amend Q 13m to read Iso 13m against front range light 47°04′31.0″N 065°24′35.5″W
(See Chart No 1 P20.2)

(G2011017) LL(1209.5) DFO(6305235-01)

This notice affects Electronic Navigational Chart: CA476125

04-MAR-2011 LNM/D. 20-AUG-2010

Chart no. 4912

Amend QR 14m to read Iso R 14m against front range light
(See Chart No 1 P20.2)
47°04′42.3″N 065°23′56.7″W
(G2011018) LL(1209.7) DFO(6305236-01)

This notice affects Electronic Navigational Chart: CA476125

20-AUG-2010
LNM/D. 13-AUG-2010

Delete depth of 7 metres, 1 decimetre
(See Chart No. 1, I10)
47°08′08.3″N 065°12′03.7″W
DFO(6304808-03)

This notice affects Electronic Navigational Chart: CA476125

20-AUG-2010
LNM/D. 13-AUG-2010

Add depth of 6 metres, 7 decimetres
(See Chart No. 1, I10)
47°08′08.2″N 065°12′03.1″W
DFO(6304808-04)

This notice affects Electronic Navigational Chart: CA476125

20-AUG-2010
LNM/D. 13-AUG-2010

Delete depth of 7 metres, 3 decimetres
(See Chart No 1 I10)
47°07′42.0″N 065°08′46.8″W
DFO(6304985-01)

This notice affects Electronic Navigational Chart: CA476125

20-AUG-2010
LNM/D. 13-AUG-2010

Amend 6.8 mètres (2004) to read 6.2 mètres (2010) against the note ATTENTION and 6.8 metres (2004) to read 6.2 metres (2010) against the note CAUTION
47°10′50.0″N 065°10′42.0″W
DFO(6304985-02)

This notice affects Electronic Navigational Chart: CA476133

20-AUG-2010
LNM/D. 13-AUG-2010

Chart no. 4912

Delete depth of 7 metres 47°07′51.0″N 065°09′46.0″W
(See Chart No. 1, I10)

DFO(6304985-03)

This notice affects Electronic Navigational Chart: CA476125

20-AUG-2010 LNM/D. 13-AUG-2010

Add depth of 6 metres, 7 decimetres 47°07′51.4″N 065°09′48.3″W
(See Chart No. 1, I10)

DFO(6304985-04)

This notice affects Electronic Navigational Chart: CA476125

20-AUG-2010 LNM/D. 13-AUG-2010

Delete depth of 7 metres, 2 decimetres 47°04′56.4″N 065°21′23.5″W
(See Chart No 1 I10)

DFO(6304989-01)

This notice affects Electronic Navigational Chart: CA476125

20-AUG-2010 LNM/D. 13-AUG-2010

Add depth of 6 metres, 5 decimetres 47°04′55.6″N 065°21′18.8″W
(See Chart No 1 I10)

DFO(6304989-02)

This notice affects Electronic Navigational Chart: CA476125

13-AUG-2010 LNM/D. 18-SEP-2009

Add note: 47°11′18.0″N 065°10′40.0″W

ENSABLEMENT
En raison d′ensablement continuel les profondeurs normales et la présentation des isobathes changent constamment. Les navigateurs sont avisés d′être prudents en naviguant dans ces eaux.

DFO(6304879-01)

SILTING
Due to continuous silting, the normal depths and the presentation of the bathymetric contours are constantly changing. Mariners are warned to exercise due caution when navigating in these waters.

This notice affects Electronic Navigational Chart: CA476125

Chart no. 4912

18-SEP-2009

Delete depth of 7 metres 47°08′06.5″N 065°11′33.0″W
(See Chart No. 1, I10)

DFO(6304547-01)

This notice affects Electronic Navigational Chart: CA476125

18-SEP-2009

Delete depth of 7 metres 47°08′02.8″N 065°11′02.8″W
(See Chart No. 1, I10)

DFO(6304547-02)

18-SEP-2009

Delete depth of 6 metres, 8 decimetres 47°08′04.8″N 065°11′19.8″W
(See Chart No. 1, I10)

DFO(6304547-03)

18-SEP-2009

Add depth of 6 metres, 4 decimetres 47°08′07.6″N 065°11′32.1″W
(See Chart No. 1, I10)

DFO(6304547-04)

18-SEP-2009

Add depth of 6 metres, 4 decimetres 47°07′59.7″N 065°10′37.5″W
(See Chart No. 1, I10)

DFO(6304547-05)

18-SEP-2009

Add depth of 6 metres, 3 decimetres 47°08′04.2″N 065°11′07.5″W
(See Chart No. 1, I10)

DFO(6304547-06)

18-SEP-2009

Add depth of 6 metres, 3 decimetres 47°08′05.5″N 065°11′19.3″W
(See Chart No. 1, I10)

DFO(6304547-07)

Chart no. 4912

4912 - Continuation A - New Edition - 27-JAN-2006 - NAD 1983

23-SEP-2022 LNM/D. 15-APR-2022

Replace depth of 7.9 metres with depth of 7.5 metres 47°03′56.7″N 065°25′05.1″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6310314-18)*

05-JUN-2020 LNM/D. 27-OCT-2017

Delete depth of 7.7 metres 47°02′04.4″N 065°28′04.5″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476126 *DFO(6308947-11)*

05-JUN-2020 LNM/D. 27-OCT-2017

Add submerged wreck Wk 47°03′39.2″N 065°26′36.8″W
(See Chart No. 1, K23)
This notice affects Electronic Navigational Chart: CA476125 *DFO(6308947-12)*

05-JUN-2020 LNM/D. 27-OCT-2017

Add depth of 0.8 metres 47°02′04.9″N 065°28′03.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476126 *DFO(6308947-13)*

04-MAR-2016 LNM/D. 27-NOV-2015

Delete front range/leading light Iso Y 13m 47°00′57.9″N 065°32′44.1″W
(See Chart No. 1, P20.2)
(G2016003) LL(1218) DFO(6307452-01)
This notice affects Electronic Navigational Chart: CA476126

04-MAR-2016 LNM/D. 27-NOV-2015

Delete rear range/leading light Iso Y 4s16m with leading line and bearings 098½° - 278½° 47°00′58.1″N 065°32′46.3″W
(See Chart No. 1, P20.2, Pe) *(G2016004) LL(1219) DFO(6307452-02)*
This notice affects Electronic Navigational Chart: CA476126

27-NOV-2015 LNM/D. 07-FEB-2014

Chart no. 4912

Amend QG to read FlG against buoy marked M73 — 47°00′16.1″N 065°33′39.5″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA476126 — *(G2015139) LL(1223) DFO(6307309-01)*

27-NOV-2015 — LNM/D. 07-FEB-2014

Reposition green port hand lighted spar buoy QG, marked M69 — from 47°00′53.4″N 065°32′33.8″W to 47°00′55.1″N 065°32′28.0″W
(See Chart No. 1, Qg)
This notice affects Electronic Navigational Chart: CA476126 — *(G2015140) LL(1220) DFO(6307309-02)*

07-FEB-2014 — LNM/D. 09-SEP-2011

Add depth of 9 metres, 8 decimetres — 47°03′30.4″N 065°27′06.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476126 — *DFO(6306580-20)*

07-FEB-2014 — LNM/D. 09-SEP-2011

Replace depth of 12 metres with depth of 11 metres, 4 decimetres — 47°03′21.5″N 065°27′27.8″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476126 — *DFO(6306580-21)*

07-FEB-2014 — LNM/D. 09-SEP-2011

Add depth of 9 metres, 9 decimetres — 47°00′32.1″N 065°33′36.9″W
(See Chart No. 1, I10)
This notice affects Electronic Navigational Chart: CA476126 — *DFO(6306580-22)*

09-SEP-2011 — LNM/D. 04-MAR-2011

Delete depth of 7 metres, 5 decimetres — 47°03′50.6″N 065°25′22.8″W
(See Chart No. 1, I10)

DFO(6305691-01)

This notice affects Electronic Navigational Chart: CA476125

09-SEP-2011 — LNM/D. 04-MAR-2011

Add depth of 7 metres, 2 decimetres — 47°03′50.9″N 065°25′23.0″W
(See Chart No. 1, I10)

DFO(6305691-02)

This notice affects Electronic Navigational Chart: CA476125

Chart no. 4912

04-MAR-2011 LNM/D. 20-AUG-2010

Amend QR 16m to read Iso R 16m against front range light 47°03′21.8″N 065°27′34.0″W
(See Chart No 1 P20.2)

(G2011019) LL(1212.5) DFO(6305237-01)

04-MAR-2011 LNM/D. 20-AUG-2010

Amend QY 13m to read Iso Y 13m against front range light 47°00′58.0″N 065°32′44.0″W
(See Chart No 1 P20.2)

(G2011020) LL(1218) DFO(6305238-01)

20-AUG-2010 LNM/D. 13-AUG-2010

Delete depth of 7 metres, 6 decimetres 46°59′55.9″N 065°33′40.9″W
(See Chart No. 1, I10)

DFO(6304808-01)

This notice affects Electronic Navigational Chart: CA476126

20-AUG-2010 LNM/D. 13-AUG-2010

Add depth of 6 metres, 9 decimetres 46°59′57.6″N 065°33′42.6″W
(See Chart No. 1, I10)

DFO(6304808-02)

This notice affects Electronic Navigational Chart: CA476126

20-AUG-2010 LNM/D. 13-AUG-2010

Delete depth of 8 metres 47°00′03.5″N 065°33′43.1″W
(See Chart No. 1, I10)

DFO(6304808-12)

This notice affects Electronic Navigational Chart: CA476126

20-AUG-2010 LNM/D. 13-AUG-2010

Add depth of 6 metres, 9 decimetres 47°00′03.7″N 065°33′43.8″W
(See Chart No. 1, I10)

DFO(6304808-13)

This notice affects Electronic Navigational Chart: CA476126